

All ordered work under Home Energy Scheme 2009-2014 (including open orders as of 22-04-14)

Work Item / Energy efficiency measure	Amount Spent	Actual Quantity of items	Ownership Declaration (HES) Joint or sole ownership vs tenanted	Date of completion	Sign Off Year
HES92 Other miscellaneous electrical heating works for EES appr	£3,310.75	1.00	Sole Property Owner	20/02/2013	2013
HES65 Stainless steel replacement hot water cylinder (210L)	£556.50	1.00	Sole Property Owner	20/02/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£826.19	1.00	Sole Property Owner	20/02/2013	2013
EES69 Miscellaneous Charge	£0.00	0.00	Sole Property Owner	20/02/2013	2013
EES66 Low energy lamp replacement	£125.07	11.00	Sole Property Owner	20/02/2013	2013
EES25 Draught stripping to exterior door	£36.75	5.00	Sole Property Owner	20/02/2013	2013
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	20/02/2013	2013
EES51b 16-20kW Gas replacement boiler	£1,563.34	1.00	Sole Property Owner	01/08/2011	2011
EES69 Miscellaneous Charge	£163.65	163.65	Sole Property Owner	01/08/2011	2011
EES01a Loft Clearance (hourly rate)	£327.60	7.00	Sole Property Owner	01/08/2011	2011
EES08 300mm thick loft insulation	£835.36	46.00	Sole Property Owner	01/08/2011	2011
EES38a Thermostatic radiator valve (per valve)	£297.45	9.00	Sole Property Owner	01/08/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£24.27	3.00	Sole Property Owner	01/08/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£202.84	22.00	Sole Property Owner	01/08/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£128.43	9.00	Sole Property Owner	01/08/2011	2011
EES66 Low energy lamp replacement	£181.92	16.00	Sole Property Owner	01/08/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	01/08/2011	2011
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	01/08/2011	2011
HES85 Building Control Officer inspection undertaken	£103.85	1.00	Sole Property Owner	01/08/2011	2011
EES25 Draught stripping to exterior door	£60.00	6.00	Sole Property Owner	01/11/2009	2009
EES27 Draught stripping to letterbox	£40.00	1.00	Sole Property Owner	01/11/2009	2009
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	01/11/2009	2009
EES75 HEC to Flat or Bedsit	£0.00	0.00	Sole Property Owner	05/07/2011	2011
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Joint Owner	02/08/2012	2012
EES02a Remove and dispose existing insulation (per squire metre	£165.00	55.00	Joint Owner	02/08/2012	2012
EES03a Remove and replace nailed floor board	£15.00	5.00	Joint Owner	02/08/2012	2012
EES08 300mm thick loft insulation	£660.00	55.00	Joint Owner	02/08/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	02/08/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	02/08/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	02/08/2012	2012
EES13a Cold water tank bye law kit (including associated product	£50.00	1.00	Joint Owner	02/08/2012	2012
EES33 Replacement hot water cylinder (150L)	£1,200.00	1.00	Joint Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£70.00	10.00	Joint Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	12.00	Joint Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	02/08/2012	2012
HES71 Storage heater rated 1kW - 2kW	£244.53	1.00	Joint Owner	02/08/2012	2012
HES73 Storage heater rated 3kW - 4kW	£375.34	1.00	Joint Owner	02/08/2012	2012
HES97 Electrician	£312.00	9.75	Joint Owner	02/08/2012	2012
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Joint Owner	02/08/2012	2012
EES02a Remove and dispose existing insulation (per squire metre	£135.00	45.00	Joint Owner	02/08/2012	2012
EES03a Remove and replace nailed floor board	£30.00	10.00	Joint Owner	02/08/2012	2012
EES08 300mm thick loft insulation	£540.00	45.00	Joint Owner	02/08/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	02/08/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	02/08/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	02/08/2012	2012
EES13a Cold water tank bye law kit (including associated product	£50.00	1.00	Joint Owner	02/08/2012	2012
EES33 Replacement hot water cylinder (150L)	£0.00	0.00	Joint Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	14.00	Joint Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	02/08/2012	2012
EES15 Insulation to 65mm wide cavity wall	£1,036.80	1,036.80	Joint Owner	02/08/2012	2012
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Joint Owner	02/08/2012	2012
HES73 Storage heater rated 3kW - 4kW	£833.64	2.00	Joint Owner	02/08/2012	2012
HES76 Storage heater miniature circuit breaker	£16.02	3.00	Joint Owner	02/08/2012	2012
HES89 Explanation of controls, manuals, EIC certification and sch	£0.00	2.00	Joint Owner	02/08/2012	2012
HES97 Electrician	£450.00	18.00	Joint Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£42.00	6.00	Joint Owner	02/08/2012	2012
HES97 Electrician	£425.00	17.00	Sole Property Owner	05/11/2012	2012
HES73 Storage heater rated 3kW - 4kW	£416.82	1.00	Sole Property Owner	05/11/2012	2012
HES75 Storage heater consumer unit	£32.92	1.00	Sole Property Owner	05/11/2012	2012
HES76 Storage heater miniature circuit breaker	£10.68	2.00	Sole Property Owner	05/11/2012	2012
HES77 Main bonding of necessary services	£6.48	2.00	Sole Property Owner	05/11/2012	2012
HES79 Heating point twin and earth mini trunk DP switch	£6.56	1.00	Sole Property Owner	05/11/2012	2012
HES80 16mm meter tails	£14.16	3.00	Sole Property Owner	05/11/2012	2012
HES54 Water heating time clock and boost controller	£92.95	1.00	Sole Property Owner	05/11/2012	2012
EES01a Loft Clearance (hourly rate)	£375.00	15.00	Sole Property Owner	05/11/2012	2012
EES02a Remove and dispose existing insulation (per squire metre	£330.00	110.00	Sole Property Owner	05/11/2012	2012
EES03a Remove and replace nailed floor board	£177.00	59.00	Sole Property Owner	05/11/2012	2012
EES08 300mm thick loft insulation	£1,320.00	110.00	Sole Property Owner	05/11/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	05/11/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	05/11/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	05/11/2012	2012
EES13a Cold water tank bye law kit (including associated product	£50.00	1.00	Sole Property Owner	05/11/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£140.00	20.00	Sole Property Owner	05/11/2012	2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	05/11/2012	2012
EES15 Insulation to 65mm wide cavity wall	£997.20	997.20	Sole Property Owner	05/11/2012	2012
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Joint Owner	06/01/2012	2012
EES02a Remove and dispose existing insulation (per squire metre	£30.00	10.00	Joint Owner	06/01/2012	2012
EES03a Remove and replace nailed floor board	£45.00	15.00	Joint Owner	06/01/2012	2012
EES07 200mm thick loft insulation	£1,170.00	130.00	Joint Owner	06/01/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	06/01/2012	2012

EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	06/01/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	06/01/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Joint Owner	06/01/2012	2012
EES38a Thermostatic radiator valve (per valve)	£935.00	11.00	Joint Owner	06/01/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£126.00	18.00	Joint Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£0.00	25.00	Joint Owner	06/01/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	06/01/2012	2012
EES15 Insulation to 65mm wide cavity wall	£1,053.60	1,053.60	Joint Owner	06/01/2012	2012
HES120 Standard QA check	£90.00	1.00	Joint Owner	06/01/2012	2012
HES54 Water heating time clock and boost controller	£0.00	1.00	Joint Owner	27/09/2012	2012
EES66 Low energy lamp replacement	£0.00	10.00	Joint Owner	27/09/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	27/09/2012	2012
EES15 Insulation to 65mm wide cavity wall	£374.40	374.40	Joint Owner	27/09/2012	2012
HES71 Storage heater rated 1kW - 2kW	£267.32	1.00	Joint Owner	27/09/2012	2012
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Joint Owner	27/09/2012	2012
HES73 Storage heater rated 3kW - 4kW	£416.82	1.00	Joint Owner	27/09/2012	2012
HES75 Storage heater consumer unit	£32.92	1.00	Joint Owner	27/09/2012	2012
HES76 Storage heater miniature circuit breaker	£21.36	4.00	Joint Owner	27/09/2012	2012
HES97 Electrician	£650.00	26.00	Joint Owner	27/09/2012	2012
HES79 Heating point twin and earth mini trunk DP switch	£19.68	3.00	Joint Owner	27/09/2012	2012
HES120 Standard QA check	£102.00	1.00	Joint Owner	27/09/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Joint Owner	06/12/2011	2011
EES66 Low energy lamp replacement	£0.00	20.00	Joint Owner	06/12/2011	2011
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	06/12/2011	2011
EES15 Insulation to 65mm wide cavity wall	£1,308.00	1,308.00	Joint Owner	06/12/2011	2011
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Joint Owner	06/12/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£200.00	20.00	Joint Owner	06/12/2011	2011
EES70 Miscellaneous heating review charge	£3,337.06	1.00	Joint Owner	06/12/2011	2011
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	06/12/2011	2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	02/08/2012	2012
EES25 Draught stripping to exterior door	£60.00	6.00	Joint Owner	02/08/2012	2012
HES71 Storage heater rated 1kW - 2kW	£244.53	1.00	Joint Owner	02/08/2012	2012
HES73 Storage heater rated 3kW - 4kW	£375.34	1.00	Joint Owner	02/08/2012	2012
HES97 Electrician	£256.00	8.00	Joint Owner	02/08/2012	2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Joint Owner	02/08/2012	2012
EES08 300mm thick loft insulation	£144.00	12.00	Joint Owner	02/08/2012	2012
EES25 Draught stripping to exterior door	£60.00	6.00	Joint Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	15.00	Joint Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	3.00	Joint Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	15.00	Sole Property Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	02/08/2012	2012
EES15 Insulation to 65mm wide cavity wall	£691.20	691.20	Sole Property Owner	02/08/2012	2012
EES77 HEC to House	£150.00	1.00	Sole Property Owner	11/08/2011	2011
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	11/08/2011	2011
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Sole Property Owner	06/01/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£54.00	18.00	Sole Property Owner	06/01/2012	2012
EES08 300mm thick loft insulation	£216.00	18.00	Sole Property Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£0.00	21.00	Sole Property Owner	06/01/2012	2012
EES51a 16-20kW Oil replacement boiler	£3,450.00	1.00	Sole Property Owner	30/05/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	30/05/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	30/05/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	30/05/2012	2012
EES44 Water heating time clock and boost	£130.00	1.00	Sole Property Owner	30/05/2012	2012
EES38a Thermostatic radiator valve (per valve)	£935.00	11.00	Sole Property Owner	30/05/2012	2012
EES34 Replacement hot water cylinder (170l)	£1,240.00	1.00	Sole Property Owner	30/05/2012	2012
EES70 Miscellaneous heating review charge	£894.00	1.00	Sole Property Owner	30/05/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£126.00	18.00	Sole Property Owner	30/05/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	30/05/2012	2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£0.00	14.00	Sole Property Owner	06/01/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	06/01/2012	2012
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Joint Owner	02/08/2012	2012
EES08 300mm thick loft insulation	£600.00	50.00	Joint Owner	02/08/2012	2012
EES10 Cold water tank insulation quilt	£0.00	0.00	Joint Owner	02/08/2012	2012
EES 11 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	02/08/2012	2012
EES12 Cold water tank lid	£0.00	0.00	Joint Owner	02/08/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£0.00	0.00	Joint Owner	02/08/2012	2012
EES33 Replacement hot water cylinder (150l)	£0.00	0.00	Joint Owner	02/08/2012	2012
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Joint Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Joint Owner	02/08/2012	2012
EES15 Insulation to 65mm wide cavity wall	£1,059.00	1,059.00	Joint Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	25.00	Joint Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	02/08/2012	2012
EES 83 Powerflush central heating system	£0.00	1.00	Joint Owner	02/08/2012	2012
EES51a 16-20kW Oil replacement boiler	£3,450.00	1.00	Joint Owner	02/08/2012	2012
EES 84 Magnetic filtration unit	£0.00	1.00	Joint Owner	02/08/2012	2012
EES34 Replacement hot water cylinder (170l)	£1,240.00	1.00	Joint Owner	02/08/2012	2012
EES38a Thermostatic radiator valve (per valve)	£680.00	8.00	Joint Owner	02/08/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Joint Owner	02/08/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Joint Owner	02/08/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Joint Owner	02/08/2012	2012
EES44 Water heating time clock and boost	£130.00	1.00	Joint Owner	02/08/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	02/08/2012	2012

EES12 Cold water tank lid	£75.00	1.00	Joint Owner	02/08/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Joint Owner	02/08/2012	2012
EES49 Pipework lagging 25mm thick to 22mm pipe	£132.00	12.00	Joint Owner	02/08/2012	2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£72.00	8.00	Joint Owner	02/08/2012	2012
EES82 Boiler replacement miscellaneous works	£1,427.90	1.00	Joint Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£238.00	34.00	Joint Owner	02/08/2012	2012
EES69 Miscellaneous Charge	£160.92	1.00	Joint Owner	02/08/2012	2012
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Not The Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	10.00	Not The Property Owner	02/08/2012	2012
EES77 HEC to House	£0.00	0.00	Not The Property Owner	02/08/2012	2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Not The Property Owner	02/08/2012	2012
EES69 Miscellaneous Charge	£60.00	1.00	Not The Property Owner	02/08/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	01/12/2011	2011
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	01/12/2011	2011
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	05/11/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	05/11/2012	2012
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	05/11/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	05/11/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	24/05/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£0.55	0.50	Not The Property Owner	24/05/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012	2012
EES77 HEC to House	£150.00	1.00	Not The Property Owner	06/01/2012	2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£1.09	1.00	Not The Property Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012	2012
HES119 Missed appointment charge	£60.00	1.00	Not The Property Owner	06/01/2012	2012
HES80 16mm meter tails	£0.00	0.00	Sole Property Owner	02/08/2012	2012
HES97 Electrician	£650.00	26.00	Sole Property Owner	02/08/2012	2012
HES71 Storage heater rated 1kW - 2kW	£801.96	3.00	Sole Property Owner	02/08/2012	2012
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Sole Property Owner	02/08/2012	2012
HES75 Storage heater consumer unit	£32.92	1.00	Sole Property Owner	02/08/2012	2012
HES76 Storage heater miniature circuit breaker	£21.36	4.00	Sole Property Owner	02/08/2012	2012
HES89 Explanation of controls, manuals, EIC certification and sch	£0.00	1.00	Sole Property Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£28.00	4.00	Sole Property Owner	02/08/2012	2012
EES07 200mm thick loft insulation	£0.00	0.00	Sole Property Owner	02/08/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	02/08/2012	2012
EES16 Insulation to 75mm wide cavity wall	£0.00	0.00	Sole Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	14.00	Sole Property Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	02/08/2012	2012
EES75 HEC to Flat or Bedsit	£0.00	0.00	Sole Property Owner	21/07/2011	2011
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	18/01/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	18/01/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	18/01/2012	2012
EES38a Thermostatic radiator valve (per valve)	£680.00	8.00	Sole Property Owner	18/01/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	18/01/2012	2012
EES52a 21-25kW Oil replacement boiler	£3,633.00	1.00	Sole Property Owner	18/01/2012	2012
EES70 Miscellaneous heating review charge	£2,350.00	2,350.00	Sole Property Owner	18/01/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£126.00	18.00	Sole Property Owner	18/01/2012	2012
EES16 Insulation to 75mm wide cavity wall	£1,111.20	1,111.20	Sole Property Owner	18/01/2012	2012
EES66 Low energy lamp replacement	£0.00	29.00	Sole Property Owner	18/01/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	18/01/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	18/01/2012	2012
EES34 Replacement hot water cylinder (170l)	£1,240.00	1.00	Sole Property Owner	02/08/2012	2012
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Sole Property Owner	02/08/2012	2012
EES52a 21-25kW Oil replacement boiler	£3,633.00	1.00	Sole Property Owner	02/08/2012	2012
EES44 Water heating time clock and boost	£130.00	1.00	Sole Property Owner	02/08/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	02/08/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	02/08/2012	2012
EES13a Cold water tank bye law kit (including associated product)	£50.00	1.00	Sole Property Owner	02/08/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	02/08/2012	2012
EES70 Miscellaneous heating review charge	£2,289.00	1.00	Sole Property Owner	02/08/2012	2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	02/08/2012	2012
EES08 300mm thick loft insulation	£336.00	28.00	Sole Property Owner	02/08/2012	2012
EES16 Insulation to 75mm wide cavity wall	£132.00	132.00	Sole Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	25.00	Sole Property Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	02/08/2012	2012
EES82 Boiler replacement miscellaneous works	£600.60	1.00	Sole Property Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£196.00	28.00	Sole Property Owner	02/08/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	02/08/2012	2012
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Sole Property Owner	06/01/2012	2012
EES16 Insulation to 75mm wide cavity wall	£1,099.20	109.92	Sole Property Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£0.00	25.00	Sole Property Owner	06/01/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	06/01/2012	2012
HES120 Standard QA check	£102.00	1.00	Sole Property Owner	19/04/2013	2013
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	19/04/2013	2013
EES66 Low energy lamp replacement	£0.00	12.00	Sole Property Owner	19/04/2013	2013
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	19/04/2013	2013
HES97 Electrician	£575.00	23.00	Sole Property Owner	19/04/2013	2013
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Sole Property Owner	19/04/2013	2013
HES73 Storage heater rated 3kW - 4kW	£833.64	2.00	Sole Property Owner	19/04/2013	2013
HES75 Storage heater consumer unit	£32.92	1.00	Sole Property Owner	19/04/2013	2013
HES76 Storage heater miniature circuit breaker	£21.36	4.00	Sole Property Owner	19/04/2013	2013
HES77 Main bonding of necessary services	£6.48	2.00	Sole Property Owner	19/04/2013	2013
HES80 16mm meter tails	£18.88	4.00	Sole Property Owner	19/04/2013	2013

HES54 Water heating time clock and boost controller	£92.95	1.00	Sole Property Owner	19/04/2013	2013
EES67 Smoke detector installation	£0.00	1.00	Joint Owner	06/01/2012	2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Joint Owner	06/01/2012	2012
EES07 200mm thick loft insulation	£495.00	55.00	Joint Owner	06/01/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	06/01/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	06/01/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	06/01/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£100.00	2.00	Joint Owner	06/01/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£84.00	12.00	Joint Owner	06/01/2012	2012
EES16 Insulation to 75mm wide cavity wall	£714.00	714.00	Joint Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£0.00	12.00	Joint Owner	06/01/2012	2012
HES120 Standard QA check	£90.00	1.00	Joint Owner	06/01/2012	2012
EES36 Electrical room thermostat	£61.60	1.00	Joint Owner	24/03/2012	2012
EES42 Two channel programmable heating controller	£139.59	1.00	Joint Owner	24/03/2012	2012
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Joint Owner	24/03/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	20.00	Joint Owner	24/03/2012	2012
EES70 Miscellaneous heating review charge	£1,195.80	1.00	Joint Owner	24/03/2012	2012
EES40 Hot water cylinder thermostat	£60.19	1.00	Joint Owner	24/03/2012	2012
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Joint Owner	24/03/2012	2012
EES03a Remove and replace nailed floor board	£24.00	8.00	Joint Owner	24/03/2012	2012
EES08 300mm thick loft insulation	£1,056.00	88.00	Joint Owner	24/03/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	24/03/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	24/03/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	24/03/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Joint Owner	24/03/2012	2012
EES38a Thermostatic radiator valve (per valve)	£595.00	7.00	Joint Owner	24/03/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£154.00	22.00	Joint Owner	24/03/2012	2012
EES66 Low energy lamp replacement	£0.00	22.00	Joint Owner	24/03/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	24/03/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	24/03/2012	2012
EES25 Draught stripping to exterior door	£40.00	4.00	Sole Property Owner	01/11/2009	2009
EES29 Hot water cylinder jacket (30x18 inch)	£100.00	1.00	Sole Property Owner	01/11/2009	2009
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	01/11/2009	2009
EES51a 16-20kW Oil replacement boiler	£3,450.00	1.00	Sole Property Owner	12/01/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	12/01/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	12/01/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	12/01/2012	2012
EES70 Miscellaneous heating review charge	£2,065.00	2,065.00	Sole Property Owner	12/01/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£294.00	42.00	Sole Property Owner	12/01/2012	2012
EES03a Remove and replace nailed floor board	£120.00	40.00	Sole Property Owner	12/01/2012	2012
EES07 200mm thick loft insulation	£360.00	40.00	Sole Property Owner	12/01/2012	2012
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Sole Property Owner	12/01/2012	2012
EES08 300mm thick loft insulation	£0.00	0.00	Sole Property Owner	12/01/2012	2012
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	12/01/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	12/01/2012	2012
EES25 Draught stripping to exterior door	£120.00	12.00	Sole Property Owner	12/01/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	12/01/2012	2012
EES07 200mm thick loft insulation	£378.00	42.00	Sole Property Owner	02/08/2012	2012
EES01a Loft Clearance (hourly rate)	£175.00	7.00	Sole Property Owner	02/08/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£66.00	22.00	Sole Property Owner	02/08/2012	2012
EES03a Remove and replace nailed floor board	£90.00	30.00	Sole Property Owner	02/08/2012	2012
EES08 300mm thick loft insulation	£0.00	0.00	Sole Property Owner	02/08/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	02/08/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	02/08/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	02/08/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£100.00	2.00	Sole Property Owner	02/08/2012	2012
EES36 Electrical room thermostat	£0.00	0.00	Sole Property Owner	02/08/2012	2012
EES38a Thermostatic radiator valve (per valve)	£255.00	3.00	Sole Property Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£140.00	20.00	Sole Property Owner	02/08/2012	2012
EES69 Miscellaneous Charge	£0.00	0.00	Sole Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	5.00	Sole Property Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	02/08/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	09/08/2012	2012
HES72 Storage heater rated 2kW - 3kW	£308.49	1.00	Sole Property Owner	09/08/2012	2012
HES63 Stainless steel replacement hot water cylinder (150L)	£231.60	1.00	Sole Property Owner	09/08/2012	2012
HES97 Electrician	£96.00	3.00	Sole Property Owner	09/08/2012	2012
HES94 Heating engineer	£192.00	6.00	Sole Property Owner	09/08/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	09/08/2012	2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Joint Owner	27/09/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£126.00	42.00	Joint Owner	27/09/2012	2012
EES03a Remove and replace nailed floor board	£75.00	25.00	Joint Owner	27/09/2012	2012
EES08 300mm thick loft insulation	£504.00	42.00	Joint Owner	27/09/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	27/09/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	27/09/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	27/09/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Joint Owner	27/09/2012	2012
EES33 Replacement hot water cylinder (150L)	£1,200.00	1.00	Joint Owner	27/09/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£112.00	16.00	Joint Owner	27/09/2012	2012
EES66 Low energy lamp replacement	£0.00	15.00	Joint Owner	27/09/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	27/09/2012	2012
HES97 Electrician	£400.00	16.00	Joint Owner	27/09/2012	2012
HES73 Storage heater rated 3kW - 4kW	£833.64	2.00	Joint Owner	27/09/2012	2012
HES75 Storage heater consumer unit	£32.92	1.00	Joint Owner	27/09/2012	2012
HES76 Storage heater miniature circuit breaker	£16.02	3.00	Joint Owner	27/09/2012	2012

HES80 16mm meter tails	£14.16	3.00	Joint Owner	27/09/2012	2012
HES54 Water heating time clock and boost controller	£92.95	1.00	Joint Owner	27/09/2012	2012
HES77 Main bonding of necessary services	£6.48	2.00	Joint Owner	27/09/2012	2012
HES120 Standard QA check	£90.00	1.00	Joint Owner	27/09/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	20/12/2013	2013
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	20/12/2013	2013
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	20/12/2013	2013
EES68 Minimum charge for lamps and detectors	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES71 Storage heater rated 1kW - 2kW	£489.06	2.00	Sole Property Owner	20/12/2013	2013
HES72 Storage heater rated 2kW - 3kW	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES73 Storage heater rated 3kW - 4kW	£375.34	1.00	Sole Property Owner	20/12/2013	2013
HES74 Comfort heat main switch	£57.20	1.00	Sole Property Owner	20/12/2013	2013
HES75 Storage heater consumer unit	£49.40	1.00	Sole Property Owner	20/12/2013	2013
HES76 Storage heater miniature circuit breaker	£39.00	4.00	Sole Property Owner	20/12/2013	2013
HES77 Main bonding of necessary services	£163.50	15.00	Sole Property Owner	20/12/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£611.36	4.00	Sole Property Owner	20/12/2013	2013
HES80 16mm meter tails	£12.48	1.00	Sole Property Owner	20/12/2013	2013
HES83 Trunking	£28.92	3.00	Sole Property Owner	20/12/2013	2013
HES54 Water heating time clock and boost controller	£58.50	1.00	Sole Property Owner	20/12/2013	2013
HES97 Electrician	£960.00	30.00	Sole Property Owner	20/12/2013	2013
EES 83 Powerflush central heating system	£0.00	1.00	Sole Property Owner	02/08/2012	2012
EES52a 21-25kW Oil replacement boiler	£3,633.00	1.00	Sole Property Owner	02/08/2012	2012
EES 84 Magnetic filtration unit	£0.00	1.00	Sole Property Owner	02/08/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	02/08/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	02/08/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	02/08/2012	2012
EES38a Thermostatic radiator valve (per valve)	£85.00	1.00	Sole Property Owner	02/08/2012	2012
EES82 Boiler replacement miscellaneous works	£2,735.00	1.00	Sole Property Owner	02/08/2012	2012
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Sole Property Owner	02/08/2012	2012
EES08 300mm thick loft insulation	£1,440.00	120.00	Sole Property Owner	02/08/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	02/08/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	02/08/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	02/08/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	02/08/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	02/08/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	02/08/2012	2012
EES38a Thermostatic radiator valve (per valve)	£765.00	9.00	Sole Property Owner	02/08/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£686.00	98.00	Sole Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	25.00	Sole Property Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	02/08/2012	2012
EES70 Miscellaneous heating review charge	£374.29	1.00	Sole Property Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£70.00	10.00	Sole Property Owner	02/08/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	02/08/2012	2012
EES01a Loft Clearance (hourly rate)	£250.00	10.00	Sole Property Owner	08/02/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£135.00	45.00	Sole Property Owner	08/02/2012	2012
EES08 300mm thick loft insulation	£540.00	45.00	Sole Property Owner	08/02/2012	2012
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	08/02/2012	2012
EES66 Low energy lamp replacement	£0.00	14.00	Sole Property Owner	08/02/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	08/02/2012	2012
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	08/02/2012	2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Joint Owner	11/10/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£135.00	45.00	Joint Owner	11/10/2012	2012
EES08 300mm thick loft insulation	£540.00	45.00	Joint Owner	11/10/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	11/10/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	11/10/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	11/10/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Joint Owner	11/10/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Joint Owner	11/10/2012	2012
EES66 Low energy lamp replacement	£0.00	17.00	Joint Owner	11/10/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	11/10/2012	2012
EES15 Insulation to 65mm wide cavity wall	£216.00	216.00	Joint Owner	11/10/2012	2012
EES69 Miscellaneous Charge	£42.00	1.00	Joint Owner	11/10/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	09/08/2012	2012
HES71 Storage heater rated 1kW - 2kW	£267.32	1.00	Sole Property Owner	09/08/2012	2012
HES73 Storage heater rated 3kW - 4kW	£416.82	1.00	Sole Property Owner	09/08/2012	2012
HES89 Explanation of controls, manuals, EIC certification and schedule	£0.00	2.00	Sole Property Owner	09/08/2012	2012
HES97 Electrician	£200.00	8.00	Sole Property Owner	09/08/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	09/08/2012	2012
EES50d 12-15kW Electrical flow boiler	£2,020.00	1.00	Sole Property Owner	01/02/2010	2010
EES07 200mm thick loft insulation	£417.30	30.00	Sole Property Owner	01/02/2010	2010
EES66 Low energy lamp replacement	£19.25	11.00	Sole Property Owner	01/02/2010	2010
EES00a Full Energy Survey	£401.67	1.00	Sole Property Owner	01/02/2010	2010
EES31 Hot water cylinder jacket (58x20 inch)	£81.62	1.00	Sole Property Owner	01/02/2010	2010
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	09/01/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£297.00	99.00	Sole Property Owner	09/01/2012	2012
EES08 300mm thick loft insulation	£1,188.00	99.00	Sole Property Owner	09/01/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	09/01/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	09/01/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	09/01/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Sole Property Owner	09/01/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£154.00	22.00	Sole Property Owner	09/01/2012	2012
EES66 Low energy lamp replacement	£0.00	7.00	Sole Property Owner	09/01/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	09/01/2012	2012

HES120 Standard QA check	£90.00	1.00	Sole Property Owner	09/01/2012	2012
EES15 Insulation to 65mm wide cavity wall	£2,436.00	100.00	Sole Property Owner	19/10/2012	2012
EES66 Low energy lamp replacement	£0.00	22.00	Sole Property Owner	19/10/2012	2012
EES67 Smoke detector installation	£0.00	3.00	Sole Property Owner	19/10/2012	2012
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	19/10/2012	2012
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Sole Property Owner	19/10/2012	2012
HES73 Storage heater rated 3kW - 4kW	£1,250.46	3.00	Sole Property Owner	19/10/2012	2012
HES76 Storage heater miniature circuit breaker	£26.70	5.00	Sole Property Owner	19/10/2012	2012
HES97 Electrician	£425.00	17.00	Sole Property Owner	19/10/2012	2012
EES01a Loft Clearance (hourly rate)	£300.00	12.00	Sole Property Owner	26/01/2012	2012
EES03a Remove and replace nailed floor board	£30.00	10.00	Sole Property Owner	26/01/2012	2012
EES08 300mm thick loft insulation	£1,140.00	95.00	Sole Property Owner	26/01/2012	2012
EES10 Cold water tank insulation quilt	£150.00	3.00	Sole Property Owner	26/01/2012	2012
EES 11 Cold water tank insulation jacket	£225.00	3.00	Sole Property Owner	26/01/2012	2012
EES12 Cold water tank lid	£225.00	3.00	Sole Property Owner	26/01/2012	2012
EES13a Cold water tank bye law kit (including associated product	£150.00	3.00	Sole Property Owner	26/01/2012	2012
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Sole Property Owner	26/01/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£168.00	24.00	Sole Property Owner	26/01/2012	2012
EES66 Low energy lamp replacement	£0.00	8.00	Sole Property Owner	26/01/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	26/01/2012	2012
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	26/01/2012	2012
EES07 200mm thick loft insulation	£702.00	78.00	Sole Property Owner	09/01/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	09/01/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	09/01/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	09/01/2012	2012
EES13a Cold water tank bye law kit (including associated product	£100.00	2.00	Sole Property Owner	09/01/2012	2012
EES25 Draught stripping to exterior door	£10.00	1.00	Sole Property Owner	09/01/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	09/01/2012	2012
EES38a Thermostatic radiator valve (per valve)	£425.00	5.00	Sole Property Owner	09/01/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£70.00	10.00	Sole Property Owner	09/01/2012	2012
EES66 Low energy lamp replacement	£0.00	14.00	Sole Property Owner	09/01/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	09/01/2012	2012
EES69 Miscellaneous Charge	£41.80	1.00	Sole Property Owner	09/01/2012	2012
EES16 Insulation to 75mm wide cavity wall	£749.00	100.00	Sole Property Owner	09/01/2012	2012
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Sole Property Owner	09/01/2012	2012
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Not The Property Owner	19/06/2012	2012
EES02a Remove and dispose existing insulation (per square metre	£0.00	0.00	Not The Property Owner	19/06/2012	2012
EES08 300mm thick loft insulation	£0.00	0.00	Not The Property Owner	19/06/2012	2012
EES10 Cold water tank insulation quilt	£0.00	0.00	Not The Property Owner	19/06/2012	2012
EES 11 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	19/06/2012	2012
EES12 Cold water tank lid	£0.00	0.00	Not The Property Owner	19/06/2012	2012
EES13a Cold water tank bye law kit (including associated product	£0.00	0.00	Not The Property Owner	19/06/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Not The Property Owner	19/06/2012	2012
EES66 Low energy lamp replacement	£0.00	0.00	Not The Property Owner	19/06/2012	2012
EES67 Smoke detector installation	£0.00	0.00	Not The Property Owner	19/06/2012	2012
EES07 200mm thick loft insulation	£360.00	40.00	Not The Property Owner	02/08/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Not The Property Owner	02/08/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Not The Property Owner	02/08/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Not The Property Owner	02/08/2012	2012
EES13a Cold water tank bye law kit (including associated product	£100.00	2.00	Not The Property Owner	02/08/2012	2012
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Not The Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	17.00	Not The Property Owner	02/08/2012	2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	09/01/2012	2012
EES66 Low energy lamp replacement	£0.00	12.00	Sole Property Owner	09/01/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	09/01/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£77.00	11.00	Joint Owner	16/03/2012	2012
EES69 Miscellaneous Charge	£121.00	1.00	Joint Owner	16/03/2012	2012
EES 84 Magnetic filtration unit	£0.00	1.00	Joint Owner	16/03/2012	2012
EES 83 Powerflush central heating system	£0.00	1.00	Joint Owner	16/03/2012	2012
EES51a 16-20kW Oil replacement boiler	£3,450.00	1.00	Joint Owner	16/03/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Joint Owner	16/03/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Joint Owner	16/03/2012	2012
EES82 Boiler replacement miscellaneous works	£2,197.00	1.00	Joint Owner	16/03/2012	2012
EES01a Loft Clearance (hourly rate)	£375.00	15.00	Joint Owner	16/03/2012	2012
EES02a Remove and dispose existing insulation (per square metre	£312.00	104.00	Joint Owner	16/03/2012	2012
EES08 300mm thick loft insulation	£1,248.00	104.00	Joint Owner	16/03/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	16/03/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	16/03/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	16/03/2012	2012
EES13a Cold water tank bye law kit (including associated product	£100.00	2.00	Joint Owner	16/03/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Joint Owner	16/03/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Joint Owner	16/03/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£147.00	21.00	Joint Owner	16/03/2012	2012
EES66 Low energy lamp replacement	£0.00	6.00	Joint Owner	16/03/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	16/03/2012	2012
EES66 Low energy lamp replacement	£0.00	5.00	Sole Property Owner	25/01/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	25/01/2012	2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	25/01/2012	2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Not The Property Owner	09/01/2012	2012
EES66 Low energy lamp replacement	£0.00	5.00	Not The Property Owner	09/01/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Not The Property Owner	09/01/2012	2012
EES66 Low energy lamp replacement	£0.00	1.00	Not The Property Owner	18/03/2011	2011
EES00a Full Energy Survey	£401.68	1.00	Not The Property Owner	18/03/2011	2011
HES89 Explanation of controls, manuals, EIC certification and sch	£0.00	1.00	Joint Owner	27/09/2012	2012

EES07 200mm thick loft insulation	£270.00	30.00	Joint Owner	27/09/2012	2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Joint Owner	27/09/2012	2012
EES66 Low energy lamp replacement	£0.00	15.00	Joint Owner	27/09/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	27/09/2012	2012
HES97 Electrician	£325.00	13.00	Joint Owner	27/09/2012	2012
HES72 Storage heater rated 2kW - 3kW	£684.46	2.00	Joint Owner	27/09/2012	2012
HES76 Storage heater miniature circuit breaker	£21.36	4.00	Joint Owner	27/09/2012	2012
HES120 Standard QA check	£90.00	1.00	Joint Owner	27/09/2012	2012
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Joint Owner	19/10/2012	2012
EES02a Remove and dispose existing insulation (per squire metre)	£129.00	43.00	Joint Owner	19/10/2012	2012
EES08 300mm thick loft insulation	£516.00	43.00	Joint Owner	19/10/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	19/10/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	19/10/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	19/10/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Joint Owner	19/10/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Joint Owner	19/10/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Joint Owner	19/10/2012	2012
EES16 Insulation to 75mm wide cavity wall	£1,220.40	122.04	Joint Owner	19/10/2012	2012
HES120 Standard QA check	£102.00	1.00	Joint Owner	19/10/2012	2012
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Sole Property Owner	27/09/2012	2012
EES02a Remove and dispose existing insulation (per squire metre)	£126.00	42.00	Sole Property Owner	27/09/2012	2012
EES03a Remove and replace nailed floor board	£18.00	6.00	Sole Property Owner	27/09/2012	2012
EES08 300mm thick loft insulation	£504.00	42.00	Sole Property Owner	27/09/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	27/09/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	27/09/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	27/09/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Sole Property Owner	27/09/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£105.00	15.00	Sole Property Owner	27/09/2012	2012
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	27/09/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	27/09/2012	2012
HES97 Electrician	£425.00	17.00	Sole Property Owner	27/09/2012	2012
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Sole Property Owner	27/09/2012	2012
HES75 Storage heater consumer unit	£32.92	1.00	Sole Property Owner	27/09/2012	2012
HES76 Storage heater miniature circuit breaker	£10.68	2.00	Sole Property Owner	27/09/2012	2012
HES80 16mm meter tails	£14.16	3.00	Sole Property Owner	27/09/2012	2012
HES54 Water heating time clock and boost controller	£92.95	1.00	Sole Property Owner	27/09/2012	2012
HES77 Main bonding of necessary services	£6.48	2.00	Sole Property Owner	27/09/2012	2012
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	27/09/2012	2012
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	08/02/2012	2012
EES02a Remove and dispose existing insulation (per squire metre)	£105.00	35.00	Sole Property Owner	08/02/2012	2012
EES03a Remove and replace nailed floor board	£45.00	15.00	Sole Property Owner	08/02/2012	2012
EES08 300mm thick loft insulation	£420.00	35.00	Sole Property Owner	08/02/2012	2012
EES66 Low energy lamp replacement	£0.00	12.00	Sole Property Owner	08/02/2012	2012
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	08/02/2012	2012
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Sole Property Owner	10/11/2011	2011
EES07 200mm thick loft insulation	£0.00	0.00	Sole Property Owner	10/11/2011	2011
EES08 300mm thick loft insulation	£0.00	0.00	Sole Property Owner	10/11/2011	2011
EES10 Cold water tank insulation quilt	£0.00	0.00	Sole Property Owner	10/11/2011	2011
EES 11 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	10/11/2011	2011
EES12 Cold water tank lid	£0.00	0.00	Sole Property Owner	10/11/2011	2011
EES13b Cold water tank bye law kit (excluding associated product)	£0.00	0.00	Sole Property Owner	10/11/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	10/11/2011	2011
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Joint Owner	12/03/2012	2012
EES02a Remove and dispose existing insulation (per squire metre)	£150.00	50.00	Joint Owner	12/03/2012	2012
EES03a Remove and replace nailed floor board	£15.00	5.00	Joint Owner	12/03/2012	2012
EES08 300mm thick loft insulation	£600.00	50.00	Joint Owner	12/03/2012	2012
EES 11 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	12/03/2012	2012
EES12 Cold water tank lid	£0.00	0.00	Joint Owner	12/03/2012	2012
EES10 Cold water tank insulation quilt	£0.00	0.00	Joint Owner	12/03/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£0.00	0.00	Joint Owner	12/03/2012	2012
EES33 Replacement hot water cylinder (150l)	£0.00	0.00	Joint Owner	12/03/2012	2012
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Joint Owner	12/03/2012	2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	08/02/2012	2012
EES02a Remove and dispose existing insulation (per squire metre)	£120.00	40.00	Sole Property Owner	08/02/2012	2012
EES03a Remove and replace nailed floor board	£12.00	4.00	Sole Property Owner	08/02/2012	2012
EES08 300mm thick loft insulation	£480.00	40.00	Sole Property Owner	08/02/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	08/02/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	08/02/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	08/02/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Sole Property Owner	08/02/2012	2012
EES16 Insulation to 75mm wide cavity wall	£0.00	0.00	Sole Property Owner	08/02/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£154.00	22.00	Sole Property Owner	08/02/2012	2012
EES66 Low energy lamp replacement	£0.00	25.00	Sole Property Owner	08/02/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	08/02/2012	2012
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	08/02/2012	2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Sole Property Owner	14/03/2012	2012
EES08 300mm thick loft insulation	£540.00	45.00	Sole Property Owner	14/03/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	14/03/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	14/03/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	14/03/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Sole Property Owner	14/03/2012	2012
EES16 Insulation to 75mm wide cavity wall	£1,053.60	1,053.60	Sole Property Owner	14/03/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	14/03/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£126.00	18.00	Sole Property Owner	14/03/2012	2012

EES66 Low energy lamp replacement	£0.00	25.00	Sole Property Owner	14/03/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	14/03/2012	2012
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	14/03/2012	2012
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Sole Property Owner	19/10/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£135.00	45.00	Sole Property Owner	19/10/2012	2012
EES08 300mm thick loft insulation	£540.00	45.00	Sole Property Owner	19/10/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	19/10/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	19/10/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	19/10/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Sole Property Owner	19/10/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	19/10/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£98.00	14.00	Sole Property Owner	19/10/2012	2012
EES66 Low energy lamp replacement	£0.00	20.00	Sole Property Owner	19/10/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	19/10/2012	2012
HES120 Standard QA check	£102.00	1.00	Sole Property Owner	19/10/2012	2012
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	19/10/2012	2012
EES38a Thermostatic radiator valve (per valve)	£63.69	1.00	Sole Property Owner	26/03/2012	2012
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	26/03/2012	2012
EES49 Pipework lagging 25mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	26/03/2012	2012
EES82 Boiler replacement miscellaneous works	£1,032.55	1.00	Sole Property Owner	26/03/2012	2012
EES40 Hot water cylinder thermostat	£60.18	1.00	Sole Property Owner	26/03/2012	2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	26/03/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£162.00	54.00	Sole Property Owner	26/03/2012	2012
EES08 300mm thick loft insulation	£648.00	54.00	Sole Property Owner	26/03/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	26/03/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	26/03/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	26/03/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Sole Property Owner	26/03/2012	2012
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Sole Property Owner	26/03/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	26/03/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£42.00	6.00	Sole Property Owner	26/03/2012	2012
EES16 Insulation to 75mm wide cavity wall	£709.20	70.92	Sole Property Owner	26/03/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	26/03/2012	2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Joint Owner	05/11/2012	2012
EES03a Remove and replace nailed floor board	£30.00	10.00	Joint Owner	05/11/2012	2012
EES08 300mm thick loft insulation	£1,260.00	105.00	Joint Owner	05/11/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	05/11/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	05/11/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	05/11/2012	2012
EES13a Cold water tank bye law kit (including associated product)	£100.00	2.00	Joint Owner	05/11/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Joint Owner	05/11/2012	2012
EES36 Electrical room thermostat	£0.00	0.00	Joint Owner	05/11/2012	2012
EES42 Two channel programmable heating controller	£0.00	0.00	Joint Owner	05/11/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£273.00	39.00	Joint Owner	05/11/2012	2012
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Joint Owner	05/11/2012	2012
EES66 Low energy lamp replacement	£0.00	19.00	Joint Owner	05/11/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	05/11/2012	2012
HES32 21-25kW Oil replacement condensing boiler	£1,920.00	1.00	Joint Owner	05/11/2012	2012
HES40 Flue specification and location	£318.25	1.00	Joint Owner	05/11/2012	2012
HES41 Condensate pipework (and pump if required)	£150.00	1.00	Joint Owner	05/11/2012	2012
HES45 Fire valve	£48.00	1.00	Joint Owner	05/11/2012	2012
HES46 Automatic bypass	£32.40	1.00	Joint Owner	05/11/2012	2012
HES47 Frost thermostat	£24.00	1.00	Joint Owner	05/11/2012	2012
HES48 Power / system flush and treatment	£480.00	1.00	Joint Owner	05/11/2012	2012
HES50 Electrical room thermostat	£22.80	1.00	Joint Owner	05/11/2012	2012
HES53 Two channel heating programmer control	£78.00	1.00	Joint Owner	05/11/2012	2012
HES55 2 port zone valve	£68.40	1.00	Joint Owner	05/11/2012	2012
HES66 15mm thick pipework lagging	£40.56	12.00	Joint Owner	05/11/2012	2012
HES67 22mm thick pipework lagging	£176.00	40.00	Joint Owner	05/11/2012	2012
HES93 Junior heating engineer	£950.00	38.00	Joint Owner	05/11/2012	2012
HES94 Heating engineer	£1,444.00	38.00	Joint Owner	05/11/2012	2012
HES95 Senior heating engineer	£117.00	3.00	Joint Owner	05/11/2012	2012
HES98 Senior electrician	£390.00	10.00	Joint Owner	05/11/2012	2012
HES99 Building works	£120.00	4.00	Joint Owner	05/11/2012	2012
HES87 Commissioning and issue of CD10 and Building Control notice	£0.00	1.00	Joint Owner	05/11/2012	2012
HES88 Commissioning and issue of CD11 and flue gas analysis	£96.00	1.00	Joint Owner	05/11/2012	2012
HES90 Other miscellaneous oil heating works for EES approval	£378.18	378.18	Joint Owner	05/11/2012	2012
HES49 Carbon Monoxide alarm	£42.00	1.00	Joint Owner	05/11/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	05/11/2012	2012
EES38a Thermostatic radiator valve (per valve)	£510.00	6.00	Joint Owner	05/11/2012	2012
EES69 Miscellaneous Charge	£76.80	1.00	Joint Owner	05/11/2012	2012
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Joint Owner	14/02/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£243.00	81.00	Joint Owner	14/02/2012	2012
EES08 300mm thick loft insulation	£972.00	81.00	Joint Owner	14/02/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	14/02/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	14/02/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	14/02/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Joint Owner	14/02/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Joint Owner	14/02/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£14.00	2.00	Joint Owner	14/02/2012	2012
EES16 Insulation to 75mm wide cavity wall	£0.00	0.00	Joint Owner	14/02/2012	2012
EES66 Low energy lamp replacement	£0.00	14.00	Joint Owner	14/02/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	14/02/2012	2012
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Joint Owner	23/02/2012	2012

EES02a Remove and dispose existing insulation (per square metre)	£144.00	48.00	Joint Owner	23/02/2012	2012
EES03a Remove and replace nailed floor board	£24.00	8.00	Joint Owner	23/02/2012	2012
EES08 300mm thick loft insulation	£576.00	48.00	Joint Owner	23/02/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	23/02/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	23/02/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	23/02/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Joint Owner	23/02/2012	2012
EES25 Draught stripping to exterior door	£60.00	6.00	Joint Owner	23/02/2012	2012
EES38a Thermostatic radiator valve (per valve)	£595.00	7.00	Joint Owner	23/02/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£63.00	9.00	Joint Owner	23/02/2012	2012
EES66 Low energy lamp replacement	£0.00	15.00	Joint Owner	23/02/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	23/02/2012	2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Not The Property Owner	09/01/2012	2012
EES66 Low energy lamp replacement	£0.00	15.00	Not The Property Owner	09/01/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Not The Property Owner	09/01/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulation)	£325.00	13.00	Sole Property Owner	21/12/2012	2012
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner	21/12/2012	2012
HES06 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	21/12/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	21/12/2012	2012
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,276.80	133.00	Sole Property Owner	21/12/2012	2012
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	21/12/2012	2012
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	21/12/2012	2012
HES39 26-35kW Gas replacement condensing boiler	£1,155.00	1.00	Sole Property Owner	21/12/2012	2012
HES40 Flue specification and location	£80.00	1.00	Sole Property Owner	21/12/2012	2012
HES41 Condensate pipework (and pump if required)	£75.00	1.00	Sole Property Owner	21/12/2012	2012
HES44 Pipework / feed modifications	£100.00	1.00	Sole Property Owner	21/12/2012	2012
HES48 Power / system flush and treatment	£25.00	1.00	Sole Property Owner	21/12/2012	2012
HES94 Heating engineer	£840.00	24.00	Sole Property Owner	21/12/2012	2012
HES97 Electrician	£140.00	4.00	Sole Property Owner	21/12/2012	2012
HES88 Commissioning and issue of CD11 and flue gas analysis	£4.50	1.00	Sole Property Owner	21/12/2012	2012
HES55 2 port zone valve	£60.19	1.00	Sole Property Owner	21/12/2012	2012
HES54 Water heating time clock and boost controller	£93.31	1.00	Sole Property Owner	21/12/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	21/12/2012	2012
HES118 Ecological Survey	£185.00	1.00	Sole Property Owner	21/12/2012	2012
HES120 Standard QA check	£102.00	1.00	Sole Property Owner	21/12/2012	2012
EES08 300mm thick loft insulation	£540.00	45.00	Sole Property Owner	08/02/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	08/02/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	08/02/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	08/02/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Sole Property Owner	08/02/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£112.00	16.00	Sole Property Owner	08/02/2012	2012
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	08/02/2012	2012
EES66 Low energy lamp replacement	£0.00	15.00	Sole Property Owner	08/02/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	08/02/2012	2012
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	08/02/2012	2012
EES01a Loft Clearance (hourly rate)	£225.00	9.00	Sole Property Owner	14/02/2012	2012
EES08 300mm thick loft insulation	£600.00	50.00	Sole Property Owner	14/02/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	14/02/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	14/02/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	14/02/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Sole Property Owner	14/02/2012	2012
EES29 Hot water cylinder jacket (30x18 inch)	£90.00	1.00	Sole Property Owner	14/02/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£70.00	10.00	Sole Property Owner	14/02/2012	2012
EES66 Low energy lamp replacement	£0.00	16.00	Sole Property Owner	14/02/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	14/02/2012	2012
HES120 Standard QA check	£102.00	1.00	Sole Property Owner	05/11/2012	2012
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	05/11/2012	2012
EES08 300mm thick loft insulation	£480.00	40.00	Sole Property Owner	05/11/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	05/11/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	05/11/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	05/11/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Sole Property Owner	05/11/2012	2012
EES29 Hot water cylinder jacket (30x18 inch)	£90.00	1.00	Sole Property Owner	05/11/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£84.00	12.00	Sole Property Owner	05/11/2012	2012
EES16 Insulation to 75mm wide cavity wall	£1,171.20	117.12	Sole Property Owner	05/11/2012	2012
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	05/11/2012	2012
HES97 Electrician	£425.00	17.00	Sole Property Owner	05/11/2012	2012
HES70 Storage heater rated < 1kW	£189.46	1.00	Sole Property Owner	05/11/2012	2012
HES72 Storage heater rated 2kW - 3kW	£684.46	2.00	Sole Property Owner	05/11/2012	2012
HES73 Storage heater rated 3kW - 4kW	£416.82	1.00	Sole Property Owner	05/11/2012	2012
HES76 Storage heater miniature circuit breaker	£26.70	5.00	Sole Property Owner	05/11/2012	2012
HES79 Heating point twin and earth mini trunk DP switch	£26.24	4.00	Sole Property Owner	05/11/2012	2012
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Sole Property Owner	27/09/2012	2012
EES08 300mm thick loft insulation	£840.00	70.00	Sole Property Owner	27/09/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	27/09/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	27/09/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	27/09/2012	2012
EES13a Cold water tank bye law kit (including associated product)	£100.00	2.00	Sole Property Owner	27/09/2012	2012
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Sole Property Owner	27/09/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	27/09/2012	2012
EES66 Low energy lamp replacement	£0.00	19.00	Sole Property Owner	27/09/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	27/09/2012	2012
EES03a Remove and replace nailed floor board	£135.00	45.00	Sole Property Owner	27/09/2012	2012
EES77 HEC to House	£150.00	1.00	Joint Owner	06/01/2012	2012

EES 84 Magnetic filtration unit	£0.00	1.00	Sole Property Owner	26/03/2012	2012
EES 83 Powerflush central heating system	£0.00	1.00	Sole Property Owner	26/03/2012	2012
EES51a 16-20kW Oil replacement boiler	£3,450.00	1.00	Sole Property Owner	26/03/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	26/03/2012	2012
EES38a Thermostatic radiator valve (per valve)	£680.00	8.00	Sole Property Owner	26/03/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	26/03/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	26/03/2012	2012
EES34 Replacement hot water cylinder (170l)	£1,240.00	1.00	Sole Property Owner	26/03/2012	2012
EES49 Pipework lagging 25mm thick to 22mm pipe	£550.00	50.00	Sole Property Owner	26/03/2012	2012
EES82 Boiler replacement miscellaneous works	£2,283.40	1.00	Sole Property Owner	26/03/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£105.00	15.00	Sole Property Owner	26/03/2012	2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Sole Property Owner	26/03/2012	2012
EES02a Remove and dispose existing insulation (per squire metre)	£270.00	90.00	Sole Property Owner	26/03/2012	2012
EES03a Remove and replace nailed floor board	£45.00	15.00	Sole Property Owner	26/03/2012	2012
EES08 300mm thick loft insulation	£960.00	80.00	Sole Property Owner	26/03/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	26/03/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	26/03/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	26/03/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£100.00	2.00	Sole Property Owner	26/03/2012	2012
EES25 Draught stripping to exterior door	£60.00	6.00	Sole Property Owner	26/03/2012	2012
EES16 Insulation to 75mm wide cavity wall	£0.00	0.00	Sole Property Owner	26/03/2012	2012
EES06 100mm thick loft insulation	£65.40	10.00	Sole Property Owner	26/03/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	26/03/2012	2012
EES68 Minimum charge for lamps and detectors	£100.00	1.00	Sole Property Owner	03/08/2010	2010
EES25 Draught stripping to exterior door	£0.00	5.00	Sole Property Owner	03/08/2010	2010
HES21 Smoke detector installation	£0.00		Sole Property Owner	03/08/2010	2010
HES22 Minimum per property charge	£0.00		Sole Property Owner	03/08/2010	2010
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Not The Property Owner	14/02/2012	2012
EES02a Remove and dispose existing insulation (per squire metre)	£45.00	15.00	Not The Property Owner	14/02/2012	2012
EES08 300mm thick loft insulation	£180.00	15.00	Not The Property Owner	14/02/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Not The Property Owner	14/02/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Not The Property Owner	14/02/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Not The Property Owner	14/02/2012	2012
EES13a Cold water tank bye law kit (including associated product)	£50.00	1.00	Not The Property Owner	14/02/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Not The Property Owner	14/02/2012	2012
EES66 Low energy lamp replacement	£0.00	5.00	Not The Property Owner	14/02/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Not The Property Owner	14/02/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012	2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	27/02/2012	2012
EES02a Remove and dispose existing insulation (per squire metre)	£147.00	49.00	Sole Property Owner	27/02/2012	2012
EES03a Remove and replace nailed floor board	£30.00	10.00	Sole Property Owner	27/02/2012	2012
EES08 300mm thick loft insulation	£588.00	49.00	Sole Property Owner	27/02/2012	2012
EES16 Insulation to 75mm wide cavity wall	£0.00	0.00	Sole Property Owner	27/02/2012	2012
EES66 Low energy lamp replacement	£0.00	30.00	Sole Property Owner	27/02/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	27/02/2012	2012
HES101 Asbestos removal & disposal	£100.00	1.00	Sole Property Owner	27/02/2012	2012
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	27/02/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	12/10/2012	2012
EES25 Draught stripping to exterior door	£0.00	0.00	Not The Property Owner	12/10/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	12/10/2012	2012
EES75 HEC to Flat or Bedsit	£0.00	0.00	Not The Property Owner	01/03/2012	2012
EES78 Home Energy Assessor hourly rate	£60.00	1.00	Not The Property Owner	01/03/2012	2012
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	14/02/2012	2012
EES27 Draught stripping to letterbox	£40.00	1.00	Not The Property Owner	14/02/2012	2012
EES66 Low energy lamp replacement	£0.00	10.00	Not The Property Owner	14/02/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Not The Property Owner	14/02/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	11/08/2011	2011
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	11/08/2011	2011
EES07 200mm thick loft insulation	£405.00	45.00	Joint Owner	20/03/2012	2012
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Joint Owner	20/03/2012	2012
EES02a Remove and dispose existing insulation (per squire metre)	£126.00	42.00	Joint Owner	20/03/2012	2012
EES03a Remove and replace nailed floor board	£30.00	10.00	Joint Owner	20/03/2012	2012
EES06 100mm thick loft insulation	£0.00	0.00	Joint Owner	20/03/2012	2012
EES08 300mm thick loft insulation	£0.00	0.00	Joint Owner	20/03/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	20/03/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	20/03/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	20/03/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£100.00	2.00	Joint Owner	20/03/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Joint Owner	20/03/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£98.00	14.00	Joint Owner	20/03/2012	2012
EES66 Low energy lamp replacement	£0.00	24.00	Joint Owner	20/03/2012	2012
EES67 Smoke detector installation	£0.00	3.00	Joint Owner	20/03/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	06/09/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/09/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Not The Property Owner	06/01/2012	2012
EES78 Home Energy Assessor hourly rate	£60.00	1.00	Not The Property Owner	06/01/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	06/01/2012	2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Not The Property Owner	09/01/2012	2012
EES66 Low energy lamp replacement	£0.00	4.00	Not The Property Owner	09/01/2012	2012
EES77 HEC to House	£150.00	1.00	Not The Property Owner	06/01/2012	2012

EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	10/08/2012	2012
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	10/08/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	10/08/2012	2012
EES25 Draught stripping to exterior door	£0.00	0.00	Not The Property Owner	03/02/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Not The Property Owner	03/02/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£56.00	8.00	Not The Property Owner	03/02/2012	2012
HES22 Minimum per property charge	£50.00	1.00	Not The Property Owner	03/02/2012	2012
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Joint Owner	02/08/2012	2012
EES07 200mm thick loft insulation	£441.00	49.00	Joint Owner	02/08/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	02/08/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	02/08/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	02/08/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Joint Owner	02/08/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Joint Owner	02/08/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Joint Owner	02/08/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Joint Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£14.00	2.00	Joint Owner	02/08/2012	2012
EES16 Insulation to 75mm wide cavity wall	£1,440.00	144.00	Joint Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	16.00	Joint Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	02/08/2012	2012
EES33 Replacement hot water cylinder (150l)	£625.80	1.00	Sole Property Owner	12/03/2010	2010
EES25 Draught stripping to exterior door	£42.48	1.00	Sole Property Owner	12/03/2010	2010
EES27 Draught stripping to letterbox	£17.91	1.00	Sole Property Owner	12/03/2010	2010
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	12/03/2010	2010
EES08 300mm thick loft insulation	£99.96	8.33	Sole Property Owner	17/04/2012	2012
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Sole Property Owner	17/04/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£330.00	110.00	Sole Property Owner	17/04/2012	2012
EES03a Remove and replace nailed floor board	£45.00	15.00	Sole Property Owner	17/04/2012	2012
EES08 300mm thick loft insulation	£1,380.00	115.00	Sole Property Owner	17/04/2012	2012
EES10 Cold water tank insulation quilt	£0.00	0.00	Sole Property Owner	17/04/2012	2012
EES 11 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	17/04/2012	2012
EES12 Cold water tank lid	£0.00	0.00	Sole Property Owner	17/04/2012	2012
EES13a Cold water tank bye law kit (including associated product)	£0.00	0.00	Sole Property Owner	17/04/2012	2012
EES33 Replacement hot water cylinder (150l)	£0.00	0.00	Sole Property Owner	17/04/2012	2012
EES36 Electrical room thermostat	£0.00	0.00	Sole Property Owner	17/04/2012	2012
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Sole Property Owner	17/04/2012	2012
EES40 Hot water cylinder thermostat	£0.00	0.00	Sole Property Owner	17/04/2012	2012
EES42 Two channel programmable heating controller	£0.00	0.00	Sole Property Owner	17/04/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	17/04/2012	2012
EES66 Low energy lamp replacement	£0.00	11.00	Sole Property Owner	17/04/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	17/04/2012	2012
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	17/04/2012	2012
EES51a 16-20kW Oil replacement boiler	£3,432.00	1.00	Sole Property Owner	17/04/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	17/04/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	17/04/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	17/04/2012	2012
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Sole Property Owner	17/04/2012	2012
EES34 Replacement hot water cylinder (170l)	£1,560.00	1.00	Sole Property Owner	17/04/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£80.00	10.00	Sole Property Owner	17/04/2012	2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£81.12	10.14	Sole Property Owner	17/04/2012	2012
EES70 Miscellaneous heating review charge	£2,061.28	2,061.28	Sole Property Owner	17/04/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	17/04/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	19/04/2013	2013
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	19/04/2013	2013
EES25 Draught stripping to exterior door	£70.00	7.00	Sole Property Owner	14/02/2012	2012
EES27 Draught stripping to letterbox	£40.00	1.00	Sole Property Owner	14/02/2012	2012
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Sole Property Owner	14/02/2012	2012
EES66 Low energy lamp replacement	£0.00	15.00	Sole Property Owner	14/02/2012	2012
EES67 Smoke detector installation	£0.00	3.00	Sole Property Owner	14/02/2012	2012
EES77 HEC to House	£150.00	1.00	Not The Property Owner	10/08/2012	2012
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	10/08/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	10/08/2012	2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	27/09/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£162.00	54.00	Sole Property Owner	27/09/2012	2012
EES03a Remove and replace nailed floor board	£18.00	6.00	Sole Property Owner	27/09/2012	2012
EES08 300mm thick loft insulation	£648.00	54.00	Sole Property Owner	27/09/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	27/09/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	27/09/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	27/09/2012	2012
EES13a Cold water tank bye law kit (including associated product)	£100.00	2.00	Sole Property Owner	27/09/2012	2012
EES25 Draught stripping to exterior door	£0.00	0.00	Sole Property Owner	27/09/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	27/09/2012	2012
EES36 Electrical room thermostat	£0.00	0.00	Sole Property Owner	27/09/2012	2012
EES38a Thermostatic radiator valve (per valve)	£680.00	8.00	Sole Property Owner	27/09/2012	2012
EES42 Two channel programmable heating controller	£0.00	0.00	Sole Property Owner	27/09/2012	2012
EES44 Water heating time clock and boost	£0.00	0.00	Sole Property Owner	27/09/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£49.00	7.00	Sole Property Owner	27/09/2012	2012
EES66 Low energy lamp replacement	£0.00	18.00	Sole Property Owner	27/09/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	27/09/2012	2012
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	27/09/2012	2012
EES69 Miscellaneous Charge	£70.00	1.00	Sole Property Owner	27/09/2012	2012

EES69 Miscellaneous Charge	£120.00	1.00	Sole Property Owner	27/09/2012	2012
HES120 Standard QA check	£102.00	1.00	Sole Property Owner	27/09/2012	2012
EES77 HEC to House	£150.00	1.00	Not The Property Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012	2012
EES01a Loft Clearance (hourly rate)	£187.20	8.00	Sole Property Owner	12/02/2010	2010
EES08 300mm thick loft insulation	£481.12	62.00	Sole Property Owner	12/02/2010	2010
EES66 Low energy lamp replacement	£181.92	16.00	Sole Property Owner	12/02/2010	2010
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	12/02/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	12/02/2010	2010
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	12/02/2010	2010
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Not The Property Owner	12/03/2012	2012
EES08 300mm thick loft insulation	£420.00	35.00	Not The Property Owner	12/03/2012	2012
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	12/03/2012	2012
EES27 Draught stripping to letterbox	£0.00	0.00	Not The Property Owner	12/03/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£35.00	5.00	Not The Property Owner	12/03/2012	2012
EES66 Low energy lamp replacement	£0.00	20.00	Not The Property Owner	12/03/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Not The Property Owner	12/03/2012	2012
EES07 200mm thick loft insulation	£405.00	45.00	Sole Property Owner	14/02/2012	2012
EES66 Low energy lamp replacement	£0.00	15.00	Sole Property Owner	14/02/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	14/02/2012	2012
EES15 Insulation to 65mm wide cavity wall	£1,428.00	142.80	Sole Property Owner	14/02/2012	2012
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Sole Property Owner	14/02/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	06/01/2012	2012
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Joint Owner	02/08/2012	2012
EES08 300mm thick loft insulation	£684.00	57.00	Joint Owner	02/08/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	02/08/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	02/08/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	02/08/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Joint Owner	02/08/2012	2012
EES27 Draught stripping to letterbox	£40.00	1.00	Joint Owner	02/08/2012	2012
EES35 Replacement hot water cylinder (210l)	£1,450.00	1.00	Joint Owner	02/08/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Joint Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£70.00	10.00	Joint Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	21.00	Joint Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	02/08/2012	2012
EES82 Boiler replacement miscellaneous works	£975.00	975.00	Joint Owner	02/08/2012	2012
EES15 Insulation to 65mm wide cavity wall	£1,664.40	1,664.40	Sole Property Owner	27/09/2012	2012
EES66 Low energy lamp replacement	£0.00	20.00	Sole Property Owner	27/09/2012	2012
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	27/09/2012	2012
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Sole Property Owner	27/09/2012	2012
HES73 Storage heater rated 3kW - 4kW	£416.82	1.00	Sole Property Owner	27/09/2012	2012
HES76 Storage heater miniature circuit breaker	£10.68	2.00	Sole Property Owner	27/09/2012	2012
HES97 Electrician	£325.00	13.00	Sole Property Owner	27/09/2012	2012
HES79 Heating point twin and earth mini trunk DP switch	£0.00	1.00	Sole Property Owner	27/09/2012	2012
EES66 Low energy lamp replacement	£0.00	23.00	Sole Property Owner	27/09/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	27/09/2012	2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	27/09/2012	2012
HES71 Storage heater rated 1kW - 2kW	£267.32	1.00	Sole Property Owner	27/09/2012	2012
HES72 Storage heater rated 2kW - 3kW	£684.46	2.00	Sole Property Owner	27/09/2012	2012
HES75 Storage heater consumer unit	£32.92	1.00	Sole Property Owner	27/09/2012	2012
HES76 Storage heater miniature circuit breaker	£21.36	4.00	Sole Property Owner	27/09/2012	2012
HES89 Explanation of controls, manuals, EIC certification and schedule	£0.00	1.00	Sole Property Owner	27/09/2012	2012
HES97 Electrician	£525.00	21.00	Sole Property Owner	27/09/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012	2012
EES25 Draught stripping to exterior door	£50.00	5.00	Sole Property Owner	27/09/2012	2012
EES66 Low energy lamp replacement	£0.00	45.00	Sole Property Owner	27/09/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	27/09/2012	2012
HES71 Storage heater rated 1kW - 2kW	£267.32	1.00	Sole Property Owner	27/09/2012	2012
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Sole Property Owner	27/09/2012	2012
HES73 Storage heater rated 3kW - 4kW	£833.64	2.00	Sole Property Owner	27/09/2012	2012
HES75 Storage heater consumer unit	£32.92	1.00	Sole Property Owner	27/09/2012	2012
HES76 Storage heater miniature circuit breaker	£21.36	4.00	Sole Property Owner	27/09/2012	2012
HES77 Main bonding of necessary services	£6.48	2.00	Sole Property Owner	27/09/2012	2012
HES79 Heating point twin and earth mini trunk DP switch	£26.24	4.00	Sole Property Owner	27/09/2012	2012
HES80 16mm meter tails	£18.88	4.00	Sole Property Owner	27/09/2012	2012
HES89 Explanation of controls, manuals, EIC certification and schedule	£0.00	1.00	Sole Property Owner	27/09/2012	2012
HES97 Electrician	£650.00	26.00	Sole Property Owner	27/09/2012	2012
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Not The Property Owner	02/08/2012	2012
EES03a Remove and replace nailed floor board	£48.00	16.00	Not The Property Owner	02/08/2012	2012
EES07 200mm thick loft insulation	£180.00	20.00	Not The Property Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Not The Property Owner	02/08/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	02/08/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Not The Property Owner	02/08/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Not The Property Owner	02/08/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Not The Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	0.00	Not The Property Owner	12/03/2010	2010
EES00a Full Energy Survey	£401.68	1.00	Not The Property Owner	12/03/2010	2010
EES29 Hot water cylinder jacket (30x18 inch)	£90.00	1.00	Sole Property Owner	02/08/2012	2012
EES34 Replacement hot water cylinder (170l)	£1,240.00	1.00	Sole Property Owner	02/08/2012	2012
EES01a Loft Clearance (hourly rate)	£350.00	14.00	Sole Property Owner	02/08/2012	2012
EES03a Remove and replace nailed floor board	£33.00	11.00	Sole Property Owner	02/08/2012	2012

EES08 300mm thick loft insulation	£1,224.00	102.00	Sole Property Owner	02/08/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	02/08/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	02/08/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	02/08/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	02/08/2012	2012
EES33 Replacement hot water cylinder (150L)	£0.00	0.00	Sole Property Owner	02/08/2012	2012
EES38a Thermostatic radiator valve (per valve)	£510.00	6.00	Sole Property Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	02/08/2012	2012
EES15 Insulation to 65mm wide cavity wall	£1,750.00	1,750.00	Sole Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	20.00	Sole Property Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	02/08/2012	2012
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	02/08/2012	2012
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	02/08/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulation)	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES15 Draught stripping to exterior door	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES17 Draught stripping to letter boxes	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES19 Draught proofing labour	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES20 Low energy lamp installation	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES94 Heating engineer	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES97 Electrician	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES51 Thermostatic radiator valve	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES52 Hot water cylinder thermostat	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES120 Standard QA check	£102.00	1.00	Joint Owner	05/11/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	05/11/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	05/11/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	05/11/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Joint Owner	05/11/2012	2012
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Joint Owner	05/11/2012	2012
EES03a Remove and replace nailed floor board	£0.00	0.00	Joint Owner	05/11/2012	2012
EES07 200mm thick loft insulation	£315.00	35.00	Joint Owner	05/11/2012	2012
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Joint Owner	05/11/2012	2012
EES66 Low energy lamp replacement	£0.00	12.00	Joint Owner	05/11/2012	2012
HES71 Storage heater rated 1kW - 2kW	£733.59	3.00	Joint Owner	05/11/2012	2012
HES72 Storage heater rated 2kW - 3kW	£308.49	1.00	Joint Owner	05/11/2012	2012
HES97 Electrician	£336.00	10.50	Joint Owner	05/11/2012	2012
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	03/01/2013	2013
HES97 Electrician	£425.00	17.00	Sole Property Owner	03/01/2013	2013
HES72 Storage heater rated 2kW - 3kW	£684.46	2.00	Sole Property Owner	03/01/2013	2013
HES73 Storage heater rated 3kW - 4kW	£416.82	1.00	Sole Property Owner	03/01/2013	2013
HES76 Storage heater miniature circuit breaker	£16.02	3.00	Sole Property Owner	03/01/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£19.68	3.00	Sole Property Owner	03/01/2013	2013
HES89 Explanation of controls, manuals, EIC certification and schedule of works	£0.00	0.00	Sole Property Owner	03/01/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£556.80	58.00	Sole Property Owner	03/01/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	03/01/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulation)	£100.00	4.00	Sole Property Owner	03/01/2013	2013
HES04 300mm thick loft insulation quilt	£337.50	27.00	Sole Property Owner	03/01/2013	2013
HES06 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	03/01/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	03/01/2013	2013
HES10 CIGA approved cavity wall insulation to 65mm wide cavity	£0.00	0.00	Sole Property Owner	03/01/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	03/01/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner	03/01/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	03/01/2013	2013
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	03/01/2013	2013
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	03/01/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	03/01/2013	2013
HES67 22mm thick pipework lagging	£33.76	8.00	Sole Property Owner	03/01/2013	2013
HES94 Heating engineer	£55.20	1.50	Sole Property Owner	03/01/2013	2013
EES34 Replacement hot water cylinder (170L)	£1,240.00	1.00	Sole Property Owner	16/03/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	16/03/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	16/03/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	16/03/2012	2012
EES 84 Magnetic filtration unit	£0.00	1.00	Sole Property Owner	16/03/2012	2012
EES51a 16-20kW Oil replacement boiler	£3,450.00	1.00	Sole Property Owner	16/03/2012	2012
EES 83 Powerflush central heating system	£0.00	1.00	Sole Property Owner	16/03/2012	2012
EES82 Boiler replacement miscellaneous works	£2,651.00	1.00	Sole Property Owner	16/03/2012	2012
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Sole Property Owner	16/03/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£120.00	40.00	Sole Property Owner	16/03/2012	2012
EES08 300mm thick loft insulation	£480.00	40.00	Sole Property Owner	16/03/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	16/03/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	16/03/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	16/03/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Sole Property Owner	16/03/2012	2012
EES25 Draught stripping to exterior door	£60.00	6.00	Sole Property Owner	16/03/2012	2012
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Sole Property Owner	16/03/2012	2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£288.00	32.00	Sole Property Owner	16/03/2012	2012
EES66 Low energy lamp replacement	£0.00	13.00	Sole Property Owner	16/03/2012	2012
EES67 Smoke detector installation	£0.00	3.00	Sole Property Owner	16/03/2012	2012
EES15 Insulation to 65mm wide cavity wall	£951.60	95.16	Sole Property Owner	16/03/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	16/03/2012	2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Joint Owner	27/09/2012	2012

EES02a Remove and dispose existing insulation (per square metre)	£0.00	0.00	Joint Owner	27/09/2012	2012
EES08 300mm thick loft insulation	£456.00	38.00	Joint Owner	27/09/2012	2012
EES38a Thermostatic radiator valve (per valve)	£510.00	6.00	Joint Owner	27/09/2012	2012
EES66 Low energy lamp replacement	£0.00	8.00	Joint Owner	27/09/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	27/09/2012	2012
EES69 Miscellaneous Charge	£420.00	1.00	Joint Owner	27/09/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	23/10/2012	2012
HES71 Storage heater rated 1kW - 2kW	£244.53	1.00	Sole Property Owner	23/10/2012	2012
HES72 Storage heater rated 2kW - 3kW	£308.49	1.00	Sole Property Owner	23/10/2012	2012
HES97 Electrician	£256.00	8.00	Sole Property Owner	23/10/2012	2012
HES94 Heating engineer	£256.00	8.00	Sole Property Owner	23/10/2012	2012
HES92 Other miscellaneous electrical heating works for EES app	£121.63	1.00	Sole Property Owner	23/10/2012	2012
HES63 Stainless steel replacement hot water cylinder (150L)	£231.60	1.00	Sole Property Owner	23/10/2012	2012
HES92 Other miscellaneous electrical heating works for EES app	£481.81	1.00	Sole Property Owner	23/10/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	23/10/2012	2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	02/08/2012	2012
EES03a Remove and replace nailed floor board	£15.00	5.00	Sole Property Owner	02/08/2012	2012
EES07 200mm thick loft insulation	£540.00	60.00	Sole Property Owner	02/08/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	02/08/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	02/08/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	02/08/2012	2012
EES13a Cold water tank bye law kit (including associated product	£100.00	2.00	Sole Property Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£266.00	38.00	Sole Property Owner	02/08/2012	2012
EES15 Insulation to 65mm wide cavity wall	£900.00	900.00	Sole Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	18.00	Sole Property Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	02/08/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	06/01/2012	2012
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Sole Property Owner	23/10/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£192.00	64.00	Sole Property Owner	23/10/2012	2012
EES08 300mm thick loft insulation	£768.00	64.00	Sole Property Owner	23/10/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	23/10/2012	2012
HES71 Storage heater rated 1kW - 2kW	£244.53	1.00	Sole Property Owner	23/10/2012	2012
HES72 Storage heater rated 2kW - 3kW	£308.49	1.00	Sole Property Owner	23/10/2012	2012
HES97 Electrician	£192.00	6.00	Sole Property Owner	23/10/2012	2012
HES92 Other miscellaneous electrical heating works for EES app	£121.63	1.00	Sole Property Owner	23/10/2012	2012
EES66 Low energy lamp replacement	£0.00	2.00	Sole Property Owner	23/10/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	23/10/2012	2012
EES67 Smoke detector installation	£9.80	1.00	Sole Property Owner	12/03/2010	2010
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	12/03/2010	2010
EES25 Draught stripping to exterior door	£67.98	7.47	Sole Property Owner	12/03/2010	2010
EES08 300mm thick loft insulation	£291.20	40.00	Sole Property Owner	12/03/2010	2010
EES22 Mastic pointing	£276.00	150.00	Sole Property Owner	12/03/2010	2010
EES25 Draught stripping to exterior door	£36.80	20.00	Sole Property Owner	12/03/2010	2010
EES26 Draught stripping to windows	£138.75	75.00	Sole Property Owner	12/03/2010	2010
EES27 Draught stripping to letterbox	£17.91	1.00	Sole Property Owner	12/03/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£12.60	3.00	Sole Property Owner	12/03/2010	2010
EES66 Low energy lamp replacement	£59.09	19.00	Sole Property Owner	12/03/2010	2010
EES67 Smoke detector installation	£14.56	2.00	Sole Property Owner	12/03/2010	2010
EES25 Draught stripping to exterior door	£127.47	3.00	Sole Property Owner	12/03/2010	2010
EES26 Draught stripping to windows	£203.00	35.00	Sole Property Owner	12/03/2010	2010
EES27 Draught stripping to letterbox	£18.18	1.00	Sole Property Owner	12/03/2010	2010
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	12/03/2010	2010
EES07 200mm thick loft insulation	£225.00	25.00	Not The Property Owner	27/09/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Not The Property Owner	27/09/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Not The Property Owner	27/09/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Not The Property Owner	27/09/2012	2012
EES13a Cold water tank bye law kit (including associated product	£100.00	2.00	Not The Property Owner	27/09/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£28.00	4.00	Not The Property Owner	27/09/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	27/09/2012	2012
HES120 Standard QA check	£102.00	1.00	Not The Property Owner	27/09/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	27/09/2012	2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Joint Owner	02/08/2012	2012
EES07 200mm thick loft insulation	£405.00	45.00	Joint Owner	02/08/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	02/08/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	02/08/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	02/08/2012	2012
EES13a Cold water tank bye law kit (including associated product	£50.00	1.00	Joint Owner	02/08/2012	2012
EES29 Hot water cylinder jacket (30x18 inch)	£0.00	0.00	Joint Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£7.00	1.00	Joint Owner	02/08/2012	2012
EES15 Insulation to 65mm wide cavity wall	£1,357.20	1,357.20	Joint Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	10.00	Joint Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	23/10/2012	2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Sole Property Owner	23/10/2012	2012
EES03a Remove and replace nailed floor board	£27.00	9.00	Sole Property Owner	23/10/2012	2012
EES08 300mm thick loft insulation	£648.00	54.00	Sole Property Owner	23/10/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	23/10/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	23/10/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	23/10/2012	2012
EES13a Cold water tank bye law kit (including associated product	£50.00	1.00	Sole Property Owner	23/10/2012	2012
EES66 Low energy lamp replacement	£0.00	28.00	Sole Property Owner	23/10/2012	2012
EES15 Insulation to 65mm wide cavity wall	£1,327.20	1,327.20	Sole Property Owner	23/10/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£98.00	14.00	Sole Property Owner	23/10/2012	2012

HES72 Storage heater rated 2kW - 3kW	£308.49	1.00	Sole Property Owner	23/10/2012	2012
HES73 Storage heater rated 3kW - 4kW	£750.68	2.00	Sole Property Owner	23/10/2012	2012
HES97 Electrician	£288.00	9.00	Sole Property Owner	23/10/2012	2012
EES34 Replacement hot water cylinder (170l)	£953.16	1.00	Sole Property Owner	27/03/2012	2012
EES38a Thermostatic radiator valve (per valve)	£61.60	1.00	Sole Property Owner	27/03/2012	2012
EES40 Hot water cylinder thermostat	£63.69	1.00	Sole Property Owner	27/03/2012	2012
EES42 Two channel programmable heating controller	£139.50	1.00	Sole Property Owner	27/03/2012	2012
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	27/03/2012	2012
EES49 Pipework lagging 25mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	27/03/2012	2012
EES82 Boiler replacement miscellaneous works	£2,376.90	1.00	Sole Property Owner	27/03/2012	2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	27/03/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£360.00	120.00	Sole Property Owner	27/03/2012	2012
EES08 300mm thick loft insulation	£1,440.00	120.00	Sole Property Owner	27/03/2012	2012
EES33 Replacement hot water cylinder (150l)	£0.00	0.00	Sole Property Owner	27/03/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	27/03/2012	2012
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	27/03/2012	2012
EES66 Low energy lamp replacement	£0.00	20.00	Sole Property Owner	27/03/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	27/03/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	27/03/2012	2012
EES69 Miscellaneous Charge	£166.80	1.00	Sole Property Owner	02/08/2012	2012
EES01a Loft Clearance (hourly rate)	£175.00	7.00	Sole Property Owner	02/08/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£72.00	24.00	Sole Property Owner	02/08/2012	2012
EES08 300mm thick loft insulation	£288.00	24.00	Sole Property Owner	02/08/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	02/08/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	02/08/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	02/08/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	02/08/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	02/08/2012	2012
EES38a Thermostatic radiator valve (per valve)	£510.00	6.00	Sole Property Owner	02/08/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	02/08/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	02/08/2012	2012
EES44 Water heating time clock and boost	£130.00	1.00	Sole Property Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£252.00	36.00	Sole Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	5.00	Sole Property Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	02/08/2012	2012
EES01a Loft Clearance (hourly rate)	£450.00	18.00	Joint Owner	27/12/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£255.00	85.00	Joint Owner	27/12/2012	2012
EES03a Remove and replace nailed floor board	£30.00	10.00	Joint Owner	27/12/2012	2012
EES08 300mm thick loft insulation	£1,020.00	85.00	Joint Owner	27/12/2012	2012
HES120 Standard QA check	£102.00	1.00	Joint Owner	27/12/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	27/12/2012	2012
HES72 Storage heater rated 2kW - 3kW	£925.47	3.00	Joint Owner	27/12/2012	2012
HES77 Main bonding of necessary services	£54.50	5.00	Joint Owner	27/12/2012	2012
HES79 Heating point twin and earth mini trunk DP switch	£152.84	1.00	Joint Owner	27/12/2012	2012
HES80 16mm meter tails	£24.96	2.00	Joint Owner	27/12/2012	2012
HES97 Electrician	£512.00	16.00	Joint Owner	27/12/2012	2012
HES92 Other miscellaneous electrical heating works for EES approval	£57.68	1.00	Joint Owner	27/12/2012	2012
HES92 Other miscellaneous electrical heating works for EES approval	£121.63	1.00	Joint Owner	27/12/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	27/12/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	27/12/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	27/12/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£210.00	30.00	Joint Owner	27/12/2012	2012
EES66 Low energy lamp replacement	£0.00	10.00	Joint Owner	27/12/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Joint Owner	27/12/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	27/12/2012	2012
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Sole Property Owner	19/10/2012	2012
EES08 300mm thick loft insulation	£144.00	12.00	Sole Property Owner	19/10/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	19/10/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	19/10/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	19/10/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	19/10/2012	2012
EES25 Draught stripping to exterior door	£0.00	0.00	Sole Property Owner	19/10/2012	2012
EES42 Two channel programmable heating controller	£0.00	0.00	Sole Property Owner	19/10/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£133.00	19.00	Sole Property Owner	19/10/2012	2012
EES66 Low energy lamp replacement	£0.00	12.00	Sole Property Owner	19/10/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	19/10/2012	2012
EES38a Thermostatic radiator valve (per valve)	£680.00	8.00	Sole Property Owner	19/10/2012	2012
EES38a Thermostatic radiator valve (per valve)	£63.69	1.00	Sole Property Owner	19/10/2012	2012
EES40 Hot water cylinder thermostat	£60.19	1.00	Sole Property Owner	19/10/2012	2012
EES42 Two channel programmable heating controller	£139.59	1.00	Sole Property Owner	19/10/2012	2012
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	19/10/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	1.00	Sole Property Owner	19/10/2012	2012
EES70 Miscellaneous heating review charge	£1,762.68	1.00	Sole Property Owner	19/10/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	19/10/2012	2012
EES 83 Powerflush central heating system	£0.00	1.00	Joint Owner	02/08/2012	2012
EES52a 21-25kW Oil replacement boiler	£3,633.00	1.00	Joint Owner	02/08/2012	2012
EES 84 Magnetic filtration unit	£0.00	1.00	Joint Owner	02/08/2012	2012
EES82 Boiler replacement miscellaneous works	£2,551.00	1.00	Joint Owner	02/08/2012	2012
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Joint Owner	02/08/2012	2012
EES07 200mm thick loft insulation	£630.00	70.00	Joint Owner	02/08/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	02/08/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	02/08/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	02/08/2012	2012
EES13b Cold water tank bye law kit (excluding associated products)	£100.00	2.00	Joint Owner	02/08/2012	2012

EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Joint Owner	02/08/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Joint Owner	02/08/2012	2012
EES38a Thermostatic radiator valve (per valve)	£510.00	6.00	Joint Owner	02/08/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Joint Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£252.00	36.00	Joint Owner	02/08/2012	2012
EES16 Insulation to 75mm wide cavity wall	£914.40	91.44	Joint Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	20.00	Joint Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Joint Owner	02/08/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	02/08/2012	2012
HES13 Miscellaneous items (brush, airbrick, vent etc), please pro	£80.10	1.00	Joint Owner	27/09/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatic	£425.00	17.00	Joint Owner	27/09/2012	2012
HES04 300mm thick loft insulation quilt	£625.00	50.00	Joint Owner	27/09/2012	2012
HES06 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	27/09/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Joint Owner	27/09/2012	2012
HES10 CIGA approved cavity wall insulation to 65mm wide cavity	£960.00	100.00	Joint Owner	27/09/2012	2012
HES20 Low energy lamp installation	£0.00	6.00	Joint Owner	27/09/2012	2012
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	27/09/2012	2012
EES50c Replacement electrical storage heater	£411.00	1.00	Joint Owner	27/09/2012	2012
EES50c Replacement electrical storage heater	£475.00	1.00	Joint Owner	27/09/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatic	£150.00	6.00	Joint Owner	29/11/2012	2012
HES04 300mm thick loft insulation quilt	£187.50	15.00	Joint Owner	29/11/2012	2012
HES06 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	29/11/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	29/11/2012	2012
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£192.00	20.00	Joint Owner	29/11/2012	2012
HES20 Low energy lamp installation	£0.00	15.00	Joint Owner	29/11/2012	2012
HES21 Smoke detector installation	£0.00	3.00	Joint Owner	29/11/2012	2012
EES35 Replacement hot water cylinder (210l)	£1,082.00	1.00	Joint Owner	29/11/2012	2012
EES36 Electrical room thermostat	£61.60	1.00	Joint Owner	29/11/2012	2012
EES42 Two channel programmable heating controller	£139.50	1.00	Joint Owner	29/11/2012	2012
EES54a 36-45kW Oil replacement boiler	£2,938.00	1.00	Joint Owner	29/11/2012	2012
EES49 Pipework lagging 25mm thick to 22mm pipe	£200.00	20.00	Joint Owner	29/11/2012	2012
EES82 Boiler replacement miscellaneous works	£1,408.05	1.00	Joint Owner	29/11/2012	2012
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	29/11/2012	2012
HES22 Minimum per property charge	£50.00	1.00	Joint Owner	29/11/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	29/11/2012	2012
EES25 Draught stripping to exterior door	£91.00	10.00	Sole Property Owner	01/02/2010	2010
EES26 Draught stripping to windows	£182.00	20.00	Sole Property Owner	01/02/2010	2010
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	01/02/2010	2010
EES66 Low energy lamp replacement	£8.75	5.00	Sole Property Owner	01/02/2010	2010
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	01/02/2010	2010
EES 30 Hot water cylinder jacket (46x18 inch)	£81.31	1.00	Sole Property Owner	01/02/2010	2010
EES66 Low energy lamp replacement	£0.00	6.00	Sole Property Owner	27/09/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	27/09/2012	2012
EES15 Insulation to 65mm wide cavity wall	£1,867.20	1,867.20	Sole Property Owner	27/09/2012	2012
HES120 Standard QA check	£102.00	1.00	Joint Owner	05/11/2012	2012
EES01a Loft Clearance (hourly rate)	£225.00	9.00	Joint Owner	05/11/2012	2012
EES03a Remove and replace nailed floor board	£42.00	14.00	Joint Owner	05/11/2012	2012
EES06 100mm thick loft insulation	£91.56	14.00	Joint Owner	05/11/2012	2012
EES08 300mm thick loft insulation	£168.00	14.00	Joint Owner	05/11/2012	2012
EES25 Draught stripping to exterior door	£0.00	0.00	Joint Owner	05/11/2012	2012
EES66 Low energy lamp replacement	£0.00	16.00	Joint Owner	05/11/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	05/11/2012	2012
EES10 Cold water tank insulation quilt	£0.00	0.00	Joint Owner	05/11/2012	2012
EES 11 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	05/11/2012	2012
EES12 Cold water tank lid	£0.00	0.00	Joint Owner	05/11/2012	2012
EES13a Cold water tank bye law kit (including associated product	£0.00	0.00	Joint Owner	05/11/2012	2012
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	03/01/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	03/01/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	03/01/2013	2013
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	03/01/2013	2013
HES44 Pipework / feed modifications	£120.00	1.00	Joint Owner	23/11/2012	2012
HES46 Automatic bypass	£32.40	1.00	Joint Owner	23/11/2012	2012
HES50 Electrical room thermostat	£22.80	1.00	Joint Owner	23/11/2012	2012
HES51 Thermostatic radiator valve	£273.60	12.00	Joint Owner	23/11/2012	2012
HES52 Hot water cylinder thermostat	£24.00	1.00	Joint Owner	23/11/2012	2012
HES53 Two channel heating programmer control	£78.00	1.00	Joint Owner	23/11/2012	2012
HES55 2 port zone valve	£136.80	2.00	Joint Owner	23/11/2012	2012
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Joint Owner	23/11/2012	2012
HES66 15mm thick pipework lagging	£20.28	6.00	Joint Owner	23/11/2012	2012
HES67 22mm thick pipework lagging	£35.20	8.00	Joint Owner	23/11/2012	2012
HES68 28mm thick pipework lagging	£18.96	4.00	Joint Owner	23/11/2012	2012
HES93 Junior heating engineer	£150.00	6.00	Joint Owner	23/11/2012	2012
HES95 Senior heating engineer	£936.00	24.00	Joint Owner	23/11/2012	2012
HES96 Junior electrician	£126.00	7.00	Joint Owner	23/11/2012	2012
HES98 Senior electrician	£624.00	16.00	Joint Owner	23/11/2012	2012
HES90 Other miscellaneous oil heating works for EES approval	£378.00	1.00	Joint Owner	23/11/2012	2012
EES02a Remove and dispose existing insulation (per squire metre	£147.00	49.00	Joint Owner	23/11/2012	2012
EES08 300mm thick loft insulation	£588.00	49.00	Joint Owner	23/11/2012	2012
EES66 Low energy lamp replacement	£0.00	25.00	Joint Owner	23/11/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	23/11/2012	2012
EES15 Insulation to 65mm wide cavity wall	£1,417.20	1,417.20	Joint Owner	23/11/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	23/11/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	23/11/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	23/11/2012	2012

EES13a Cold water tank bye law kit (including associated product	£100.00	2.00	Joint Owner	23/11/2012	2012
HES122 Consultancy Fees	£65.00	1.00	Joint Owner	23/11/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	05/11/2012	2012
HES33 26-35kW Oil replacement condensing boiler	£2,984.00	1.00	Sole Property Owner	05/11/2012	2012
HES43 Central heating pump	£44.00	1.00	Sole Property Owner	05/11/2012	2012
HES45 Fire valve	£52.00	1.00	Sole Property Owner	05/11/2012	2012
HES47 Frost thermostat	£18.00	1.00	Sole Property Owner	05/11/2012	2012
HES48 Power / system flush and treatment	£3.50	1.00	Sole Property Owner	05/11/2012	2012
HES53 Two channel heating programmer control	£47.00	1.00	Sole Property Owner	05/11/2012	2012
HES55 2 port zone valve	£108.00	2.00	Sole Property Owner	05/11/2012	2012
HES67 22mm thick pipework lagging	£8.70	3.00	Sole Property Owner	05/11/2012	2012
HES68 28mm thick pipework lagging	£9.90	3.00	Sole Property Owner	05/11/2012	2012
HES94 Heating engineer	£1,188.00	36.00	Sole Property Owner	05/11/2012	2012
HES97 Electrician	£99.00	3.00	Sole Property Owner	05/11/2012	2012
HES50 Electrical room thermostat	£13.88	1.00	Sole Property Owner	05/11/2012	2012
HES40 Flue specification and location	£167.00	1.00	Sole Property Owner	05/11/2012	2012
HES49 Carbon Monoxide alarm	£31.00	1.00	Sole Property Owner	05/11/2012	2012
HES51 Thermostatic radiator valve	£120.00	8.00	Sole Property Owner	05/11/2012	2012
EES66 Low energy lamp replacement	£0.00	15.00	Sole Property Owner	05/11/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	05/11/2012	2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	05/11/2012	2012
HES71 Storage heater rated 1kW - 2kW	£489.06	2.00	Sole Property Owner	03/07/2013	2013
HES72 Storage heater rated 2kW - 3kW	£616.98	2.00	Sole Property Owner	03/07/2013	2013
HES74 Comfort heat main switch	£57.20	1.00	Sole Property Owner	03/07/2013	2013
HES77 Main bonding of necessary services	£54.50	5.00	Sole Property Owner	03/07/2013	2013
HES78 Twin and earth 16mm cabling with clips and trunking	£280.05	15.00	Sole Property Owner	03/07/2013	2013
HES80 16mm meter tails	£12.48	1.00	Sole Property Owner	03/07/2013	2013
HES97 Electrician	£640.00	20.00	Sole Property Owner	03/07/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£57.68	1.00	Sole Property Owner	03/07/2013	2013
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Sole Property Owner	03/07/2013	2013
EES02a Remove and dispose existing insulation (per squire metre	£135.00	45.00	Sole Property Owner	03/07/2013	2013
EES03a Remove and replace nailed floor board	£15.00	5.00	Sole Property Owner	03/07/2013	2013
EES08 300mm thick loft insulation	£540.00	45.00	Sole Property Owner	03/07/2013	2013
EES66 Low energy lamp replacement	£0.00	17.00	Sole Property Owner	03/07/2013	2013
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	03/07/2013	2013
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	03/07/2013	2013
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	03/07/2013	2013
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	03/07/2013	2013
EES13a Cold water tank bye law kit (including associated product	£50.00	1.00	Sole Property Owner	03/07/2013	2013
HES120 Standard QA check	£0.00	1.00	Sole Property Owner	03/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£125.00	5.00	Not The Property Owner	20/02/2013	2013
HES04 300mm thick loft insulation quilt	£337.50	27.00	Not The Property Owner	20/02/2013	2013
HES21 Smoke detector installation	£0.00	0.00	Not The Property Owner	20/02/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Not The Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Not The Property Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£16.88	4.00	Not The Property Owner	20/02/2013	2013
HES94 Heating engineer	£73.60	2.00	Not The Property Owner	20/02/2013	2013
HES50 Electrical room thermostat	£13.88	1.00	Joint Owner	05/11/2012	2012
HES51 Thermostatic radiator valve	£135.00	9.00	Joint Owner	05/11/2012	2012
HES94 Heating engineer	£297.00	9.00	Joint Owner	05/11/2012	2012
HES97 Electrician	£33.00	1.00	Joint Owner	05/11/2012	2012
HES48 Power / system flush and treatment	£350.00	1.00	Joint Owner	05/11/2012	2012
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Joint Owner	05/11/2012	2012
EES08 300mm thick loft insulation	£480.00	40.00	Joint Owner	05/11/2012	2012
EES66 Low energy lamp replacement	£0.00	15.00	Joint Owner	05/11/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Joint Owner	05/11/2012	2012
EES10 Cold water tank insulation quilt	£0.00	0.00	Joint Owner	05/11/2012	2012
EES 11 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	05/11/2012	2012
EES12 Cold water tank lid	£0.00	0.00	Joint Owner	05/11/2012	2012
EES13a Cold water tank bye law kit (including associated product	£0.00	0.00	Joint Owner	05/11/2012	2012
HES66 15mm thick pipework lagging	£81.00	25.00	Joint Owner	05/11/2012	2012
HES67 22mm thick pipework lagging	£16.88	4.00	Joint Owner	05/11/2012	2012
HES94 Heating engineer	£220.80	6.00	Joint Owner	05/11/2012	2012
EES66 Low energy lamp replacement	£0.00	3.00	Sole Property Owner	23/11/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	23/11/2012	2012
EES01a Loft Clearance (hourly rate)	£250.00	10.00	Sole Property Owner	23/11/2012	2012
EES02a Remove and dispose existing insulation (per squire metre	£225.00	75.00	Sole Property Owner	23/11/2012	2012
EES03a Remove and replace nailed floor board	£30.00	10.00	Sole Property Owner	23/11/2012	2012
EES08 300mm thick loft insulation	£900.00	75.00	Sole Property Owner	23/11/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	23/11/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	23/11/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	23/11/2012	2012
EES13a Cold water tank bye law kit (including associated product	£50.00	1.00	Sole Property Owner	23/11/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	23/11/2012	2012
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	02/08/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	02/08/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	01/12/2009	2009
EES25 Draught stripping to exterior door	£50.00	5.00	Sole Property Owner	05/11/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	05/11/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	05/11/2012	2012
HES10 CIGA approved cavity wall insulation to 65mm wide cavity	£1,017.60	106.00	Not The Property Owner	23/11/2012	2012
HES20 Low energy lamp installation	£0.00	12.00	Not The Property Owner	23/11/2012	2012
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner	23/11/2012	2012

HES55 2 port zone valve	£68.40	1.00	Not The Property Owner	20/02/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Not The Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£47.32	14.00	Not The Property Owner	20/02/2013	2013
HES68 28mm thick pipework lagging	£56.88	12.00	Not The Property Owner	20/02/2013	2013
HES93 Junior heating engineer	£250.00	10.00	Not The Property Owner	20/02/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£300.00	12.00	Not The Property Owner	20/02/2013	2013
HES04 300mm thick loft insulation quilt	£500.00	40.00	Not The Property Owner	20/02/2013	2013
HES06 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	20/02/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Not The Property Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Not The Property Owner	20/02/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner	20/02/2013	2013
HES51 Thermostatic radiator valve	£136.80	6.00	Not The Property Owner	20/02/2013	2013
HES53 Two channel heating programmer control	£78.00	1.00	Not The Property Owner	20/02/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£0.00	0.00	Not The Property Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£52.80	12.00	Not The Property Owner	20/02/2013	2013
HES94 Heating engineer	£266.00	7.00	Not The Property Owner	20/02/2013	2013
HES96 Junior electrician	£0.00	0.00	Not The Property Owner	20/02/2013	2013
HES97 Electrician	£114.00	3.00	Not The Property Owner	20/02/2013	2013
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£67.10	1.00	Not The Property Owner	20/02/2013	2013
HES120 Standard QA check	£102.00	1.00	Not The Property Owner	20/02/2013	2013
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Not The Property Owner	02/08/2012	2012
EES07 200mm thick loft insulation	£315.00	35.00	Not The Property Owner	02/08/2012	2012
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Not The Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	2.00	Not The Property Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Not The Property Owner	02/08/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	02/08/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatic	£150.00	6.00	Not The Property Owner	21/12/2012	2012
HES03 200mm thick loft insulation quilt	£133.00	14.00	Not The Property Owner	21/12/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Not The Property Owner	21/12/2012	2012
HES15 Draught stripping to exterior door	£33.00	11.00	Not The Property Owner	21/12/2012	2012
HES19 Draught proofing labour	£100.00	4.00	Not The Property Owner	21/12/2012	2012
HES52 Hot water cylinder thermostat	£0.00	0.00	Not The Property Owner	21/12/2012	2012
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Not The Property Owner	21/12/2012	2012
HES95 Senior heating engineer	£0.00	0.00	Not The Property Owner	21/12/2012	2012
HES97 Electrician	£0.00	0.00	Not The Property Owner	21/12/2012	2012
HES67 22mm thick pipework lagging	£8.80	2.00	Not The Property Owner	21/12/2012	2012
HES68 28mm thick pipework lagging	£28.44	6.00	Not The Property Owner	21/12/2012	2012
HES93 Junior heating engineer	£100.00	4.00	Not The Property Owner	21/12/2012	2012
HES94 Heating engineer	£228.00	6.00	Not The Property Owner	21/12/2012	2012
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£58.20	1.00	Not The Property Owner	21/12/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	21/12/2012	2012
HES66 15mm thick pipework lagging	£3.24	1.00	Not The Property Owner	21/12/2012	2012
HES67 22mm thick pipework lagging	£16.88	4.00	Not The Property Owner	21/12/2012	2012
HES94 Heating engineer	£36.80	1.00	Not The Property Owner	21/12/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	21/12/2012	2012
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	17/09/2013	2013
HES93 Junior heating engineer	£25.00	1.00	Joint Owner	17/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£250.00	10.00	Joint Owner	17/09/2013	2013
HES03 200mm thick loft insulation quilt	£142.50	15.00	Joint Owner	17/09/2013	2013
HES04 300mm thick loft insulation quilt	£250.00	20.00	Joint Owner	17/09/2013	2013
HES06 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	17/09/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	17/09/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,286.40	134.00	Joint Owner	17/09/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner	17/09/2013	2013
HES20 Low energy lamp installation	£0.00	14.00	Joint Owner	17/09/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	17/09/2013	2013
HES51 Thermostatic radiator valve	£364.80	16.00	Joint Owner	17/09/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner	17/09/2013	2013
HES95 Senior heating engineer	£312.00	8.00	Joint Owner	17/09/2013	2013
HES98 Senior electrician	£0.00	0.00	Joint Owner	17/09/2013	2013
HES33 26-35kW Oil replacement condensing boiler	£2,415.00	1.00	Joint Owner	17/09/2013	2013
HES40 Flue specification and location	£642.90	1.00	Joint Owner	17/09/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Joint Owner	17/09/2013	2013
HES44 Pipework / feed modifications	£347.30	1.00	Joint Owner	17/09/2013	2013
HES45 Fire valve	£46.00	1.00	Joint Owner	17/09/2013	2013
HES46 Automatic bypass	£31.05	1.00	Joint Owner	17/09/2013	2013
HES47 Frost thermostat	£23.00	1.00	Joint Owner	17/09/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Joint Owner	17/09/2013	2013
HES49 Carbon Monoxide alarm	£42.00	1.00	Joint Owner	17/09/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Joint Owner	17/09/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Joint Owner	17/09/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Joint Owner	17/09/2013	2013
HES55 2 port zone valve	£131.10	2.00	Joint Owner	17/09/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Joint Owner	17/09/2013	2013
HES67 22mm thick pipework lagging	£50.64	12.00	Joint Owner	17/09/2013	2013
HES68 28mm thick pipework lagging	£45.40	10.00	Joint Owner	17/09/2013	2013
HES93 Junior heating engineer	£131.82	6.00	Joint Owner	17/09/2013	2013
HES94 Heating engineer	£993.60	27.00	Joint Owner	17/09/2013	2013
HES95 Senior heating engineer	£79.36	2.00	Joint Owner	17/09/2013	2013
HES98 Senior electrician	£396.80	10.00	Joint Owner	17/09/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	17/09/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Joint Owner	17/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£345.00	1.00	Joint Owner	17/09/2013	2013

HES92 Other miscellaneous electrical heating works for EES approval	£517.39	517.39	Joint Owner	17/09/2013	2013
HES101 Asbestos removal & disposal	£520.00	1.00	Joint Owner	17/09/2013	2013
HES101 Asbestos removal & disposal	£1,558.00	1.00	Joint Owner	17/09/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£422.50	1.00	Joint Owner	17/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulation)	£150.00	6.00	Joint Owner	17/09/2013	2013
HES02 100mm thick loft insulation quilt	£0.00	0.00	Joint Owner	17/09/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	17/09/2013	2013
HES100 Asbestos survey & sample	£500.00	1.00	Joint Owner	17/09/2013	2013
HES03 200mm thick loft insulation quilt	£180.50	19.00	Joint Owner	17/09/2013	2013
HES66 15mm thick pipework lagging	£22.68	7.00	Joint Owner	17/09/2013	2013
HES67 22mm thick pipework lagging	£4.22	1.00	Joint Owner	17/09/2013	2013
HES94 Heating engineer	£128.80	3.50	Joint Owner	17/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£4.20	1.00	Joint Owner	17/09/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	05/11/2012	2012
HES30 12-15kW Oil replacement condensing boiler	£1,278.00	1.00	Sole Property Owner	05/11/2012	2012
HES40 Flue specification and location	£669.40	1.00	Sole Property Owner	05/11/2012	2012
HES41 Condensate pipework (and pump if required)	£125.50	1.00	Sole Property Owner	05/11/2012	2012
HES44 Pipework / feed modifications	£200.00	200.00	Sole Property Owner	05/11/2012	2012
HES45 Fire valve	£36.90	1.00	Sole Property Owner	05/11/2012	2012
HES46 Automatic bypass	£27.50	1.00	Sole Property Owner	05/11/2012	2012
HES48 Power / system flush and treatment	£43.80	1.00	Sole Property Owner	05/11/2012	2012
HES51 Thermostatic radiator valve	£103.20	8.00	Sole Property Owner	05/11/2012	2012
HES52 Hot water cylinder thermostat	£14.80	1.00	Sole Property Owner	05/11/2012	2012
HES53 Two channel heating programmer control	£33.80	1.00	Sole Property Owner	05/11/2012	2012
HES55 2 port zone valve	£98.00	2.00	Sole Property Owner	05/11/2012	2012
HES66 15mm thick pipework lagging	£3.22	2.00	Sole Property Owner	05/11/2012	2012
HES67 22mm thick pipework lagging	£15.84	8.00	Sole Property Owner	05/11/2012	2012
HES68 28mm thick pipework lagging	£14.46	6.00	Sole Property Owner	05/11/2012	2012
HES95 Senior heating engineer	£1,050.00	30.00	Sole Property Owner	05/11/2012	2012
HES98 Senior electrician	£280.00	8.00	Sole Property Owner	05/11/2012	2012
HES99 Building works	£88.00	4.00	Sole Property Owner	05/11/2012	2012
HES87 Commissioning and issue of CD10 and Building Control notice	£0.00	1.00	Sole Property Owner	05/11/2012	2012
HES90 Other miscellaneous oil heating works for EES approval	£70.00	1.00	Sole Property Owner	05/11/2012	2012
EES01a Loft Clearance (hourly rate)	£250.00	10.00	Sole Property Owner	05/11/2012	2012
EES07 200mm thick loft insulation	£612.00	68.00	Sole Property Owner	05/11/2012	2012
EES66 Low energy lamp replacement	£0.00	15.00	Sole Property Owner	05/11/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	05/11/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	05/11/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	05/11/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	05/11/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	05/11/2012	2012
HES44 Pipework / feed modifications	£80.00	1.00	Sole Property Owner	05/11/2012	2012
HES32 21-25kW Oil replacement condensing boiler	£1,817.37	1.00	Joint Owner	27/09/2012	2012
HES40 Flue specification and location	£461.12	1.00	Joint Owner	27/09/2012	2012
HES41 Condensate pipework (and pump if required)	£230.00	1.00	Joint Owner	27/09/2012	2012
HES43 Central heating pump	£141.55	1.00	Joint Owner	27/09/2012	2012
HES44 Pipework / feed modifications	£200.00	1.00	Joint Owner	27/09/2012	2012
HES46 Automatic bypass	£46.32	1.00	Joint Owner	27/09/2012	2012
HES48 Power / system flush and treatment	£38.00	1.00	Joint Owner	27/09/2012	2012
HES49 Carbon Monoxide alarm	£85.35	1.00	Joint Owner	27/09/2012	2012
HES51 Thermostatic radiator valve	£315.70	7.00	Joint Owner	27/09/2012	2012
HES53 Two channel heating programmer control	£85.11	1.00	Joint Owner	27/09/2012	2012
HES55 2 port zone valve	£138.56	2.00	Joint Owner	27/09/2012	2012
HES67 22mm thick pipework lagging	£69.80	20.00	Joint Owner	27/09/2012	2012
HES68 28mm thick pipework lagging	£37.60	10.00	Joint Owner	27/09/2012	2012
HES94 Heating engineer	£1,216.00	32.00	Joint Owner	27/09/2012	2012
HES97 Electrician	£150.00	6.00	Joint Owner	27/09/2012	2012
HES87 Commissioning and issue of CD10 and Building Control notice	£0.00	1.00	Joint Owner	27/09/2012	2012
HES88 Commissioning and issue of CD11 and flue gas analysis	£38.00	1.00	Joint Owner	27/09/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	27/09/2012	2012
EES66 Low energy lamp replacement	£0.00	10.00	Joint Owner	27/09/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	27/09/2012	2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Joint Owner	27/09/2012	2012
HES90 Other miscellaneous oil heating works for EES approval	£235.91	1.00	Joint Owner	27/09/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	06/01/2012	2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Sole Property Owner	03/01/2013	2013
EES02a Remove and dispose existing insulation (per square metre)	£147.00	49.00	Sole Property Owner	03/01/2013	2013
EES03a Remove and replace nailed floor board	£30.00	10.00	Sole Property Owner	03/01/2013	2013
EES08 300mm thick loft insulation	£588.00	49.00	Sole Property Owner	03/01/2013	2013
EES66 Low energy lamp replacement	£0.00	16.00	Sole Property Owner	03/01/2013	2013
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	03/01/2013	2013
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	03/01/2013	2013
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	03/01/2013	2013
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	03/01/2013	2013
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Sole Property Owner	03/01/2013	2013
HES120 Standard QA check	£102.00	1.00	Sole Property Owner	03/01/2013	2013
EES53b 26-35kW Gas replacement boiler	£1,433.00	1.00	Sole Property Owner	24/02/2011	2011
EES70 Miscellaneous heating review charge	£260.83	260.83	Sole Property Owner	24/02/2011	2011
EES38a Thermostatic radiator valve (per valve)	£169.32	4.00	Sole Property Owner	24/02/2011	2011
EES68 Minimum charge for lamps and detectors	£32.00	1.00	Sole Property Owner	24/02/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	24/02/2011	2011
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	24/02/2011	2011
EES66 Low energy lamp replacement	£0.00	5.00	Joint Owner	02/08/2012	2012

EES68 Minimum charge for lamps and detectors	£50.00	1.00	Joint Owner	02/08/2012	2012
EES01a Loft Clearance (hourly rate)	£375.00	15.00	Sole Property Owner	27/09/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£240.00	80.00	Sole Property Owner	27/09/2012	2012
EES03a Remove and replace nailed floor board	£15.00	5.00	Sole Property Owner	27/09/2012	2012
EES07 200mm thick loft insulation	£162.00	18.00	Sole Property Owner	27/09/2012	2012
EES08 300mm thick loft insulation	£960.00	80.00	Sole Property Owner	27/09/2012	2012
EES66 Low energy lamp replacement	£0.00	15.00	Sole Property Owner	27/09/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	27/09/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	27/09/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	27/09/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	27/09/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	27/09/2012	2012
HES66 15mm thick pipework lagging	£25.92	8.00	Sole Property Owner	27/09/2012	2012
HES67 22mm thick pipework lagging	£33.76	8.00	Sole Property Owner	27/09/2012	2012
HES68 28mm thick pipework lagging	£27.24	6.00	Sole Property Owner	27/09/2012	2012
HES94 Heating engineer	£73.60	2.00	Sole Property Owner	27/09/2012	2012
EES50b 12-15kW Gas replacement boiler	£971.00	1.00	Sole Property Owner	23/10/2012	2012
EES36 Electrical room thermostat	£0.00	1.00	Sole Property Owner	23/10/2012	2012
EES38a Thermostatic radiator valve (per valve)	£0.00	5.00	Sole Property Owner	23/10/2012	2012
EES40 Hot water cylinder thermostat	£0.00	1.00	Sole Property Owner	23/10/2012	2012
EES42 Two channel programmable heating controller	£0.00	1.00	Sole Property Owner	23/10/2012	2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£0.00	10.00	Sole Property Owner	23/10/2012	2012
EES70 Miscellaneous heating review charge	£1,280.43	1,280.43	Sole Property Owner	23/10/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulation)	£200.00	8.00	Sole Property Owner	23/10/2012	2012
HES04 300mm thick loft insulation quilt	£500.00	40.00	Sole Property Owner	23/10/2012	2012
HES06 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	23/10/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	23/10/2012	2012
HES20 Low energy lamp installation	£0.00	20.00	Sole Property Owner	23/10/2012	2012
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	23/10/2012	2012
HES66 15mm thick pipework lagging	£25.92	8.00	Sole Property Owner	23/10/2012	2012
HES67 22mm thick pipework lagging	£33.76	8.00	Sole Property Owner	23/10/2012	2012
HES94 Heating engineer	£73.60	2.00	Sole Property Owner	23/10/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	23/10/2012	2012
HES67 22mm thick pipework lagging	£69.80	20.00	Sole Property Owner	05/11/2012	2012
HES68 28mm thick pipework lagging	£37.60	10.00	Sole Property Owner	05/11/2012	2012
HES94 Heating engineer	£1,216.00	32.00	Sole Property Owner	05/11/2012	2012
HES97 Electrician	£150.00	6.00	Sole Property Owner	05/11/2012	2012
HES40 Flue specification and location	£481.00	1.00	Sole Property Owner	05/11/2012	2012
HES41 Condensate pipework (and pump if required)	£150.00	1.00	Sole Property Owner	05/11/2012	2012
HES43 Central heating pump	£141.55	1.00	Sole Property Owner	05/11/2012	2012
HES44 Pipework / feed modifications	£262.00	1.00	Sole Property Owner	05/11/2012	2012
HES46 Automatic bypass	£46.32	1.00	Sole Property Owner	05/11/2012	2012
HES49 Carbon Monoxide alarm	£85.35	1.00	Sole Property Owner	05/11/2012	2012
HES51 Thermostatic radiator valve	£451.00	10.00	Sole Property Owner	05/11/2012	2012
HES53 Two channel heating programmer control	£85.11	1.00	Sole Property Owner	05/11/2012	2012
HES55 2 port zone valve	£138.56	2.00	Sole Property Owner	05/11/2012	2012
HES87 Commissioning and issue of CD10 and Building Control notice	£0.00	1.00	Sole Property Owner	05/11/2012	2012
HES88 Commissioning and issue of CD11 and flue gas analysis	£38.00	1.00	Sole Property Owner	05/11/2012	2012
HES32 21-25kW Oil replacement condensing boiler	£1,817.37	1.00	Sole Property Owner	05/11/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	05/11/2012	2012
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Sole Property Owner	05/11/2012	2012
EES03a Remove and replace nailed floor board	£12.00	4.00	Sole Property Owner	05/11/2012	2012
EES08 300mm thick loft insulation	£840.00	70.00	Sole Property Owner	05/11/2012	2012
EES15 Insulation to 65mm wide cavity wall	£1,110.00	1,110.00	Sole Property Owner	05/11/2012	2012
EES66 Low energy lamp replacement	£0.00	28.00	Sole Property Owner	05/11/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	05/11/2012	2012
EES10 Cold water tank insulation quilt	£0.00	0.00	Sole Property Owner	05/11/2012	2012
EES 11 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	05/11/2012	2012
EES12 Cold water tank lid	£0.00	0.00	Sole Property Owner	05/11/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£0.00	0.00	Sole Property Owner	05/11/2012	2012
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	05/11/2012	2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	05/11/2012	2012
HES32 21-25kW Oil replacement condensing boiler	£1,817.37	1.00	Joint Owner	05/11/2012	2012
HES40 Flue specification and location	£833.28	1.00	Joint Owner	05/11/2012	2012
HES41 Condensate pipework (and pump if required)	£150.00	1.00	Joint Owner	05/11/2012	2012
HES43 Central heating pump	£141.55	1.00	Joint Owner	05/11/2012	2012
HES46 Automatic bypass	£46.32	1.00	Joint Owner	05/11/2012	2012
HES49 Carbon Monoxide alarm	£85.35	1.00	Joint Owner	05/11/2012	2012
HES51 Thermostatic radiator valve	£225.50	5.00	Joint Owner	05/11/2012	2012
HES55 2 port zone valve	£207.84	3.00	Joint Owner	05/11/2012	2012
HES67 22mm thick pipework lagging	£69.80	20.00	Joint Owner	05/11/2012	2012
HES68 28mm thick pipework lagging	£37.60	10.00	Joint Owner	05/11/2012	2012
HES94 Heating engineer	£1,216.00	32.00	Joint Owner	05/11/2012	2012
HES97 Electrician	£150.00	6.00	Joint Owner	05/11/2012	2012
HES87 Commissioning and issue of CD10 and Building Control notice	£0.00	1.00	Joint Owner	05/11/2012	2012
HES88 Commissioning and issue of CD11 and flue gas analysis	£38.00	1.00	Joint Owner	05/11/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	05/11/2012	2012
EES01a Loft Clearance (hourly rate)	£350.00	14.00	Joint Owner	05/11/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£210.00	70.00	Joint Owner	05/11/2012	2012
EES03a Remove and replace nailed floor board	£30.00	10.00	Joint Owner	05/11/2012	2012
EES08 300mm thick loft insulation	£840.00	70.00	Joint Owner	05/11/2012	2012
EES66 Low energy lamp replacement	£0.00	12.00	Joint Owner	05/11/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Joint Owner	05/11/2012	2012
EES15 Insulation to 65mm wide cavity wall	£1,521.60	1,521.60	Joint Owner	05/11/2012	2012

EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	05/11/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	05/11/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	05/11/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Joint Owner	05/11/2012	2012
HES66 15mm thick pipework lagging	£6.48	2.00	Joint Owner	05/11/2012	2012
HES67 22mm thick pipework lagging	£8.44	2.00	Joint Owner	05/11/2012	2012
HES94 Heating engineer	£36.80	1.00	Joint Owner	05/11/2012	2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Joint Owner	05/11/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£135.00	45.00	Joint Owner	05/11/2012	2012
EES03a Remove and replace nailed floor board	£24.00	8.00	Joint Owner	05/11/2012	2012
EES08 300mm thick loft insulation	£540.00	45.00	Joint Owner	05/11/2012	2012
EES66 Low energy lamp replacement	£0.00	2.00	Joint Owner	05/11/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Joint Owner	05/11/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	05/11/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	05/11/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	05/11/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Joint Owner	05/11/2012	2012
HES66 15mm thick pipework lagging	£19.44	6.00	Joint Owner	05/11/2012	2012
HES67 22mm thick pipework lagging	£4.22	1.00	Joint Owner	05/11/2012	2012
HES94 Heating engineer	£110.40	3.00	Joint Owner	05/11/2012	2012
HES66 15mm thick pipework lagging	£19.44	6.00	Joint Owner	05/11/2012	2012
HES67 22mm thick pipework lagging	£4.22	1.00	Joint Owner	05/11/2012	2012
HES94 Heating engineer	£73.60	2.00	Joint Owner	05/11/2012	2012
EES50c Replacement electrical storage heater	£539.00	1.00	Sole Property Owner	28/09/2012	2012
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	28/09/2012	2012
EES50c Replacement electrical storage heater	£1,332.00	3.00	Sole Property Owner	28/09/2012	2012
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Sole Property Owner	28/09/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£0.00	0.00	Sole Property Owner	28/09/2012	2012
EES03a Remove and replace nailed floor board	£0.00	0.00	Sole Property Owner	28/09/2012	2012
EES08 300mm thick loft insulation	£0.00	0.00	Sole Property Owner	28/09/2012	2012
EES66 Low energy lamp replacement	£0.00	20.00	Sole Property Owner	28/09/2012	2012
EES10 Cold water tank insulation quilt	£0.00	0.00	Sole Property Owner	28/09/2012	2012
EES 11 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	28/09/2012	2012
EES12 Cold water tank lid	£0.00	0.00	Sole Property Owner	28/09/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£0.00	0.00	Sole Property Owner	28/09/2012	2012
HES97 Electrician	£675.00	27.00	Sole Property Owner	08/01/2013	2013
HES71 Storage heater rated 1kW - 2kW	£267.32	1.00	Sole Property Owner	08/01/2013	2013
HES72 Storage heater rated 2kW - 3kW	£684.46	2.00	Sole Property Owner	08/01/2013	2013
HES75 Storage heater consumer unit	£32.92	1.00	Sole Property Owner	08/01/2013	2013
HES76 Storage heater miniature circuit breaker	£16.02	3.00	Sole Property Owner	08/01/2013	2013
HES77 Main bonding of necessary services	£9.72	3.00	Sole Property Owner	08/01/2013	2013
HES80 16mm meter tails	£14.16	3.00	Sole Property Owner	08/01/2013	2013
HES78 Twin and earth 16mm cabling with clips and trunking	£140.20	10.00	Sole Property Owner	08/01/2013	2013
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	08/01/2013	2013
HES120 Standard QA check	£102.00	1.00	Sole Property Owner	08/01/2013	2013
EES66 Low energy lamp replacement	£34.11	3.00	Not The Property Owner	15/12/2009	2009
EES00a Full Energy Survey	£246.55	1.00	Not The Property Owner	15/12/2009	2009
EES07 200mm thick loft insulation	£405.00	45.00	Sole Property Owner	05/11/2012	2012
HES100 Asbestos survey & sample	£55.00	1.00	Sole Property Owner	05/11/2012	2012
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Sole Property Owner	05/11/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£0.00	0.00	Sole Property Owner	05/11/2012	2012
EES08 300mm thick loft insulation	£0.00	0.00	Sole Property Owner	05/11/2012	2012
EES66 Low energy lamp replacement	£0.00	11.00	Sole Property Owner	05/11/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	05/11/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	05/11/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	05/11/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	05/11/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Sole Property Owner	05/11/2012	2012
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	05/11/2012	2012
HES94 Heating engineer	£73.60	2.00	Sole Property Owner	05/11/2012	2012
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	05/11/2012	2012
HES94 Heating engineer	£73.60	2.00	Sole Property Owner	05/11/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulation)	£350.00	14.00	Joint Owner	19/10/2012	2012
HES04 300mm thick loft insulation quilt	£500.00	40.00	Joint Owner	19/10/2012	2012
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£220.80	23.00	Joint Owner	19/10/2012	2012
HES20 Low energy lamp installation	£0.00	15.00	Joint Owner	19/10/2012	2012
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	19/10/2012	2012
HES19 Draught proofing labour	£175.00	7.00	Sole Property Owner	05/11/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulation)	£200.00	8.00	Sole Property Owner	05/11/2012	2012
HES04 300mm thick loft insulation quilt	£687.50	55.00	Sole Property Owner	05/11/2012	2012
HES06 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	05/11/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	05/11/2012	2012
HES15 Draught stripping to exterior door	£75.00	25.00	Sole Property Owner	05/11/2012	2012
HES20 Low energy lamp installation	£0.00	22.00	Sole Property Owner	05/11/2012	2012
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	05/11/2012	2012
HES66 15mm thick pipework lagging	£19.44	6.00	Sole Property Owner	05/11/2012	2012
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	05/11/2012	2012
HES68 28mm thick pipework lagging	£4.54	1.00	Sole Property Owner	05/11/2012	2012
HES94 Heating engineer	£73.60	2.00	Sole Property Owner	05/11/2012	2012
HES66 15mm thick pipework lagging	£19.44	6.00	Sole Property Owner	05/11/2012	2012
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	05/11/2012	2012
HES68 28mm thick pipework lagging	£4.54	1.00	Sole Property Owner	05/11/2012	2012
HES94 Heating engineer	£55.20	1.50	Sole Property Owner	05/11/2012	2012
HES32 21-25kW Oil replacement condensing boiler	£1,817.37	1.00	Joint Owner	22/01/2013	2013

HES40 Flue specification and location	£461.12	1.00	Joint Owner	22/01/2013	2013
HES41 Condensate pipework (and pump if required)	£150.00	1.00	Joint Owner	22/01/2013	2013
HES43 Central heating pump	£141.55	1.00	Joint Owner	22/01/2013	2013
HES44 Pipework / feed modifications	£200.00	1.00	Joint Owner	22/01/2013	2013
HES46 Automatic bypass	£46.32	1.00	Joint Owner	22/01/2013	2013
HES49 Carbon Monoxide alarm	£85.35	1.00	Joint Owner	22/01/2013	2013
HES53 Two channel heating programmer control	£85.11	1.00	Joint Owner	22/01/2013	2013
HES55 2 port zone valve	£138.56	2.00	Joint Owner	22/01/2013	2013
HES67 22mm thick pipework lagging	£69.80	20.00	Joint Owner	22/01/2013	2013
HES68 28mm thick pipework lagging	£37.60	10.00	Joint Owner	22/01/2013	2013
HES94 Heating engineer	£1,368.00	36.00	Joint Owner	22/01/2013	2013
HES97 Electrician	£150.00	6.00	Joint Owner	22/01/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	22/01/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£38.00	1.00	Joint Owner	22/01/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	22/01/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00	0.00	Joint Owner	22/01/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Joint Owner	22/01/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	22/01/2013	2013
HES20 Low energy lamp installation	£0.00	4.00	Joint Owner	22/01/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Joint Owner	22/01/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£2,138.00	1.00	Joint Owner	03/01/2013	2013
HES43 Central heating pump	£0.00	0.00	Joint Owner	03/01/2013	2013
HES45 Fire valve	£52.00	1.00	Joint Owner	03/01/2013	2013
HES50 Electrical room thermostat	£13.88	1.00	Joint Owner	03/01/2013	2013
HES53 Two channel heating programmer control	£47.00	1.00	Joint Owner	03/01/2013	2013
HES55 2 port zone valve	£108.00	2.00	Joint Owner	03/01/2013	2013
HES94 Heating engineer	£660.00	20.00	Joint Owner	03/01/2013	2013
HES97 Electrician	£99.00	3.00	Joint Owner	03/01/2013	2013
HES99 Building works	£66.00	2.00	Joint Owner	03/01/2013	2013
HES49 Carbon Monoxide alarm	£31.00	1.00	Joint Owner	03/01/2013	2013
HES40 Flue specification and location	£257.00	1.00	Joint Owner	03/01/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£150.00	6.00	Joint Owner	03/01/2013	2013
HES03 200mm thick loft insulation quilt	£570.00	60.00	Joint Owner	03/01/2013	2013
HES06 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	03/01/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	03/01/2013	2013
HES20 Low energy lamp installation	£0.00	14.00	Joint Owner	03/01/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	03/01/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	03/01/2013	2013
HES49 Carbon Monoxide alarm	£31.00	1.00	Joint Owner	27/11/2012	2012
HES50 Electrical room thermostat	£13.00	1.00	Joint Owner	27/11/2012	2012
HES51 Thermostatic radiator valve	£150.00	10.00	Joint Owner	27/11/2012	2012
HES53 Two channel heating programmer control	£47.00	1.00	Joint Owner	27/11/2012	2012
HES94 Heating engineer	£330.00	10.00	Joint Owner	27/11/2012	2012
HES97 Electrician	£66.00	2.00	Joint Owner	27/11/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatic	£325.00	13.00	Joint Owner	27/11/2012	2012
HES04 300mm thick loft insulation quilt	£450.00	36.00	Joint Owner	27/11/2012	2012
HES06 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	27/11/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	27/11/2012	2012
HES20 Low energy lamp installation	£0.00	15.00	Joint Owner	27/11/2012	2012
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	27/11/2012	2012
HES90 Other miscellaneous oil heating works for EES approval	£8.00	1.00	Joint Owner	27/11/2012	2012
HES90 Other miscellaneous oil heating works for EES approval	£0.00	0.00	Joint Owner	27/11/2012	2012
HES46 Automatic bypass	£18.00	1.00	Joint Owner	27/11/2012	2012
HES94 Heating engineer	£99.00	3.00	Joint Owner	27/11/2012	2012
HES90 Other miscellaneous oil heating works for EES approval	£83.00	1.00	Joint Owner	27/11/2012	2012
HES32 21-25kW Oil replacement condensing boiler	£1,410.00	1.00	Joint Owner	20/02/2013	2013
HES40 Flue specification and location	£733.80	1.00	Joint Owner	20/02/2013	2013
HES41 Condensate pipework (and pump if required)	£168.22	1.00	Joint Owner	20/02/2013	2013
HES43 Central heating pump	£84.28	1.00	Joint Owner	20/02/2013	2013
HES44 Pipework / feed modifications	£318.24	1.00	Joint Owner	20/02/2013	2013
HES45 Fire valve	£36.90	1.00	Joint Owner	20/02/2013	2013
HES46 Automatic bypass	£27.50	1.00	Joint Owner	20/02/2013	2013
HES48 Power / system flush and treatment	£43.80	1.00	Joint Owner	20/02/2013	2013
HES50 Electrical room thermostat	£13.45	1.00	Joint Owner	20/02/2013	2013
HES51 Thermostatic radiator valve	£12.90	1.00	Joint Owner	20/02/2013	2013
HES53 Two channel heating programmer control	£33.80	1.00	Joint Owner	20/02/2013	2013
HES55 2 port zone valve	£98.00	2.00	Joint Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£19.32	12.00	Joint Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£63.36	32.00	Joint Owner	20/02/2013	2013
HES95 Senior heating engineer	£1,610.00	46.00	Joint Owner	20/02/2013	2013
HES98 Senior electrician	£210.00	6.00	Joint Owner	20/02/2013	2013
HES99 Building works	£110.00	5.00	Joint Owner	20/02/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	20/02/2013	2013
HES23 Scaffold / cherry picker	£220.00	1.00	Joint Owner	20/02/2013	2013
HES49 Carbon Monoxide alarm	£68.40	1.00	Joint Owner	20/02/2013	2013
HES101 Asbestos removal & disposal	£250.00	1.00	Joint Owner	20/02/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£475.00	19.00	Joint Owner	20/02/2013	2013
HES04 300mm thick loft insulation quilt	£1,750.00	140.00	Joint Owner	20/02/2013	2013
HES06 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	20/02/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	20/02/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£806.40	84.00	Joint Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	30.00	Joint Owner	20/02/2013	2013
HES21 Smoke detector installation	£0.00	0.00	Joint Owner	20/02/2013	2013
HES120 Standard QA check	£102.00	1.00	Joint Owner	20/02/2013	2013

HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	20/02/2013	2013
HES72 Storage heater rated 2kW - 3kW	£616.98	2.00	Joint Owner	20/02/2013	2013
HES73 Storage heater rated 3kW - 4kW	£1,126.02	3.00	Joint Owner	20/02/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£283.83	1.00	Joint Owner	20/02/2013	2013
HES97 Electrician	£528.00	16.50	Joint Owner	20/02/2013	2013
HES94 Heating engineer	£192.00	6.00	Joint Owner	20/02/2013	2013
HES92 Other miscellaneous electrical heating works for EES approval	£351.61	1.00	Joint Owner	20/02/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulation)	£75.00	3.00	Joint Owner	20/02/2013	2013
HES03 200mm thick loft insulation quilt	£114.00	12.00	Joint Owner	20/02/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Joint Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Joint Owner	20/02/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	20/02/2013	2013
HES71 Storage heater rated 1kW - 2kW	£244.53	1.00	Joint Owner	20/02/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulation)	£250.00	10.00	Sole Property Owner	26/11/2012	2012
HES04 300mm thick loft insulation quilt	£925.00	74.00	Sole Property Owner	26/11/2012	2012
HES06 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	26/11/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	26/11/2012	2012
HES20 Low energy lamp installation	£0.00	8.00	Sole Property Owner	26/11/2012	2012
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	26/11/2012	2012
EES25 Draught stripping to exterior door	£40.00	4.00	Sole Property Owner	03/12/2009	2009
EES29 Hot water cylinder jacket (30x18 inch)	£100.00	1.00	Sole Property Owner	03/12/2009	2009
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	03/12/2009	2009
HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner	19/04/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	6.00	Joint Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	19/04/2013	2013
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	19/04/2013	2013
HES111 HER Survey for Flat	£120.00	1.00	Joint Owner	19/04/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£283.83	1.00	Joint Owner	19/04/2013	2013
HES94 Heating engineer	£192.00	6.00	Joint Owner	19/04/2013	2013
HES19 Draught proofing labour	£212.50	8.50	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulation)	£525.00	21.00	Joint Owner		0
HES04 300mm thick loft insulation quilt	£0.00	0.00	Joint Owner		0
HES06 Cold water tank insulation jacket	£0.00	0.00	Joint Owner		0
HES10 CIGA approved cavity wall insulation to 65mm wide cavity	£0.00	0.00	Joint Owner		0
HES15 Draught stripping to exterior door	£108.00	36.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	15.00	Joint Owner		0
HES21 Smoke detector installation	£0.00	3.00	Joint Owner		0
HES38 21-25kW Gas replacement condensing boiler	£659.00	1.00	Joint Owner		0
HES40 Flue specification and location	£102.00	1.00	Joint Owner		0
HES41 Condensate pipework (and pump if required)	£20.00	1.00	Joint Owner		0
HES48 Power / system flush and treatment	£250.00	1.00	Joint Owner		0
HES50 Electrical room thermostat	£15.75	1.00	Joint Owner		0
HES51 Thermostatic radiator valve	£336.00	14.00	Joint Owner		0
HES53 Two channel heating programmer control	£46.16	1.00	Joint Owner		0
HES55 2 port zone valve	£34.36	2.00	Joint Owner		0
HES66 15mm thick pipework lagging	£2.23	1.00	Joint Owner		0
HES67 22mm thick pipework lagging	£8.76	3.00	Joint Owner		0
HES94 Heating engineer	£897.75	19.00	Joint Owner		0
HES97 Electrician	£236.25	5.00	Joint Owner		0
HES88 Commissioning and issue of CD11 and flue gas analysis	£47.25	1.00	Joint Owner		0
HES91 Other miscellaneous gas heating works for EES approval	£188.00	188.00	Joint Owner		0
HES91 Other miscellaneous gas heating works for EES approval	£0.00	0.00	Joint Owner		0
HES02 100mm thick loft insulation quilt	£300.00	40.00	Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EES approval	£60.60	1.00	Joint Owner		0
HES102 QA Survey for House/Bungalow/Flat	£422.50	1.00	Joint Owner		0
HES66 15mm thick pipework lagging	£3.24	1.00	Joint Owner		0
HES94 Heating engineer	£36.80	1.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulation)	£325.00	13.00	Joint Owner	17/01/2013	2013
HES04 300mm thick loft insulation quilt	£600.00	48.00	Joint Owner	17/01/2013	2013
HES20 Low energy lamp installation	£0.00	30.00	Joint Owner	17/01/2013	2013
HES66 15mm thick pipework lagging	£6.44	4.00	Joint Owner	17/01/2013	2013
HES67 22mm thick pipework lagging	£17.82	9.00	Joint Owner	17/01/2013	2013
HES68 28mm thick pipework lagging	£21.69	9.00	Joint Owner	17/01/2013	2013
HES95 Senior heating engineer	£1,960.00	56.00	Joint Owner	17/01/2013	2013
HES98 Senior electrician	£280.00	8.00	Joint Owner	17/01/2013	2013
HES99 Building works	£132.00	6.00	Joint Owner	17/01/2013	2013
HES87 Commissioning and issue of CD10 and Building Control notice	£0.00	1.00	Joint Owner	17/01/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Joint Owner	17/01/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,410.00	1.00	Joint Owner	17/01/2013	2013
HES40 Flue specification and location	£1,206.25	1.00	Joint Owner	17/01/2013	2013
HES41 Condensate pipework (and pump if required)	£257.25	1.00	Joint Owner	17/01/2013	2013
HES43 Central heating pump	£84.28	1.00	Joint Owner	17/01/2013	2013
HES44 Pipework / feed modifications	£387.90	1.00	Joint Owner	17/01/2013	2013
HES45 Fire valve	£36.90	1.00	Joint Owner	17/01/2013	2013
HES46 Automatic bypass	£27.50	1.00	Joint Owner	17/01/2013	2013
HES48 Power / system flush and treatment	£43.80	1.00	Joint Owner	17/01/2013	2013
HES49 Carbon Monoxide alarm	£68.40	1.00	Joint Owner	17/01/2013	2013
HES50 Electrical room thermostat	£13.45	1.00	Joint Owner	17/01/2013	2013
HES51 Thermostatic radiator valve	£116.10	9.00	Joint Owner	17/01/2013	2013
HES52 Hot water cylinder thermostat	£14.80	1.00	Joint Owner	17/01/2013	2013
HES53 Two channel heating programmer control	£33.80	1.00	Joint Owner	17/01/2013	2013
HES55 2 port zone valve	£98.00	2.00	Joint Owner	17/01/2013	2013

HES23 Scaffold / cherry picker	£210.12	1.00	Joint Owner	17/01/2013	2013
HES101 Asbestos removal & disposal	£250.00	1.00	Joint Owner	17/01/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	17/01/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£435.60	1.00	Sole Property Owner	05/11/2012	2012
HES94 Heating engineer	£228.00	6.00	Sole Property Owner	05/11/2012	2012
HES97 Electrician	£25.00	1.00	Sole Property Owner	05/11/2012	2012
HES120 Standard QA check	£102.00	1.00	Sole Property Owner	05/11/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Sole Property Owner	05/11/2012	2012
HES04 300mm thick loft insulation quilt	£437.50	35.00	Sole Property Owner	05/11/2012	2012
HES06 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	05/11/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	05/11/2012	2012
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	05/11/2012	2012
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner	05/11/2012	2012
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	05/11/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatio	£125.00	5.00	Joint Owner	05/11/2012	2012
HES04 300mm thick loft insulation quilt	£150.00	12.00	Joint Owner	05/11/2012	2012
HES06 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	05/11/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	05/11/2012	2012
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	05/11/2012	2012
HES20 Low energy lamp installation	£0.00	12.00	Joint Owner	05/11/2012	2012
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	05/11/2012	2012
HES66 15mm thick pipework lagging	£6.48	2.00	Joint Owner	05/11/2012	2012
HES94 Heating engineer	£36.80	1.00	Joint Owner	05/11/2012	2012
HES66 15mm thick pipework lagging	£6.48	2.00	Joint Owner	05/11/2012	2012
HES94 Heating engineer	£73.60	2.00	Joint Owner	05/11/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatio	£125.00	5.00	Sole Property Owner	21/12/2012	2012
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner	21/12/2012	2012
HES06 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	21/12/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	21/12/2012	2012
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	21/12/2012	2012
HES20 Low energy lamp installation	£0.00	11.00	Sole Property Owner	21/12/2012	2012
HES120 Standard QA check	£102.00	1.00	Sole Property Owner	21/12/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatio	£175.00	7.00	Sole Property Owner	05/11/2012	2012
HES04 300mm thick loft insulation quilt	£300.00	24.00	Sole Property Owner	05/11/2012	2012
HES06 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	05/11/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	05/11/2012	2012
HES20 Low energy lamp installation	£0.00	8.00	Sole Property Owner	05/11/2012	2012
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	05/11/2012	2012
HES66 15mm thick pipework lagging	£3.24	1.00	Sole Property Owner	05/11/2012	2012
HES67 22mm thick pipework lagging	£4.22	1.00	Sole Property Owner	05/11/2012	2012
HES94 Heating engineer	£18.40	0.50	Sole Property Owner	05/11/2012	2012
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	19/04/2013	2013
HES48 Power / system flush and treatment	£250.00	1.00	Joint Owner	19/04/2013	2013
HES94 Heating engineer	£47.25	1.00	Joint Owner	19/04/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£51.08	51.08	Joint Owner	19/04/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£100.00	4.00	Joint Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£250.00	20.00	Joint Owner	19/04/2013	2013
HES06 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	19/04/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	19/04/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	16.00	Joint Owner	19/04/2013	2013
HES66 15mm thick pipework lagging	£9.72	3.00	Joint Owner	19/04/2013	2013
HES94 Heating engineer	£36.80	1.00	Joint Owner	19/04/2013	2013
HES48 Power / system flush and treatment	£250.00	1.00	Joint Owner	19/04/2013	2013
HES50 Electrical room thermostat	£15.75	1.00	Joint Owner	19/04/2013	2013
HES97 Electrician	£94.50	2.00	Joint Owner	19/04/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£71.65	71.65	Joint Owner	19/04/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	19/04/2013	2013
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	19/04/2013	2013
HES13 Miscellaneous items (brush, airbrick, vent etc), please pro	£47.00	1.00	Joint Owner	22/08/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£0.00	0.00	Joint Owner	22/08/2013	2013
HES40 Flue specification and location	£0.00	0.00	Joint Owner	22/08/2013	2013
HES41 Condensate pipework (and pump if required)	£0.00	0.00	Joint Owner	22/08/2013	2013
HES43 Central heating pump	£0.00	0.00	Joint Owner	22/08/2013	2013
HES44 Pipework / feed modifications	£0.00	0.00	Joint Owner	22/08/2013	2013
HES46 Automatic bypass	£0.00	0.00	Joint Owner	22/08/2013	2013
HES49 Carbon Monoxide alarm	£0.00	0.00	Joint Owner	22/08/2013	2013
HES50 Electrical room thermostat	£0.00	0.00	Joint Owner	22/08/2013	2013
HES51 Thermostatic radiator valve	£0.00	0.00	Joint Owner	22/08/2013	2013
HES52 Hot water cylinder thermostat	£0.00	0.00	Joint Owner	22/08/2013	2013
HES53 Two channel heating programmer control	£0.00	0.00	Joint Owner	22/08/2013	2013
HES55 2 port zone valve	£0.00	0.00	Joint Owner	22/08/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Joint Owner	22/08/2013	2013
HES04 300mm thick loft insulation quilt	£525.00	42.00	Joint Owner	22/08/2013	2013
HES06 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	22/08/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	22/08/2013	2013
HES20 Low energy lamp installation	£0.00	18.00	Joint Owner	22/08/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	22/08/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	22/08/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,817.37	1.00	Joint Owner	22/08/2013	2013
HES40 Flue specification and location	£532.12	1.00	Joint Owner	22/08/2013	2013
HES41 Condensate pipework (and pump if required)	£100.00	1.00	Joint Owner	22/08/2013	2013
HES42 Purpose built lime soakaway (condensate sump)	£36.23	1.00	Joint Owner	22/08/2013	2013

HES43 Central heating pump	£141.55	1.00	Joint Owner	22/08/2013	2013
HES44 Pipework / feed modifications	£612.00	1.00	Joint Owner	22/08/2013	2013
HES45 Fire valve	£42.32	1.00	Joint Owner	22/08/2013	2013
HES46 Automatic bypass	£46.32	1.00	Joint Owner	22/08/2013	2013
HES49 Carbon Monoxide alarm	£0.00	0.00	Joint Owner	22/08/2013	2013
HES50 Electrical room thermostat	£53.32	1.00	Joint Owner	22/08/2013	2013
HES52 Hot water cylinder thermostat	£0.00	0.00	Joint Owner	22/08/2013	2013
HES53 Two channel heating programmer control	£85.11	1.00	Joint Owner	22/08/2013	2013
HES54 Water heating time clock and boost controller	£92.95	1.00	Joint Owner	22/08/2013	2013
HES67 22mm thick pipework lagging	£104.70	30.00	Joint Owner	22/08/2013	2013
HES68 28mm thick pipework lagging	£75.20	20.00	Joint Owner	22/08/2013	2013
HES94 Heating engineer	£1,824.00	48.00	Joint Owner	22/08/2013	2013
HES97 Electrician	£300.00	12.00	Joint Owner	22/08/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	22/08/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£38.00	1.00	Joint Owner	22/08/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£150.00	1.00	Joint Owner	22/08/2013	2013
HES101 Asbestos removal & disposal	£450.00	450.00	Joint Owner	22/08/2013	2013
HES55 2 port zone valve	£138.56	2.00	Joint Owner	22/08/2013	2013
HES101 Asbestos removal & disposal	£1,800.00	1.00	Joint Owner	22/08/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£25.00	1.00	Joint Owner	22/08/2013	2013
HES66 15mm thick pipework lagging	£16.20	5.00	Joint Owner	22/08/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Joint Owner	22/08/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	22/08/2013	2013
HES51 Thermostatic radiator valve	£360.80	8.00	Joint Owner	22/08/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£86.03	1.00	Joint Owner	22/08/2013	2013
HES120 Standard QA check	£0.00	1.00	Joint Owner	22/08/2013	2013
EES01a Loft Clearance (hourly rate)	£187.20	8.00	Sole Property Owner	01/11/2009	2009
EES07 200mm thick loft insulation	£924.94	103.00	Sole Property Owner	01/11/2009	2009
EES03a Remove and replace nailed floor board	£267.80	103.00	Sole Property Owner	01/11/2009	2009
EES38a Thermostatic radiator valve (per valve)	£231.35	7.00	Sole Property Owner	01/11/2009	2009
EES47 Pipework lagging 13mm thick to 22mm pipe	£80.90	10.00	Sole Property Owner	01/11/2009	2009
EES48 Pipework lagging 19mm thick to 22mm pipe	£92.20	10.00	Sole Property Owner	01/11/2009	2009
EES10 Cold water tank insulation quilt	£64.89	1.00	Sole Property Owner	01/11/2009	2009
EES66 Low energy lamp replacement	£125.07	11.00	Sole Property Owner	01/11/2009	2009
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	01/11/2009	2009
EES10 Cold water tank insulation quilt	£51.12	1.00	Sole Property Owner	01/11/2009	2009
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	01/11/2009	2009
HES01 Loft preparation labour (clearance, disposal of old insulatic	£525.00	21.00	Joint Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£750.00	60.00	Joint Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Joint Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	28/11/2013	2013
HES53 Two channel heating programmer control	£33.80	1.00	Joint Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£153.40	1.00	Joint Owner	28/11/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Joint Owner	28/11/2013	2013
HES45 Fire valve	£36.90	1.00	Joint Owner	28/11/2013	2013
HES46 Automatic bypass	£27.50	1.00	Joint Owner	28/11/2013	2013
HES48 Power / system flush and treatment	£43.80	1.00	Joint Owner	28/11/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	28/11/2013	2013
HES50 Electrical room thermostat	£13.45	1.00	Joint Owner	28/11/2013	2013
HES51 Thermostatic radiator valve	£90.30	7.00	Joint Owner	28/11/2013	2013
HES52 Hot water cylinder thermostat	£29.60	2.00	Joint Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£0.00	0.00	Joint Owner	28/11/2013	2013
HES61 Hot water cylinder jacket (46 x 18 inch)	£56.46	2.00	Joint Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£12.88	8.00	Joint Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£39.60	20.00	Joint Owner	28/11/2013	2013
HES68 28mm thick pipework lagging	£38.56	16.00	Joint Owner	28/11/2013	2013
HES95 Senior heating engineer	£910.00	26.00	Joint Owner	28/11/2013	2013
HES98 Senior electrician	£280.00	8.00	Joint Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£173.36	173.36	Joint Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£75.00	3.00	Sole Property Owner	05/11/2012	2012
HES03 200mm thick loft insulation quilt	£342.00	36.00	Sole Property Owner	05/11/2012	2012
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	05/11/2012	2012
HES20 Low energy lamp installation	£0.00	57.00	Sole Property Owner	05/11/2012	2012
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	05/11/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£750.00	3.00	Sole Property Owner	05/11/2012	2012
HES66 15mm thick pipework lagging	£3.24	1.00	Sole Property Owner	05/11/2012	2012
HES67 22mm thick pipework lagging	£4.22	1.00	Sole Property Owner	05/11/2012	2012
HES94 Heating engineer	£27.60	0.75	Sole Property Owner	05/11/2012	2012
HES20 Low energy lamp installation	£0.00	12.00	Sole Property Owner	05/11/2012	2012
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	05/11/2012	2012
HES65 Stainless steel replacement hot water cylinder (210L)	£349.20	1.00	Not The Property Owner		0
HES67 22mm thick pipework lagging	£17.60	4.00	Not The Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£62.40	1.00	Not The Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£100.00	4.00	Not The Property Owner		0
HES03 200mm thick loft insulation quilt	£1,045.00	110.00	Not The Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£883.20	92.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	25.00	Not The Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner		0
HES64 Stainless steel replacement hot water cylinder (170L)	£0.00	0.00	Not The Property Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Not The Property Owner		0
HES93 Junior heating engineer	£0.00	0.00	Not The Property Owner		0
HES94 Heating engineer	£190.00	5.00	Not The Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£125.00	5.00	Joint Owner	24/01/2013	2013

HES03 200mm thick loft insulation quilt	£66.50	7.00	Joint Owner	24/01/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Joint Owner	24/01/2013	2013
HES71 Storage heater rated 1kW - 2kW	£244.53	1.00	Joint Owner	24/01/2013	2013
HES72 Storage heater rated 2kW - 3kW	£308.49	1.00	Joint Owner	24/01/2013	2013
HES97 Electrician	£176.00	5.50	Joint Owner	24/01/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£221.33	1.00	Joint Owner	24/01/2013	2013
HES10 CIGA approved cavity wall insulation to 65mm wide cavity	£0.00	0.00	Joint Owner	24/01/2013	2013
HES04 300mm thick loft insulation quilt	£75.00	6.00	Not The Property Owner	03/07/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£499.20	52.00	Not The Property Owner	03/07/2013	2013
HES20 Low energy lamp installation	£0.00	3.00	Not The Property Owner	03/07/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Not The Property Owner	03/07/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	03/07/2013	2013
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	03/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£25.00	1.00	Not The Property Owner	03/07/2013	2013
HES93 Junior heating engineer	£100.00	4.00	Not The Property Owner	03/07/2013	2013
HES94 Heating engineer	£152.00	4.00	Not The Property Owner	03/07/2013	2013
HES13 Miscellaneous items (brush, airbrick, vent etc), please pro	£62.54	1.00	Not The Property Owner	03/07/2013	2013
HES120 Standard QA check	£0.00	1.00	Not The Property Owner	03/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£850.00	34.00	Sole Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£875.00	70.00	Sole Property Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	28/11/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	14.00	Sole Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES40 Flue specification and location	£461.80	1.00	Sole Property Owner	28/11/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£422.50	1.00	Sole Property Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£92.00	2.50	Sole Property Owner	28/11/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	28/11/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£1,476.28	1.00	Sole Property Owner	28/11/2013	2013
HES43 Central heating pump	£141.55	1.00	Sole Property Owner	28/11/2013	2013
HES44 Pipework / feed modifications	£200.00	1.00	Sole Property Owner	28/11/2013	2013
HES46 Automatic bypass	£46.32	1.00	Sole Property Owner	28/11/2013	2013
HES49 Carbon Monoxide alarm	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES50 Electrical room thermostat	£53.32	1.00	Sole Property Owner	28/11/2013	2013
HES51 Thermostatic radiator valve	£451.00	10.00	Sole Property Owner	28/11/2013	2013
HES53 Two channel heating programmer control	£85.11	1.00	Sole Property Owner	28/11/2013	2013
HES55 2 port zone valve	£69.28	1.00	Sole Property Owner	28/11/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£435.60	1.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£69.80	20.00	Sole Property Owner	28/11/2013	2013
HES68 28mm thick pipework lagging	£75.20	20.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£1,520.00	40.00	Sole Property Owner	28/11/2013	2013
HES97 Electrician	£200.00	8.00	Sole Property Owner	28/11/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£38.00	1.00	Sole Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£625.00	25.00	Sole Property Owner	20/02/2013	2013
HES04 300mm thick loft insulation quilt	£1,250.00	100.00	Sole Property Owner	20/02/2013	2013
HES06 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	20/02/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	20/02/2013	2013
HES10 CIGA approved cavity wall insulation to 65mm wide cavity	£0.00	0.00	Sole Property Owner	20/02/2013	2013
HES03 200mm thick loft insulation quilt	£285.00	30.00	Sole Property Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner	20/02/2013	2013
HES97 Electrician	£400.00	16.00	Sole Property Owner	01/03/2013	2013
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Sole Property Owner	01/03/2013	2013
HES73 Storage heater rated 3kW - 4kW	£833.64	2.00	Sole Property Owner	01/03/2013	2013
HES76 Storage heater miniature circuit breaker	£16.02	3.00	Sole Property Owner	01/03/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£100.00	4.00	Sole Property Owner	01/03/2013	2013
HES04 300mm thick loft insulation quilt	£525.00	42.00	Sole Property Owner	01/03/2013	2013
HES06 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	01/03/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	01/03/2013	2013
HES20 Low energy lamp installation	£0.00	8.00	Sole Property Owner	01/03/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	01/03/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£150.00	6.00	Joint Owner	05/11/2012	2012
HES03 200mm thick loft insulation quilt	£95.00	10.00	Joint Owner	05/11/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	05/11/2012	2012
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	05/11/2012	2012
HES20 Low energy lamp installation	£0.00	3.00	Joint Owner	05/11/2012	2012
HES97 Electrician	£425.00	17.00	Sole Property Owner	01/03/2013	2013
HES94 Heating engineer	£304.00	8.00	Sole Property Owner	01/03/2013	2013
HES73 Storage heater rated 3kW - 4kW	£833.64	2.00	Sole Property Owner	01/03/2013	2013
HES76 Storage heater miniature circuit breaker	£21.36	4.00	Sole Property Owner	01/03/2013	2013
HES65 Stainless steel replacement hot water cylinder (210L)	£590.12	1.00	Sole Property Owner	01/03/2013	2013
HES67 22mm thick pipework lagging	£34.90	10.00	Sole Property Owner	01/03/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£225.00	9.00	Sole Property Owner	01/03/2013	2013
HES04 300mm thick loft insulation quilt	£512.50	41.00	Sole Property Owner	01/03/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	01/03/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,382.40	144.00	Sole Property Owner	01/03/2013	2013
HES20 Low energy lamp installation	£0.00	26.00	Sole Property Owner	01/03/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	01/03/2013	2013
HES94 Heating engineer	£27.60	0.75	Sole Property Owner	01/03/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	01/03/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	01/03/2013	2013

EES08 300mm thick loft insulation	£353.60	34.00	Not The Property Owner	10/09/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Not The Property Owner	10/09/2010	2010
EES00a Full Energy Survey	£246.55	1.00	Not The Property Owner	10/09/2010	2010
HES20 Low energy lamp installation	£0.00	4.00	Sole Property Owner	20/02/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	20/02/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£1,800.00	1.00	Sole Property Owner	20/02/2013	2013
HES40 Flue specification and location	£209.30	1.00	Sole Property Owner	20/02/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Sole Property Owner	20/02/2013	2013
HES44 Pipework / feed modifications	£276.00	1.00	Sole Property Owner	20/02/2013	2013
HES45 Fire valve	£48.00	1.00	Sole Property Owner	20/02/2013	2013
HES47 Frost thermostat	£24.00	1.00	Sole Property Owner	20/02/2013	2013
HES48 Power / system flush and treatment	£480.00	1.00	Sole Property Owner	20/02/2013	2013
HES49 Carbon Monoxide alarm	£42.00	1.00	Sole Property Owner	20/02/2013	2013
HES50 Electrical room thermostat	£22.80	1.00	Sole Property Owner	20/02/2013	2013
HES51 Thermostatic radiator valve	£182.40	8.00	Sole Property Owner	20/02/2013	2013
HES53 Two channel heating programmer control	£78.00	1.00	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£33.80	10.00	Sole Property Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£17.60	4.00	Sole Property Owner	20/02/2013	2013
HES93 Junior heating engineer	£50.00	2.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£1,064.00	28.00	Sole Property Owner	20/02/2013	2013
HES95 Senior heating engineer	£78.00	2.00	Sole Property Owner	20/02/2013	2013
HES98 Senior electrician	£195.00	5.00	Sole Property Owner	20/02/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£1,255.57	1.00	Sole Property Owner	20/02/2013	2013
HES92 Other miscellaneous electrical heating works for EES approval	£223.33	1.00	Sole Property Owner	20/02/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	20/02/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£1,725.00	1.00	Sole Property Owner	18/04/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Sole Property Owner	18/04/2013	2013
HES44 Pipework / feed modifications	£322.00	1.00	Sole Property Owner	18/04/2013	2013
HES45 Fire valve	£46.00	1.00	Sole Property Owner	18/04/2013	2013
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner	18/04/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	18/04/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	18/04/2013	2013
HES51 Thermostatic radiator valve	£218.50	10.00	Sole Property Owner	18/04/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	18/04/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	18/04/2013	2013
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	18/04/2013	2013
HES66 15mm thick pipework lagging	£12.96	4.00	Sole Property Owner	18/04/2013	2013
HES67 22mm thick pipework lagging	£42.20	10.00	Sole Property Owner	18/04/2013	2013
HES68 28mm thick pipework lagging	£18.16	4.00	Sole Property Owner	18/04/2013	2013
HES93 Junior heating engineer	£87.88	4.00	Sole Property Owner	18/04/2013	2013
HES94 Heating engineer	£1,324.80	36.00	Sole Property Owner	18/04/2013	2013
HES95 Senior heating engineer	£158.72	4.00	Sole Property Owner	18/04/2013	2013
HES98 Senior electrician	£396.80	10.00	Sole Property Owner	18/04/2013	2013
HES99 Building works	£58.66	2.00	Sole Property Owner	18/04/2013	2013
HES87 Commissioning and issue of CD10 and Building Control notice	£0.00	1.00	Sole Property Owner	18/04/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	18/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£1,130.15	1.00	Sole Property Owner	18/04/2013	2013
HES101 Asbestos removal & disposal	£520.00	1.00	Sole Property Owner	18/04/2013	2013
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Sole Property Owner	18/04/2013	2013
EES02a Remove and dispose existing insulation (per square metre)	£105.00	35.00	Sole Property Owner	18/04/2013	2013
EES03a Remove and replace nailed floor board	£15.00	5.00	Sole Property Owner	18/04/2013	2013
EES08 300mm thick loft insulation	£420.00	35.00	Sole Property Owner	18/04/2013	2013
EES66 Low energy lamp replacement	£0.00	20.00	Sole Property Owner	18/04/2013	2013
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	18/04/2013	2013
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	18/04/2013	2013
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	18/04/2013	2013
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	18/04/2013	2013
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	18/04/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	18/04/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	18/04/2013	2013
HES94 Heating engineer	£18.40	0.50	Sole Property Owner	18/04/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	18/04/2013	2013
HES17 Draught stripping to letter boxes	£12.00	1.00	Sole Property Owner	18/04/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	18/04/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulation)	£200.00	8.00	Sole Property Owner	20/02/2013	2013
HES04 300mm thick loft insulation quilt	£375.00	30.00	Sole Property Owner	20/02/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	18.00	Sole Property Owner	20/02/2013	2013
HES44 Pipework / feed modifications	£178.25	1.00	Sole Property Owner	20/02/2013	2013
HES51 Thermostatic radiator valve	£22.80	1.00	Sole Property Owner	20/02/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£13.52	4.00	Sole Property Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£44.00	10.00	Sole Property Owner	20/02/2013	2013
HES93 Junior heating engineer	£75.00	3.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£418.00	11.00	Sole Property Owner	20/02/2013	2013
HES95 Senior heating engineer	£78.00	2.00	Sole Property Owner	20/02/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£36.91	36.91	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Sole Property Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	20/02/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulation)	£125.00	5.00	Joint Owner	27/02/2013	2013
HES04 300mm thick loft insulation quilt	£600.00	48.00	Joint Owner	27/02/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	27/02/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£854.40	89.00	Joint Owner	27/02/2013	2013

HES20 Low energy lamp installation	£0.00	13.00	Joint Owner	27/02/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	27/02/2013	2013
HES44 Pipework / feed modifications	£126.50	1.00	Joint Owner	27/02/2013	2013
HES51 Thermostatic radiator valve	£174.80	8.00	Joint Owner	27/02/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Joint Owner	27/02/2013	2013
HES66 15mm thick pipework lagging	£45.36	14.00	Joint Owner	27/02/2013	2013
HES67 22mm thick pipework lagging	£50.64	12.00	Joint Owner	27/02/2013	2013
HES68 28mm thick pipework lagging	£27.24	6.00	Joint Owner	27/02/2013	2013
HES93 Junior heating engineer	£87.88	4.00	Joint Owner	27/02/2013	2013
HES94 Heating engineer	£588.80	16.00	Joint Owner	27/02/2013	2013
HES95 Senior heating engineer	£79.36	2.00	Joint Owner	27/02/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£588.55	588.55	Joint Owner	27/02/2013	2013
HES72 Storage heater rated 2kW - 3kW	£616.98	2.00	Sole Property Owner	24/01/2013	2013
HES73 Storage heater rated 3kW - 4kW	£375.34	1.00	Sole Property Owner	24/01/2013	2013
HES97 Electrician	£384.00	12.00	Sole Property Owner	24/01/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£125.00	5.00	Sole Property Owner	24/01/2013	2013
HES04 300mm thick loft insulation quilt	£525.00	42.00	Sole Property Owner	24/01/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	24/01/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	24/01/2013	2013
HES20 Low energy lamp installation	£0.00	16.00	Sole Property Owner	24/01/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	24/01/2013	2013
HES71 Storage heater rated 1kW - 2kW	£244.53	1.00	Sole Property Owner	24/01/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£25.00	1.00	Sole Property Owner	20/02/2013	2013
HES72 Storage heater rated 2kW - 3kW	£925.47	3.00	Sole Property Owner	20/02/2013	2013
HES74 Comfort heat main switch	£57.20	1.00	Sole Property Owner	20/02/2013	2013
HES75 Storage heater consumer unit	£49.40	1.00	Sole Property Owner	20/02/2013	2013
HES76 Storage heater miniature circuit breaker	£39.00	4.00	Sole Property Owner	20/02/2013	2013
HES77 Main bonding of necessary services	£163.50	15.00	Sole Property Owner	20/02/2013	2013
HES78 Twin and earth 16mm cabling with clips and trunking	£130.69	7.00	Sole Property Owner	20/02/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£152.84	1.00	Sole Property Owner	20/02/2013	2013
HES80 16mm meter tails	£12.48	1.00	Sole Property Owner	20/02/2013	2013
HES83 Trunking	£19.28	2.00	Sole Property Owner	20/02/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£231.60	1.00	Sole Property Owner	20/02/2013	2013
HES97 Electrician	£832.00	26.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£192.00	6.00	Sole Property Owner	20/02/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£426.36	1.00	Sole Property Owner	20/02/2013	2013
HES03 200mm thick loft insulation quilt	£551.00	58.00	Sole Property Owner	20/02/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	20/02/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	20/02/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Sole Property Owner	20/02/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£29.16	9.00	Sole Property Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£55.20	1.50	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£29.16	9.00	Sole Property Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£73.60	2.00	Sole Property Owner	20/02/2013	2013
EES06 100mm thick loft insulation	£336.00	56.00	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£25.00	1.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	29/01/2010	2010
EES03a Remove and replace nailed floor board	£35.40	3.00	Sole Property Owner	01/02/2010	2010
EES07 200mm thick loft insulation	£418.77	47.00	Sole Property Owner	01/02/2010	2010
EES66 Low energy lamp replacement	£19.25	11.00	Sole Property Owner	01/02/2010	2010
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	01/02/2010	2010
EES44 Water heating time clock and boost	£134.21	1.00	Sole Property Owner	01/02/2010	2010
HES01 Loft preparation labour (clearance, disposal of old insulatic	£450.00	18.00	Sole Property Owner	23/11/2012	2012
HES04 300mm thick loft insulation quilt	£812.50	65.00	Sole Property Owner	23/11/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	23/11/2012	2012
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£220.80	23.00	Sole Property Owner	23/11/2012	2012
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	23/11/2012	2012
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	23/11/2012	2012
HES66 15mm thick pipework lagging	£45.36	14.00	Sole Property Owner	23/11/2012	2012
HES67 22mm thick pipework lagging	£37.98	9.00	Sole Property Owner	23/11/2012	2012
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	23/11/2012	2012
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	19.00	Sole Property Owner	20/02/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	20/02/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	20/02/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£1,725.00	1.00	Sole Property Owner	20/02/2013	2013
HES40 Flue specification and location	£403.83	1.00	Sole Property Owner	20/02/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Sole Property Owner	20/02/2013	2013
HES43 Central heating pump	£92.00	1.00	Sole Property Owner	20/02/2013	2013
HES44 Pipework / feed modifications	£278.07	1.00	Sole Property Owner	20/02/2013	2013
HES45 Fire valve	£46.00	1.00	Sole Property Owner	20/02/2013	2013
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner	20/02/2013	2013
HES47 Frost thermostat	£23.00	1.00	Sole Property Owner	20/02/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	20/02/2013	2013
HES49 Carbon Monoxide alarm	£42.00	1.00	Sole Property Owner	20/02/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	20/02/2013	2013
HES51 Thermostatic radiator valve	£43.70	2.00	Sole Property Owner	20/02/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	20/02/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	20/02/2013	2013
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	20/02/2013	2013

HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Sole Property Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£25.32	6.00	Sole Property Owner	20/02/2013	2013
HES68 28mm thick pipework lagging	£9.08	2.00	Sole Property Owner	20/02/2013	2013
HES93 Junior heating engineer	£87.88	4.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£1,177.60	32.00	Sole Property Owner	20/02/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	20/02/2013	2013
HES98 Senior electrician	£396.80	10.00	Sole Property Owner	20/02/2013	2013
HES99 Building works	£87.99	3.00	Sole Property Owner	20/02/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	20/02/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	20/02/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£437.00	1.00	Sole Property Owner	20/02/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£656.87	656.87	Sole Property Owner	20/02/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	20/02/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Joint Owner	01/03/2013	2013
HES03 200mm thick loft insulation quilt	£465.50	49.00	Joint Owner	01/03/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£633.60	66.00	Joint Owner	01/03/2013	2013
HES20 Low energy lamp installation	£0.00	22.00	Joint Owner	01/03/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	01/03/2013	2013
HES44 Pipework / feed modifications	£115.00	1.00	Joint Owner	01/03/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Joint Owner	01/03/2013	2013
HES66 15mm thick pipework lagging	£6.76	2.00	Joint Owner	01/03/2013	2013
HES67 22mm thick pipework lagging	£8.80	2.00	Joint Owner	01/03/2013	2013
HES93 Junior heating engineer	£25.00	1.00	Joint Owner	01/03/2013	2013
HES94 Heating engineer	£228.00	6.00	Joint Owner	01/03/2013	2013
HES95 Senior heating engineer	£39.00	1.00	Joint Owner	01/03/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£587.36	587.36	Joint Owner	01/03/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	19/10/2012	2012
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	19/10/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	19/10/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	19/10/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/03/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	30/03/2012	2012
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,084.80	113.00	Joint Owner	01/03/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,817.37	1.00	Joint Owner	01/03/2013	2013
HES40 Flue specification and location	£1,080.00	1,080.00	Joint Owner	01/03/2013	2013
HES41 Condensate pipework (and pump if required)	£150.00	1.00	Joint Owner	01/03/2013	2013
HES42 Purpose built lime soakaway (condensate sump)	£36.23	1.00	Joint Owner	01/03/2013	2013
HES43 Central heating pump	£141.55	1.00	Joint Owner	01/03/2013	2013
HES44 Pipework / feed modifications	£274.00	1.00	Joint Owner	01/03/2013	2013
HES46 Automatic bypass	£46.32	1.00	Joint Owner	01/03/2013	2013
HES49 Carbon Monoxide alarm	£85.35	1.00	Joint Owner	01/03/2013	2013
HES51 Thermostatic radiator valve	£270.60	6.00	Joint Owner	01/03/2013	2013
HES52 Hot water cylinder thermostat	£33.21	1.00	Joint Owner	01/03/2013	2013
HES53 Two channel heating programmer control	£85.11	1.00	Joint Owner	01/03/2013	2013
HES55 2 port zone valve	£138.56	2.00	Joint Owner	01/03/2013	2013
HES65 Stainless steel replacement hot water cylinder (210L)	£590.12	1.00	Joint Owner	01/03/2013	2013
HES67 22mm thick pipework lagging	£52.35	15.00	Joint Owner	01/03/2013	2013
HES68 28mm thick pipework lagging	£75.20	20.00	Joint Owner	01/03/2013	2013
HES94 Heating engineer	£1,596.00	42.00	Joint Owner	01/03/2013	2013
HES97 Electrician	£150.00	6.00	Joint Owner	01/03/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	01/03/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£38.00	1.00	Joint Owner	01/03/2013	2013
HES23 Scaffold / cherry picker	£500.00	500.00	Joint Owner	01/03/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	01/03/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£275.00	11.00	Joint Owner	01/03/2013	2013
HES04 300mm thick loft insulation quilt	£650.00	52.00	Joint Owner	01/03/2013	2013
HES06 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	01/03/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	01/03/2013	2013
HES10 CIGA approved cavity wall insulation to 65mm wide cavity	£0.00	0.00	Joint Owner	01/03/2013	2013
HES20 Low energy lamp installation	£0.00	15.00	Joint Owner	01/03/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	01/03/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Joint Owner	01/03/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Joint Owner	01/03/2013	2013
HES94 Heating engineer	£18.40	0.50	Joint Owner	01/03/2013	2013
HES54 Water heating time clock and boost controller	£0.00	0.00	Joint Owner	01/03/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	21/12/2012	2012
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	21/12/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	21/12/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	21/12/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	05/11/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatio	£150.00	6.00	Joint Owner	05/11/2012	2012
HES03 200mm thick loft insulation quilt	£427.50	45.00	Joint Owner	05/11/2012	2012
HES20 Low energy lamp installation	£0.00	24.00	Joint Owner	05/11/2012	2012
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	05/11/2012	2012
HES66 15mm thick pipework lagging	£26.90	10.00	Joint Owner	05/11/2012	2012
HES94 Heating engineer	£1,216.00	32.00	Joint Owner	05/11/2012	2012
HES97 Electrician	£250.00	10.00	Joint Owner	05/11/2012	2012
HES87 Commissioning and issue of CD10 and Building Control no	£38.00	1.00	Joint Owner	05/11/2012	2012
HES33 26-35kW Oil replacement condensing boiler	£1,817.37	1.00	Joint Owner	05/11/2012	2012
HES43 Central heating pump	£141.55	1.00	Joint Owner	05/11/2012	2012
HES45 Fire valve	£0.00	0.00	Joint Owner	05/11/2012	2012
HES46 Automatic bypass	£46.32	1.00	Joint Owner	05/11/2012	2012
HES48 Power / system flush and treatment	£38.00	1.00	Joint Owner	05/11/2012	2012

HES50 Electrical room thermostat	£53.32	1.00	Joint Owner	05/11/2012	2012
HES53 Two channel heating programmer control	£85.11	1.00	Joint Owner	05/11/2012	2012
HES55 2 port zone valve	£138.56	2.00	Joint Owner	05/11/2012	2012
HES67 22mm thick pipework lagging	£69.80	20.00	Joint Owner	05/11/2012	2012
HES41 Condensate pipework (and pump if required)	£100.00	1.00	Joint Owner	05/11/2012	2012
HES44 Pipework / feed modifications	£240.00	1.00	Joint Owner	05/11/2012	2012
HES88 Commissioning and issue of CD11 and flue gas analysis	£0.00	1.00	Joint Owner	05/11/2012	2012
HES40 Flue specification and location	£461.12	1.00	Joint Owner	05/11/2012	2012
HES49 Carbon Monoxide alarm	£85.35	1.00	Joint Owner	05/11/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulation)	£425.00	17.00	Sole Property Owner	03/07/2013	2013
HES04 300mm thick loft insulation quilt	£1,125.00	90.00	Sole Property Owner	03/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	03/07/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£288.00	30.00	Sole Property Owner	03/07/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	03/07/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	03/07/2013	2013
HES20 Low energy lamp installation	£0.00	8.00	Sole Property Owner	03/07/2013	2013
HES66 15mm thick pipework lagging	£3.24	1.00	Sole Property Owner	03/07/2013	2013
HES68 28mm thick pipework lagging	£13.62	3.00	Sole Property Owner	03/07/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	03/07/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£1,725.00	1.00	Sole Property Owner	03/07/2013	2013
HES40 Flue specification and location	£1,253.94	1.00	Sole Property Owner	03/07/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Sole Property Owner	03/07/2013	2013
HES43 Central heating pump	£92.00	1.00	Sole Property Owner	03/07/2013	2013
HES44 Pipework / feed modifications	£260.00	1.00	Sole Property Owner	03/07/2013	2013
HES45 Fire valve	£0.00	0.00	Sole Property Owner	03/07/2013	2013
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner	03/07/2013	2013
HES47 Frost thermostat	£23.00	1.00	Sole Property Owner	03/07/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	03/07/2013	2013
HES49 Carbon Monoxide alarm	£42.00	1.00	Sole Property Owner	03/07/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	03/07/2013	2013
HES51 Thermostatic radiator valve	£196.65	9.00	Sole Property Owner	03/07/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	03/07/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	03/07/2013	2013
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	03/07/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Sole Property Owner	03/07/2013	2013
HES67 22mm thick pipework lagging	£33.76	8.00	Sole Property Owner	03/07/2013	2013
HES93 Junior heating engineer	£43.94	2.00	Sole Property Owner	03/07/2013	2013
HES94 Heating engineer	£1,840.00	50.00	Sole Property Owner	03/07/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	03/07/2013	2013
HES98 Senior electrician	£396.80	10.00	Sole Property Owner	03/07/2013	2013
HES99 Building works	£58.66	2.00	Sole Property Owner	03/07/2013	2013
HES87 Commissioning and issue of CD10 and Building Control notice	£0.00	1.00	Sole Property Owner	03/07/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	03/07/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£345.00	1.00	Sole Property Owner	03/07/2013	2013
HES92 Other miscellaneous electrical heating works for EES approval	£395.21	1.00	Sole Property Owner	03/07/2013	2013
HES92 Other miscellaneous electrical heating works for EES approval	£146.91	1.00	Sole Property Owner	03/07/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	03/07/2013	2013
HES68 28mm thick pipework lagging	£13.62	3.00	Sole Property Owner	03/07/2013	2013
HES120 Standard QA check	£0.00	1.00	Sole Property Owner	03/07/2013	2013
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Not The Property Owner	01/11/2009	2009
EES00a Full Energy Survey	£401.68	1.00	Not The Property Owner	01/11/2009	2009
HES01 Loft preparation labour (clearance, disposal of old insulation)	£175.00	7.00	Sole Property Owner	03/07/2013	2013
HES04 300mm thick loft insulation quilt	£500.00	40.00	Sole Property Owner	03/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	03/07/2013	2013
HES20 Low energy lamp installation	£0.00	7.00	Sole Property Owner	03/07/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	03/07/2013	2013
HES44 Pipework / feed modifications	£178.25	1.00	Sole Property Owner	03/07/2013	2013
HES51 Thermostatic radiator valve	£45.60	2.00	Sole Property Owner	03/07/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Sole Property Owner	03/07/2013	2013
HES66 15mm thick pipework lagging	£40.56	12.00	Sole Property Owner	03/07/2013	2013
HES67 22mm thick pipework lagging	£35.20	8.00	Sole Property Owner	03/07/2013	2013
HES93 Junior heating engineer	£125.00	5.00	Sole Property Owner	03/07/2013	2013
HES94 Heating engineer	£456.00	12.00	Sole Property Owner	03/07/2013	2013
HES95 Senior heating engineer	£78.00	2.00	Sole Property Owner	03/07/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£26.34	26.34	Sole Property Owner	03/07/2013	2013
HES68 28mm thick pipework lagging	£37.92	8.00	Sole Property Owner	03/07/2013	2013
HES120 Standard QA check	£0.00	1.00	Sole Property Owner	03/07/2013	2013
HES20 Low energy lamp installation	£0.00	7.00	Joint Owner	31/07/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	31/07/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Joint Owner	31/07/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£1,800.00	1.00	Joint Owner	31/07/2013	2013
HES40 Flue specification and location	£1,492.51	1.00	Joint Owner	31/07/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Joint Owner	31/07/2013	2013
HES43 Central heating pump	£96.00	1.00	Joint Owner	31/07/2013	2013
HES44 Pipework / feed modifications	£260.00	1.00	Joint Owner	31/07/2013	2013
HES45 Fire valve	£48.00	1.00	Joint Owner	31/07/2013	2013
HES46 Automatic bypass	£32.40	1.00	Joint Owner	31/07/2013	2013
HES48 Power / system flush and treatment	£480.00	1.00	Joint Owner	31/07/2013	2013
HES50 Electrical room thermostat	£22.80	1.00	Joint Owner	31/07/2013	2013
HES51 Thermostatic radiator valve	£0.00	8.00	Joint Owner	31/07/2013	2013
HES53 Two channel heating programmer control	£78.00	1.00	Joint Owner	31/07/2013	2013
HES55 2 port zone valve	£136.80	2.00	Joint Owner	31/07/2013	2013
HES66 15mm thick pipework lagging	£20.28	6.00	Joint Owner	31/07/2013	2013
HES67 22mm thick pipework lagging	£26.40	6.00	Joint Owner	31/07/2013	2013

HES93 Junior heating engineer	£75.00	3.00	Joint Owner	31/07/2013	2013
HES94 Heating engineer	£1,900.00	50.00	Joint Owner	31/07/2013	2013
HES95 Senior heating engineer	£117.00	3.00	Joint Owner	31/07/2013	2013
HES98 Senior electrician	£390.00	10.00	Joint Owner	31/07/2013	2013
HES99 Building works	£90.00	3.00	Joint Owner	31/07/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	31/07/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£96.00	1.00	Joint Owner	31/07/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£57.50	1.00	Joint Owner	31/07/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£361.38	1.00	Joint Owner	31/07/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	31/07/2013	2013
HES68 28mm thick pipework lagging	£36.32	8.00	Joint Owner	31/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£100.00	4.00	Joint Owner	12/02/2013	2013
HES03 200mm thick loft insulation quilt	£332.50	35.00	Joint Owner	12/02/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	12/02/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,948.80	203.00	Joint Owner	12/02/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner	12/02/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	12/02/2013	2013
HES20 Low energy lamp installation	£0.00	20.00	Joint Owner	12/02/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	12/02/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Joint Owner	12/02/2013	2013
HES40 Flue specification and location	£209.30	1.00	Joint Owner	12/02/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Joint Owner	12/02/2013	2013
HES43 Central heating pump	£92.00	1.00	Joint Owner	12/02/2013	2013
HES44 Pipework / feed modifications	£276.34	1.00	Joint Owner	12/02/2013	2013
HES45 Fire valve	£46.00	1.00	Joint Owner	12/02/2013	2013
HES46 Automatic bypass	£31.05	1.00	Joint Owner	12/02/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Joint Owner	12/02/2013	2013
HES49 Carbon Monoxide alarm	£42.00	1.00	Joint Owner	12/02/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Joint Owner	12/02/2013	2013
HES51 Thermostatic radiator valve	£240.35	11.00	Joint Owner	12/02/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Joint Owner	12/02/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Joint Owner	12/02/2013	2013
HES55 2 port zone valve	£131.10	2.00	Joint Owner	12/02/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£304.80	1.00	Joint Owner	12/02/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Joint Owner	12/02/2013	2013
HES67 22mm thick pipework lagging	£42.20	10.00	Joint Owner	12/02/2013	2013
HES68 28mm thick pipework lagging	£36.32	8.00	Joint Owner	12/02/2013	2013
HES93 Junior heating engineer	£109.85	5.00	Joint Owner	12/02/2013	2013
HES94 Heating engineer	£1,288.00	35.00	Joint Owner	12/02/2013	2013
HES95 Senior heating engineer	£158.72	4.00	Joint Owner	12/02/2013	2013
HES98 Senior electrician	£396.80	10.00	Joint Owner	12/02/2013	2013
HES99 Building works	£146.65	5.00	Joint Owner	12/02/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	12/02/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Joint Owner	12/02/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£379.50	1.00	Joint Owner	12/02/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£582.84	582.84	Joint Owner	12/02/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	12/02/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£475.00	19.00	Sole Property Owner	01/03/2013	2013
HES04 300mm thick loft insulation quilt	£787.50	63.00	Sole Property Owner	01/03/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner	01/03/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	01/03/2013	2013
HES94 Heating engineer	£304.00	8.00	Sole Property Owner	01/03/2013	2013
HES97 Electrician	£425.00	17.00	Sole Property Owner	01/03/2013	2013
HES71 Storage heater rated 1kW - 2kW	£534.64	2.00	Sole Property Owner	01/03/2013	2013
HES72 Storage heater rated 2kW - 3kW	£684.46	2.00	Sole Property Owner	01/03/2013	2013
HES76 Storage heater miniature circuit breaker	£21.36	4.00	Sole Property Owner	01/03/2013	2013
HES65 Stainless steel replacement hot water cylinder (210L)	£590.12	1.00	Sole Property Owner	01/03/2013	2013
HES67 22mm thick pipework lagging	£34.90	10.00	Sole Property Owner	01/03/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	01/03/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	01/03/2013	2013
HES94 Heating engineer	£18.40	0.50	Sole Property Owner	01/03/2013	2013
HES03 200mm thick loft insulation quilt	£665.00	70.00	Joint Owner	16/05/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,411.20	147.00	Joint Owner	16/05/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Joint Owner	16/05/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	16/05/2013	2013
HES72 Storage heater rated 2kW - 3kW	£684.46	2.00	Joint Owner	16/05/2013	2013
HES73 Storage heater rated 3kW - 4kW	£833.64	2.00	Joint Owner	16/05/2013	2013
HES76 Storage heater miniature circuit breaker	£21.36	4.00	Joint Owner	16/05/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£26.24	4.00	Joint Owner	16/05/2013	2013
HES97 Electrician	£450.00	18.00	Joint Owner	16/05/2013	2013
HES44 Pipework / feed modifications	£482.00	1.00	Sole Property Owner	21/12/2012	2012
HES94 Heating engineer	£560.00	16.00	Sole Property Owner	21/12/2012	2012
HES97 Electrician	£210.00	6.00	Sole Property Owner	21/12/2012	2012
HES91 Other miscellaneous gas heating works for EES approval	£30.00	1.00	Sole Property Owner	21/12/2012	2012
HES91 Other miscellaneous gas heating works for EES approval	£802.00	1.00	Sole Property Owner	21/12/2012	2012
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	21/12/2012	2012
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	21/12/2012	2012
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	21/12/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	21/12/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatio	£250.00	10.00	Joint Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£500.00	40.00	Joint Owner	19/04/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Joint Owner	19/04/2013	2013
HES97 Electrician	£400.00	16.00	Joint Owner	19/04/2013	2013

HES71 Storage heater rated 1kW - 2kW	£801.96	3.00	Joint Owner	19/04/2013	2013
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Joint Owner	19/04/2013	2013
HES76 Storage heater miniature circuit breaker	£21.36	4.00	Joint Owner	19/04/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£0.00	0.00	Joint Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	25.00	Joint Owner	03/07/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	03/07/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Joint Owner	03/07/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£2,298.00	1.00	Joint Owner	03/07/2013	2013
HES40 Flue specification and location	£387.02	387.02	Joint Owner	03/07/2013	2013
HES45 Fire valve	£52.00	1.00	Joint Owner	03/07/2013	2013
HES49 Carbon Monoxide alarm	£31.00	1.00	Joint Owner	03/07/2013	2013
HES50 Electrical room thermostat	£13.88	1.00	Joint Owner	03/07/2013	2013
HES53 Two channel heating programmer control	£47.00	1.00	Joint Owner	03/07/2013	2013
HES67 22mm thick pipework lagging	£5.80	2.00	Joint Owner	03/07/2013	2013
HES68 28mm thick pipework lagging	£3.30	1.00	Joint Owner	03/07/2013	2013
HES94 Heating engineer	£396.00	12.00	Joint Owner	03/07/2013	2013
HES97 Electrician	£99.00	3.00	Joint Owner	03/07/2013	2013
HES99 Building works	£33.00	1.00	Joint Owner	03/07/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	03/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Sole Property Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Sole Property Owner	19/04/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	19/04/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£835.20	87.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	18.00	Sole Property Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	19/04/2013	2013
HES02 100mm thick loft insulation quilt	£450.00	60.00	Sole Property Owner	19/04/2013	2013
HES03 200mm thick loft insulation quilt	£342.00	36.00	Sole Property Owner	19/04/2013	2013
HES51 Thermostatic radiator valve	£0.00	6.00	Sole Property Owner	19/04/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	19/04/2013	2013
HES67 22mm thick pipework lagging	£12.66	3.00	Sole Property Owner	19/04/2013	2013
HES68 28mm thick pipework lagging	£9.08	2.00	Sole Property Owner	19/04/2013	2013
HES93 Junior heating engineer	£65.91	3.00	Sole Property Owner	19/04/2013	2013
HES94 Heating engineer	£331.20	9.00	Sole Property Owner	19/04/2013	2013
HES95 Senior heating engineer	£79.36	2.00	Sole Property Owner	19/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£25.30	1.00	Sole Property Owner	19/04/2013	2013
EES66 Low energy lamp replacement	£0.00	10.00	Not The Property Owner	12/03/2010	2010
EES00a Full Energy Survey	£401.68	1.00	Not The Property Owner	12/03/2010	2010
HES20 Low energy lamp installation	£0.00	52.00	Sole Property Owner	19/04/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	19/04/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	19/04/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	19/04/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,410.00	1.00	Sole Property Owner	19/04/2013	2013
HES40 Flue specification and location	£1,185.10	1.00	Sole Property Owner	19/04/2013	2013
HES41 Condensate pipework (and pump if required)	£298.00	1.00	Sole Property Owner	19/04/2013	2013
HES43 Central heating pump	£84.28	1.00	Sole Property Owner	19/04/2013	2013
HES44 Pipework / feed modifications	£392.35	1.00	Sole Property Owner	19/04/2013	2013
HES45 Fire valve	£36.90	1.00	Sole Property Owner	19/04/2013	2013
HES46 Automatic bypass	£27.50	1.00	Sole Property Owner	19/04/2013	2013
HES48 Power / system flush and treatment	£43.80	1.00	Sole Property Owner	19/04/2013	2013
HES49 Carbon Monoxide alarm	£68.40	1.00	Sole Property Owner	19/04/2013	2013
HES50 Electrical room thermostat	£13.45	1.00	Sole Property Owner	19/04/2013	2013
HES52 Hot water cylinder thermostat	£14.80	1.00	Sole Property Owner	19/04/2013	2013
HES53 Two channel heating programmer control	£33.80	1.00	Sole Property Owner	19/04/2013	2013
HES55 2 port zone valve	£98.00	2.00	Sole Property Owner	19/04/2013	2013
HES66 15mm thick pipework lagging	£3.22	2.00	Sole Property Owner	19/04/2013	2013
HES67 22mm thick pipework lagging	£15.84	8.00	Sole Property Owner	19/04/2013	2013
HES68 28mm thick pipework lagging	£19.28	8.00	Sole Property Owner	19/04/2013	2013
HES95 Senior heating engineer	£1,820.00	52.00	Sole Property Owner	19/04/2013	2013
HES98 Senior electrician	£420.00	12.00	Sole Property Owner	19/04/2013	2013
HES99 Building works	£176.00	8.00	Sole Property Owner	19/04/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Sole Property Owner	19/04/2013	2013
HES23 Scaffold / cherry picker	£250.00	1.00	Sole Property Owner	19/04/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	0.00	Sole Property Owner	19/04/2013	2013
HES101 Asbestos removal & disposal	£220.00	1.00	Sole Property Owner	19/04/2013	2013
HES101 Asbestos removal & disposal	£0.00	0.00	Sole Property Owner	19/04/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	19/04/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£625.00	25.00	Sole Property Owner	20/02/2013	2013
HES02 100mm thick loft insulation quilt	£450.00	60.00	Sole Property Owner	20/02/2013	2013
HES03 200mm thick loft insulation quilt	£1,064.00	112.00	Sole Property Owner	20/02/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£720.00	75.00	Sole Property Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner	20/02/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	20/02/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£150.00	6.00	Sole Property Owner	20/02/2013	2013
HES04 300mm thick loft insulation quilt	£875.00	70.00	Sole Property Owner	20/02/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	8.00	Sole Property Owner	20/02/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£1,278.00	1.00	Sole Property Owner	20/02/2013	2013
HES40 Flue specification and location	£325.00	1.00	Sole Property Owner	20/02/2013	2013
HES41 Condensate pipework (and pump if required)	£62.00	1.00	Sole Property Owner	20/02/2013	2013
HES42 Purpose built lime soakaway (condensate sump)	£228.00	1.00	Sole Property Owner	20/02/2013	2013

HES43 Central heating pump	£84.28	1.00	Sole Property Owner	20/02/2013	2013
HES44 Pipework / feed modifications	£318.20	1.00	Sole Property Owner	20/02/2013	2013
HES45 Fire valve	£36.90	1.00	Sole Property Owner	20/02/2013	2013
HES46 Automatic bypass	£27.50	1.00	Sole Property Owner	20/02/2013	2013
HES48 Power / system flush and treatment	£43.80	1.00	Sole Property Owner	20/02/2013	2013
HES49 Carbon Monoxide alarm	£68.40	1.00	Sole Property Owner	20/02/2013	2013
HES50 Electrical room thermostat	£13.45	1.00	Sole Property Owner	20/02/2013	2013
HES52 Hot water cylinder thermostat	£14.80	1.00	Sole Property Owner	20/02/2013	2013
HES53 Two channel heating programmer control	£33.80	1.00	Sole Property Owner	20/02/2013	2013
HES55 2 port zone valve	£98.00	2.00	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£6.44	4.00	Sole Property Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£27.72	14.00	Sole Property Owner	20/02/2013	2013
HES68 28mm thick pipework lagging	£28.92	12.00	Sole Property Owner	20/02/2013	2013
HES95 Senior heating engineer	£1,540.00	44.00	Sole Property Owner	20/02/2013	2013
HES98 Senior electrician	£350.00	10.00	Sole Property Owner	20/02/2013	2013
HES99 Building works	£132.00	6.00	Sole Property Owner	20/02/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	20/02/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£35.64	11.00	Sole Property Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£50.64	12.00	Sole Property Owner	20/02/2013	2013
HES68 28mm thick pipework lagging	£9.08	2.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£73.60	2.00	Sole Property Owner	20/02/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	6.00	Sole Property Owner	20/02/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	20/02/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	13/01/2014	2014
HES20 Low energy lamp installation	£0.00	8.00	Sole Property Owner	13/01/2014	2014
HES21 Smoke detector installation	£0.00	0.00	Sole Property Owner	13/01/2014	2014
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	13/01/2014	2014
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	13/01/2014	2014
HES37 16-20kW Gas replacement condensing boiler	£627.00	1.00	Sole Property Owner	13/01/2014	2014
HES40 Flue specification and location	£187.00	1.00	Sole Property Owner	13/01/2014	2014
HES41 Condensate pipework (and pump if required)	£20.00	1.00	Sole Property Owner	13/01/2014	2014
HES43 Central heating pump	£71.67	1.00	Sole Property Owner	13/01/2014	2014
HES44 Pipework / feed modifications	£68.50	68.50	Sole Property Owner	13/01/2014	2014
HES46 Automatic bypass	£43.30	1.00	Sole Property Owner	13/01/2014	2014
HES48 Power / system flush and treatment	£250.00	1.00	Sole Property Owner	13/01/2014	2014
HES51 Thermostatic radiator valve	£288.00	12.00	Sole Property Owner	13/01/2014	2014
HES55 2 port zone valve	£34.36	2.00	Sole Property Owner	13/01/2014	2014
HES94 Heating engineer	£803.25	17.00	Sole Property Owner	13/01/2014	2014
HES97 Electrician	£236.25	5.00	Sole Property Owner	13/01/2014	2014
HES88 Commissioning and issue of CD11 and flue gas analysis	£47.25	1.00	Sole Property Owner	13/01/2014	2014
HES91 Other miscellaneous gas heating works for EES approval	£130.00	1.00	Sole Property Owner	13/01/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£150.00	6.00	Sole Property Owner	31/07/2013	2013
HES04 300mm thick loft insulation quilt	£1,125.00	90.00	Sole Property Owner	31/07/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£508.80	53.00	Sole Property Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	25.00	Sole Property Owner	31/07/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	31/07/2013	2013
HES66 15mm thick pipework lagging	£4.83	3.00	Sole Property Owner	31/07/2013	2013
HES67 22mm thick pipework lagging	£23.76	12.00	Sole Property Owner	31/07/2013	2013
HES95 Senior heating engineer	£1,470.00	42.00	Sole Property Owner	31/07/2013	2013
HES98 Senior electrician	£280.00	8.00	Sole Property Owner	31/07/2013	2013
HES99 Building works	£132.00	6.00	Sole Property Owner	31/07/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	31/07/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Sole Property Owner	31/07/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,490.80	1.00	Sole Property Owner	31/07/2013	2013
HES40 Flue specification and location	£325.00	1.00	Sole Property Owner	31/07/2013	2013
HES41 Condensate pipework (and pump if required)	£134.33	1.00	Sole Property Owner	31/07/2013	2013
HES44 Pipework / feed modifications	£212.90	1.00	Sole Property Owner	31/07/2013	2013
HES45 Fire valve	£36.90	1.00	Sole Property Owner	31/07/2013	2013
HES46 Automatic bypass	£27.50	1.00	Sole Property Owner	31/07/2013	2013
HES48 Power / system flush and treatment	£43.80	1.00	Sole Property Owner	31/07/2013	2013
HES51 Thermostatic radiator valve	£12.90	1.00	Sole Property Owner	31/07/2013	2013
HES53 Two channel heating programmer control	£0.00	0.00	Sole Property Owner	31/07/2013	2013
HES55 2 port zone valve	£0.00	0.00	Sole Property Owner	31/07/2013	2013
HES49 Carbon Monoxide alarm	£68.40	1.00	Sole Property Owner	31/07/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	31/07/2013	2013
HES120 Standard QA check	£0.00	1.00	Sole Property Owner	31/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Joint Owner	03/07/2013	2013
HES04 300mm thick loft insulation quilt	£875.00	70.00	Joint Owner	03/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	03/07/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£902.40	94.00	Joint Owner	03/07/2013	2013
HES20 Low energy lamp installation	£0.00	21.00	Joint Owner	03/07/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	03/07/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£1,278.00	1.00	Joint Owner	03/07/2013	2013
HES40 Flue specification and location	£1,181.90	1.00	Joint Owner	03/07/2013	2013
HES41 Condensate pipework (and pump if required)	£82.00	1.00	Joint Owner	03/07/2013	2013
HES43 Central heating pump	£84.28	1.00	Joint Owner	03/07/2013	2013
HES44 Pipework / feed modifications	£338.19	1.00	Joint Owner	03/07/2013	2013
HES45 Fire valve	£36.90	1.00	Joint Owner	03/07/2013	2013
HES46 Automatic bypass	£27.50	1.00	Joint Owner	03/07/2013	2013
HES48 Power / system flush and treatment	£43.80	1.00	Joint Owner	03/07/2013	2013
HES49 Carbon Monoxide alarm	£68.40	1.00	Joint Owner	03/07/2013	2013
HES50 Electrical room thermostat	£13.45	1.00	Joint Owner	03/07/2013	2013

HES51 Thermostatic radiator valve	£90.30	7.00	Joint Owner	03/07/2013	2013
HES52 Hot water cylinder thermostat	£14.80	1.00	Joint Owner	03/07/2013	2013
HES53 Two channel heating programmer control	£33.80	1.00	Joint Owner	03/07/2013	2013
HES55 2 port zone valve	£98.00	2.00	Joint Owner	03/07/2013	2013
HES66 15mm thick pipework lagging	£6.44	4.00	Joint Owner	03/07/2013	2013
HES67 22mm thick pipework lagging	£19.80	10.00	Joint Owner	03/07/2013	2013
HES68 28mm thick pipework lagging	£19.28	8.00	Joint Owner	03/07/2013	2013
HES95 Senior heating engineer	£1,820.00	52.00	Joint Owner	03/07/2013	2013
HES98 Senior electrician	£280.00	8.00	Joint Owner	03/07/2013	2013
HES99 Building works	£176.00	8.00	Joint Owner	03/07/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Joint Owner	03/07/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£243.06	243.06	Joint Owner	03/07/2013	2013
HES23 Scaffold / cherry picker	£250.00	1.00	Joint Owner	03/07/2013	2013
HES101 Asbestos removal & disposal	£240.00	1.00	Joint Owner	03/07/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£425.25	425.25	Joint Owner	03/07/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	03/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£25.00	1.00	Joint Owner	03/07/2013	2013
HES66 15mm thick pipework lagging	£16.20	5.00	Joint Owner	03/07/2013	2013
HES67 22mm thick pipework lagging	£25.32	6.00	Joint Owner	03/07/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	16/05/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	16/05/2013	2013
HES20 Low energy lamp installation	£0.00	13.00	Sole Property Owner	16/05/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	16/05/2013	2013
HES97 Electrician	£425.00	17.00	Sole Property Owner	16/05/2013	2013
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Sole Property Owner	16/05/2013	2013
HES73 Storage heater rated 3kW - 4kW	£833.64	2.00	Sole Property Owner	16/05/2013	2013
HES75 Storage heater consumer unit	£32.92	1.00	Sole Property Owner	16/05/2013	2013
HES76 Storage heater miniature circuit breaker	£16.02	3.00	Sole Property Owner	16/05/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£19.68	3.00	Sole Property Owner	16/05/2013	2013
EES66 Low energy lamp replacement	£33.60	7.00	Not The Property Owner	01/11/2009	2009
EES67 Smoke detector installation	£4.80	1.00	Not The Property Owner	01/11/2009	2009
EES49 Pipework lagging 25mm thick to 22mm pipe	£6.50	1.00	Not The Property Owner	01/11/2009	2009
EES00a Full Energy Survey	£401.70	1.00	Not The Property Owner	01/11/2009	2009
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00	0.00	Not The Property Owner	02/10/2012	2012
HES04 300mm thick loft insulation quilt	£0.00	0.00	Not The Property Owner	02/10/2012	2012
HES06 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	02/10/2012	2012
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Not The Property Owner	02/10/2012	2012
HES20 Low energy lamp installation	£0.00	0.00	Not The Property Owner	02/10/2012	2012
HES50 Electrical room thermostat	£0.00	0.00	Not The Property Owner	02/10/2012	2012
HES51 Thermostatic radiator valve	£0.00	0.00	Not The Property Owner	02/10/2012	2012
HES67 22mm thick pipework lagging	£0.00	0.00	Not The Property Owner	02/10/2012	2012
HES93 Junior heating engineer	£0.00	0.00	Not The Property Owner	02/10/2012	2012
HES94 Heating engineer	£0.00	0.00	Not The Property Owner	02/10/2012	2012
HES97 Electrician	£0.00	0.00	Not The Property Owner	02/10/2012	2012
HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner	20/02/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	20/02/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	20/02/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£1,278.00	1.00	Joint Owner	20/02/2013	2013
HES40 Flue specification and location	£325.00	1.00	Joint Owner	20/02/2013	2013
HES41 Condensate pipework (and pump if required)	£242.88	1.00	Joint Owner	20/02/2013	2013
HES43 Central heating pump	£84.28	1.00	Joint Owner	20/02/2013	2013
HES44 Pipework / feed modifications	£343.00	1.00	Joint Owner	20/02/2013	2013
HES45 Fire valve	£36.90	1.00	Joint Owner	20/02/2013	2013
HES46 Automatic bypass	£27.50	1.00	Joint Owner	20/02/2013	2013
HES48 Power / system flush and treatment	£43.80	1.00	Joint Owner	20/02/2013	2013
HES49 Carbon Monoxide alarm	£68.40	1.00	Joint Owner	20/02/2013	2013
HES50 Electrical room thermostat	£13.45	1.00	Joint Owner	20/02/2013	2013
HES53 Two channel heating programmer control	£33.80	1.00	Joint Owner	20/02/2013	2013
HES55 2 port zone valve	£98.00	2.00	Joint Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£9.66	6.00	Joint Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£15.84	8.00	Joint Owner	20/02/2013	2013
HES68 28mm thick pipework lagging	£7.23	3.00	Joint Owner	20/02/2013	2013
HES95 Senior heating engineer	£1,680.00	48.00	Joint Owner	20/02/2013	2013
HES98 Senior electrician	£280.00	8.00	Joint Owner	20/02/2013	2013
HES99 Building works	£154.00	7.00	Joint Owner	20/02/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	20/02/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Joint Owner	20/02/2013	2013
HES52 Hot water cylinder thermostat	£0.00	1.00	Joint Owner	20/02/2013	2013
HES47 Frost thermostat	£16.51	1.00	Joint Owner	20/02/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£22.30	1.00	Joint Owner	20/02/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	27.00	Sole Property Owner	09/08/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	09/08/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	09/08/2013	2013
HES20 Low energy lamp installation	£0.00	22.00	Sole Property Owner	16/05/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	16/05/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£6.56	1.00	Sole Property Owner	16/05/2013	2013
HES71 Storage heater rated 1kW - 2kW	£534.64	2.00	Sole Property Owner	16/05/2013	2013
HES73 Storage heater rated 3kW - 4kW	£416.82	1.00	Sole Property Owner	16/05/2013	2013
HES75 Storage heater consumer unit	£32.92	1.00	Sole Property Owner	16/05/2013	2013
HES76 Storage heater miniature circuit breaker	£21.36	4.00	Sole Property Owner	16/05/2013	2013
HES78 Twin and earth 16mm cabling with clips and trunking	£0.00	0.00	Sole Property Owner	16/05/2013	2013
HES54 Water heating time clock and boost controller	£0.00	0.00	Sole Property Owner	16/05/2013	2013
HES97 Electrician	£500.00	20.00	Sole Property Owner	16/05/2013	2013

HES22 Minimum per property charge	£50.00	1.00	Joint Owner	12/07/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	12/07/2013	2013
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	12/07/2013	2013
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	12/07/2013	2013
HES72 Storage heater rated 2kW - 3kW	£925.47	3.00	Joint Owner	12/07/2013	2013
HES74 Comfort heat main switch	£57.20	1.00	Joint Owner	12/07/2013	2013
HES75 Storage heater consumer unit	£49.40	1.00	Joint Owner	12/07/2013	2013
HES76 Storage heater miniature circuit breaker	£39.00	4.00	Joint Owner	12/07/2013	2013
HES77 Main bonding of necessary services	£109.00	10.00	Joint Owner	12/07/2013	2013
HES78 Twin and earth 16mm cabling with clips and trunking	£336.06	18.00	Joint Owner	12/07/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£611.36	4.00	Joint Owner	12/07/2013	2013
HES80 16mm meter tails	£12.48	1.00	Joint Owner	12/07/2013	2013
HES83 Trunking	£144.60	15.00	Joint Owner	12/07/2013	2013
HES54 Water heating time clock and boost controller	£58.50	1.00	Joint Owner	12/07/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£231.60	1.00	Joint Owner	12/07/2013	2013
HES97 Electrician	£1,024.00	32.00	Joint Owner	12/07/2013	2013
HES94 Heating engineer	£192.00	6.00	Joint Owner	12/07/2013	2013
HES15 Draught stripping to exterior door	£15.00	5.00	Sole Property Owner	01/03/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	01/03/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	01/03/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	01/03/2013	2013
HES03 200mm thick loft insulation quilt	£427.50	45.00	Sole Property Owner	09/09/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	09/09/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£662.40	69.00	Sole Property Owner	09/09/2013	2013
HES20 Low energy lamp installation	£0.00	15.00	Sole Property Owner	09/09/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	09/09/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	09/09/2013	2013
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	09/09/2013	2013
HES94 Heating engineer	£18.40	0.50	Sole Property Owner	09/09/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	09/09/2013	2013
HES48 Power / system flush and treatment	£250.00	1.00	Sole Property Owner	09/09/2013	2013
HES50 Electrical room thermostat	£15.75	1.00	Sole Property Owner	09/09/2013	2013
HES52 Hot water cylinder thermostat	£4.62	1.00	Sole Property Owner	09/09/2013	2013
HES94 Heating engineer	£47.25	1.00	Sole Property Owner	09/09/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£62.28	62.28	Sole Property Owner	09/09/2013	2013
HES97 Electrician	£94.50	2.00	Sole Property Owner	09/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£50.00	2.00	Sole Property Owner	09/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£75.00	3.00	Joint Owner	03/07/2013	2013
HES03 200mm thick loft insulation quilt	£456.00	48.00	Joint Owner	03/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£750.00	3.00	Joint Owner	03/07/2013	2013
HES20 Low energy lamp installation	£0.00	16.00	Joint Owner	03/07/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	03/07/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,817.37	1.00	Joint Owner	03/07/2013	2013
HES40 Flue specification and location	£595.00	1.00	Joint Owner	03/07/2013	2013
HES41 Condensate pipework (and pump if required)	£150.00	1.00	Joint Owner	03/07/2013	2013
HES44 Pipework / feed modifications	£425.00	1.00	Joint Owner	03/07/2013	2013
HES46 Automatic bypass	£46.32	1.00	Joint Owner	03/07/2013	2013
HES49 Carbon Monoxide alarm	£85.35	1.00	Joint Owner	03/07/2013	2013
HES51 Thermostatic radiator valve	£405.90	9.00	Joint Owner	03/07/2013	2013
HES53 Two channel heating programmer control	£85.11	1.00	Joint Owner	03/07/2013	2013
HES55 2 port zone valve	£138.56	2.00	Joint Owner	03/07/2013	2013
HES68 28mm thick pipework lagging	£112.80	30.00	Joint Owner	03/07/2013	2013
HES94 Heating engineer	£1,748.00	46.00	Joint Owner	03/07/2013	2013
HES97 Electrician	£150.00	6.00	Joint Owner	03/07/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	03/07/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£38.00	1.00	Joint Owner	03/07/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£348.12	1.00	Joint Owner	03/07/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	03/07/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£0.00	0.00	Joint Owner	03/07/2013	2013
HES120 Standard QA check	£0.00	1.00	Joint Owner	03/07/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	02/08/2012	2012
EES25 Draught stripping to exterior door	£110.00	11.00	Not The Property Owner	01/02/2010	2010
EES26 Draught stripping to windows	£30.00	3.00	Not The Property Owner	01/02/2010	2010
EES27 Draught stripping to letterbox	£70.00	1.75	Not The Property Owner	01/02/2010	2010
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Not The Property Owner	01/02/2010	2010
EES69 Miscellaneous Charge	£105.00	1.00	Not The Property Owner	01/02/2010	2010
EES00a Full Energy Survey	£401.70	1.00	Not The Property Owner	01/02/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	23/11/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	23/11/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Not The Property Owner	23/11/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatic	£125.00	5.00	Sole Property Owner	11/06/2013	2013
HES03 200mm thick loft insulation quilt	£380.00	40.00	Sole Property Owner	11/06/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	11/06/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£225.00	9.00	Not The Property Owner	17/09/2013	2013
HES04 300mm thick loft insulation quilt	£562.50	45.00	Not The Property Owner	17/09/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Not The Property Owner	17/09/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£326.40	34.00	Not The Property Owner	17/09/2013	2013
HES20 Low energy lamp installation	£0.00	6.00	Not The Property Owner	17/09/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner	17/09/2013	2013
HES54 Water heating time clock and boost controller	£0.00	0.00	Not The Property Owner	17/09/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Not The Property Owner	17/09/2013	2013
HES95 Senior heating engineer	£351.00	9.00	Not The Property Owner	17/09/2013	2013
HES98 Senior electrician	£0.00	0.00	Not The Property Owner	17/09/2013	2013

HES01 Loft preparation labour (clearance, disposal of old insulatio	£250.00	10.00	Not The Property Owner	03/07/2013	2013
HES04 300mm thick loft insulation quilt	£312.50	25.00	Not The Property Owner	03/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Not The Property Owner	03/07/2013	2013
HES20 Low energy lamp installation	£0.00	7.00	Not The Property Owner	03/07/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner	03/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£100.00	4.00	Sole Property Owner	20/02/2013	2013
HES04 300mm thick loft insulation quilt	£250.00	20.00	Sole Property Owner	20/02/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	20/02/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£902.40	94.00	Sole Property Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	13.00	Sole Property Owner	20/02/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£55.20	1.50	Sole Property Owner	20/02/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£75.00	3.00	Sole Property Owner	20/02/2013	2013
HES04 300mm thick loft insulation quilt	£875.00	70.00	Sole Property Owner	20/02/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	15.00	Sole Property Owner	20/02/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	20/02/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£350.00	14.00	Sole Property Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£1,125.00	90.00	Sole Property Owner	19/04/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	19/04/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	20.00	Sole Property Owner	19/04/2013	2013
HES51 Thermostatic radiator valve	£131.10	6.00	Sole Property Owner	19/04/2013	2013
HES94 Heating engineer	£257.60	7.00	Sole Property Owner	19/04/2013	2013
HES95 Senior heating engineer	£39.68	1.00	Sole Property Owner	19/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£23.00	1.00	Sole Property Owner	19/04/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	30/03/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	30/03/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatio	£325.00	13.00	Joint Owner	16/05/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Joint Owner	16/05/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	16/05/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Joint Owner	16/05/2013	2013
HES21 Smoke detector installation	£0.00	3.00	Joint Owner	16/05/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£338.51	1.00	Joint Owner	16/05/2013	2013
HES94 Heating engineer	£304.00	8.00	Joint Owner	16/05/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£127.37	1.00	Joint Owner	16/05/2013	2013
HES02 100mm thick loft insulation quilt	£225.00	30.00	Joint Owner	16/05/2013	2013
HES03 200mm thick loft insulation quilt	£142.50	15.00	Sole Property Owner	19/04/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	19/04/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	19/04/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	7.00	Sole Property Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	19/04/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£50.00	2.00	Sole Property Owner	19/04/2013	2013
EES01a Loft Clearance (hourly rate)	£63.25	1.00	Sole Property Owner	08/09/2011	2011
EES02a Remove and dispose existing insulation (per squire metre	£126.00	30.00	Sole Property Owner	08/09/2011	2011
EES06 100mm thick loft insulation	£344.00	50.00	Sole Property Owner	08/09/2011	2011
EES07 200mm thick loft insulation	£908.82	102.00	Sole Property Owner	08/09/2011	2011
EES36 Electrical room thermostat	£103.40	1.00	Sole Property Owner	08/09/2011	2011
EES38a Thermostatic radiator valve (per valve)	£352.00	8.00	Sole Property Owner	08/09/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£40.90	5.00	Sole Property Owner	08/09/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£37.10	5.00	Sole Property Owner	08/09/2011	2011
EES66 Low energy lamp replacement	£49.00	1.00	Sole Property Owner	08/09/2011	2011
EES40 Hot water cylinder thermostat	£60.19	1.00	Sole Property Owner	08/09/2011	2011
EES42 Two channel programmable heating controller	£139.50	1.00	Sole Property Owner	08/09/2011	2011
EES51a 16-20kW Oil replacement boiler	£2,684.52	1.00	Sole Property Owner	08/09/2011	2011
EES70 Miscellaneous heating review charge	£630.00	1.00	Sole Property Owner	08/09/2011	2011
EES70 Miscellaneous heating review charge	£906.98	1.00	Sole Property Owner	08/09/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	08/09/2011	2011
HES01 Loft preparation labour (clearance, disposal of old insulatio	£275.00	11.00	Joint Owner	20/02/2013	2013
HES03 200mm thick loft insulation quilt	£142.50	15.00	Joint Owner	20/02/2013	2013
HES04 300mm thick loft insulation quilt	£187.50	15.00	Joint Owner	20/02/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	20/02/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£892.80	93.00	Joint Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	3.00	Joint Owner	20/02/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	20/02/2013	2013
HES02 100mm thick loft insulation quilt	£30.00	4.00	Joint Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Joint Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£25.32	6.00	Joint Owner	20/02/2013	2013
HES94 Heating engineer	£55.20	1.50	Joint Owner	20/02/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Not The Property Owner	01/03/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	01/03/2013	2013
HES17 Draught stripping to letter boxes	£0.00	0.00	Not The Property Owner	01/03/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	01/03/2013	2013
HES20 Low energy lamp installation	£0.00	4.00	Not The Property Owner	01/03/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner	01/03/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£550.00	22.00	Sole Property Owner	19/04/2013	2013
HES03 200mm thick loft insulation quilt	£95.00	10.00	Sole Property Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£1,250.00	100.00	Sole Property Owner	19/04/2013	2013

HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	23.00	Sole Property Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	19/04/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	19/04/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	19/04/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	30/03/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	30/03/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	30/03/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatic	£250.00	10.00	Joint Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£562.50	45.00	Joint Owner	19/04/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	19/04/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,219.20	127.00	Joint Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	20.00	Joint Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	19/04/2013	2013
HES43 Central heating pump	£141.55	1.00	Joint Owner	19/04/2013	2013
HES46 Automatic bypass	£46.32	1.00	Joint Owner	19/04/2013	2013
HES49 Carbon Monoxide alarm	£85.35	1.00	Joint Owner	19/04/2013	2013
HES51 Thermostatic radiator valve	£586.30	13.00	Joint Owner	19/04/2013	2013
HES53 Two channel heating programmer control	£85.11	1.00	Joint Owner	19/04/2013	2013
HES97 Electrician	£125.00	5.00	Joint Owner	19/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£35.00	1.00	Joint Owner	19/04/2013	2013
HES62 Hot water cylinder jacket (58 x 20 inch)	£58.32	1.00	Joint Owner	19/04/2013	2013
HES94 Heating engineer	£912.00	24.00	Joint Owner	19/04/2013	2013
HES66 15mm thick pipework lagging	£16.20	5.00	Joint Owner	19/04/2013	2013
HES67 22mm thick pipework lagging	£25.32	6.00	Joint Owner	19/04/2013	2013
HES94 Heating engineer	£73.60	2.00	Joint Owner	19/04/2013	2013
HES50 Electrical room thermostat	£53.32	1.00	Joint Owner	19/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£92.00	1.00	Joint Owner	19/04/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£100.00	4.00	Sole Property Owner	20/02/2013	2013
HES03 200mm thick loft insulation quilt	£247.00	26.00	Sole Property Owner	20/02/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	20/02/2013	2013
HES15 Draught stripping to exterior door	£33.00	11.00	Sole Property Owner	20/02/2013	2013
HES19 Draught proofing labour	£100.00	4.00	Sole Property Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	11.00	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£55.20	1.50	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£55.20	1.50	Sole Property Owner	20/02/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£50.00	2.00	Sole Property Owner	20/02/2013	2013
HES02 100mm thick loft insulation quilt	£180.00	24.00	Sole Property Owner	20/02/2013	2013
HES03 200mm thick loft insulation quilt	£313.50	33.00	Sole Property Owner	20/02/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	20/02/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,632.00	170.00	Sole Property Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	17.00	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£9.72	3.00	Sole Property Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£4.22	1.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	20/02/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£150.00	6.00	Sole Property Owner	23/04/2013	2013
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner	23/04/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	23/04/2013	2013
HES20 Low energy lamp installation	£0.00	25.00	Sole Property Owner	23/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	23/04/2013	2013
HES66 15mm thick pipework lagging	£3.24	1.00	Sole Property Owner	23/04/2013	2013
HES67 22mm thick pipework lagging	£4.22	1.00	Sole Property Owner	23/04/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	23/04/2013	2013
HES72 Storage heater rated 2kW - 3kW	£616.98	2.00	Sole Property Owner	23/04/2013	2013
HES73 Storage heater rated 3kW - 4kW	£750.68	2.00	Sole Property Owner	23/04/2013	2013
HES97 Electrician	£384.00	12.00	Sole Property Owner	23/04/2013	2013
HES66 15mm thick pipework lagging	£3.24	1.00	Sole Property Owner	23/04/2013	2013
HES67 22mm thick pipework lagging	£4.22	1.00	Sole Property Owner	23/04/2013	2013
HES94 Heating engineer	£55.20	1.50	Sole Property Owner	23/04/2013	2013
HES03 200mm thick loft insulation quilt	£190.00	20.00	Not The Property Owner	20/02/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Not The Property Owner	20/02/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	20/02/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	7.00	Not The Property Owner	20/02/2013	2013
HES51 Thermostatic radiator valve	£109.25	5.00	Not The Property Owner	20/02/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Not The Property Owner	20/02/2013	2013
HES54 Water heating time clock and boost controller	£0.00	0.00	Not The Property Owner	20/02/2013	2013
HES61 Hot water cylinder jacket (46 x 18 inch)	£0.00	0.00	Not The Property Owner	20/02/2013	2013
HES95 Senior heating engineer	£0.00	0.00	Not The Property Owner	20/02/2013	2013
HES98 Senior electrician	£79.36	2.00	Not The Property Owner	20/02/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner	20/02/2013	2013
HES93 Junior heating engineer	£131.82	6.00	Not The Property Owner	20/02/2013	2013
HES94 Heating engineer	£220.80	6.00	Not The Property Owner	20/02/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£100.00	4.00	Joint Owner	19/04/2013	2013
HES03 200mm thick loft insulation quilt	£171.00	18.00	Joint Owner	19/04/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	40.00	Joint Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	19/04/2013	2013
HES34 36-45kW Oil replacement condensing boiler	£2,530.00	1.00	Joint Owner	19/04/2013	2013
HES40 Flue specification and location	£849.39	1.00	Joint Owner	19/04/2013	2013

HES41 Condensate pipework (and pump if required)	£161.00	1.00	Joint Owner	19/04/2013	2013
HES44 Pipework / feed modifications	£347.33	1.00	Joint Owner	19/04/2013	2013
HES45 Fire valve	£46.00	1.00	Joint Owner	19/04/2013	2013
HES46 Automatic bypass	£31.05	1.00	Joint Owner	19/04/2013	2013
HES47 Frost thermostat	£0.00	0.00	Joint Owner	19/04/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Joint Owner	19/04/2013	2013
HES49 Carbon Monoxide alarm	£42.00	1.00	Joint Owner	19/04/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Joint Owner	19/04/2013	2013
HES51 Thermostatic radiator valve	£0.00	0.00	Joint Owner	19/04/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Joint Owner	19/04/2013	2013
HES55 2 port zone valve	£65.55	1.00	Joint Owner	19/04/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Joint Owner	19/04/2013	2013
HES94 Heating engineer	£1,840.00	50.00	Joint Owner	19/04/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Joint Owner	19/04/2013	2013
HES98 Senior electrician	£396.80	10.00	Joint Owner	19/04/2013	2013
HES99 Building works	£175.98	6.00	Joint Owner	19/04/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	19/04/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Joint Owner	19/04/2013	2013
HES23 Scaffold / cherry picker	£637.10	637.10	Joint Owner	19/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£353.72	1.00	Joint Owner	19/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£276.00	1.00	Joint Owner	19/04/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£206.70	1.00	Joint Owner	19/04/2013	2013
HES67 22mm thick pipework lagging	£25.32	6.00	Joint Owner	19/04/2013	2013
HES68 28mm thick pipework lagging	£45.40	10.00	Joint Owner	19/04/2013	2013
HES93 Junior heating engineer	£131.82	6.00	Joint Owner	19/04/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	19/04/2013	2013
HES16 Draught stripping to windows	£144.00	48.00	Joint Owner	19/04/2013	2013
HES19 Draught proofing labour	£225.00	9.00	Joint Owner	19/04/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£186.58	1.00	Joint Owner	19/04/2013	2013
EES07 200mm thick loft insulation	£695.50	50.00	Sole Property Owner	12/03/2010	2010
EES25 Draught stripping to exterior door	£91.00	10.00	Sole Property Owner	12/03/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£80.16	6.00	Sole Property Owner	12/03/2010	2010
EES66 Low energy lamp replacement	£21.00	12.00	Sole Property Owner	12/03/2010	2010
EES00a Full Energy Survey	£401.70	1.00	Sole Property Owner	12/03/2010	2010
HES01 Loft preparation labour (clearance, disposal of old insulatio	£125.00	5.00	Joint Owner	03/07/2013	2013
HES04 300mm thick loft insulation quilt	£1,125.00	90.00	Joint Owner	03/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	03/07/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,056.00	110.00	Joint Owner	03/07/2013	2013
HES20 Low energy lamp installation	£0.00	13.00	Joint Owner	03/07/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	03/07/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£1,725.00	1.00	Joint Owner	03/07/2013	2013
HES40 Flue specification and location	£426.12	1.00	Joint Owner	03/07/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Joint Owner	03/07/2013	2013
HES45 Fire valve	£46.00	1.00	Joint Owner	03/07/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Joint Owner	03/07/2013	2013
HES49 Carbon Monoxide alarm	£42.00	1.00	Joint Owner	03/07/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Joint Owner	03/07/2013	2013
HES51 Thermostatic radiator valve	£196.65	9.00	Joint Owner	03/07/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Joint Owner	03/07/2013	2013
HES66 15mm thick pipework lagging	£25.92	8.00	Joint Owner	03/07/2013	2013
HES67 22mm thick pipework lagging	£33.76	8.00	Joint Owner	03/07/2013	2013
HES93 Junior heating engineer	£43.94	2.00	Joint Owner	03/07/2013	2013
HES94 Heating engineer	£1,251.20	34.00	Joint Owner	03/07/2013	2013
HES95 Senior heating engineer	£79.36	2.00	Joint Owner	03/07/2013	2013
HES98 Senior electrician	£198.40	5.00	Joint Owner	03/07/2013	2013
HES99 Building works	£117.32	4.00	Joint Owner	03/07/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	03/07/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Joint Owner	03/07/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£1,062.60	1.00	Joint Owner	03/07/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£322.97	1.00	Joint Owner	03/07/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£263.15	1.00	Joint Owner	03/07/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£205.11	1.00	Joint Owner	03/07/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	03/07/2013	2013
HES44 Pipework / feed modifications	£345.00	1.00	Joint Owner	03/07/2013	2013
HES120 Standard QA check	£0.00	1.00	Joint Owner	03/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Sole Property Owner	19/04/2013	2013
HES02 100mm thick loft insulation quilt	£75.00	10.00	Sole Property Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£437.50	35.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	36.00	Sole Property Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	19/04/2013	2013
HES51 Thermostatic radiator valve	£43.70	2.00	Sole Property Owner	19/04/2013	2013
HES94 Heating engineer	£220.80	6.00	Sole Property Owner	19/04/2013	2013
HES95 Senior heating engineer	£39.68	1.00	Sole Property Owner	19/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£23.00	1.00	Sole Property Owner	19/04/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£250.00	10.00	Sole Property Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£500.00	40.00	Sole Property Owner	19/04/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	19/04/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£115.20	12.00	Sole Property Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	21.00	Sole Property Owner	19/04/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,368.00	1.00	Sole Property Owner	19/04/2013	2013
HES40 Flue specification and location	£288.90	1.00	Sole Property Owner	19/04/2013	2013
HES41 Condensate pipework (and pump if required)	£98.44	1.00	Sole Property Owner	19/04/2013	2013
HES42 Purpose built lime soakaway (condensate sump)	£228.00	1.00	Sole Property Owner	19/04/2013	2013

HES43 Central heating pump	£84.28	1.00	Sole Property Owner	19/04/2013	2013
HES44 Pipework / feed modifications	£241.11	1.00	Sole Property Owner	19/04/2013	2013
HES45 Fire valve	£36.90	1.00	Sole Property Owner	19/04/2013	2013
HES46 Automatic bypass	£27.50	1.00	Sole Property Owner	19/04/2013	2013
HES48 Power / system flush and treatment	£43.80	1.00	Sole Property Owner	19/04/2013	2013
HES49 Carbon Monoxide alarm	£68.40	1.00	Sole Property Owner	19/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£122.90	1.00	Sole Property Owner	19/04/2013	2013
HES53 Two channel heating programmer control	£33.80	1.00	Sole Property Owner	19/04/2013	2013
HES55 2 port zone valve	£98.00	2.00	Sole Property Owner	19/04/2013	2013
HES66 15mm thick pipework lagging	£8.05	5.00	Sole Property Owner	19/04/2013	2013
HES67 22mm thick pipework lagging	£9.90	5.00	Sole Property Owner	19/04/2013	2013
HES95 Senior heating engineer	£1,330.00	38.00	Sole Property Owner	19/04/2013	2013
HES98 Senior electrician	£280.00	8.00	Sole Property Owner	19/04/2013	2013
HES99 Building works	£88.00	4.00	Sole Property Owner	19/04/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	19/04/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Sole Property Owner	19/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£87.04	1.00	Sole Property Owner	19/04/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	19/04/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,152.00	120.00	Joint Owner	12/02/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Joint Owner	12/02/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	12/02/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Sole Property Owner	11/06/2013	2013
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner	11/06/2013	2013
HES15 Draught stripping to exterior door	£36.00	12.00	Sole Property Owner	11/06/2013	2013
HES19 Draught proofing labour	£100.00	4.00	Sole Property Owner	11/06/2013	2013
HES20 Low energy lamp installation	£0.00	25.00	Sole Property Owner	11/06/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	11/06/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,983.72	1.00	Sole Property Owner	11/06/2013	2013
HES40 Flue specification and location	£489.12	1.00	Sole Property Owner	11/06/2013	2013
HES41 Condensate pipework (and pump if required)	£100.22	1.00	Sole Property Owner	11/06/2013	2013
HES44 Pipework / feed modifications	£278.29	1.00	Sole Property Owner	11/06/2013	2013
HES45 Fire valve	£36.90	1.00	Sole Property Owner	11/06/2013	2013
HES46 Automatic bypass	£27.50	1.00	Sole Property Owner	11/06/2013	2013
HES48 Power / system flush and treatment	£43.80	1.00	Sole Property Owner	11/06/2013	2013
HES49 Carbon Monoxide alarm	£0.00	0.00	Sole Property Owner	11/06/2013	2013
HES51 Thermostatic radiator valve	£129.00	10.00	Sole Property Owner	11/06/2013	2013
HES53 Two channel heating programmer control	£33.80	1.00	Sole Property Owner	11/06/2013	2013
HES55 2 port zone valve	£0.00	0.00	Sole Property Owner	11/06/2013	2013
HES66 15mm thick pipework lagging	£4.83	3.00	Sole Property Owner	11/06/2013	2013
HES67 22mm thick pipework lagging	£9.90	5.00	Sole Property Owner	11/06/2013	2013
HES95 Senior heating engineer	£1,820.00	52.00	Sole Property Owner	11/06/2013	2013
HES98 Senior electrician	£280.00	8.00	Sole Property Owner	11/06/2013	2013
HES99 Building works	£154.00	7.00	Sole Property Owner	11/06/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	11/06/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Sole Property Owner	11/06/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£36.90	1.00	Sole Property Owner	11/06/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	11/06/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	11/06/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£225.00	9.00	Sole Property Owner	01/03/2013	2013
HES04 300mm thick loft insulation quilt	£187.50	15.00	Sole Property Owner	01/03/2013	2013
HES15 Draught stripping to exterior door	£36.00	12.00	Sole Property Owner	01/03/2013	2013
HES19 Draught proofing labour	£100.00	4.00	Sole Property Owner	01/03/2013	2013
HES20 Low energy lamp installation	£0.00	18.00	Sole Property Owner	01/03/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	01/03/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	01/03/2013	2013
HES94 Heating engineer	£55.20	1.50	Sole Property Owner	01/03/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	01/03/2013	2013
HES94 Heating engineer	£55.20	1.50	Sole Property Owner	01/03/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£600.00	48.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£9.72	3.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner		0
HES15 Draught stripping to exterior door	£3.00	1.00	Sole Property Owner		0
HES19 Draught proofing labour	£25.00	1.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	12.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	3.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£450.00	18.00	Sole Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	17.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/03/2014	2014
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	17/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£294.46	294.46	Sole Property Owner	17/03/2014	2014
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Sole Property Owner	17/03/2014	2014
HES40 Flue specification and location	£590.86	1.00	Sole Property Owner	17/03/2014	2014
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Sole Property Owner	17/03/2014	2014
HES43 Central heating pump	£92.00	1.00	Sole Property Owner	17/03/2014	2014
HES44 Pipework / feed modifications	£138.00	1.00	Sole Property Owner	17/03/2014	2014
HES45 Fire valve	£46.00	1.00	Sole Property Owner	17/03/2014	2014
HES47 Frost thermostat	£23.00	1.00	Sole Property Owner	17/03/2014	2014

HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	17/03/2014	2014
HES51 Thermostatic radiator valve	£262.20	12.00	Sole Property Owner	17/03/2014	2014
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	17/03/2014	2014
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	17/03/2014	2014
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£58.32	18.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£151.92	36.00	Sole Property Owner	17/03/2014	2014
HES68 28mm thick pipework lagging	£13.62	3.00	Sole Property Owner	17/03/2014	2014
HES93 Junior heating engineer	£175.76	8.00	Sole Property Owner	17/03/2014	2014
HES94 Heating engineer	£1,472.00	40.00	Sole Property Owner	17/03/2014	2014
HES95 Senior heating engineer	£357.12	9.00	Sole Property Owner	17/03/2014	2014
HES98 Senior electrician	£396.80	10.00	Sole Property Owner	17/03/2014	2014
HES99 Building works	£117.32	4.00	Sole Property Owner	17/03/2014	2014
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	17/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£126.50	1.00	Sole Property Owner	17/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£218.50	1.00	Sole Property Owner	17/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£25.30	1.00	Sole Property Owner	17/03/2014	2014
HES92 Other miscellaneous electrical heating works for EES appr	£214.15	214.15	Sole Property Owner	17/03/2014	2014
HES92 Other miscellaneous electrical heating works for EES appr	£268.48	268.48	Sole Property Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	7.00	Joint Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	19/04/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Joint Owner	19/04/2013	2013
HES71 Storage heater rated 1kW - 2kW	£244.53	1.00	Joint Owner	19/04/2013	2013
HES72 Storage heater rated 2kW - 3kW	£308.49	1.00	Joint Owner	19/04/2013	2013
HES73 Storage heater rated 3kW - 4kW	£375.34	1.00	Joint Owner	19/04/2013	2013
HES75 Storage heater consumer unit	£49.40	1.00	Joint Owner	19/04/2013	2013
HES76 Storage heater miniature circuit breaker	£68.25	7.00	Joint Owner	19/04/2013	2013
HES77 Main bonding of necessary services	£54.50	5.00	Joint Owner	19/04/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£305.68	2.00	Joint Owner	19/04/2013	2013
HES80 16mm meter tails	£24.96	2.00	Joint Owner	19/04/2013	2013
HES54 Water heating time clock and boost controller	£117.00	2.00	Joint Owner	19/04/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£463.20	2.00	Joint Owner	19/04/2013	2013
HES97 Electrician	£768.00	24.00	Joint Owner	19/04/2013	2013
HES94 Heating engineer	£512.00	16.00	Joint Owner	19/04/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£200.00	8.00	Sole Property Owner	20/02/2013	2013
HES04 300mm thick loft insulation quilt	£437.50	35.00	Sole Property Owner	20/02/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	20/02/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	20/02/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	20/02/2013	2013
HES67 22mm thick pipework lagging	£4.22	1.00	Sole Property Owner	20/02/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	20/02/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	17/04/2014	2014
HES20 Low energy lamp installation	£0.00	14.00	Sole Property Owner	17/04/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/04/2014	2014
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	17/04/2014	2014
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	17/04/2014	2014
HES102 QA Survey for House/Bungalow/Flat	£422.50	1.00	Sole Property Owner	17/04/2014	2014
HES47 Frost thermostat	£18.00	1.00	Sole Property Owner	17/04/2014	2014
HES55 2 port zone valve	£54.00	1.00	Sole Property Owner	17/04/2014	2014
HES95 Senior heating engineer	£94.70	2.00	Sole Property Owner	17/04/2014	2014
HES31 16-20kW Oil replacement condensing boiler	£2,138.00	1.00	Sole Property Owner	17/04/2014	2014
HES40 Flue specification and location	£257.00	257.00	Sole Property Owner	17/04/2014	2014
HES41 Condensate pipework (and pump if required)	£20.00	1.00	Sole Property Owner	17/04/2014	2014
HES43 Central heating pump	£44.00	1.00	Sole Property Owner	17/04/2014	2014
HES45 Fire valve	£52.00	1.00	Sole Property Owner	17/04/2014	2014
HES49 Carbon Monoxide alarm	£31.00	1.00	Sole Property Owner	17/04/2014	2014
HES50 Electrical room thermostat	£13.88	1.00	Sole Property Owner	17/04/2014	2014
HES51 Thermostatic radiator valve	£0.00	0.00	Sole Property Owner	17/04/2014	2014
HES53 Two channel heating programmer control	£47.00	1.00	Sole Property Owner	17/04/2014	2014
HES94 Heating engineer	£528.00	16.00	Sole Property Owner	17/04/2014	2014
HES97 Electrician	£132.00	4.00	Sole Property Owner	17/04/2014	2014
HES99 Building works	£0.00	0.00	Sole Property Owner	17/04/2014	2014
HES47 Frost thermostat	£18.00	1.00	Sole Property Owner	17/04/2014	2014
HES66 15mm thick pipework lagging	£18.40	8.00	Sole Property Owner	17/04/2014	2014
HES67 22mm thick pipework lagging	£23.20	8.00	Sole Property Owner	17/04/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatic	£350.00	14.00	Joint Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£1,125.00	90.00	Joint Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Joint Owner	28/11/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Joint Owner	28/11/2013	2013
HES94 Heating engineer	£27.60	0.75	Joint Owner	28/11/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£0.00		Joint Owner	28/11/2013	2013
HES40 Flue specification and location	£0.00		Joint Owner	28/11/2013	2013
HES41 Condensate pipework (and pump if required)	£0.00		Joint Owner	28/11/2013	2013
HES43 Central heating pump	£0.00		Joint Owner	28/11/2013	2013
HES44 Pipework / feed modifications	£0.00		Joint Owner	28/11/2013	2013
HES46 Automatic bypass	£0.00		Joint Owner	28/11/2013	2013
HES48 Power / system flush and treatment	£0.00		Joint Owner	28/11/2013	2013
HES117 Carbon Monoxide alarm	£0.00		Joint Owner	28/11/2013	2013

HES50 Electrical room thermostat	£0.00		Joint Owner	28/11/2013	2013
HES51 Thermostatic radiator valve	£0.00		Joint Owner	28/11/2013	2013
HES52 Hot water cylinder thermostat	£0.00		Joint Owner	28/11/2013	2013
HES53 Two channel heating programmer control	£0.00		Joint Owner	28/11/2013	2013
HES55 2 port zone valve	£0.00		Joint Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£0.00		Joint Owner	28/11/2013	2013
HES68 28mm thick pipework lagging	£0.00		Joint Owner	28/11/2013	2013
HES94 Heating engineer	£0.00		Joint Owner	28/11/2013	2013
HES97 Electrician	£0.00		Joint Owner	28/11/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£0.00	0.00	Joint Owner	28/11/2013	2013
HES40 Flue specification and location	£0.00	0.00	Joint Owner	28/11/2013	2013
HES43 Central heating pump	£0.00	0.00	Joint Owner	28/11/2013	2013
HES45 Fire valve	£0.00	0.00	Joint Owner	28/11/2013	2013
HES49 Carbon Monoxide alarm	£0.00	0.00	Joint Owner	28/11/2013	2013
HES50 Electrical room thermostat	£0.00	0.00	Joint Owner	28/11/2013	2013
HES51 Thermostatic radiator valve	£0.00	0.00	Joint Owner	28/11/2013	2013
HES53 Two channel heating programmer control	£0.00	0.00	Joint Owner	28/11/2013	2013
HES94 Heating engineer	£0.00	0.00	Joint Owner	28/11/2013	2013
HES97 Electrician	£0.00	0.00	Joint Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£100.00	4.00	Joint Owner	02/07/2013	2013
HES04 300mm thick loft insulation quilt	£937.50	75.00	Joint Owner	02/07/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Joint Owner	02/07/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	02/07/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	02/07/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£2,138.00	1.00	Joint Owner	02/07/2013	2013
HES40 Flue specification and location	£490.52	490.52	Joint Owner	02/07/2013	2013
HES41 Condensate pipework (and pump if required)	£20.00	1.00	Joint Owner	02/07/2013	2013
HES43 Central heating pump	£44.00	1.00	Joint Owner	02/07/2013	2013
HES45 Fire valve	£52.00	1.00	Joint Owner	02/07/2013	2013
HES47 Frost thermostat	£18.00	1.00	Joint Owner	02/07/2013	2013
HES49 Carbon Monoxide alarm	£31.00	1.00	Joint Owner	02/07/2013	2013
HES53 Two channel heating programmer control	£47.00	1.00	Joint Owner	02/07/2013	2013
HES66 15mm thick pipework lagging	£18.40	8.00	Joint Owner	02/07/2013	2013
HES67 22mm thick pipework lagging	£23.20	8.00	Joint Owner	02/07/2013	2013
HES94 Heating engineer	£627.00	19.00	Joint Owner	02/07/2013	2013
HES97 Electrician	£132.00	4.00	Joint Owner	02/07/2013	2013
HES50 Electrical room thermostat	£13.88	1.00	Joint Owner	02/07/2013	2013
HES51 Thermostatic radiator valve	£165.00	11.00	Joint Owner	02/07/2013	2013
HES99 Building works	£66.00	2.00	Joint Owner	02/07/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	01/08/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	01/08/2012	2012
HES20 Low energy lamp installation	£0.00	18.00	Sole Property Owner	28/11/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	28/11/2013	2013
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Sole Property Owner	28/11/2013	2013
HES75 Storage heater consumer unit	£32.92	1.00	Sole Property Owner	28/11/2013	2013
HES76 Storage heater miniature circuit breaker	£5.34	1.00	Sole Property Owner	28/11/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£6.56	1.00	Sole Property Owner	28/11/2013	2013
HES80 16mm meter tails	£4.72	1.00	Sole Property Owner	28/11/2013	2013
HES54 Water heating time clock and boost controller	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES97 Electrician	£400.00	16.00	Sole Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£75.00	3.00	Sole Property Owner	17/09/2013	2013
HES04 300mm thick loft insulation quilt	£300.00	24.00	Sole Property Owner	17/09/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Sole Property Owner	17/09/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	17/09/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/09/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,410.00	1.00	Sole Property Owner	17/09/2013	2013
HES40 Flue specification and location	£345.90	1.00	Sole Property Owner	17/09/2013	2013
HES41 Condensate pipework (and pump if required)	£331.88	1.00	Sole Property Owner	17/09/2013	2013
HES43 Central heating pump	£84.28	1.00	Sole Property Owner	17/09/2013	2013
HES44 Pipework / feed modifications	£233.00	1.00	Sole Property Owner	17/09/2013	2013
HES45 Fire valve	£36.90	1.00	Sole Property Owner	17/09/2013	2013
HES46 Automatic bypass	£27.50	1.00	Sole Property Owner	17/09/2013	2013
HES48 Power / system flush and treatment	£43.80	1.00	Sole Property Owner	17/09/2013	2013
HES49 Carbon Monoxide alarm	£0.00	0.00	Sole Property Owner	17/09/2013	2013
HES53 Two channel heating programmer control	£67.60	2.00	Sole Property Owner	17/09/2013	2013
HES55 2 port zone valve	£98.00	2.00	Sole Property Owner	17/09/2013	2013
HES66 15mm thick pipework lagging	£3.22	2.00	Sole Property Owner	17/09/2013	2013
HES67 22mm thick pipework lagging	£11.88	6.00	Sole Property Owner	17/09/2013	2013
HES68 28mm thick pipework lagging	£9.64	4.00	Sole Property Owner	17/09/2013	2013
HES95 Senior heating engineer	£1,540.00	44.00	Sole Property Owner	17/09/2013	2013
HES98 Senior electrician	£280.00	8.00	Sole Property Owner	17/09/2013	2013
HES99 Building works	£44.00	2.00	Sole Property Owner	17/09/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	17/09/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Sole Property Owner	17/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£91.11	1.00	Sole Property Owner	17/09/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	17/09/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	16.00	Sole Property Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	19/04/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	19/04/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	01/08/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	01/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Not The Property Owner	01/08/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Not The Property Owner	03/07/2013	2013

HES03 200mm thick loft insulation quilt	£285.00	30.00	Not The Property Owner	03/07/2013	2013
HES04 300mm thick loft insulation quilt	£375.00	30.00	Not The Property Owner	03/07/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	03/07/2013	2013
HES17 Draught stripping to letter boxes	£0.00	0.00	Not The Property Owner	03/07/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	03/07/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	03/07/2013	2013
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	03/07/2013	2013
HES120 Standard QA check	£0.00	1.00	Not The Property Owner	03/07/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	01/08/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	01/08/2012	2012
EES01a Loft Clearance (hourly rate)	£94.89	3.00	Sole Property Owner	01/02/2010	2010
EES03a Remove and replace nailed floor board	£35.40	3.00	Sole Property Owner	01/02/2010	2010
EES07 200mm thick loft insulation	£873.18	98.00	Sole Property Owner	01/02/2010	2010
EES09 Intumescent bag/fire hood to downlighter	£172.00	8.00	Sole Property Owner	01/02/2010	2010
EES10 Cold water tank insulation quilt	£34.62	1.00	Sole Property Owner	01/02/2010	2010
EES66 Low energy lamp replacement	£22.75	13.00	Sole Property Owner	01/02/2010	2010
EES00a Full Energy Survey	£401.70	1.00	Sole Property Owner	01/02/2010	2010
HES01 Loft preparation labour (clearance, disposal of old insulatic	£200.00	8.00	Not The Property Owner	10/05/2013	2013
HES04 300mm thick loft insulation quilt	£500.00	40.00	Not The Property Owner	10/05/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Not The Property Owner	10/05/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,689.60	176.00	Not The Property Owner	10/05/2013	2013
HES20 Low energy lamp installation	£0.00	15.00	Not The Property Owner	10/05/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner	10/05/2013	2013
HES95 Senior heating engineer	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES51 Thermostatic radiator valve	£43.70	2.00	Not The Property Owner	10/05/2013	2013
HES94 Heating engineer	£110.40	3.00	Not The Property Owner	10/05/2013	2013
HES97 Electrician	£110.40	3.00	Not The Property Owner	10/05/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Not The Property Owner	10/05/2013	2013
HES51 Thermostatic radiator valve	£152.95	7.00	Not The Property Owner	10/05/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Not The Property Owner	10/05/2013	2013
HES94 Heating engineer	£257.60	7.00	Not The Property Owner	10/05/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00	0.00	Sole Property Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Sole Property Owner	19/04/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Sole Property Owner	19/04/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£931.20	97.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	8.00	Sole Property Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	19/04/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	19/04/2013	2013
HES65 Stainless steel replacement hot water cylinder (210L)	£590.12	1.00	Sole Property Owner	19/04/2013	2013
HES67 22mm thick pipework lagging	£34.90	10.00	Sole Property Owner	19/04/2013	2013
HES94 Heating engineer	£1,216.00	32.00	Sole Property Owner	19/04/2013	2013
HES97 Electrician	£150.00	6.00	Sole Property Owner	19/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£37.00	1.00	Sole Property Owner	19/04/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,817.37	1.00	Sole Property Owner	19/04/2013	2013
HES41 Condensate pipework (and pump if required)	£150.00	1.00	Sole Property Owner	19/04/2013	2013
HES43 Central heating pump	£141.55	1.00	Sole Property Owner	19/04/2013	2013
HES44 Pipework / feed modifications	£200.00	1.00	Sole Property Owner	19/04/2013	2013
HES46 Automatic bypass	£46.32	1.00	Sole Property Owner	19/04/2013	2013
HES51 Thermostatic radiator valve	£135.30	3.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	22.00	Sole Property Owner	19/04/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	19/04/2013	2013
HES51 Thermostatic radiator valve	£631.40	14.00	Sole Property Owner	19/04/2013	2013
HES94 Heating engineer	£304.00	8.00	Sole Property Owner	19/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£44.62	1.00	Sole Property Owner	19/04/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,372.80	143.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner	19/04/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	21/12/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	21/12/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Joint Owner	21/12/2012	2012
EES49 Pipework lagging 25mm thick to 22mm pipe	£1.90	1.00	Joint Owner	21/12/2012	2012
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Sole Property Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	28/11/2013	2013
HES93 Junior heating engineer	£43.94	2.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£220.80	6.00	Sole Property Owner	28/11/2013	2013
HES95 Senior heating engineer	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£560.25	560.25	Sole Property Owner	28/11/2013	2013
HES44 Pipework / feed modifications	£115.00	115.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£18.40	0.50	Sole Property Owner	28/11/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£100.00	4.00	Sole Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£250.00	20.00	Sole Property Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	28/11/2013	2013
HES15 Draught stripping to exterior door	£75.00	25.00	Sole Property Owner	28/11/2013	2013
HES19 Draught proofing labour	£175.00	7.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	40.00	Sole Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	28/11/2013	2013
HES37 16-20kW Gas replacement condensing boiler	£690.00	1.00	Sole Property Owner	31/07/2013	2013
HES40 Flue specification and location	£277.12	1.00	Sole Property Owner	31/07/2013	2013
HES41 Condensate pipework (and pump if required)	£42.38	1.00	Sole Property Owner	31/07/2013	2013
HES43 Central heating pump	£95.11	1.00	Sole Property Owner	31/07/2013	2013
HES44 Pipework / feed modifications	£110.36	1.00	Sole Property Owner	31/07/2013	2013
HES46 Automatic bypass	£25.00	1.00	Sole Property Owner	31/07/2013	2013

HES48 Power / system flush and treatment	£25.00	1.00	Sole Property Owner	31/07/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	31/07/2013	2013
HES50 Electrical room thermostat	£15.20	1.00	Sole Property Owner	31/07/2013	2013
HES52 Hot water cylinder thermostat	£15.20	1.00	Sole Property Owner	31/07/2013	2013
HES53 Two channel heating programmer control	£70.91	1.00	Sole Property Owner	31/07/2013	2013
HES55 2 port zone valve	£120.38	2.00	Sole Property Owner	31/07/2013	2013
HES94 Heating engineer	£1,435.00	41.00	Sole Property Owner	31/07/2013	2013
HES97 Electrician	£245.00	7.00	Sole Property Owner	31/07/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£4.50	1.00	Sole Property Owner	31/07/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£175.00	1.00	Sole Property Owner	31/07/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	31/07/2013	2013
HES66 15mm thick pipework lagging	£13.56	6.00	Sole Property Owner	31/07/2013	2013
HES67 22mm thick pipework lagging	£28.71	9.00	Sole Property Owner	31/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Sole Property Owner	31/07/2013	2013
HES03 200mm thick loft insulation quilt	£161.50	17.00	Sole Property Owner	31/07/2013	2013
HES04 300mm thick loft insulation quilt	£775.00	62.00	Sole Property Owner	31/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	31/07/2013	2013
HES15 Draught stripping to exterior door	£0.00	0.00	Sole Property Owner	31/07/2013	2013
HES19 Draught proofing labour	£0.00	0.00	Sole Property Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	31/07/2013	2013
HES21 Smoke detector installation	£0.00	0.00	Sole Property Owner	31/07/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	01/08/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	01/08/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatio	£100.00	4.00	Joint Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£100.00	8.00	Joint Owner	19/04/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	19/04/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner	19/04/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	20.00	Joint Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	19/04/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£325.00	13.00	Sole Property Owner	18/09/2013	2013
HES04 300mm thick loft insulation quilt	£750.00	60.00	Sole Property Owner	18/09/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	18/09/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,488.00	155.00	Sole Property Owner	18/09/2013	2013
HES20 Low energy lamp installation	£0.00	30.00	Sole Property Owner	18/09/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	18/09/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Sole Property Owner	18/09/2013	2013
HES40 Flue specification and location	£1,108.32	1.00	Sole Property Owner	18/09/2013	2013
HES41 Condensate pipework (and pump if required)	£92.00	1.00	Sole Property Owner	18/09/2013	2013
HES43 Central heating pump	£92.00	1.00	Sole Property Owner	18/09/2013	2013
HES44 Pipework / feed modifications	£437.00	1.00	Sole Property Owner	18/09/2013	2013
HES45 Fire valve	£46.00	1.00	Sole Property Owner	18/09/2013	2013
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner	18/09/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	18/09/2013	2013
HES49 Carbon Monoxide alarm	£42.00	1.00	Sole Property Owner	18/09/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	18/09/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	18/09/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	18/09/2013	2013
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	18/09/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Sole Property Owner	18/09/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	18/09/2013	2013
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	18/09/2013	2013
HES68 28mm thick pipework lagging	£18.16	4.00	Sole Property Owner	18/09/2013	2013
HES93 Junior heating engineer	£65.91	3.00	Sole Property Owner	18/09/2013	2013
HES94 Heating engineer	£1,987.20	54.00	Sole Property Owner	18/09/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	18/09/2013	2013
HES98 Senior electrician	£515.84	13.00	Sole Property Owner	18/09/2013	2013
HES99 Building works	£58.66	2.00	Sole Property Owner	18/09/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	18/09/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	18/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£393.30	1.00	Sole Property Owner	18/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£245.77	1.00	Sole Property Owner	18/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£205.11	1.00	Sole Property Owner	18/09/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	18/09/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	17/09/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	17/09/2013	2013
HES111 HER Survey for Flat	£136.00	1.00	Not The Property Owner	17/09/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner	17/09/2013	2013
HES03 200mm thick loft insulation quilt	£237.50	25.00	Not The Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Not The Property Owner	19/04/2013	2013
HES51 Thermostatic radiator valve	£349.60	16.00	Joint Owner	31/07/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Joint Owner	31/07/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Joint Owner	31/07/2013	2013
HES93 Junior heating engineer	£21.97	1.00	Joint Owner	31/07/2013	2013
HES94 Heating engineer	£809.60	22.00	Joint Owner	31/07/2013	2013
HES95 Senior heating engineer	£79.36	2.00	Joint Owner	31/07/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£50.00	1.00	Joint Owner	31/07/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£101.20	1.00	Joint Owner	31/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£150.00	6.00	Joint Owner	31/07/2013	2013
HES03 200mm thick loft insulation quilt	£76.00	8.00	Joint Owner	31/07/2013	2013
HES04 300mm thick loft insulation quilt	£250.00	20.00	Joint Owner	31/07/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£873.60	91.00	Joint Owner	31/07/2013	2013
HES15 Draught stripping to exterior door	£90.00	30.00	Joint Owner	31/07/2013	2013
HES16 Draught stripping to windows	£60.00	20.00	Joint Owner	31/07/2013	2013

HES19 Draught proofing labour	£375.00	15.00	Joint Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	55.00	Joint Owner	31/07/2013	2013
HES21 Smoke detector installation	£0.00	3.00	Joint Owner	31/07/2013	2013
HES68 28mm thick pipework lagging	£18.16	4.00	Joint Owner	31/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£126.50	1.00	Sole Property Owner	16/05/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,430.40	149.00	Sole Property Owner	16/05/2013	2013
HES20 Low energy lamp installation	£0.00	22.00	Sole Property Owner	16/05/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	16/05/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Sole Property Owner	16/05/2013	2013
HES40 Flue specification and location	£835.65	1.00	Sole Property Owner	16/05/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Sole Property Owner	16/05/2013	2013
HES43 Central heating pump	£92.00	1.00	Sole Property Owner	16/05/2013	2013
HES44 Pipework / feed modifications	£322.00	1.00	Sole Property Owner	16/05/2013	2013
HES45 Fire valve	£46.00	1.00	Sole Property Owner	16/05/2013	2013
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner	16/05/2013	2013
HES47 Frost thermostat	£0.00	0.00	Sole Property Owner	16/05/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	16/05/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	16/05/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	16/05/2013	2013
HES51 Thermostatic radiator valve	£196.65	9.00	Sole Property Owner	16/05/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	16/05/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	16/05/2013	2013
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	16/05/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Sole Property Owner	16/05/2013	2013
HES67 22mm thick pipework lagging	£25.32	6.00	Sole Property Owner	16/05/2013	2013
HES68 28mm thick pipework lagging	£18.16	4.00	Sole Property Owner	16/05/2013	2013
HES93 Junior heating engineer	£43.94	2.00	Sole Property Owner	16/05/2013	2013
HES94 Heating engineer	£1,766.40	48.00	Sole Property Owner	16/05/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	16/05/2013	2013
HES98 Senior electrician	£396.80	10.00	Sole Property Owner	16/05/2013	2013
HES99 Building works	£175.98	6.00	Sole Property Owner	16/05/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	16/05/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	16/05/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£414.50	1.00	Sole Property Owner	16/05/2013	2013
HES92 Other miscellaneous electrical heating works for EES approval	£513.98	1.00	Sole Property Owner	16/05/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	16/05/2013	2013
HES70 Storage heater rated < 1kW	£0.00	0.00	Sole Property Owner		0
HES71 Storage heater rated 1kW - 2kW	£0.00	0.00	Sole Property Owner		0
HES72 Storage heater rated 2kW - 3kW	£0.00	0.00	Sole Property Owner		0
HES75 Storage heater consumer unit	£49.40	1.00	Sole Property Owner		0
HES76 Storage heater miniature circuit breaker	£58.50	6.00	Sole Property Owner		0
HES77 Main bonding of necessary services	£109.00	10.00	Sole Property Owner		0
HES79 Heating point twin and earth mini trunk DP switch	£458.52	3.00	Sole Property Owner		0
HES80 16mm meter tails	£12.48	1.00	Sole Property Owner		0
HES63 Stainless steel replacement hot water cylinder (150L)	£231.60	1.00	Sole Property Owner		0
HES97 Electrician	£1,024.00	32.00	Sole Property Owner		0
HES94 Heating engineer	£256.00	8.00	Sole Property Owner		0
HES92 Other miscellaneous electrical heating works for EES approval	£297.88	1.00	Sole Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EES approval	£100.00	1.00	Sole Property Owner		0
HES101 Asbestos removal & disposal	£760.00	1.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulation)	£175.00	7.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00	0.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner		0
HES02 100mm thick loft insulation quilt	£112.50	15.00	Sole Property Owner		0
HES03 200mm thick loft insulation quilt	£304.00	32.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulation)	£50.00	2.00	Joint Owner	19/04/2013	2013
HES03 200mm thick loft insulation quilt	£465.50	49.00	Joint Owner	19/04/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,027.20	107.00	Joint Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	14.00	Joint Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	19/04/2013	2013
HES49 Carbon Monoxide alarm	£0.00	0.00	Joint Owner	19/04/2013	2013
HES51 Thermostatic radiator valve	£0.00	0.00	Joint Owner	19/04/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner	19/04/2013	2013
HES67 22mm thick pipework lagging	£0.00	0.00	Joint Owner	19/04/2013	2013
HES68 28mm thick pipework lagging	£0.00	0.00	Joint Owner	19/04/2013	2013
HES93 Junior heating engineer	£0.00	0.00	Joint Owner	19/04/2013	2013
HES94 Heating engineer	£0.00	0.00	Joint Owner	19/04/2013	2013
HES95 Senior heating engineer	£0.00	0.00	Joint Owner	19/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£0.00	0.00	Joint Owner	19/04/2013	2013
HES03 200mm thick loft insulation quilt	£427.50	45.00	Sole Property Owner	11/06/2013	2013
HES13 Miscellaneous items (brush, airbrick, vent etc), please provide details	£63.71	1.00	Sole Property Owner	11/06/2013	2013
HES71 Storage heater rated 1kW - 2kW	£978.12	4.00	Sole Property Owner	11/06/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£152.84	1.00	Sole Property Owner	11/06/2013	2013
HES54 Water heating time clock and boost controller	£58.50	1.00	Sole Property Owner	11/06/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£283.83	1.00	Sole Property Owner	11/06/2013	2013
HES97 Electrician	£704.00	22.00	Sole Property Owner	11/06/2013	2013
HES94 Heating engineer	£192.00	6.00	Sole Property Owner	11/06/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulation)	£375.00	15.00	Sole Property Owner	11/06/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Sole Property Owner	11/06/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Sole Property Owner	11/06/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	11/06/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	11/06/2013	2013
HES20 Low energy lamp installation	£0.00	8.00	Sole Property Owner	11/06/2013	2013

HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	11/06/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£150.00	6.00	Sole Property Owner	14/08/2013	2013
HES04 300mm thick loft insulation quilt	£437.50	35.00	Sole Property Owner	14/08/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£681.60	71.00	Sole Property Owner	14/08/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner	14/08/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	14/08/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£1,725.00	1.00	Sole Property Owner	14/08/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Sole Property Owner	14/08/2013	2013
HES44 Pipework / feed modifications	£575.00	1.00	Sole Property Owner	14/08/2013	2013
HES45 Fire valve	£46.00	1.00	Sole Property Owner	14/08/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	14/08/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	14/08/2013	2013
HES51 Thermostatic radiator valve	£218.50	10.00	Sole Property Owner	14/08/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	14/08/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	14/08/2013	2013
HES67 22mm thick pipework lagging	£59.08	14.00	Sole Property Owner	14/08/2013	2013
HES93 Junior heating engineer	£65.91	3.00	Sole Property Owner	14/08/2013	2013
HES94 Heating engineer	£1,324.80	36.00	Sole Property Owner	14/08/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	14/08/2013	2013
HES96 Junior electrician	£219.70	10.00	Sole Property Owner	14/08/2013	2013
HES98 Senior electrician	£396.80	10.00	Sole Property Owner	14/08/2013	2013
HES99 Building works	£234.64	8.00	Sole Property Owner	14/08/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	14/08/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	14/08/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£1,101.70	1.00	Sole Property Owner	14/08/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£602.63	1.00	Sole Property Owner	14/08/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	14/08/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00	0.00	Joint Owner	24/12/2012	2012
HES04 300mm thick loft insulation quilt	£0.00	0.00	Joint Owner	24/12/2012	2012
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	24/12/2012	2012
HES20 Low energy lamp installation	£0.00	0.00	Joint Owner	24/12/2012	2012
HES21 Smoke detector installation	£0.00	0.00	Joint Owner	24/12/2012	2012
EES50b 12-15kW Gas replacement boiler	£971.00	1.00	Sole Property Owner	14/02/2012	2012
EES70 Miscellaneous heating review charge	£1,070.68	1,070.68	Sole Property Owner	14/02/2012	2012
EES01a Loft Clearance (hourly rate)	£234.00	10.00	Sole Property Owner	14/02/2012	2012
EES07 200mm thick loft insulation	£762.72	42.00	Sole Property Owner	14/02/2012	2012
EES38a Thermostatic radiator valve (per valve)	£231.35	7.00	Sole Property Owner	14/02/2012	2012
EES15 Insulation to 65mm wide cavity wall	£74.90	10.00	Sole Property Owner	14/02/2012	2012
EES66 Low energy lamp replacement	£102.33	9.00	Sole Property Owner	14/02/2012	2012
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	14/02/2012	2012
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	14/02/2012	2012
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	14/02/2012	2012
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	14/02/2012	2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Sole Property Owner	26/01/2012	2012
EES03a Remove and replace nailed floor board	£17.50	7.00	Sole Property Owner	26/01/2012	2012
EES69 Miscellaneous Charge	£21.00	7.00	Sole Property Owner	26/01/2012	2012
EES08 300mm thick loft insulation	£84.00	7.00	Sole Property Owner	26/01/2012	2012
EES12 Cold water tank lid	£280.00	1.00	Sole Property Owner	26/01/2012	2012
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Sole Property Owner	26/01/2012	2012
EES69 Miscellaneous Charge	£50.00	1.00	Sole Property Owner	26/01/2012	2012
EES50c Replacement electrical storage heater	£788.37	3.00	Sole Property Owner	26/01/2012	2012
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	26/01/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatic	£150.00	6.00	Joint Owner		0
HES04 300mm thick loft insulation quilt	£512.50	41.00	Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£902.40	94.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	23.00	Joint Owner		0
HES21 Smoke detector installation	£0.00	1.00	Joint Owner		0
HES51 Thermostatic radiator valve	£43.20	3.00	Joint Owner		0
HES94 Heating engineer	£105.00	3.00	Joint Owner		0
HES91 Other miscellaneous gas heating works for EES approval	£12.50	1.00	Joint Owner		0
HES66 15mm thick pipework lagging	£19.44	6.00	Joint Owner		0
HES44 Pipework / feed modifications	£0.00		Joint Owner		0
HES66 15mm thick pipework lagging	£0.00		Joint Owner		0
HES67 22mm thick pipework lagging	£0.00		Joint Owner		0
HES93 Junior heating engineer	£0.00		Joint Owner		0
HES94 Heating engineer	£0.00		Joint Owner		0
HES95 Senior heating engineer	£0.00		Joint Owner		0
HES103 Copper replacement hot water cylinder (150L)	£0.00		Joint Owner		0
HES94 Heating engineer	£36.80	1.00	Joint Owner		0
HES37 16-20kW Gas replacement condensing boiler	£690.00	1.00	Sole Property Owner		0
HES40 Flue specification and location	£415.10	1.00	Sole Property Owner		0
HES41 Condensate pipework (and pump if required)	£131.64	1.00	Sole Property Owner		0
HES43 Central heating pump	£95.11	1.00	Sole Property Owner		0
HES44 Pipework / feed modifications	£159.44	1.00	Sole Property Owner		0
HES46 Automatic bypass	£25.00	1.00	Sole Property Owner		0
HES47 Frost thermostat	£0.00	0.00	Sole Property Owner		0
HES48 Power / system flush and treatment	£25.00	1.00	Sole Property Owner		0
HES50 Electrical room thermostat	£15.20	1.00	Sole Property Owner		0
HES53 Two channel heating programmer control	£70.91	1.00	Sole Property Owner		0
HES55 2 port zone valve	£120.38	2.00	Sole Property Owner		0
HES94 Heating engineer	£1,400.00	40.00	Sole Property Owner		0
HES97 Electrician	£122.50	3.50	Sole Property Owner		0
HES88 Commissioning and issue of CD11 and flue gas analysis	£4.50	1.00	Sole Property Owner		0

HES91 Other miscellaneous gas heating works for EES approval	£126.00	1.00	Sole Property Owner		0
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner		0
HES101 Asbestos removal & disposal	£150.00	1.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner		0
HES94 Heating engineer	£36.80	1.00	Sole Property Owner		0
HES100 Asbestos survey & sample	£166.00	166.00	Sole Property Owner		0
HES102 QA Survey for House/Bungalow/Flat	£422.50	1.00	Sole Property Owner		0
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner		0
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£225.00	9.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£525.00	42.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	20.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£75.00	3.00	Sole Property Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£587.50	47.00	Sole Property Owner	19/04/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	19/04/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Sole Property Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	19/04/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Sole Property Owner	19/04/2013	2013
HES67 22mm thick pipework lagging	£25.32	6.00	Sole Property Owner	19/04/2013	2013
HES94 Heating engineer	£73.60	2.00	Sole Property Owner	19/04/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	19/04/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£100.00	4.00	Sole Property Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£400.00	32.00	Sole Property Owner	19/04/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	19/04/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£960.00	100.00	Sole Property Owner	19/04/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	19/04/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	11.00	Sole Property Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	19/04/2013	2013
HES66 15mm thick pipework lagging	£9.72	3.00	Sole Property Owner	19/04/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	19/04/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Sole Property Owner	19/04/2013	2013
HES40 Flue specification and location	£414.63	414.63	Sole Property Owner	19/04/2013	2013
HES41 Condensate pipework (and pump if required)	£199.82	1.00	Sole Property Owner	19/04/2013	2013
HES43 Central heating pump	£92.00	1.00	Sole Property Owner	19/04/2013	2013
HES44 Pipework / feed modifications	£322.00	1.00	Sole Property Owner	19/04/2013	2013
HES45 Fire valve	£46.00	1.00	Sole Property Owner	19/04/2013	2013
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner	19/04/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	19/04/2013	2013
HES49 Carbon Monoxide alarm	£42.00	1.00	Sole Property Owner	19/04/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	19/04/2013	2013
HES51 Thermostatic radiator valve	£174.80	8.00	Sole Property Owner	19/04/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	19/04/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	19/04/2013	2013
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	19/04/2013	2013
HES66 15mm thick pipework lagging	£38.88	12.00	Sole Property Owner	19/04/2013	2013
HES67 22mm thick pipework lagging	£50.64	12.00	Sole Property Owner	19/04/2013	2013
HES68 28mm thick pipework lagging	£9.08	2.00	Sole Property Owner	19/04/2013	2013
HES93 Junior heating engineer	£87.88	4.00	Sole Property Owner	19/04/2013	2013
HES94 Heating engineer	£1,987.20	54.00	Sole Property Owner	19/04/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	19/04/2013	2013
HES98 Senior electrician	£515.84	13.00	Sole Property Owner	19/04/2013	2013
HES99 Building works	£58.66	2.00	Sole Property Owner	19/04/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	19/04/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	19/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£393.30	1.00	Sole Property Owner	19/04/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£208.72	1.00	Sole Property Owner	19/04/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	19/04/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£500.00	20.00	Sole Property Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£725.00	58.00	Sole Property Owner	19/04/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£750.00	3.00	Sole Property Owner	19/04/2013	2013
HES15 Draught stripping to exterior door	£36.00	12.00	Sole Property Owner	19/04/2013	2013
HES19 Draught proofing labour	£100.00	4.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	4.00	Sole Property Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	19/04/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£125.00	5.00	Sole Property Owner	11/06/2013	2013
HES04 300mm thick loft insulation quilt	£100.00	8.00	Sole Property Owner	11/06/2013	2013
HES20 Low energy lamp installation	£0.00	6.00	Sole Property Owner	11/06/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	11/06/2013	2013
HES66 15mm thick pipework lagging	£9.72	3.00	Joint Owner	28/11/2013	2013
HES94 Heating engineer	£27.60	0.75	Joint Owner	28/11/2013	2013
HES44 Pipework / feed modifications	£150.00	1.00	Joint Owner	28/11/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Joint Owner	28/11/2013	2013
HES94 Heating engineer	£294.40	8.00	Joint Owner	28/11/2013	2013
HES95 Senior heating engineer	£39.68	1.00	Joint Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£86.45	1.00	Joint Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£550.00	1.00	Joint Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£225.00	9.00	Joint Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£375.00	30.00	Joint Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	28/11/2013	2013

HES20 Low energy lamp installation	£0.00	18.00	Joint Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	28/11/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Joint Owner	28/11/2013	2013
HES40 Flue specification and location	£0.00	0.00	Joint Owner	28/11/2013	2013
HES41 Condensate pipework (and pump if required)	£92.00	92.00	Joint Owner	28/11/2013	2013
HES43 Central heating pump	£92.00	1.00	Joint Owner	28/11/2013	2013
HES44 Pipework / feed modifications	£374.50	374.50	Joint Owner	28/11/2013	2013
HES45 Fire valve	£46.00	1.00	Joint Owner	28/11/2013	2013
HES46 Automatic bypass	£31.05	1.00	Joint Owner	28/11/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Joint Owner	28/11/2013	2013
HES117 Carbon Monoxide alarm	£0.00	0.00	Joint Owner	28/11/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Joint Owner	28/11/2013	2013
HES51 Thermostatic radiator valve	£131.10	6.00	Joint Owner	28/11/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Joint Owner	28/11/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Joint Owner	28/11/2013	2013
HES55 2 port zone valve	£131.10	2.00	Joint Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£67.52	16.00	Joint Owner	28/11/2013	2013
HES68 28mm thick pipework lagging	£9.08	2.00	Joint Owner	28/11/2013	2013
HES93 Junior heating engineer	£263.64	12.00	Joint Owner	28/11/2013	2013
HES94 Heating engineer	£2,171.20	59.00	Joint Owner	28/11/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Joint Owner	28/11/2013	2013
HES98 Senior electrician	£515.84	13.00	Joint Owner	28/11/2013	2013
HES99 Building works	£293.30	10.00	Joint Owner	28/11/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	28/11/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Joint Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£126.50	1.00	Joint Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£23.50	1.00	Joint Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£150.00	1.00	Joint Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£218.50	1.00	Joint Owner	28/11/2013	2013
HES92 Other miscellaneous electrical heating works for EES approval	£522.43	1.00	Joint Owner	28/11/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulation)	£850.00	34.00	Not The Property Owner	26/09/2013	2013
HES03 200mm thick loft insulation quilt	£237.50	25.00	Not The Property Owner	26/09/2013	2013
HES04 300mm thick loft insulation quilt	£937.50	75.00	Not The Property Owner	26/09/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,075.20	112.00	Not The Property Owner	26/09/2013	2013
HES20 Low energy lamp installation	£0.00	18.00	Not The Property Owner	26/09/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner	26/09/2013	2013
HES51 Thermostatic radiator valve	£109.25	5.00	Not The Property Owner	26/09/2013	2013
HES66 15mm thick pipework lagging	£12.96	4.00	Not The Property Owner	26/09/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Not The Property Owner	26/09/2013	2013
HES93 Junior heating engineer	£65.91	3.00	Not The Property Owner	26/09/2013	2013
HES94 Heating engineer	£294.40	8.00	Not The Property Owner	26/09/2013	2013
HES95 Senior heating engineer	£79.36	2.00	Not The Property Owner	26/09/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£25.30	1.00	Not The Property Owner	26/09/2013	2013
HES37 16-20kW Gas replacement condensing boiler	£690.00	1.00	Sole Property Owner	31/07/2013	2013
HES40 Flue specification and location	£143.20	143.20	Sole Property Owner	31/07/2013	2013
HES41 Condensate pipework (and pump if required)	£52.15	52.15	Sole Property Owner	31/07/2013	2013
HES43 Central heating pump	£95.11	1.00	Sole Property Owner	31/07/2013	2013
HES44 Pipework / feed modifications	£355.05	355.05	Sole Property Owner	31/07/2013	2013
HES48 Power / system flush and treatment	£25.00	1.00	Sole Property Owner	31/07/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	31/07/2013	2013
HES50 Electrical room thermostat	£15.20	1.00	Sole Property Owner	31/07/2013	2013
HES51 Thermostatic radiator valve	£72.00	5.00	Sole Property Owner	31/07/2013	2013
HES52 Hot water cylinder thermostat	£15.20	1.00	Sole Property Owner	31/07/2013	2013
HES53 Two channel heating programmer control	£70.91	1.00	Sole Property Owner	31/07/2013	2013
HES55 2 port zone valve	£120.38	2.00	Sole Property Owner	31/07/2013	2013
HES67 22mm thick pipework lagging	£31.90	10.00	Sole Property Owner	31/07/2013	2013
HES94 Heating engineer	£1,671.25	47.75	Sole Property Owner	31/07/2013	2013
HES97 Electrician	£140.00	4.00	Sole Property Owner	31/07/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£4.50	1.00	Sole Property Owner	31/07/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	31/07/2013	2013
HES66 15mm thick pipework lagging	£4.52	2.00	Sole Property Owner	31/07/2013	2013
HES46 Automatic bypass	£25.00	1.00	Sole Property Owner	31/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulation)	£50.00	2.00	Sole Property Owner	31/07/2013	2013
HES03 200mm thick loft insulation quilt	£427.50	45.00	Sole Property Owner	31/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	31/07/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,104.00	115.00	Sole Property Owner	31/07/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	31/07/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	19.00	Sole Property Owner	31/07/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£126.50	126.50	Sole Property Owner	17/12/2013	2013
HES38 21-25kW Gas replacement condensing boiler	£0.00	0.00	Sole Property Owner	17/12/2013	2013
HES40 Flue specification and location	£103.00	1.00	Sole Property Owner	17/12/2013	2013
HES41 Condensate pipework (and pump if required)	£92.00	92.00	Sole Property Owner	17/12/2013	2013
HES44 Pipework / feed modifications	£115.00	1.00	Sole Property Owner	17/12/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	17/12/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	17/12/2013	2013
HES51 Thermostatic radiator valve	£131.10	6.00	Sole Property Owner	17/12/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	17/12/2013	2013
HES66 15mm thick pipework lagging	£32.40	10.00	Sole Property Owner	17/12/2013	2013
HES67 22mm thick pipework lagging	£50.64	12.00	Sole Property Owner	17/12/2013	2013
HES93 Junior heating engineer	£65.91	3.00	Sole Property Owner	17/12/2013	2013
HES95 Senior heating engineer	£79.36	2.00	Sole Property Owner	17/12/2013	2013

HES94 Heating engineer	£1,030.40	28.00	Sole Property Owner	17/12/2013	2013
HES98 Senior electrician	£158.72	4.00	Sole Property Owner	17/12/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	17/12/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£918.85	1.00	Sole Property Owner	17/12/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£25.30	1.00	Sole Property Owner	17/12/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£39.68	1.00	Sole Property Owner	17/12/2013	2013
HES92 Other miscellaneous electrical heating works for EES approval	£326.61	1.00	Sole Property Owner	17/12/2013	2013
HES92 Other miscellaneous electrical heating works for EES approval	£0.00	0.00	Sole Property Owner	17/12/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	17/12/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulation)	£150.00	6.00	Sole Property Owner	17/12/2013	2013
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner	17/12/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,027.20	107.00	Sole Property Owner	17/12/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	17/12/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	17/12/2013	2013
HES20 Low energy lamp installation	£0.00	7.00	Sole Property Owner	17/12/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/12/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	17/12/2013	2013
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Not The Property Owner	01/11/2009	2009
EES66 Low energy lamp replacement	£0.00	6.00	Not The Property Owner	01/11/2009	2009
EES00a Full Energy Survey	£401.70	1.00	Not The Property Owner	01/11/2009	2009
HES112 HER Survey for House	£187.00	1.00	Sole Property Owner	24/04/2013	2013
HES20 Low energy lamp installation	£0.00	2.00	Sole Property Owner	24/04/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulation)	£0.00		Not The Property Owner	29/07/2013	2013
HES02 100mm thick loft insulation quilt	£0.00		Not The Property Owner	29/07/2013	2013
HES04 300mm thick loft insulation quilt	£0.00		Not The Property Owner	29/07/2013	2013
HES67 22mm thick pipework lagging	£0.00		Not The Property Owner	29/07/2013	2013
HES111 HER Survey for Flat	£136.00	1.00	Not The Property Owner	29/07/2013	2013
HES20 Low energy lamp installation	£0.00	11.00	Not The Property Owner	29/07/2013	2013
HES44 Pipework / feed modifications	£172.50	1.00	Joint Owner	24/06/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	24/06/2013	2013
HES51 Thermostatic radiator valve	£131.10	6.00	Joint Owner	24/06/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Joint Owner	24/06/2013	2013
HES94 Heating engineer	£588.80	16.00	Joint Owner	24/06/2013	2013
HES95 Senior heating engineer	£79.36	2.00	Joint Owner	24/06/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£25.30	1.00	Joint Owner	24/06/2013	2013
HES66 15mm thick pipework lagging	£16.20	5.00	Joint Owner	24/06/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Joint Owner	24/06/2013	2013
HES94 Heating engineer	£27.60	0.75	Joint Owner	24/06/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulation)	£250.00	10.00	Joint Owner	24/06/2013	2013
HES04 300mm thick loft insulation quilt	£1,050.00	84.00	Joint Owner	24/06/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	24/06/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£912.00	95.00	Joint Owner	24/06/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Joint Owner	24/06/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	24/06/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulation)	£50.00	2.00	Sole Property Owner	09/09/2013	2013
HES03 200mm thick loft insulation quilt	£304.00	32.00	Sole Property Owner	09/09/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	09/09/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	09/09/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	09/09/2013	2013
HES50 Electrical room thermostat	£15.75	1.00	Sole Property Owner	09/09/2013	2013
HES97 Electrician	£94.50	2.00	Sole Property Owner	09/09/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£94.70	94.70	Sole Property Owner	09/09/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	28/11/2013	2013
HES36 12-15kW Gas replacement condensing boiler	£616.00	1.00	Sole Property Owner	28/11/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£577.00	577.00	Sole Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulation)	£250.00	10.00	Sole Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	28/11/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	28/11/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	28/11/2013	2013
HES40 Flue specification and location	£358.00	1.00	Sole Property Owner	28/11/2013	2013
HES41 Condensate pipework (and pump if required)	£139.60	139.60	Sole Property Owner	28/11/2013	2013
HES43 Central heating pump	£71.67	1.00	Sole Property Owner	28/11/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES50 Electrical room thermostat	£15.75	1.00	Sole Property Owner	28/11/2013	2013
HES52 Hot water cylinder thermostat	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES53 Two channel heating programmer control	£46.16	1.00	Sole Property Owner	28/11/2013	2013
HES55 2 port zone valve	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£254.16	1.00	Sole Property Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£17.52	6.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£1,417.50	30.00	Sole Property Owner	28/11/2013	2013
HES97 Electrician	£330.75	7.00	Sole Property Owner	28/11/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£47.25	1.00	Sole Property Owner	28/11/2013	2013
HES23 Scaffold / cherry picker	£1,008.15	1,008.15	Sole Property Owner	28/11/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£290.00	290.00	Sole Property Owner	28/11/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulation)	£125.00	5.00	Joint Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£312.50	25.00	Joint Owner	19/04/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	19/04/2013	2013

HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Joint Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	19/04/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	31/07/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Joint Owner	31/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£450.00	18.00	Joint Owner	31/07/2013	2013
HES04 300mm thick loft insulation quilt	£812.50	65.00	Joint Owner	31/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	15.00	Joint Owner	31/07/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	31/07/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Joint Owner	31/07/2013	2013
HES40 Flue specification and location	£504.85	1.00	Joint Owner	31/07/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Joint Owner	31/07/2013	2013
HES43 Central heating pump	£92.00	1.00	Joint Owner	31/07/2013	2013
HES44 Pipework / feed modifications	£322.00	1.00	Joint Owner	31/07/2013	2013
HES45 Fire valve	£46.00	1.00	Joint Owner	31/07/2013	2013
HES46 Automatic bypass	£31.05	1.00	Joint Owner	31/07/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Joint Owner	31/07/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	31/07/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Joint Owner	31/07/2013	2013
HES51 Thermostatic radiator valve	£262.20	12.00	Joint Owner	31/07/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Joint Owner	31/07/2013	2013
HES55 2 port zone valve	£131.10	2.00	Joint Owner	31/07/2013	2013
HES66 15mm thick pipework lagging	£12.96	4.00	Joint Owner	31/07/2013	2013
HES67 22mm thick pipework lagging	£25.32	6.00	Joint Owner	31/07/2013	2013
HES68 28mm thick pipework lagging	£18.16	4.00	Joint Owner	31/07/2013	2013
HES93 Junior heating engineer	£87.88	4.00	Joint Owner	31/07/2013	2013
HES94 Heating engineer	£1,729.60	47.00	Joint Owner	31/07/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Joint Owner	31/07/2013	2013
HES98 Senior electrician	£515.84	13.00	Joint Owner	31/07/2013	2013
HES99 Building works	£87.99	3.00	Joint Owner	31/07/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£218.50	1.00	Joint Owner	31/07/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£79.93	79.93	Joint Owner	31/07/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	31/07/2013	2013
HES111 HER Survey for Flat	£136.00	1.00	Sole Property Owner	24/04/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	24/04/2013	2013
EES01a Loft Clearance (hourly rate)	£63.26	2.00	Sole Property Owner	07/10/2011	2011
EES03a Remove and replace nailed floor board	£70.80	6.00	Sole Property Owner	07/10/2011	2011
EES02a Remove and dispose existing insulation (per squire metre	£81.90	39.00	Sole Property Owner	07/10/2011	2011
EES08 300mm thick loft insulation	£804.96	39.00	Sole Property Owner	07/10/2011	2011
EES10 Cold water tank insulation quilt	£34.62	1.00	Sole Property Owner	07/10/2011	2011
EES66 Low energy lamp replacement	£19.25	11.00	Sole Property Owner	07/10/2011	2011
EES67 Smoke detector installation	£9.80	1.00	Sole Property Owner	07/10/2011	2011
EES00a Full Energy Survey	£401.70	1.00	Sole Property Owner	07/10/2011	2011
HES66 15mm thick pipework lagging	£38.88	12.00	Joint Owner	24/06/2013	2013
HES67 22mm thick pipework lagging	£59.08	14.00	Joint Owner	24/06/2013	2013
HES68 28mm thick pipework lagging	£18.16	4.00	Joint Owner	24/06/2013	2013
HES94 Heating engineer	£147.20	4.00	Joint Owner	24/06/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£1,725.00	1.00	Joint Owner	24/06/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£400.00	16.00	Joint Owner	24/06/2013	2013
HES03 200mm thick loft insulation quilt	£95.00	10.00	Joint Owner	24/06/2013	2013
HES04 300mm thick loft insulation quilt	£625.00	50.00	Joint Owner	24/06/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	24/06/2013	2013
HES20 Low energy lamp installation	£0.00	25.00	Joint Owner	24/06/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	24/06/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£0.00	0.00	Joint Owner	24/06/2013	2013
HES40 Flue specification and location	£505.26	1.00	Joint Owner	24/06/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Joint Owner	24/06/2013	2013
HES43 Central heating pump	£92.00	1.00	Joint Owner	24/06/2013	2013
HES44 Pipework / feed modifications	£322.00	1.00	Joint Owner	24/06/2013	2013
HES45 Fire valve	£46.00	1.00	Joint Owner	24/06/2013	2013
HES46 Automatic bypass	£31.05	1.00	Joint Owner	24/06/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Joint Owner	24/06/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	24/06/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Joint Owner	24/06/2013	2013
HES51 Thermostatic radiator valve	£21.85	1.00	Joint Owner	24/06/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Joint Owner	24/06/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Joint Owner	24/06/2013	2013
HES55 2 port zone valve	£131.10	2.00	Joint Owner	24/06/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner	24/06/2013	2013
HES67 22mm thick pipework lagging	£25.32	6.00	Joint Owner	24/06/2013	2013
HES68 28mm thick pipework lagging	£9.08	2.00	Joint Owner	24/06/2013	2013
HES93 Junior heating engineer	£43.94	2.00	Joint Owner	24/06/2013	2013
HES94 Heating engineer	£1,030.40	28.00	Joint Owner	24/06/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Joint Owner	24/06/2013	2013
HES98 Senior electrician	£396.80	10.00	Joint Owner	24/06/2013	2013
HES99 Building works	£29.33	1.00	Joint Owner	24/06/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	24/06/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Joint Owner	24/06/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£242.00	1.00	Joint Owner	24/06/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£166.75	1.00	Joint Owner	24/06/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	24/06/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£75.00	3.00	Joint Owner	19/04/2013	2013
HES03 200mm thick loft insulation quilt	£76.00	8.00	Joint Owner	19/04/2013	2013

HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner	19/04/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	4.00	Joint Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	19/04/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/09/2013	2013
HES51 Thermostatic radiator valve	£152.95	7.00	Sole Property Owner	17/09/2013	2013
HES94 Heating engineer	£368.00	10.00	Sole Property Owner	17/09/2013	2013
HES95 Senior heating engineer	£39.68	1.00	Sole Property Owner	17/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£25.30	1.00	Sole Property Owner	17/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£125.00	5.00	Sole Property Owner	17/09/2013	2013
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner	17/09/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,353.60	141.00	Sole Property Owner	17/09/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	17/09/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/09/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£1,476.28	1.00	Sole Property Owner	28/11/2013	2013
HES40 Flue specification and location	£312.00	1.00	Sole Property Owner	28/11/2013	2013
HES41 Condensate pipework (and pump if required)	£120.00	1.00	Sole Property Owner	28/11/2013	2013
HES43 Central heating pump	£141.55	1.00	Sole Property Owner	28/11/2013	2013
HES44 Pipework / feed modifications	£221.00	1.00	Sole Property Owner	28/11/2013	2013
HES45 Fire valve	£42.32	1.00	Sole Property Owner	28/11/2013	2013
HES46 Automatic bypass	£46.32	1.00	Sole Property Owner	28/11/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES50 Electrical room thermostat	£53.32	1.00	Sole Property Owner	28/11/2013	2013
HES53 Two channel heating programmer control	£85.11	1.00	Sole Property Owner	28/11/2013	2013
HES55 2 port zone valve	£138.56	2.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£1,520.00	40.00	Sole Property Owner	28/11/2013	2013
HES97 Electrician	£200.00	8.00	Sole Property Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£25.00	1.00	Sole Property Owner	28/11/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	28/11/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£50.00	2.00	Sole Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£125.00	10.00	Sole Property Owner	28/11/2013	2013
HES112 HER Survey for House	£187.00	1.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	2.00	Sole Property Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Joint Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Joint Owner	20/12/2013	2013
HES94 Heating engineer	£55.20	1.50	Joint Owner	20/12/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Joint Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Joint Owner	20/12/2013	2013
HES94 Heating engineer	£73.60	2.00	Joint Owner	20/12/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Joint Owner	20/12/2013	2013
HES04 300mm thick loft insulation quilt	£612.50	49.00	Joint Owner	20/12/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	20/12/2013	2013
HES15 Draught stripping to exterior door	£15.00	5.00	Joint Owner	20/12/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Joint Owner	20/12/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	20/12/2013	2013
HES48 Power / system flush and treatment	£250.00	1.00	Joint Owner	20/12/2013	2013
HES94 Heating engineer	£141.75	3.00	Joint Owner	20/12/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£70.00	1.00	Joint Owner	20/12/2013	2013
HES66 15mm thick pipework lagging	£29.16	9.00	Joint Owner	31/07/2013	2013
HES67 22mm thick pipework lagging	£33.76	8.00	Joint Owner	31/07/2013	2013
HES94 Heating engineer	£73.60	2.00	Joint Owner	31/07/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	31/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Joint Owner	31/07/2013	2013
HES03 200mm thick loft insulation quilt	£589.00	62.00	Joint Owner	31/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	31/07/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£950.40	99.00	Joint Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Joint Owner	31/07/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	31/07/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,490.80	1.00	Joint Owner	31/07/2013	2013
HES40 Flue specification and location	£325.00	1.00	Joint Owner	31/07/2013	2013
HES41 Condensate pipework (and pump if required)	£114.20	1.00	Joint Owner	31/07/2013	2013
HES42 Purpose built lime soakaway (condensate sump)	£0.00	0.00	Joint Owner	31/07/2013	2013
HES44 Pipework / feed modifications	£289.22	1.00	Joint Owner	31/07/2013	2013
HES45 Fire valve	£36.90	1.00	Joint Owner	31/07/2013	2013
HES46 Automatic bypass	£27.50	1.00	Joint Owner	31/07/2013	2013
HES47 Frost thermostat	£16.51	1.00	Joint Owner	31/07/2013	2013
HES48 Power / system flush and treatment	£43.80	1.00	Joint Owner	31/07/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	31/07/2013	2013
HES50 Electrical room thermostat	£13.45	1.00	Joint Owner	31/07/2013	2013
HES52 Hot water cylinder thermostat	£14.80	1.00	Joint Owner	31/07/2013	2013
HES53 Two channel heating programmer control	£33.80	1.00	Joint Owner	31/07/2013	2013
HES56 3 port zone valve	£59.55	1.00	Joint Owner	31/07/2013	2013
HES66 15mm thick pipework lagging	£9.66	6.00	Joint Owner	31/07/2013	2013
HES67 22mm thick pipework lagging	£35.64	18.00	Joint Owner	31/07/2013	2013
HES68 28mm thick pipework lagging	£0.00	0.00	Joint Owner	31/07/2013	2013
HES95 Senior heating engineer	£1,610.00	46.00	Joint Owner	31/07/2013	2013
HES98 Senior electrician	£280.00	8.00	Joint Owner	31/07/2013	2013
HES99 Building works	£110.00	5.00	Joint Owner	31/07/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Joint Owner	31/07/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£121.10	1.00	Joint Owner	31/07/2013	2013
HES112 HER Survey for House	£0.00	0.00	Sole Property Owner	24/04/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	24/04/2013	2013

HES111 HER Survey for Flat	£136.00	1.00	Sole Property Owner	24/04/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Joint Owner	20/12/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£50.00	2.00	Joint Owner	20/12/2013	2013
HES04 300mm thick loft insulation quilt	£375.00	30.00	Joint Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	15.00	Joint Owner	20/12/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	20/12/2013	2013
HES44 Pipework / feed modifications	£44.20	1.00	Joint Owner	20/12/2013	2013
HES46 Automatic bypass	£27.50	1.00	Joint Owner	20/12/2013	2013
HES68 28mm thick pipework lagging	£7.23	3.00	Joint Owner	20/12/2013	2013
HES95 Senior heating engineer	£280.00	8.00	Joint Owner	20/12/2013	2013
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Sole Property Owner	01/11/2009	2009
EES00a Full Energy Survey	£401.70	1.00	Sole Property Owner	01/11/2009	2009
HES66 15mm thick pipework lagging	£16.20	5.00	Sole Property Owner	19/04/2013	2013
HES67 22mm thick pipework lagging	£12.66	3.00	Sole Property Owner	19/04/2013	2013
HES94 Heating engineer	£55.20	1.50	Sole Property Owner	19/04/2013	2013
HES66 15mm thick pipework lagging	£16.20	5.00	Sole Property Owner	19/04/2013	2013
HES67 22mm thick pipework lagging	£12.66	3.00	Sole Property Owner	19/04/2013	2013
HES94 Heating engineer	£55.20	1.50	Sole Property Owner	19/04/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£650.00	26.00	Sole Property Owner	19/04/2013	2013
HES03 200mm thick loft insulation quilt	£47.50	5.00	Sole Property Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£1,000.00	80.00	Sole Property Owner	19/04/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	40.00	Sole Property Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	19/04/2013	2013
HES51 Thermostatic radiator valve	£0.00	0.00	Sole Property Owner	19/04/2013	2013
HES94 Heating engineer	£0.00	0.00	Sole Property Owner	19/04/2013	2013
HES95 Senior heating engineer	£0.00	0.00	Sole Property Owner	19/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£0.00	0.00	Sole Property Owner	19/04/2013	2013
HES111 HER Survey for Flat	£136.00	1.00	Sole Property Owner	24/04/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	24/04/2013	2013
HES112 HER Survey for House	£187.00	1.00	Joint Owner	24/04/2013	2013
HES20 Low energy lamp installation	£0.00	13.00	Joint Owner	24/04/2013	2013
HES97 Electrician	£200.00	8.00	Sole Property Owner	31/07/2013	2013
HES71 Storage heater rated 1kW - 2kW	£267.32	1.00	Sole Property Owner	31/07/2013	2013
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Sole Property Owner	31/07/2013	2013
HES76 Storage heater miniature circuit breaker	£10.68	2.00	Sole Property Owner	31/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Sole Property Owner	31/07/2013	2013
HES04 300mm thick loft insulation quilt	£687.50	55.00	Sole Property Owner	31/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	31/07/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	31/07/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	31/07/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	17.00	Sole Property Owner	31/07/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	31/07/2013	2013
HES97 Electrician	£425.00	17.00	Sole Property Owner	28/11/2013	2013
HES70 Storage heater rated < 1kW	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES72 Storage heater rated 2kW - 3kW	£684.46	2.00	Sole Property Owner	28/11/2013	2013
HES75 Storage heater consumer unit	£32.92	1.00	Sole Property Owner	28/11/2013	2013
HES76 Storage heater miniature circuit breaker	£16.02	3.00	Sole Property Owner	28/11/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£19.68	3.00	Sole Property Owner	28/11/2013	2013
HES80 16mm meter tails	£14.16	3.00	Sole Property Owner	28/11/2013	2013
HES71 Storage heater rated 1kW - 2kW	£267.32	1.00	Sole Property Owner	28/11/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	28/11/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	17/09/2013	2013
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	17/09/2013	2013
HES94 Heating engineer	£73.60	2.00	Sole Property Owner	17/09/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	17/09/2013	2013
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	17/09/2013	2013
HES94 Heating engineer	£73.60	2.00	Sole Property Owner	17/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£175.00	7.00	Sole Property Owner	17/09/2013	2013
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner	17/09/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	17/09/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£211.20	22.00	Sole Property Owner	17/09/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	17/09/2013	2013
HES66 15mm thick pipework lagging	£71.28	22.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£21.10	5.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£147.20	4.00	Sole Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Sole Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£675.00	54.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES36 12-15kW Gas replacement condensing boiler	£616.00	1.00	Sole Property Owner	28/11/2013	2013
HES40 Flue specification and location	£136.50	1.00	Sole Property Owner	28/11/2013	2013
HES41 Condensate pipework (and pump if required)	£35.00	1.00	Sole Property Owner	28/11/2013	2013
HES44 Pipework / feed modifications	£112.76	112.76	Sole Property Owner	28/11/2013	2013
HES48 Power / system flush and treatment	£250.00	1.00	Sole Property Owner	28/11/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES50 Electrical room thermostat	£15.75	1.00	Sole Property Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£6.69	3.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£17.52	6.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£803.25	17.00	Sole Property Owner	28/11/2013	2013

HES97 Electrician	£141.75	3.00	Sole Property Owner	28/11/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£47.25	1.00	Sole Property Owner	28/11/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£397.40	397.40	Sole Property Owner	28/11/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£303.50	1.00	Sole Property Owner	28/11/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	28/11/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£3.24	1.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£12.66	3.00	Sole Property Owner	17/03/2014	2014
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	17/03/2014	2014
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Sole Property Owner	17/03/2014	2014
HES03 200mm thick loft insulation quilt	£513.00	54.00	Sole Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES32 21-25kW Oil replacement condensing boiler	£1,410.00	1.00	Sole Property Owner	17/03/2014	2014
HES40 Flue specification and location	£486.44	1.00	Sole Property Owner	17/03/2014	2014
HES41 Condensate pipework (and pump if required)	£196.22	1.00	Sole Property Owner	17/03/2014	2014
HES43 Central heating pump	£168.56	2.00	Sole Property Owner	17/03/2014	2014
HES44 Pipework / feed modifications	£385.25	1.00	Sole Property Owner	17/03/2014	2014
HES45 Fire valve	£36.90	1.00	Sole Property Owner	17/03/2014	2014
HES46 Automatic bypass	£55.00	2.00	Sole Property Owner	17/03/2014	2014
HES48 Power / system flush and treatment	£43.80	1.00	Sole Property Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES50 Electrical room thermostat	£13.45	1.00	Sole Property Owner	17/03/2014	2014
HES51 Thermostatic radiator valve	£77.40	6.00	Sole Property Owner	17/03/2014	2014
HES53 Two channel heating programmer control	£33.80	1.00	Sole Property Owner	17/03/2014	2014
HES55 2 port zone valve	£98.00	2.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£3.22	2.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£11.88	6.00	Sole Property Owner	17/03/2014	2014
HES68 28mm thick pipework lagging	£14.46	6.00	Sole Property Owner	17/03/2014	2014
HES95 Senior heating engineer	£1,680.00	48.00	Sole Property Owner	17/03/2014	2014
HES98 Senior electrician	£280.00	8.00	Sole Property Owner	17/03/2014	2014
HES99 Building works	£176.00	8.00	Sole Property Owner	17/03/2014	2014
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Sole Property Owner	17/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£111.00	1.00	Sole Property Owner	17/03/2014	2014
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£375.00	15.00	Joint Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£562.50	45.00	Joint Owner	19/04/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	19/04/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner	19/04/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Joint Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	19/04/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	19/04/2013	2013
HES112 HER Survey for House	£187.00	1.00	Joint Owner	10/05/2013	2013
HES20 Low energy lamp installation	£0.00	22.00	Joint Owner	10/05/2013	2013
EES01a Loft Clearance (hourly rate)	£126.52	4.00	Sole Property Owner	07/09/2011	2011
EES03a Remove and replace nailed floor board	£200.60	17.00	Sole Property Owner	07/09/2011	2011
EES07 200mm thick loft insulation	£313.20	40.00	Sole Property Owner	07/09/2011	2011
EES09 Intumescent bag/fire hood to downlighter	£85.00	4.00	Sole Property Owner	07/09/2011	2011
EES66 Low energy lamp replacement	£38.50	22.00	Sole Property Owner	07/09/2011	2011
EES69 Miscellaneous Charge	£60.00	1.00	Sole Property Owner	07/09/2011	2011
EES38a Thermostatic radiator valve (per valve)	£573.21	9.00	Sole Property Owner	07/09/2011	2011
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	07/09/2011	2011
EES70 Miscellaneous heating review charge	£908.62	1.00	Sole Property Owner	07/09/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	1.00	Sole Property Owner	07/09/2011	2011
EES70 Miscellaneous heating review charge	£608.89	1.00	Sole Property Owner	07/09/2011	2011
EES70 Miscellaneous heating review charge	£215.50	1.00	Sole Property Owner	07/09/2011	2011
EES00a Full Energy Survey	£401.70	1.00	Sole Property Owner	07/09/2011	2011
HES85 Building Control Officer inspection undertaken	£103.85	1.00	Sole Property Owner	07/09/2011	2011
EES31 Hot water cylinder jacket (58x20 inch)	£81.62	1.00	Sole Property Owner	07/09/2011	2011
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Joint Owner	03/07/2013	2013
HES40 Flue specification and location	£207.00	1.00	Joint Owner	03/07/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Joint Owner	03/07/2013	2013
HES44 Pipework / feed modifications	£345.00	1.00	Joint Owner	03/07/2013	2013
HES45 Fire valve	£46.00	1.00	Joint Owner	03/07/2013	2013
HES46 Automatic bypass	£0.00	0.00	Joint Owner	03/07/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Joint Owner	03/07/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	03/07/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Joint Owner	03/07/2013	2013
HES51 Thermostatic radiator valve	£174.80	8.00	Joint Owner	03/07/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Joint Owner	03/07/2013	2013
HES66 15mm thick pipework lagging	£12.96	4.00	Joint Owner	03/07/2013	2013
HES67 22mm thick pipework lagging	£25.32	6.00	Joint Owner	03/07/2013	2013
HES93 Junior heating engineer	£43.94	2.00	Joint Owner	03/07/2013	2013
HES94 Heating engineer	£1,251.20	34.00	Joint Owner	03/07/2013	2013
HES95 Senior heating engineer	£79.36	2.00	Joint Owner	03/07/2013	2013
HES98 Senior electrician	£198.40	5.00	Joint Owner	03/07/2013	2013
HES99 Building works	£0.00	0.00	Joint Owner	03/07/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	03/07/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Joint Owner	03/07/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£1,202.96	1.00	Joint Owner	03/07/2013	2013

HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	03/07/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£415.52	1.00	Joint Owner	03/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£250.00	10.00	Joint Owner	03/07/2013	2013
HES03 200mm thick loft insulation quilt	£237.50	25.00	Joint Owner	03/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	03/07/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,219.20	127.00	Joint Owner	03/07/2013	2013
HES20 Low energy lamp installation	£0.00	6.00	Joint Owner	03/07/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	03/07/2013	2013
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£15.00	1.00	Sole Property Owner	31/07/2013	2013
HES94 Heating engineer	£18.40	0.50	Sole Property Owner	31/07/2013	2013
HES71 Storage heater rated 1kW - 2kW	£267.32	1.00	Sole Property Owner	31/07/2013	2013
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Sole Property Owner	31/07/2013	2013
HES73 Storage heater rated 3kW - 4kW	£833.64	2.00	Sole Property Owner	31/07/2013	2013
HES76 Storage heater miniature circuit breaker	£21.36	4.00	Sole Property Owner	31/07/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£26.24	4.00	Sole Property Owner	31/07/2013	2013
HES97 Electrician	£400.00	16.00	Sole Property Owner	31/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£250.00	10.00	Sole Property Owner	31/07/2013	2013
HES04 300mm thick loft insulation quilt	£437.50	35.00	Sole Property Owner	31/07/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	26.00	Sole Property Owner	31/07/2013	2013
HES101 Asbestos removal & disposal	£190.00	1.00	Joint Owner	26/09/2013	2013
HES66 15mm thick pipework lagging	£12.96	4.00	Joint Owner	26/09/2013	2013
HES67 22mm thick pipework lagging	£33.76	8.00	Joint Owner	26/09/2013	2013
HES94 Heating engineer	£110.40	3.00	Joint Owner	26/09/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	26/09/2013	2013
HES100 Asbestos survey & sample	£176.00	176.00	Joint Owner	26/09/2013	2013
HES67 22mm thick pipework lagging	£69.80	20.00	Joint Owner	26/09/2013	2013
HES68 28mm thick pipework lagging	£22.56	6.00	Joint Owner	26/09/2013	2013
HES94 Heating engineer	£1,824.00	48.00	Joint Owner	26/09/2013	2013
HES97 Electrician	£200.00	8.00	Joint Owner	26/09/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	26/09/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£38.00	1.00	Joint Owner	26/09/2013	2013
HES34 36-45kW Oil replacement condensing boiler	£2,032.40	1.00	Joint Owner	26/09/2013	2013
HES40 Flue specification and location	£536.00	1.00	Joint Owner	26/09/2013	2013
HES41 Condensate pipework (and pump if required)	£100.00	1.00	Joint Owner	26/09/2013	2013
HES43 Central heating pump	£141.55	1.00	Joint Owner	26/09/2013	2013
HES44 Pipework / feed modifications	£350.00	1.00	Joint Owner	26/09/2013	2013
HES46 Automatic bypass	£46.32	1.00	Joint Owner	26/09/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	26/09/2013	2013
HES50 Electrical room thermostat	£53.32	1.00	Joint Owner	26/09/2013	2013
HES51 Thermostatic radiator valve	£180.40	4.00	Joint Owner	26/09/2013	2013
HES52 Hot water cylinder thermostat	£33.21	1.00	Joint Owner	26/09/2013	2013
HES53 Two channel heating programmer control	£85.11	1.00	Joint Owner	26/09/2013	2013
HES55 2 port zone valve	£138.56	2.00	Joint Owner	26/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Joint Owner	26/09/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Joint Owner	26/09/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	26/09/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	26/09/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner	26/09/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	26/09/2013	2013
HES20 Low energy lamp installation	£0.00	30.00	Joint Owner	26/09/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	26/09/2013	2013
HES02 100mm thick loft insulation quilt	£292.50	39.00	Joint Owner	26/09/2013	2013
HES66 15mm thick pipework lagging	£16.20	5.00	Sole Property Owner	16/05/2013	2013
HES67 22mm thick pipework lagging	£4.22	1.00	Sole Property Owner	16/05/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	16/05/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£25.00	1.00	Sole Property Owner	16/05/2013	2013
HES04 300mm thick loft insulation quilt	£625.00	50.00	Sole Property Owner	16/05/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	16/05/2013	2013
HES15 Draught stripping to exterior door	£0.00	0.00	Sole Property Owner	16/05/2013	2013
HES19 Draught proofing labour	£0.00	0.00	Sole Property Owner	16/05/2013	2013
HES20 Low energy lamp installation	£0.00	20.00	Sole Property Owner	16/05/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	16/05/2013	2013
HES44 Pipework / feed modifications	£115.00	1.00	Sole Property Owner	16/05/2013	2013
HES103 Copper replacement hot water cylinder (150L)	£803.85	1.00	Sole Property Owner	16/05/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	16/05/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	16/05/2013	2013
HES93 Junior heating engineer	£21.97	1.00	Sole Property Owner	16/05/2013	2013
HES94 Heating engineer	£220.80	6.00	Sole Property Owner	16/05/2013	2013
HES95 Senior heating engineer	£39.68	1.00	Sole Property Owner	16/05/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£37.30	1.00	Sole Property Owner	16/05/2013	2013
HES20 Low energy lamp installation	£0.00	18.00	Joint Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	19/04/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Joint Owner	19/04/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£6.56	1.00	Sole Property Owner	16/05/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Sole Property Owner	16/05/2013	2013
HES04 300mm thick loft insulation quilt	£1,000.00	80.00	Sole Property Owner	16/05/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	16/05/2013	2013
HES15 Draught stripping to exterior door	£15.00	5.00	Sole Property Owner	16/05/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	16/05/2013	2013
HES20 Low energy lamp installation	£0.00	14.00	Sole Property Owner	16/05/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	16/05/2013	2013
HES70 Storage heater rated < 1kW	£189.46	1.00	Sole Property Owner	16/05/2013	2013
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Sole Property Owner	16/05/2013	2013

HES73 Storage heater rated 3kW - 4kW	£833.64	2.00	Sole Property Owner	16/05/2013	2013
HES97 Electrician	£450.00	18.00	Sole Property Owner	16/05/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£75.00	3.00	Joint Owner	19/04/2013	2013
HES04 300mm thick loft insulation quilt	£450.00	36.00	Joint Owner	19/04/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner	19/04/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Joint Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	19/04/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	19/04/2013	2013
HES67 22mm thick pipework lagging	£25.32	6.00	Sole Property Owner	19/04/2013	2013
HES94 Heating engineer	£55.20	1.50	Sole Property Owner	19/04/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£225.00	9.00	Sole Property Owner	19/04/2013	2013
HES03 200mm thick loft insulation quilt	£380.00	40.00	Sole Property Owner	19/04/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner	19/04/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	19/04/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	28/11/2013	2013
HES101 Asbestos removal & disposal	£180.00	180.00	Joint Owner	28/11/2013	2013
HES100 Asbestos survey & sample	£176.00	176.00	Joint Owner	28/11/2013	2013
HES68 28mm thick pipework lagging	£9.08	2.00	Joint Owner	28/11/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£1,725.00	1.00	Joint Owner	28/11/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Joint Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Joint Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Joint Owner	28/11/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£931.20	97.00	Joint Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	0.00	Joint Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	28/11/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£0.00	0.00	Joint Owner	28/11/2013	2013
HES40 Flue specification and location	£593.98	1.00	Joint Owner	28/11/2013	2013
HES41 Condensate pipework (and pump if required)	£92.00	1.00	Joint Owner	28/11/2013	2013
HES43 Central heating pump	£92.00	1.00	Joint Owner	28/11/2013	2013
HES44 Pipework / feed modifications	£322.00	1.00	Joint Owner	28/11/2013	2013
HES45 Fire valve	£46.00	1.00	Joint Owner	28/11/2013	2013
HES46 Automatic bypass	£31.05	1.00	Joint Owner	28/11/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Joint Owner	28/11/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	28/11/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Joint Owner	28/11/2013	2013
HES51 Thermostatic radiator valve	£174.80	8.00	Joint Owner	28/11/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Joint Owner	28/11/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Joint Owner	28/11/2013	2013
HES55 2 port zone valve	£131.10	2.00	Joint Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£12.96	4.00	Joint Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£50.64	12.00	Joint Owner	28/11/2013	2013
HES93 Junior heating engineer	£65.91	3.00	Joint Owner	28/11/2013	2013
HES94 Heating engineer	£1,398.40	38.00	Joint Owner	28/11/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Joint Owner	28/11/2013	2013
HES98 Senior electrician	£396.80	10.00	Joint Owner	28/11/2013	2013
HES99 Building works	£234.64	8.00	Joint Owner	28/11/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Joint Owner	28/11/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	28/11/2013	2013
HES23 Scaffold / cherry picker	£581.90	1.00	Joint Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£669.30	1.00	Joint Owner	28/11/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£421.48	1.00	Joint Owner	28/11/2013	2013
HES03 200mm thick loft insulation quilt	£399.00	42.00	Joint Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	9.00	Joint Owner	31/07/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	31/07/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Joint Owner	31/07/2013	2013
HES71 Storage heater rated 1kW - 2kW	£534.64	2.00	Joint Owner	31/07/2013	2013
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Joint Owner	31/07/2013	2013
HES76 Storage heater miniature circuit breaker	£16.02	3.00	Joint Owner	31/07/2013	2013
HES97 Electrician	£400.00	16.00	Joint Owner	31/07/2013	2013
EES66 Low energy lamp replacement	£51.20	8.00	Not The Property Owner	12/03/2010	2010
EES66 Low energy lamp replacement	£15.00	2.00	Not The Property Owner	12/03/2010	2010
EES00a Full Energy Survey	£401.70	1.00	Not The Property Owner	12/03/2010	2010
HES01 Loft preparation labour (clearance, disposal of old insulatio	£125.00	5.00	Sole Property Owner	11/06/2013	2013
HES03 200mm thick loft insulation quilt	£285.00	30.00	Sole Property Owner	11/06/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	11/06/2013	2013
HES20 Low energy lamp installation	£0.00	13.00	Sole Property Owner	11/06/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£425.00	17.00	Joint Owner	11/06/2013	2013
HES02 100mm thick loft insulation quilt	£112.50	15.00	Joint Owner	11/06/2013	2013
HES04 300mm thick loft insulation quilt	£425.00	34.00	Joint Owner	11/06/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	11/06/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,094.40	114.00	Joint Owner	11/06/2013	2013
HES20 Low energy lamp installation	£0.00	15.00	Joint Owner	11/06/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	11/06/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£154.95	154.95	Sole Property Owner		0
HES123 BCO Inspection - 2014 Price	£0.00		Sole Property Owner		0
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner		0
HES43 Central heating pump	£84.28	1.00	Sole Property Owner		0
HES44 Pipework / feed modifications	£348.30	1.00	Sole Property Owner		0
HES46 Automatic bypass	£27.50	1.00	Sole Property Owner		0
HES48 Power / system flush and treatment	£43.80	1.00	Sole Property Owner		0
HES50 Electrical room thermostat	£13.45	1.00	Sole Property Owner		0
HES53 Two channel heating programmer control	£33.80	1.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£9.66	6.00	Sole Property Owner		0

HES67 22mm thick pipework lagging	£31.68	16.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£175.00	7.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£500.00	40.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner		0
HES15 Draught stripping to exterior door	£0.00	0.00	Sole Property Owner		0
HES19 Draught proofing labour	£0.00	0.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	7.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner		0
HES107 Electric flow boiler 8-11kW	£685.46	1.00	Sole Property Owner		0
HES51 Thermostatic radiator valve	£64.50	5.00	Sole Property Owner		0
HES54 Water heating time clock and boost controller	£85.90	1.00	Sole Property Owner		0
HES55 2 port zone valve	£49.00	1.00	Sole Property Owner		0
HES95 Senior heating engineer	£1,680.00	48.00	Sole Property Owner		0
HES98 Senior electrician	£980.00	28.00	Sole Property Owner		0
HES99 Building works	£176.00	8.00	Sole Property Owner		0
HES92 Other miscellaneous electrical heating works for EES appr	£401.51	401.51	Sole Property Owner		0
HES44 Pipework / feed modifications	£0.00		Sole Property Owner		0
HES54 Water heating time clock and boost controller	£0.00		Sole Property Owner		0
HES63 Stainless steel replacement hot water cylinder (150L)	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES95 Senior heating engineer	£0.00		Sole Property Owner		0
HES98 Senior electrician	£0.00		Sole Property Owner		0
HES99 Building works	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£300.00	12.00	Sole Property Owner		0
HES02 100mm thick loft insulation quilt	£300.00	40.00	Sole Property Owner		0
HES03 200mm thick loft insulation quilt	£294.50	31.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£3.24	1.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Sole Property Owner		0
HES15 Draught stripping to exterior door	£15.00	5.00	Sole Property Owner		0
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	9.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner		0
HES111 HER Survey for Flat	£136.00	1.00	Sole Property Owner	24/04/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	11/06/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	11/06/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	11/06/2013	2013
HES66 15mm thick pipework lagging	£9.72	3.00	Sole Property Owner	31/10/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	31/10/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£375.00	15.00	Sole Property Owner	31/10/2013	2013
HES02 100mm thick loft insulation quilt	£37.50	5.00	Sole Property Owner	31/10/2013	2013
HES03 200mm thick loft insulation quilt	£484.50	51.00	Sole Property Owner	31/10/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,027.20	107.00	Sole Property Owner	31/10/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	31/10/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	31/10/2013	2013
HES20 Low energy lamp installation	£0.00	35.00	Sole Property Owner	31/10/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	31/10/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	10/09/2013	2013
HES100 Asbestos survey & sample	£186.00	186.00	Sole Property Owner	10/09/2013	2013
HES101 Asbestos removal & disposal	£225.00	225.00	Sole Property Owner	10/09/2013	2013
HES66 15mm thick pipework lagging	£77.76	24.00	Sole Property Owner	10/09/2013	2013
HES68 28mm thick pipework lagging	£27.24	6.00	Sole Property Owner	10/09/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	10/09/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	10/09/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	10/09/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	10/09/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Sole Property Owner	10/09/2013	2013
HES40 Flue specification and location	£744.93	1.00	Sole Property Owner	10/09/2013	2013
HES43 Central heating pump	£92.00	1.00	Sole Property Owner	10/09/2013	2013
HES45 Fire valve	£46.00	1.00	Sole Property Owner	10/09/2013	2013
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner	10/09/2013	2013
HES47 Frost thermostat	£0.00	0.00	Sole Property Owner	10/09/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	10/09/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	10/09/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	10/09/2013	2013
HES51 Thermostatic radiator valve	£131.10	6.00	Sole Property Owner	10/09/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	10/09/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	10/09/2013	2013
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	10/09/2013	2013
HES67 22mm thick pipework lagging	£71.74	17.00	Sole Property Owner	10/09/2013	2013
HES93 Junior heating engineer	£351.52	16.00	Sole Property Owner	10/09/2013	2013
HES94 Heating engineer	£1,361.60	37.00	Sole Property Owner	10/09/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	10/09/2013	2013
HES98 Senior electrician	£396.80	10.00	Sole Property Owner	10/09/2013	2013
HES87 Commissioning and issue of CD10 and Building Control ne	£0.00	1.00	Sole Property Owner	10/09/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	10/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£447.47	1.00	Sole Property Owner	10/09/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£367.14	367.14	Sole Property Owner	10/09/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Sole Property Owner	10/09/2013	2013
HES44 Pipework / feed modifications	£322.00	1.00	Sole Property Owner	10/09/2013	2013
HES02 100mm thick loft insulation quilt	£60.00	8.00	Joint Owner	18/06/2013	2013
HES03 200mm thick loft insulation quilt	£351.50	37.00	Joint Owner	18/06/2013	2013

HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	18/06/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£200.00	8.00	Joint Owner	18/06/2013	2013
HES03 200mm thick loft insulation quilt	£237.50	25.00	Joint Owner	18/06/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£681.60	71.00	Joint Owner	18/06/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Joint Owner	18/06/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	18/06/2013	2013
HES44 Pipework / feed modifications	£115.00	1.00	Joint Owner	18/06/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	18/06/2013	2013
HES51 Thermostatic radiator valve	£131.10	6.00	Joint Owner	18/06/2013	2013
HES103 Copper replacement hot water cylinder (150L)	£803.85	1.00	Joint Owner	18/06/2013	2013
HES67 22mm thick pipework lagging	£0.00	0.00	Joint Owner	18/06/2013	2013
HES93 Junior heating engineer	£43.94	2.00	Joint Owner	18/06/2013	2013
HES94 Heating engineer	£552.00	15.00	Joint Owner	18/06/2013	2013
HES95 Senior heating engineer	£79.36	2.00	Joint Owner	18/06/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£37.30	1.00	Joint Owner	18/06/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£225.00	9.00	Joint Owner	18/06/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Joint Owner	18/06/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Joint Owner	30/09/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner	30/09/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	30/09/2013	2013
HES20 Low energy lamp installation	£0.00	15.00	Joint Owner	30/09/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	30/09/2013	2013
HES23 Scaffold / cherry picker	£0.00	0.00	Joint Owner	30/09/2013	2013
HES33 26-35kW Oil replacement condensing boiler	£2,415.00	1.00	Joint Owner	30/09/2013	2013
HES40 Flue specification and location	£1,324.49	1,324.49	Joint Owner	30/09/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Joint Owner	30/09/2013	2013
HES43 Central heating pump	£92.00	1.00	Joint Owner	30/09/2013	2013
HES44 Pipework / feed modifications	£494.50	1.00	Joint Owner	30/09/2013	2013
HES45 Fire valve	£46.00	1.00	Joint Owner	30/09/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Joint Owner	30/09/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	30/09/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Joint Owner	30/09/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Joint Owner	30/09/2013	2013
HES55 2 port zone valve	£131.10	2.00	Joint Owner	30/09/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Joint Owner	30/09/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Joint Owner	30/09/2013	2013
HES67 22mm thick pipework lagging	£16.88	4.00	Joint Owner	30/09/2013	2013
HES93 Junior heating engineer	£65.91	3.00	Joint Owner	30/09/2013	2013
HES94 Heating engineer	£1,324.80	36.00	Joint Owner	30/09/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Joint Owner	30/09/2013	2013
HES98 Senior electrician	£396.80	10.00	Joint Owner	30/09/2013	2013
HES99 Building works	£87.99	3.00	Joint Owner	30/09/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	30/09/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Joint Owner	30/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£343.85	343.85	Joint Owner	30/09/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£466.33	466.33	Joint Owner	30/09/2013	2013
HES46 Automatic bypass	£31.05	1.00	Joint Owner	30/09/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	30/09/2013	2013
HES101 Asbestos removal & disposal	£88.00	1.00	Joint Owner	30/09/2013	2013
HES68 28mm thick pipework lagging	£45.40	10.00	Joint Owner	30/09/2013	2013
HES23 Scaffold / cherry picker	£57.50	1.00	Joint Owner	30/09/2013	2013
HES111 HER Survey for Flat	£136.00	1.00	Not The Property Owner	24/04/2013	2013
HES20 Low energy lamp installation	£0.00	8.00	Not The Property Owner	24/04/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	11/06/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Joint Owner	11/06/2013	2013
HES21 Smoke detector installation	£0.00	0.00	Joint Owner	11/06/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Joint Owner	11/06/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	07/10/2013	2013
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner	07/10/2013	2013
HES66 15mm thick pipework lagging	£51.84	16.00	Sole Property Owner	07/10/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	07/10/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£375.00	15.00	Sole Property Owner	07/10/2013	2013
HES03 200mm thick loft insulation quilt	£760.00	80.00	Sole Property Owner	07/10/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Sole Property Owner	07/10/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	07/10/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	07/10/2013	2013
HES18 Draught proofing to loft lid	£12.00	4.00	Sole Property Owner	07/10/2013	2013
HES19 Draught proofing labour	£25.00	1.00	Sole Property Owner	07/10/2013	2013
HES20 Low energy lamp installation	£0.00	17.00	Sole Property Owner	07/10/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	07/10/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Sole Property Owner	07/10/2013	2013
HES40 Flue specification and location	£432.69	1.00	Sole Property Owner	07/10/2013	2013
HES41 Condensate pipework (and pump if required)	£207.00	1.00	Sole Property Owner	07/10/2013	2013
HES43 Central heating pump	£92.00	1.00	Sole Property Owner	07/10/2013	2013
HES44 Pipework / feed modifications	£322.00	1.00	Sole Property Owner	07/10/2013	2013
HES45 Fire valve	£46.00	1.00	Sole Property Owner	07/10/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	07/10/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	07/10/2013	2013
HES51 Thermostatic radiator valve	£109.25	5.00	Sole Property Owner	07/10/2013	2013
HES67 22mm thick pipework lagging	£59.08	14.00	Sole Property Owner	07/10/2013	2013
HES68 28mm thick pipework lagging	£27.24	6.00	Sole Property Owner	07/10/2013	2013
HES93 Junior heating engineer	£87.88	4.00	Sole Property Owner	07/10/2013	2013
HES94 Heating engineer	£1,251.20	34.00	Sole Property Owner	07/10/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	07/10/2013	2013

HES98 Senior electrician	£198.40	5.00	Sole Property Owner	07/10/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	07/10/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	07/10/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£416.30	1.00	Sole Property Owner	07/10/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£613.85	1.00	Sole Property Owner	07/10/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£902.40	94.00	Sole Property Owner	07/10/2013	2013
HES112 HER Survey for House	£187.00	1.00	Sole Property Owner	24/04/2013	2013
HES20 Low energy lamp installation	£0.00	16.00	Sole Property Owner	24/04/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Sole Property Owner	24/06/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	24/06/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£100.00	4.00	Sole Property Owner	24/06/2013	2013
HES04 300mm thick loft insulation quilt	£687.50	55.00	Sole Property Owner	24/06/2013	2013
HES06 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	24/06/2013	2013
HES20 Low energy lamp installation	£0.00	15.00	Sole Property Owner	24/06/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	24/06/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	24/06/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£375.00	15.00	Not The Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£525.00	42.00	Not The Property Owner	28/11/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Not The Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	3.00	Not The Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner	28/11/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,123.20	117.00	Joint Owner	24/06/2013	2013
HES20 Low energy lamp installation	£0.00	19.00	Joint Owner	24/06/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	24/06/2013	2013
EES01a Loft Clearance (hourly rate)	£221.38	3.50	Sole Property Owner	01/02/2010	2010
EES03a Remove and replace nailed floor board	£59.00	5.00	Sole Property Owner	01/02/2010	2010
EES02a Remove and dispose existing insulation (per squire metre	£88.20	42.00	Sole Property Owner	01/02/2010	2010
EES08 300mm thick loft insulation	£272.97	27.00	Sole Property Owner	01/02/2010	2010
EES12 Cold water tank lid	£69.24	2.00	Sole Property Owner	01/02/2010	2010
EES22 Mastic pointing	£101.40	26.00	Sole Property Owner	01/02/2010	2010
EES25 Draught stripping to exterior door	£91.00	10.00	Sole Property Owner	01/02/2010	2010
EES26 Draught stripping to windows	£673.40	74.00	Sole Property Owner	01/02/2010	2010
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	01/02/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£40.08	3.00	Sole Property Owner	01/02/2010	2010
EES66 Low energy lamp replacement	£42.00	24.00	Sole Property Owner	01/02/2010	2010
EES67 Smoke detector installation	£19.60	2.00	Sole Property Owner	01/02/2010	2010
EES00a Full Energy Survey	£401.70	1.00	Sole Property Owner	01/02/2010	2010
EES33 Replacement hot water cylinder (150l)	£544.43	1.00	Sole Property Owner	01/02/2010	2010
EES44 Water heating time clock and boost	£134.21	1.00	Sole Property Owner	01/02/2010	2010
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	17/03/2014	2014
HES68 28mm thick pipework lagging	£9.08	2.00	Sole Property Owner	17/03/2014	2014
HES94 Heating engineer	£18.40	0.50	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£3.22	2.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£19.80	10.00	Sole Property Owner	17/03/2014	2014
HES68 28mm thick pipework lagging	£9.64	4.00	Sole Property Owner	17/03/2014	2014
HES95 Senior heating engineer	£140.00	4.00	Sole Property Owner	17/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£12.85	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatic	£125.00	5.00	Sole Property Owner	17/03/2014	2014
HES03 200mm thick loft insulation quilt	£332.50	35.00	Sole Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	15.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	28/11/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Joint Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£12.96	4.00	Joint Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£37.98	9.00	Joint Owner	28/11/2013	2013
HES94 Heating engineer	£110.40	3.00	Joint Owner	28/11/2013	2013
HES100 Asbestos survey & sample	£166.00	166.00	Joint Owner	28/11/2013	2013
HES47 Frost thermostat	£23.00	1.00	Joint Owner	28/11/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Joint Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£200.00	8.00	Joint Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£625.00	50.00	Joint Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	20.00	Joint Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	28/11/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	28/11/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Joint Owner	28/11/2013	2013
HES51 Thermostatic radiator valve	£65.55	3.00	Joint Owner	28/11/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Joint Owner	28/11/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Joint Owner	28/11/2013	2013
HES55 2 port zone valve	£131.10	2.00	Joint Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£3.24	1.00	Joint Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£37.98	9.00	Joint Owner	28/11/2013	2013
HES93 Junior heating engineer	£65.91	3.00	Joint Owner	28/11/2013	2013
HES94 Heating engineer	£368.00	10.00	Joint Owner	28/11/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Joint Owner	28/11/2013	2013
HES98 Senior electrician	£396.80	10.00	Joint Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£243.80	1.00	Joint Owner	28/11/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£625.80	1.00	Joint Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£12.96	4.00	Joint Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£37.98	9.00	Joint Owner	28/11/2013	2013
HES94 Heating engineer	£73.60	2.00	Joint Owner	28/11/2013	2013

HES94 Heating engineer	£304.00	8.00	Sole Property Owner	17/09/2013	2013
HES97 Electrician	£200.00	8.00	Sole Property Owner	17/09/2013	2013
HES73 Storage heater rated 3kW - 4kW	£416.82	1.00	Sole Property Owner	17/09/2013	2013
HES76 Storage heater miniature circuit breaker	£16.02	3.00	Sole Property Owner	17/09/2013	2013
HES54 Water heating time clock and boost controller	£92.95	1.00	Sole Property Owner	17/09/2013	2013
HES65 Stainless steel replacement hot water cylinder (210L)	£590.12	1.00	Sole Property Owner	17/09/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	17/09/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	17/09/2013	2013
HES111 HER Survey for Flat	£136.00	1.00	Sole Property Owner	17/09/2013	2013
HES20 Low energy lamp installation	£0.00	11.00	Sole Property Owner	17/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£175.00	7.00	Joint Owner	31/07/2013	2013
HES04 300mm thick loft insulation quilt	£525.00	42.00	Joint Owner	31/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	15.00	Joint Owner	31/07/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	31/07/2013	2013
HES97 Electrician	£425.00	17.00	Joint Owner	31/07/2013	2013
HES71 Storage heater rated 1kW - 2kW	£267.32	1.00	Joint Owner	31/07/2013	2013
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Joint Owner	31/07/2013	2013
HES73 Storage heater rated 3kW - 4kW	£416.82	1.00	Joint Owner	31/07/2013	2013
HES75 Storage heater consumer unit	£32.92	1.00	Joint Owner	31/07/2013	2013
HES76 Storage heater miniature circuit breaker	£21.36	4.00	Joint Owner	31/07/2013	2013
HES66 15mm thick pipework lagging	£9.72	3.00	Sole Property Owner	31/10/2013	2013
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	31/10/2013	2013
HES68 28mm thick pipework lagging	£9.08	2.00	Sole Property Owner	31/10/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	31/10/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£425.00	17.00	Sole Property Owner	31/10/2013	2013
HES04 300mm thick loft insulation quilt	£812.50	65.00	Sole Property Owner	31/10/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	31/10/2013	2013
HES20 Low energy lamp installation	£0.00	0.00	Sole Property Owner	31/10/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	31/10/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£150.00	6.00	Sole Property Owner	20/12/2013	2013
HES04 300mm thick loft insulation quilt	£687.50	55.00	Sole Property Owner	20/12/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	20/12/2013	2013
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	20/12/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	20/12/2013	2013
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£290.50	1.00	Sole Property Owner	20/12/2013	2013
HES31 16-20kW Oil replacement condensing boiler	£1,278.00	1.00	Sole Property Owner	20/12/2013	2013
HES40 Flue specification and location	£325.00	1.00	Sole Property Owner	20/12/2013	2013
HES41 Condensate pipework (and pump if required)	£214.20	1.00	Sole Property Owner	20/12/2013	2013
HES43 Central heating pump	£84.28	1.00	Sole Property Owner	20/12/2013	2013
HES44 Pipework / feed modifications	£211.40	1.00	Sole Property Owner	20/12/2013	2013
HES45 Fire valve	£36.90	1.00	Sole Property Owner	20/12/2013	2013
HES46 Automatic bypass	£27.50	1.00	Sole Property Owner	20/12/2013	2013
HES48 Power / system flush and treatment	£43.80	1.00	Sole Property Owner	20/12/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	20/12/2013	2013
HES50 Electrical room thermostat	£13.45	1.00	Sole Property Owner	20/12/2013	2013
HES51 Thermostatic radiator valve	£51.60	4.00	Sole Property Owner	20/12/2013	2013
HES53 Two channel heating programmer control	£33.80	1.00	Sole Property Owner	20/12/2013	2013
HES55 2 port zone valve	£98.00	2.00	Sole Property Owner	20/12/2013	2013
HES66 15mm thick pipework lagging	£12.88	8.00	Sole Property Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£15.84	8.00	Sole Property Owner	20/12/2013	2013
HES68 28mm thick pipework lagging	£4.82	2.00	Sole Property Owner	20/12/2013	2013
HES95 Senior heating engineer	£1,400.00	40.00	Sole Property Owner	20/12/2013	2013
HES98 Senior electrician	£350.00	10.00	Sole Property Owner	20/12/2013	2013
HES99 Building works	£88.00	4.00	Sole Property Owner	20/12/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	20/12/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Sole Property Owner	20/12/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£56.40	1.00	Sole Property Owner	20/12/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	20/12/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	20/12/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00	0.00	Joint Owner	02/04/2013	2013
HES03 200mm thick loft insulation quilt	£0.00	0.00	Joint Owner	02/04/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Joint Owner	02/04/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	02/04/2013	2013
HES20 Low energy lamp installation	£0.00	0.00	Joint Owner	02/04/2013	2013
HES21 Smoke detector installation	£0.00	0.00	Joint Owner	02/04/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£283.83	1.00	Joint Owner	31/07/2013	2013
HES94 Heating engineer	£256.00	8.00	Joint Owner	31/07/2013	2013
HES97 Electrician	£32.00	1.00	Joint Owner	31/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Joint Owner	31/07/2013	2013
HES02 100mm thick loft insulation quilt	£487.50	65.00	Joint Owner	31/07/2013	2013
HES03 200mm thick loft insulation quilt	£0.00	0.00	Joint Owner	31/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	3.00	Joint Owner	31/07/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	31/07/2013	2013
HES111 HER Survey for Flat	£136.00	1.00	Joint Owner	24/04/2013	2013
HES20 Low energy lamp installation	£0.00	1.00	Joint Owner	24/04/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	14/08/2013	2013
HES101 Asbestos removal & disposal	£520.00	520.00	Sole Property Owner	14/08/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Sole Property Owner	14/08/2013	2013
HES40 Flue specification and location	£840.08	1.00	Sole Property Owner	14/08/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Sole Property Owner	14/08/2013	2013

HES43 Central heating pump	£92.00	1.00	Sole Property Owner	14/08/2013	2013
HES44 Pipework / feed modifications	£322.00	1.00	Sole Property Owner	14/08/2013	2013
HES45 Fire valve	£46.00	1.00	Sole Property Owner	14/08/2013	2013
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner	14/08/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	14/08/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	14/08/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	14/08/2013	2013
HES51 Thermostatic radiator valve	£174.80	8.00	Sole Property Owner	14/08/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	14/08/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	14/08/2013	2013
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	14/08/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Sole Property Owner	14/08/2013	2013
HES67 22mm thick pipework lagging	£33.76	8.00	Sole Property Owner	14/08/2013	2013
HES68 28mm thick pipework lagging	£18.16	4.00	Sole Property Owner	14/08/2013	2013
HES93 Junior heating engineer	£65.91	3.00	Sole Property Owner	14/08/2013	2013
HES94 Heating engineer	£1,398.40	38.00	Sole Property Owner	14/08/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	14/08/2013	2013
HES98 Senior electrician	£396.80	10.00	Sole Property Owner	14/08/2013	2013
HES99 Building works	£87.99	3.00	Sole Property Owner	14/08/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	14/08/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	14/08/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£218.50	1.00	Sole Property Owner	14/08/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£25.30	1.00	Sole Property Owner	14/08/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£28.75	1.00	Sole Property Owner	14/08/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£196.13	1.00	Sole Property Owner	14/08/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£186.59	186.59	Sole Property Owner	14/08/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	14/08/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£400.00	16.00	Sole Property Owner	14/08/2013	2013
HES04 300mm thick loft insulation quilt	£1,500.00	120.00	Sole Property Owner	14/08/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	14/08/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	14/08/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	14/08/2013	2013
HES20 Low energy lamp installation	£0.00	20.00	Sole Property Owner	14/08/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	14/08/2013	2013
HES48 Power / system flush and treatment	£350.00	1.00	Sole Property Owner	29/11/2013	2013
HES51 Thermostatic radiator valve	£90.00	6.00	Sole Property Owner	29/11/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£412.00	1.00	Sole Property Owner	29/11/2013	2013
HES94 Heating engineer	£396.00	12.00	Sole Property Owner	29/11/2013	2013
HES97 Electrician	£66.00	2.00	Sole Property Owner	29/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£29.00	1.00	Sole Property Owner	29/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£30.00	1.00	Sole Property Owner	29/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£100.00	4.00	Sole Property Owner	29/11/2013	2013
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner	29/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	29/11/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	29/11/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	29/11/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	29/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	29/11/2013	2013
HES72 Storage heater rated 2kW - 3kW	£308.49	1.00	Sole Property Owner	01/08/2013	2013
HES72 Storage heater rated 2kW - 3kW	£0.00	0.00	Sole Property Owner	01/08/2013	2013
HES73 Storage heater rated 3kW - 4kW	£375.34	1.00	Sole Property Owner	01/08/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£231.60	1.00	Sole Property Owner	01/08/2013	2013
HES94 Heating engineer	£192.00	6.00	Sole Property Owner	01/08/2013	2013
HES97 Electrician	£384.00	12.00	Sole Property Owner	01/08/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£5.40	1.00	Sole Property Owner	01/08/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£250.00	10.00	Sole Property Owner	01/08/2013	2013
HES04 300mm thick loft insulation quilt	£1,000.00	80.00	Sole Property Owner	01/08/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	01/08/2013	2013
HES20 Low energy lamp installation	£0.00	15.00	Sole Property Owner	01/08/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Joint Owner	28/11/2013	2013
HES40 Flue specification and location	£207.00	1.00	Joint Owner	28/11/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Joint Owner	28/11/2013	2013
HES44 Pipework / feed modifications	£494.50	1.00	Joint Owner	28/11/2013	2013
HES45 Fire valve	£46.00	1.00	Joint Owner	28/11/2013	2013
HES46 Automatic bypass	£31.05	1.00	Joint Owner	28/11/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Joint Owner	28/11/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	28/11/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Joint Owner	28/11/2013	2013
HES51 Thermostatic radiator valve	£109.25	5.00	Joint Owner	28/11/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Joint Owner	28/11/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Joint Owner	28/11/2013	2013
HES55 2 port zone valve	£131.10	2.00	Joint Owner	28/11/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Joint Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Joint Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£59.08	14.00	Joint Owner	28/11/2013	2013
HES68 28mm thick pipework lagging	£4.54	1.00	Joint Owner	28/11/2013	2013
HES93 Junior heating engineer	£131.82	6.00	Joint Owner	28/11/2013	2013
HES94 Heating engineer	£1,104.00	30.00	Joint Owner	28/11/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Joint Owner	28/11/2013	2013
HES98 Senior electrician	£396.80	10.00	Joint Owner	28/11/2013	2013
HES99 Building works	£29.33	1.00	Joint Owner	28/11/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	28/11/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Joint Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£71.30	1.00	Joint Owner	28/11/2013	2013

HES90 Other miscellaneous oil heating works for EES approval	£25.30	1.00	Joint Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£218.50	1.00	Joint Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£322.00	1.00	Joint Owner	28/11/2013	2013
HES92 Other miscellaneous electrical heating works for EES approval	£574.94	574.94	Joint Owner	28/11/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Joint Owner	28/11/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	28/11/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner	28/11/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,056.00	110.00	Joint Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	25.00	Joint Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	28/11/2013	2013
HES23 Scaffold / cherry picker	£0.00	0.00	Joint Owner	28/11/2013	2013
HES111 HER Survey for Flat	£0.00	0.00	Sole Property Owner	16/01/2013	2013
HES112 HER Survey for House	£187.00	1.00	Sole Property Owner	24/04/2013	2013
HES20 Low energy lamp installation	£0.00	13.00	Sole Property Owner	24/04/2013	2013
HES39 26-35kW Gas replacement condensing boiler	£1,155.00	1.00	Joint Owner		0
HES40 Flue specification and location	£154.90	154.90	Joint Owner		0
HES41 Condensate pipework (and pump if required)	£35.00	35.00	Joint Owner		0
HES44 Pipework / feed modifications	£136.86	136.86	Joint Owner		0
HES48 Power / system flush and treatment	£25.00	1.00	Joint Owner		0
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner		0
HES51 Thermostatic radiator valve	£43.20	3.00	Joint Owner		0
HES54 Water heating time clock and boost controller	£93.31	1.00	Joint Owner		0
HES94 Heating engineer	£840.00	24.00	Joint Owner		0
HES97 Electrician	£70.00	2.00	Joint Owner		0
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner		0
HES15 Draught stripping to exterior door	£15.00	5.00	Joint Owner		0
HES19 Draught proofing labour	£50.00	2.00	Joint Owner		0
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner		0
HES111 HER Survey for Flat	£136.00	1.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	16.00	Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£316.80	33.00	Joint Owner	11/06/2013	2013
HES20 Low energy lamp installation	£0.00	17.00	Joint Owner	11/06/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	11/06/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£750.00	30.00	Sole Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£2,187.50	175.00	Sole Property Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	28/11/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	28/01/2010	2010
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	14/08/2013	2013
HES51 Thermostatic radiator valve	£196.65	9.00	Joint Owner	14/08/2013	2013
HES94 Heating engineer	£331.20	9.00	Joint Owner	14/08/2013	2013
HES95 Senior heating engineer	£39.68	1.00	Joint Owner	14/08/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£25.30	1.00	Joint Owner	14/08/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£225.00	9.00	Joint Owner	14/08/2013	2013
HES03 200mm thick loft insulation quilt	£190.00	20.00	Joint Owner	14/08/2013	2013
HES04 300mm thick loft insulation quilt	£687.50	55.00	Joint Owner	14/08/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Joint Owner	14/08/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	14/08/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Joint Owner	17/09/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	17/09/2013	2013
HES51 Thermostatic radiator valve	£131.10	6.00	Joint Owner	17/09/2013	2013
HES67 22mm thick pipework lagging	£33.76	8.00	Joint Owner	17/09/2013	2013
HES93 Junior heating engineer	£21.97	1.00	Joint Owner	17/09/2013	2013
HES94 Heating engineer	£294.40	8.00	Joint Owner	17/09/2013	2013
HES95 Senior heating engineer	£39.68	1.00	Joint Owner	17/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£25.30	1.00	Joint Owner	17/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£250.00	10.00	Joint Owner	17/09/2013	2013
HES04 300mm thick loft insulation quilt	£562.50	45.00	Joint Owner	17/09/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	17/09/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Joint Owner	17/09/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	17/09/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Sole Property Owner	17/09/2013	2013
HES40 Flue specification and location	£245.94	245.94	Sole Property Owner	17/09/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Sole Property Owner	17/09/2013	2013
HES43 Central heating pump	£92.00	1.00	Sole Property Owner	17/09/2013	2013
HES44 Pipework / feed modifications	£494.50	1.00	Sole Property Owner	17/09/2013	2013
HES45 Fire valve	£46.00	1.00	Sole Property Owner	17/09/2013	2013
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner	17/09/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	17/09/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/09/2013	2013
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	17/09/2013	2013
HES51 Thermostatic radiator valve	£131.10	6.00	Sole Property Owner	17/09/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	17/09/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	17/09/2013	2013
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	17/09/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Sole Property Owner	17/09/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	17/09/2013	2013
HES67 22mm thick pipework lagging	£33.76	8.00	Sole Property Owner	17/09/2013	2013
HES68 28mm thick pipework lagging	£13.62	3.00	Sole Property Owner	17/09/2013	2013
HES93 Junior heating engineer	£65.91	3.00	Sole Property Owner	17/09/2013	2013
HES94 Heating engineer	£1,435.20	39.00	Sole Property Owner	17/09/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	17/09/2013	2013

HES98 Senior electrician	£396.80	10.00	Sole Property Owner	17/09/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	17/09/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	17/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£218.50	1.00	Sole Property Owner	17/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£25.30	1.00	Sole Property Owner	17/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£71.30	1.00	Sole Property Owner	17/09/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£278.27	278.27	Sole Property Owner	17/09/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£292.10	292.10	Sole Property Owner	17/09/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	17/09/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	17/09/2013	2013
HES99 Building works	£58.66	2.00	Sole Property Owner	17/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£41.58	41.58	Sole Property Owner	17/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£100.00	4.00	Sole Property Owner	17/09/2013	2013
HES03 200mm thick loft insulation quilt	£332.50	35.00	Sole Property Owner	17/09/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	17/09/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	17/09/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	17/09/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/09/2013	2013
HES23 Scaffold / cherry picker	£0.00	0.00	Sole Property Owner	17/09/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Joint Owner	22/08/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Joint Owner	22/08/2013	2013
HES94 Heating engineer	£73.60	2.00	Joint Owner	22/08/2013	2013
HES97 Electrician	£200.00	8.00	Joint Owner	22/08/2013	2013
HES73 Storage heater rated 3kW - 4kW	£416.82	1.00	Joint Owner	22/08/2013	2013
HES76 Storage heater miniature circuit breaker	£5.34	1.00	Joint Owner	22/08/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Joint Owner	22/08/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Joint Owner	22/08/2013	2013
HES94 Heating engineer	£55.20	1.50	Joint Owner	22/08/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£175.00	7.00	Joint Owner	22/08/2013	2013
HES04 300mm thick loft insulation quilt	£525.00	42.00	Joint Owner	22/08/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	22/08/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Joint Owner	22/08/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	22/08/2013	2013
HES97 Electrician	£425.00	17.00	Sole Property Owner	31/07/2013	2013
HES70 Storage heater rated < 1kW	£189.46	1.00	Sole Property Owner	31/07/2013	2013
HES73 Storage heater rated 3kW - 4kW	£1,250.46	3.00	Sole Property Owner	31/07/2013	2013
HES75 Storage heater consumer unit	£32.92	1.00	Sole Property Owner	31/07/2013	2013
HES76 Storage heater miniature circuit breaker	£26.70	5.00	Sole Property Owner	31/07/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£26.24	4.00	Sole Property Owner	31/07/2013	2013
HES80 16mm meter tails	£14.16	3.00	Sole Property Owner	31/07/2013	2013
HES54 Water heating time clock and boost controller	£92.95	1.00	Sole Property Owner	31/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£350.00	14.00	Sole Property Owner	31/07/2013	2013
HES04 300mm thick loft insulation quilt	£625.00	50.00	Sole Property Owner	31/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	31/07/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	31/07/2013	2013
HES100 Asbestos survey & sample	£186.00	1.00	Sole Property Owner		0
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner		0
HES36 12-15kW Gas replacement condensing boiler	£616.00	1.00	Sole Property Owner		0
HES40 Flue specification and location	£430.00	1.00	Sole Property Owner		0
HES41 Condensate pipework (and pump if required)	£26.00	26.00	Sole Property Owner		0
HES43 Central heating pump	£71.67	1.00	Sole Property Owner		0
HES44 Pipework / feed modifications	£275.00	275.00	Sole Property Owner		0
HES46 Automatic bypass	£43.30	1.00	Sole Property Owner		0
HES48 Power / system flush and treatment	£250.00	1.00	Sole Property Owner		0
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner		0
HES50 Electrical room thermostat	£15.75	1.00	Sole Property Owner		0
HES52 Hot water cylinder thermostat	£4.62	1.00	Sole Property Owner		0
HES53 Two channel heating programmer control	£46.16	1.00	Sole Property Owner		0
HES55 2 port zone valve	£34.36	2.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£4.46	2.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£5.84	2.00	Sole Property Owner		0
HES94 Heating engineer	£897.75	19.00	Sole Property Owner		0
HES97 Electrician	£283.50	6.00	Sole Property Owner		0
HES88 Commissioning and issue of CD11 and flue gas analysis	£47.25	1.00	Sole Property Owner		0
HES23 Scaffold / cherry picker	£395.00	395.00	Sole Property Owner		0
HES91 Other miscellaneous gas heating works for EES approval	£191.70	191.70	Sole Property Owner		0
HES101 Asbestos removal & disposal	£0.00	0.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£100.00	4.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£375.00	30.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	12.00	Sole Property Owner		0
HES111 HER Survey for Flat	£136.00	1.00	Sole Property Owner	24/04/2013	2013
HES20 Low energy lamp installation	£0.00	4.00	Sole Property Owner	24/04/2013	2013
HES111 HER Survey for Flat	£136.00	1.00	Sole Property Owner	24/04/2013	2013
HES20 Low energy lamp installation	£0.00	6.00	Sole Property Owner	24/04/2013	2013
HES66 15mm thick pipework lagging	£9.72	3.00	Sole Property Owner	17/09/2013	2013
HES67 22mm thick pipework lagging	£4.22	1.00	Sole Property Owner	17/09/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	17/09/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/09/2013	2013
HES51 Thermostatic radiator valve	£174.80	8.00	Sole Property Owner	17/09/2013	2013
HES94 Heating engineer	£294.40	8.00	Sole Property Owner	17/09/2013	2013
HES95 Senior heating engineer	£39.68	1.00	Sole Property Owner	17/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£25.30	1.00	Sole Property Owner	17/09/2013	2013

HES66 15mm thick pipework lagging	£9.72	3.00	Sole Property Owner	17/09/2013	2013
HES67 22mm thick pipework lagging	£4.22	1.00	Sole Property Owner	17/09/2013	2013
HES94 Heating engineer	£55.20	1.50	Sole Property Owner	17/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£125.00	5.00	Sole Property Owner	17/09/2013	2013
HES04 300mm thick loft insulation quilt	£187.50	15.00	Sole Property Owner	17/09/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£537.60	56.00	Sole Property Owner	17/09/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Sole Property Owner	17/09/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	17/09/2013	2013
EES66 Low energy lamp replacement	£159.18	14.00	Sole Property Owner	05/07/2011	2011
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	05/07/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	05/07/2011	2011
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	05/07/2011	2011
HES51 Thermostatic radiator valve	£21.85	1.00	Joint Owner	14/08/2013	2013
HES94 Heating engineer	£73.60	2.00	Joint Owner	14/08/2013	2013
HES95 Senior heating engineer	£39.68	1.00	Joint Owner	14/08/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£250.00	10.00	Joint Owner	14/08/2013	2013
HES03 200mm thick loft insulation quilt	£617.50	65.00	Joint Owner	14/08/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Joint Owner	14/08/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£393.60	41.00	Joint Owner	14/08/2013	2013
HES20 Low energy lamp installation	£0.00	2.00	Joint Owner	14/08/2013	2013
HES02 100mm thick loft insulation quilt	£375.00	50.00	Joint Owner	14/08/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner		0
HES51 Thermostatic radiator valve	£86.40	6.00	Sole Property Owner		0
HES94 Heating engineer	£140.00	4.00	Sole Property Owner		0
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner		0
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner		0
HES111 HER Survey for Flat	£136.00	1.00	Sole Property Owner		0
HES13 Miscellaneous items (brush, airbrick, vent etc), please pro	£68.00	1.00	Sole Property Owner		0
HES33 26-35kW Oil replacement condensing boiler	£2,415.00	1.00	Joint Owner	17/09/2013	2013
HES40 Flue specification and location	£207.00	1.00	Joint Owner	17/09/2013	2013
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Joint Owner	17/09/2013	2013
HES44 Pipework / feed modifications	£322.00	1.00	Joint Owner	17/09/2013	2013
HES45 Fire valve	£46.00	1.00	Joint Owner	17/09/2013	2013
HES46 Automatic bypass	£31.05	1.00	Joint Owner	17/09/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Joint Owner	17/09/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	17/09/2013	2013
HES50 Electrical room thermostat	£43.70	2.00	Joint Owner	17/09/2013	2013
HES51 Thermostatic radiator valve	£174.80	8.00	Joint Owner	17/09/2013	2013
HES52 Hot water cylinder thermostat	£23.00	1.00	Joint Owner	17/09/2013	2013
HES53 Two channel heating programmer control	£74.75	1.00	Joint Owner	17/09/2013	2013
HES55 2 port zone valve	£196.65	3.00	Joint Owner	17/09/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Joint Owner	17/09/2013	2013
HES67 22mm thick pipework lagging	£59.08	14.00	Joint Owner	17/09/2013	2013
HES68 28mm thick pipework lagging	£9.08	2.00	Joint Owner	17/09/2013	2013
HES93 Junior heating engineer	£65.91	3.00	Joint Owner	17/09/2013	2013
HES94 Heating engineer	£1,324.80	36.00	Joint Owner	17/09/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Joint Owner	17/09/2013	2013
HES98 Senior electrician	£515.84	13.00	Joint Owner	17/09/2013	2013
HES99 Building works	£58.66	2.00	Joint Owner	17/09/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	17/09/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Joint Owner	17/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£218.50	1.00	Joint Owner	17/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£25.30	1.00	Joint Owner	17/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£322.00	1.00	Joint Owner	17/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£67.65	1.00	Joint Owner	17/09/2013	2013
HES92 Other miscellaneous electrical heating works for EES appr	£298.08	298.08	Joint Owner	17/09/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	17/09/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner	17/09/2013	2013
HES101 Asbestos removal & disposal	£88.00	1.00	Joint Owner	17/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£400.00	16.00	Joint Owner	17/09/2013	2013
HES04 300mm thick loft insulation quilt	£875.00	70.00	Joint Owner	17/09/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	17/09/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£633.60	66.00	Joint Owner	17/09/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Joint Owner	17/09/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	17/09/2013	2013
HES66 15mm thick pipework lagging	£16.20	5.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£54.86	13.00	Sole Property Owner	28/11/2013	2013
HES68 28mm thick pipework lagging	£4.54	1.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£110.40	3.00	Sole Property Owner	28/11/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Sole Property Owner	28/11/2013	2013
HES03 200mm thick loft insulation quilt	£247.00	26.00	Sole Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£125.00	10.00	Sole Property Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	28/11/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	14.00	Sole Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	28/11/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	17/03/2014	2014
HES124 Central heating pump - 2014 revised	£136.62	1.00	Sole Property Owner	17/03/2014	2014
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	17/03/2014	2014
HES16 Draught stripping to windows	£54.00	18.00	Sole Property Owner	17/03/2014	2014
HES17 Draught stripping to letter boxes	£12.00	1.00	Sole Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£150.00	6.00	Sole Property Owner	17/03/2014	2014

HES38 21-25kW Gas replacement condensing boiler	£1,253.50	1.00	Sole Property Owner	17/03/2014	2014
HES40 Flue specification and location	£103.00	1.00	Sole Property Owner	17/03/2014	2014
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Sole Property Owner	17/03/2014	2014
HES43 Central heating pump	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES44 Pipework / feed modifications	£430.00	1.00	Sole Property Owner	17/03/2014	2014
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	17/03/2014	2014
HES51 Thermostatic radiator valve	£109.25	5.00	Sole Property Owner	17/03/2014	2014
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	17/03/2014	2014
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	17/03/2014	2014
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	17/03/2014	2014
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£59.08	14.00	Sole Property Owner	17/03/2014	2014
HES93 Junior heating engineer	£87.88	4.00	Sole Property Owner	17/03/2014	2014
HES94 Heating engineer	£1,398.40	38.00	Sole Property Owner	17/03/2014	2014
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	17/03/2014	2014
HES98 Senior electrician	£396.80	10.00	Sole Property Owner	17/03/2014	2014
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	17/03/2014	2014
HES91 Other miscellaneous gas heating works for EES approval	£255.30	255.30	Sole Property Owner	17/03/2014	2014
HES92 Other miscellaneous electrical heating works for EES approval	£185.98	185.98	Sole Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£136.00	1.00	Sole Property Owner	17/03/2014	2014
HES13 Miscellaneous items (brush, airbrick, vent etc), please pro	£51.00	1.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	9.00	Sole Property Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£15.00	5.00	Joint Owner	31/07/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	31/07/2013	2013
HES111 HER Survey for Flat	£136.00	1.00	Joint Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	14.00	Joint Owner	31/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£175.00	7.00	Sole Property Owner	28/11/2013	2013
HES02 100mm thick loft insulation quilt	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	28/11/2013	2013
HES15 Draught stripping to exterior door	£15.00	5.00	Sole Property Owner	28/11/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	28/11/2013	2013
HES68 28mm thick pipework lagging	£9.08	2.00	Sole Property Owner	28/11/2013	2013
HES03 200mm thick loft insulation quilt	£95.00	10.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	28/11/2013	2013
HES111 HER Survey for Flat	£136.00	1.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	3.00	Sole Property Owner	28/11/2013	2013
HES37 16-20kW Gas replacement condensing boiler	£0.00	0.00	Joint Owner	17/03/2014	2014
HES40 Flue specification and location	£0.00	0.00	Joint Owner	17/03/2014	2014
HES41 Condensate pipework (and pump if required)	£0.00	0.00	Joint Owner	17/03/2014	2014
HES43 Central heating pump	£0.00	0.00	Joint Owner	17/03/2014	2014
HES44 Pipework / feed modifications	£0.00	0.00	Joint Owner	17/03/2014	2014
HES46 Automatic bypass	£0.00	0.00	Joint Owner	17/03/2014	2014
HES48 Power / system flush and treatment	£0.00	0.00	Joint Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	0.00	Joint Owner	17/03/2014	2014
HES50 Electrical room thermostat	£0.00	0.00	Joint Owner	17/03/2014	2014
HES54 Water heating time clock and boost controller	£0.00	0.00	Joint Owner	17/03/2014	2014
HES94 Heating engineer	£0.00	0.00	Joint Owner	17/03/2014	2014
HES97 Electrician	£0.00	0.00	Joint Owner	17/03/2014	2014
HES91 Other miscellaneous gas heating works for EES approval	£0.00	0.00	Joint Owner	17/03/2014	2014
HES101 Asbestos removal & disposal	£0.00	0.00	Joint Owner	17/03/2014	2014
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	17/03/2014	2014
HES100 Asbestos survey & sample	£176.00	1.00	Joint Owner	17/03/2014	2014
HES37 16-20kW Gas replacement condensing boiler	£0.00		Joint Owner	17/03/2014	2014
HES40 Flue specification and location	£0.00		Joint Owner	17/03/2014	2014
HES41 Condensate pipework (and pump if required)	£0.00		Joint Owner	17/03/2014	2014
HES44 Pipework / feed modifications	£0.00		Joint Owner	17/03/2014	2014
HES46 Automatic bypass	£0.00		Joint Owner	17/03/2014	2014
HES48 Power / system flush and treatment	£0.00		Joint Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00		Joint Owner	17/03/2014	2014
HES50 Electrical room thermostat	£0.00		Joint Owner	17/03/2014	2014
HES52 Hot water cylinder thermostat	£0.00		Joint Owner	17/03/2014	2014
HES53 Two channel heating programmer control	£0.00		Joint Owner	17/03/2014	2014
HES55 2 port zone valve	£0.00		Joint Owner	17/03/2014	2014
HES63 Stainless steel replacement hot water cylinder (150L)	£0.00		Joint Owner	17/03/2014	2014
HES94 Heating engineer	£0.00		Joint Owner	17/03/2014	2014
HES97 Electrician	£0.00		Joint Owner	17/03/2014	2014
HES88 Commissioning and issue of CD11 and flue gas analysis	£0.00		Joint Owner	17/03/2014	2014
HES91 Other miscellaneous gas heating works for EES approval	£0.00		Joint Owner	17/03/2014	2014
HES43 Central heating pump	£0.00		Joint Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£250.00	10.00	Joint Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£375.00	30.00	Joint Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£220.80	23.00	Joint Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	8.00	Joint Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	17/03/2014	2014
EES69 Miscellaneous Charge	£50.00	1.00	Sole Property Owner	01/11/2009	2009
EES00a Full Energy Survey	£401.70	1.00	Sole Property Owner	01/11/2009	2009
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	17/03/2014	2014

HES71 Storage heater rated 1kW - 2kW	£0.00		Sole Property Owner	17/03/2014	2014
HES73 Storage heater rated 3kW - 4kW	£0.00		Sole Property Owner	17/03/2014	2014
HES74 Cornfort heat main switch	£0.00		Sole Property Owner	17/03/2014	2014
HES75 Storage heater consumer unit	£0.00		Sole Property Owner	17/03/2014	2014
HES76 Storage heater miniature circuit breaker	£0.00		Sole Property Owner	17/03/2014	2014
HES78 Twin and earth 16mm cabling with clips and trunking	£0.00		Sole Property Owner	17/03/2014	2014
HES80 16mm meter tails	£0.00		Sole Property Owner	17/03/2014	2014
HES54 Water heating time clock and boost controller	£0.00		Sole Property Owner	17/03/2014	2014
HES97 Electrician	£0.00		Sole Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£136.00	1.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	3.00	Sole Property Owner	17/03/2014	2014
HES64 Stainless steel replacement hot water cylinder (170L)	£283.83	1.00	Sole Property Owner	01/08/2013	2013
HES94 Heating engineer	£256.00	8.00	Sole Property Owner	01/08/2013	2013
HES97 Electrician	£32.00	1.00	Sole Property Owner	01/08/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Sole Property Owner	01/08/2013	2013
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner	01/08/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	01/08/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Sole Property Owner	01/08/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	31/07/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	31/07/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	31/07/2013	2013
HES72 Storage heater rated 2kW - 3kW	£616.98	2.00	Sole Property Owner	31/07/2013	2013
HES73 Storage heater rated 3kW - 4kW	£375.34	1.00	Sole Property Owner	31/07/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£231.60	1.00	Sole Property Owner	31/07/2013	2013
HES94 Heating engineer	£256.00	8.00	Sole Property Owner	31/07/2013	2013
HES97 Electrician	£320.00	10.00	Sole Property Owner	31/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£100.00	4.00	Sole Property Owner	31/07/2013	2013
HES04 300mm thick loft insulation quilt	£175.00	14.00	Sole Property Owner	31/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	13.00	Sole Property Owner	31/07/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	31/07/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner		0
HES92 Other miscellaneous electrical heating works for EES appr	£0.00		Sole Property Owner		0
HES123 BCO Inspection - 2014 Price	£95.00	1.00	Sole Property Owner		0
HES31 16-20kW Oil replacement condensing boiler	£0.00		Sole Property Owner		0
HES41 Condensate pipework (and pump if required)	£0.00		Sole Property Owner		0
HES44 Pipework / feed modifications	£0.00		Sole Property Owner		0
HES45 Fire valve	£0.00		Sole Property Owner		0
HES46 Automatic bypass	£0.00		Sole Property Owner		0
HES48 Power / system flush and treatment	£0.00		Sole Property Owner		0
HES50 Electrical room thermostat	£0.00		Sole Property Owner		0
HES51 Thermostatic radiator valve	£0.00		Sole Property Owner		0
HES53 Two channel heating programmer control	£0.00		Sole Property Owner		0
HES55 2 port zone valve	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES93 Junior heating engineer	£0.00		Sole Property Owner		0
HES94 Heating engineer	£0.00		Sole Property Owner		0
HES95 Senior heating engineer	£0.00		Sole Property Owner		0
HES98 Senior electrician	£0.00		Sole Property Owner		0
HES87 Commissioning and issue of CD10 and Building Control no	£0.00		Sole Property Owner		0
HES88 Commissioning and issue of CD11 and flue gas analysis	£0.00		Sole Property Owner		0
HES90 Other miscellaneous oil heating works for EES approval	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£250.00	10.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£150.00	12.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES15 Draught stripping to exterior door	£30.00	10.00	Not The Property Owner	17/09/2013	2013
HES19 Draught proofing labour	£75.00	3.00	Not The Property Owner	17/09/2013	2013
HES111 HER Survey for Flat	£136.00	1.00	Not The Property Owner	17/09/2013	2013
HES20 Low energy lamp installation	£0.00	11.00	Not The Property Owner	17/09/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£25.92	8.00	Joint Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£12.66	3.00	Joint Owner	28/11/2013	2013
HES94 Heating engineer	£73.60	2.00	Joint Owner	28/11/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,817.37	1.00	Joint Owner	28/11/2013	2013
HES40 Flue specification and location	£521.76	1.00	Joint Owner	28/11/2013	2013
HES41 Condensate pipework (and pump if required)	£106.63	1.00	Joint Owner	28/11/2013	2013
HES43 Central heating pump	£141.55	1.00	Joint Owner	28/11/2013	2013
HES44 Pipework / feed modifications	£273.12	1.00	Joint Owner	28/11/2013	2013
HES46 Automatic bypass	£46.32	1.00	Joint Owner	28/11/2013	2013
HES48 Power / system flush and treatment	£38.00	1.00	Joint Owner	28/11/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	28/11/2013	2013
HES50 Electrical room thermostat	£53.32	1.00	Joint Owner	28/11/2013	2013
HES51 Thermostatic radiator valve	£631.40	14.00	Joint Owner	28/11/2013	2013
HES52 Hot water cylinder thermostat	£33.21	1.00	Joint Owner	28/11/2013	2013
HES53 Two channel heating programmer control	£85.11	1.00	Joint Owner	28/11/2013	2013
HES55 2 port zone valve	£138.56	2.00	Joint Owner	28/11/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£435.60	1.00	Joint Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£69.80	20.00	Joint Owner	28/11/2013	2013
HES68 28mm thick pipework lagging	£37.60	10.00	Joint Owner	28/11/2013	2013
HES94 Heating engineer	£1,444.00	38.00	Joint Owner	28/11/2013	2013

HES97 Electrician	£200.00	8.00	Joint Owner	28/11/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Joint Owner	28/11/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner	28/11/2013	2013
HES101 Asbestos removal & disposal	£180.00	1.00	Joint Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£850.00	34.00	Joint Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£962.50	77.00	Joint Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	28/11/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£912.00	95.00	Joint Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	18.00	Joint Owner	28/11/2013	2013
HES44 Pipework / feed modifications	£172.50	1.00	Sole Property Owner	20/12/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Sole Property Owner	20/12/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES93 Junior heating engineer	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES94 Heating engineer	£294.40	8.00	Sole Property Owner	20/12/2013	2013
HES95 Senior heating engineer	£79.36	2.00	Sole Property Owner	20/12/2013	2013
HES99 Building works	£117.32	4.00	Sole Property Owner	20/12/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£377.72	377.72	Sole Property Owner	20/12/2013	2013
HES15 Draught stripping to exterior door	£15.00	5.00	Sole Property Owner	20/12/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner	20/12/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	20/12/2013	2013
HES71 Storage heater rated 1kW - 2kW	£489.06	2.00	Joint Owner	19/08/2013	2013
HES71 Storage heater rated 1kW - 2kW	£244.53	1.00	Joint Owner	19/08/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£283.83	1.00	Joint Owner	19/08/2013	2013
HES94 Heating engineer	£192.00	6.00	Joint Owner	19/08/2013	2013
HES97 Electrician	£384.00	12.00	Joint Owner	19/08/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Joint Owner	19/08/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	19/08/2013	2013
HES20 Low energy lamp installation	£0.00	6.00	Joint Owner	19/08/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	19/08/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£87.48	1.00	Sole Property Owner	17/09/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	17/09/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	17/09/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£435.60	1.00	Sole Property Owner	17/09/2013	2013
HES67 22mm thick pipework lagging	£34.90	10.00	Sole Property Owner	17/09/2013	2013
HES94 Heating engineer	£760.00	20.00	Sole Property Owner	17/09/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£32.00	1.00	Sole Property Owner	17/09/2013	2013
HES117 Carbon Monoxide alarm	£0.00	0.00	Sole Property Owner	17/09/2013	2013
HES51 Thermostatic radiator valve	£405.90	9.00	Sole Property Owner	17/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£100.00	4.00	Sole Property Owner	17/09/2013	2013
HES03 200mm thick loft insulation quilt	£950.00	100.00	Sole Property Owner	17/09/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	17/09/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	17/09/2013	2013
HES20 Low energy lamp installation	£0.00	20.00	Sole Property Owner	17/09/2013	2013
EES38a Thermostatic radiator valve (per valve)	£296.31	7.00	Not The Property Owner	01/03/2010	2010
EES66 Low energy lamp replacement	£192.00	40.00	Not The Property Owner	01/03/2010	2010
EES00a Full Energy Survey	£401.70	1.00	Not The Property Owner	01/03/2010	2010
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	19/12/2013	2013
HES16 Draught stripping to windows	£117.00	39.00	Not The Property Owner	19/12/2013	2013
HES19 Draught proofing labour	£150.00	6.00	Not The Property Owner	19/12/2013	2013
HES111 HER Survey for Flat	£136.00	1.00	Not The Property Owner	19/12/2013	2013
HES20 Low energy lamp installation	£0.00	6.00	Not The Property Owner	19/12/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	31/07/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	31/07/2013	2013
HES111 HER Survey for Flat	£136.00	1.00	Sole Property Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	3.00	Sole Property Owner	31/07/2013	2013
HES15 Draught stripping to exterior door	£15.00	5.00	Not The Property Owner	17/09/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	17/09/2013	2013
HES111 HER Survey for Flat	£136.00	1.00	Not The Property Owner	17/09/2013	2013
HES20 Low energy lamp installation	£0.00	3.00	Not The Property Owner	17/09/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner		0
HES16 Draught stripping to windows	£27.00	9.00	Sole Property Owner		0
HES19 Draught proofing labour	£100.00	4.00	Sole Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	18.00	Sole Property Owner		0
HES73 Storage heater rated 3kW - 4kW	£0.00		Sole Property Owner		0
HES63 Stainless steel replacement hot water cylinder (150L)	£0.00		Sole Property Owner		0
HES94 Heating engineer	£0.00		Sole Property Owner		0
HES97 Electrician	£0.00		Sole Property Owner		0
HES71 Storage heater rated 1kW - 2kW	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£100.00	4.00	Joint Owner	31/07/2013	2013
HES03 200mm thick loft insulation quilt	£380.00	40.00	Joint Owner	31/07/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£336.00	35.00	Joint Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	6.00	Joint Owner	31/07/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	31/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,075.20	112.00	Sole Property Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	3.00	Sole Property Owner	20/12/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	20/12/2013	2013
HES44 Pipework / feed modifications	£78.80	1.00	Sole Property Owner	20/12/2013	2013
HES46 Automatic bypass	£27.50	1.00	Sole Property Owner	20/12/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	20/12/2013	2013

HES50 Electrical room thermostat	£13.45	1.00	Sole Property Owner	20/12/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£98.65	1.00	Sole Property Owner	20/12/2013	2013
HES66 15mm thick pipework lagging	£3.22	2.00	Sole Property Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£19.80	10.00	Sole Property Owner	20/12/2013	2013
HES68 28mm thick pipework lagging	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES95 Senior heating engineer	£420.00	12.00	Sole Property Owner	20/12/2013	2013
HES98 Senior electrician	£210.00	6.00	Sole Property Owner	20/12/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES15 Draught stripping to exterior door	£21.00	7.00	Sole Property Owner	28/11/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	2.00	Sole Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	28/11/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES95 Senior heating engineer	£79.36	2.00	Sole Property Owner	28/11/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£25.30	1.00	Sole Property Owner	28/11/2013	2013
HES47 Frost thermostat	£16.51	1.00	Sole Property Owner	20/12/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	20/12/2013	2013
HES101 Asbestos removal & disposal	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,410.00	1.00	Sole Property Owner	20/12/2013	2013
HES40 Flue specification and location	£486.44	1.00	Sole Property Owner	20/12/2013	2013
HES41 Condensate pipework (and pump if required)	£72.12	1.00	Sole Property Owner	20/12/2013	2013
HES43 Central heating pump	£84.28	1.00	Sole Property Owner	20/12/2013	2013
HES44 Pipework / feed modifications	£285.80	1.00	Sole Property Owner	20/12/2013	2013
HES45 Fire valve	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES46 Automatic bypass	£27.50	1.00	Sole Property Owner	20/12/2013	2013
HES48 Power / system flush and treatment	£43.80	1.00	Sole Property Owner	20/12/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	20/12/2013	2013
HES50 Electrical room thermostat	£13.45	1.00	Sole Property Owner	20/12/2013	2013
HES52 Hot water cylinder thermostat	£14.80	1.00	Sole Property Owner	20/12/2013	2013
HES53 Two channel heating programmer control	£33.80	1.00	Sole Property Owner	20/12/2013	2013
HES55 2 port zone valve	£98.00	2.00	Sole Property Owner	20/12/2013	2013
HES66 15mm thick pipework lagging	£6.44	4.00	Sole Property Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£3.96	2.00	Sole Property Owner	20/12/2013	2013
HES68 28mm thick pipework lagging	£9.64	4.00	Sole Property Owner	20/12/2013	2013
HES95 Senior heating engineer	£1,400.00	40.00	Sole Property Owner	20/12/2013	2013
HES98 Senior electrician	£280.00	8.00	Sole Property Owner	20/12/2013	2013
HES99 Building works	£110.00	5.00	Sole Property Owner	20/12/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	20/12/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Sole Property Owner	20/12/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£62.90	1.00	Sole Property Owner	20/12/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	20/12/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	20/12/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	15.00	Sole Property Owner	20/12/2013	2013
HES21 Smoke detector installation	£0.00	3.00	Sole Property Owner	20/12/2013	2013
HES23 Scaffold / cherry picker	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES100 Asbestos survey & sample	£186.00	1.00	Sole Property Owner	17/03/2014	2014
HES68 28mm thick pipework lagging	£9.08	2.00	Sole Property Owner	17/03/2014	2014
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£789.54	1.00	Sole Property Owner	17/03/2014	2014
HES31 16-20kW Oil replacement condensing boiler	£1,725.00	1.00	Sole Property Owner	17/03/2014	2014
HES40 Flue specification and location	£432.68	1.00	Sole Property Owner	17/03/2014	2014
HES41 Condensate pipework (and pump if required)	£96.00	1.00	Sole Property Owner	17/03/2014	2014
HES43 Central heating pump	£92.00	1.00	Sole Property Owner	17/03/2014	2014
HES44 Pipework / feed modifications	£322.00	1.00	Sole Property Owner	17/03/2014	2014
HES45 Fire valve	£46.00	1.00	Sole Property Owner	17/03/2014	2014
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner	17/03/2014	2014
HES47 Frost thermostat	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	17/03/2014	2014
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	17/03/2014	2014
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	17/03/2014	2014
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	17/03/2014	2014
HES93 Junior heating engineer	£43.94	2.00	Sole Property Owner	17/03/2014	2014
HES94 Heating engineer	£1,251.20	34.00	Sole Property Owner	17/03/2014	2014
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	17/03/2014	2014
HES98 Senior electrician	£396.80	10.00	Sole Property Owner	17/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£347.33	347.33	Sole Property Owner	17/03/2014	2014
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	17/03/2014	2014
HES101 Asbestos removal & disposal	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£775.00	31.00	Sole Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£625.00	50.00	Sole Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£90.72	28.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£101.28	24.00	Sole Property Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	17/03/2014	2014

HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/03/2014	2014
HES112 HER Survey for House	£0.00	1.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	4.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Sole Property Owner		0
HES19 Draught proofing labour	£0.00		Sole Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	26/07/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Not The Property Owner	26/07/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner	28/11/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	28/11/2013	2013
HES111 HER Survey for Flat	£0.00	1.00	Joint Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Joint Owner	28/11/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	3.00	Sole Property Owner	20/12/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	20/12/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	20/12/2013	2013
HES66 15mm thick pipework lagging	£3.22	2.00	Sole Property Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£11.88	6.00	Sole Property Owner	20/12/2013	2013
HES95 Senior heating engineer	£105.00	3.00	Sole Property Owner	20/12/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	20/12/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£100.00	4.00	Sole Property Owner	11/06/2013	2013
HES04 300mm thick loft insulation quilt	£187.50	15.00	Sole Property Owner	11/06/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	11/06/2013	2013
HES112 HER Survey for House	£0.00	1.00	Not The Property Owner	27/06/2013	2013
HES20 Low energy lamp installation	£0.00	19.00	Not The Property Owner	27/06/2013	2013
HES112 HER Survey for House	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner	28/11/2013	2013
HES15 Draught stripping to exterior door	£3.00	1.00	Sole Property Owner	28/11/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	11.00	Not The Property Owner	16/05/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Not The Property Owner	16/05/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Not The Property Owner	16/05/2013	2013
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	01/11/2009	2009
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	01/11/2009	2009
HES01 Loft preparation labour (clearance, disposal of old insulatic	£175.00	7.00	Sole Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£462.50	37.00	Sole Property Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	28/11/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	28/11/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	18.00	Sole Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£12.96	4.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£42.20	10.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£73.60	2.00	Sole Property Owner	28/11/2013	2013
HES101 Asbestos removal & disposal	£0.00		Sole Property Owner	28/11/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,817.37	1.00	Sole Property Owner	28/11/2013	2013
HES41 Condensate pipework (and pump if required)	£150.00	1.00	Sole Property Owner	28/11/2013	2013
HES43 Central heating pump	£141.55	1.00	Sole Property Owner	28/11/2013	2013
HES44 Pipework / feed modifications	£565.81	1.00	Sole Property Owner	28/11/2013	2013
HES46 Automatic bypass	£46.32	1.00	Sole Property Owner	28/11/2013	2013
HES47 Frost thermostat	£26.58	1.00	Sole Property Owner	28/11/2013	2013
HES51 Thermostatic radiator valve	£45.10	1.00	Sole Property Owner	28/11/2013	2013
HES53 Two channel heating programmer control	£85.11	1.00	Sole Property Owner	28/11/2013	2013
HES55 2 port zone valve	£138.56	2.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£69.80	20.00	Sole Property Owner	28/11/2013	2013
HES68 28mm thick pipework lagging	£75.20	20.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£1,824.00	48.00	Sole Property Owner	28/11/2013	2013
HES97 Electrician	£200.00	8.00	Sole Property Owner	28/11/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£38.00	1.00	Sole Property Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£32.00	1.00	Sole Property Owner	28/11/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	28/11/2013	2013
HES101 Asbestos removal & disposal	£328.00	1.00	Sole Property Owner	28/11/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£12.96	4.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£42.20	10.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£55.20	1.50	Sole Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£250.00	10.00	Sole Property Owner	17/09/2013	2013
HES02 100mm thick loft insulation quilt	£52.50	7.00	Sole Property Owner	17/09/2013	2013
HES04 300mm thick loft insulation quilt	£312.50	25.00	Sole Property Owner	17/09/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Sole Property Owner	17/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00	0.00	Not The Property Owner	25/09/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Not The Property Owner	25/09/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Not The Property Owner	25/09/2013	2013
HES20 Low energy lamp installation	£0.00	0.00	Not The Property Owner	25/09/2013	2013
HES21 Smoke detector installation	£0.00	0.00	Not The Property Owner	25/09/2013	2013
HES117 Carbon Monoxide alarm	£0.00	0.00	Not The Property Owner	25/09/2013	2013
HES53 Two channel heating programmer control	£0.00	0.00	Not The Property Owner	25/09/2013	2013
HES97 Electrician	£0.00	0.00	Not The Property Owner	25/09/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Not The Property Owner	25/09/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	31/07/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	31/07/2013	2013

HES20 Low energy lamp installation	£0.00	5.00	Not The Property Owner	31/07/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner	31/07/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	15.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/03/2014	2014
HES71 Storage heater rated 1kW - 2kW	£0.00		Sole Property Owner	17/03/2014	2014
HES72 Storage heater rated 2kW - 3kW	£0.00		Sole Property Owner	17/03/2014	2014
HES73 Storage heater rated 3kW - 4kW	£0.00		Sole Property Owner	17/03/2014	2014
HES97 Electrician	£0.00		Sole Property Owner	17/03/2014	2014
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£850.00	34.00	Joint Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£775.00	62.00	Joint Owner	28/11/2013	2013
HES15 Draught stripping to exterior door	£15.00	5.00	Joint Owner	28/11/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	28/11/2013	2013
HES100 Asbestos survey & sample	£60.00	1.00	Joint Owner	28/11/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Joint Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£325.00	13.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£1,225.00	98.00	Sole Property Owner		0
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner		0
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	30.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Sole Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	9.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£0.00	1.00	Sole Property Owner	26/07/2013	2013
HES20 Low energy lamp installation	£0.00	4.00	Sole Property Owner	26/07/2013	2013
HES111 HER Survey for Flat	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	9.00	Sole Property Owner	28/11/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	28/11/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£125.00	5.00	Joint Owner	11/12/2013	2013
HES04 300mm thick loft insulation quilt	£562.50	45.00	Joint Owner	11/12/2013	2013
HES20 Low energy lamp installation	£0.00	7.00	Joint Owner	11/12/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	11/12/2013	2013
HES33 26-35kW Oil replacement condensing boiler	£1,752.00	1.00	Joint Owner	11/12/2013	2013
HES40 Flue specification and location	£486.44	1.00	Joint Owner	11/12/2013	2013
HES41 Condensate pipework (and pump if required)	£0.00	0.00	Joint Owner	11/12/2013	2013
HES42 Purpose built lime soakaway (condensate sump)	£228.00	1.00	Joint Owner	11/12/2013	2013
HES43 Central heating pump	£84.28	1.00	Joint Owner	11/12/2013	2013
HES44 Pipework / feed modifications	£232.77	1.00	Joint Owner	11/12/2013	2013
HES45 Fire valve	£36.90	1.00	Joint Owner	11/12/2013	2013
HES46 Automatic bypass	£27.50	1.00	Joint Owner	11/12/2013	2013
HES48 Power / system flush and treatment	£43.80	1.00	Joint Owner	11/12/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	11/12/2013	2013
HES50 Electrical room thermostat	£13.45	1.00	Joint Owner	11/12/2013	2013
HES51 Thermostatic radiator valve	£129.00	10.00	Joint Owner	11/12/2013	2013
HES52 Hot water cylinder thermostat	£14.80	1.00	Joint Owner	11/12/2013	2013
HES53 Two channel heating programmer control	£33.80	1.00	Joint Owner	11/12/2013	2013
HES55 2 port zone valve	£98.00	2.00	Joint Owner	11/12/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner	11/12/2013	2013
HES67 22mm thick pipework lagging	£7.92	4.00	Joint Owner	11/12/2013	2013
HES95 Senior heating engineer	£1,890.00	54.00	Joint Owner	11/12/2013	2013
HES98 Senior electrician	£805.00	23.00	Joint Owner	11/12/2013	2013
HES99 Building works	£110.00	5.00	Joint Owner	11/12/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	11/12/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Joint Owner	11/12/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£206.11	206.11	Joint Owner	11/12/2013	2013
HES101 Asbestos removal & disposal	£370.00	1.00	Joint Owner	11/12/2013	2013
HES72 Storage heater rated 2kW - 3kW	£308.49	1.00	Joint Owner	11/12/2013	2013
HES97 Electrician	£128.00	4.00	Joint Owner	11/12/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	11/12/2013	2013
HES47 Frost thermostat	£16.51	1.00	Joint Owner	11/12/2013	2013
HES100 Asbestos survey & sample	£196.00	1.00	Joint Owner	11/12/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Not The Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£175.00	14.00	Not The Property Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Not The Property Owner	28/11/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£384.00	40.00	Not The Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	15.00	Not The Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner	28/11/2013	2013
HES52 Hot water cylinder thermostat	£0.00	0.00	Not The Property Owner	28/11/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Not The Property Owner	28/11/2013	2013
HES94 Heating engineer	£331.20	9.00	Not The Property Owner	28/11/2013	2013
HES97 Electrician	£0.00	0.00	Not The Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£375.00	15.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£500.00	40.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	6.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner		0
HES94 Heating engineer	£18.40	0.50	Sole Property Owner		0

HES48 Power / system flush and treatment	£250.00	1.00	Sole Property Owner		0
HES51 Thermostatic radiator valve	£144.00	6.00	Sole Property Owner		0
HES94 Heating engineer	£283.50	6.00	Sole Property Owner		0
HES91 Other miscellaneous gas heating works for EES approval	£75.00	1.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES15 Draught stripping to exterior door	£15.00	5.00	Sole Property Owner	20/12/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	3.00	Sole Property Owner	20/12/2013	2013
HES48 Power / system flush and treatment	£250.00	1.00	Sole Property Owner	20/12/2013	2013
HES94 Heating engineer	£236.25	5.00	Sole Property Owner	20/12/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£97.20	1.00	Sole Property Owner	20/12/2013	2013
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Joint Owner	09/08/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	09/08/2012	2012
EES07 200mm thick loft insulation	£162.00	18.00	Joint Owner	09/08/2012	2012
EES25 Draught stripping to exterior door	£120.00	12.00	Joint Owner	09/08/2012	2012
EES66 Low energy lamp replacement	£0.00	4.00	Joint Owner	09/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	09/08/2012	2012
EES00a Full Energy Survey	£290.32	1.00	Joint Owner	09/08/2012	2012
HES01 Loft preparation labour (clearance, disposal of old insulatio	£425.00	17.00	Sole Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£962.50	77.00	Sole Property Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	28/11/2013	2013
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	7.00	Sole Property Owner	28/11/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES51 Thermostatic radiator valve	£43.70	2.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£331.20	9.00	Sole Property Owner	28/11/2013	2013
HES95 Senior heating engineer	£79.36	2.00	Sole Property Owner	28/11/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£37.30	37.30	Sole Property Owner	28/11/2013	2013
HES43 Central heating pump	£92.00	1.00	Sole Property Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£42.20	10.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£16.88	4.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	8.00	Not The Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£100.00	4.00	Not The Property Owner		0
HES03 200mm thick loft insulation quilt	£513.00	54.00	Not The Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£1,000.00	4.00	Not The Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£50.00	1.00	Not The Property Owner		0
HES94 Heating engineer	£36.80	1.00	Not The Property Owner		0
HES117 Carbon Monoxide alarm	£0.00	2.00	Sole Property Owner	17/09/2013	2013
HES94 Heating engineer	£76.00	2.00	Sole Property Owner	17/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£850.00	34.00	Sole Property Owner	17/09/2013	2013
HES04 300mm thick loft insulation quilt	£1,187.50	95.00	Sole Property Owner	17/09/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	17/09/2013	2013
HES20 Low energy lamp installation	£0.00	18.00	Sole Property Owner	17/09/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/09/2013	2013
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Sole Property Owner	17/09/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	17/09/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	17/09/2013	2013
HES68 28mm thick pipework lagging	£36.32	8.00	Sole Property Owner	17/09/2013	2013
HES54 Water heating time clock and boost controller	£86.25	1.00	Not The Property Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Not The Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Not The Property Owner	28/11/2013	2013
HES93 Junior heating engineer	£175.76	8.00	Not The Property Owner	28/11/2013	2013
HES94 Heating engineer	£294.40	8.00	Not The Property Owner	28/11/2013	2013
HES98 Senior electrician	£79.36	2.00	Not The Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Not The Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£625.00	50.00	Not The Property Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Not The Property Owner	28/11/2013	2013
HES15 Draught stripping to exterior door	£15.00	5.00	Not The Property Owner	28/11/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Not The Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner	28/11/2013	2013
HES50 Electrical room thermostat	£0.00	0.00	Not The Property Owner	28/11/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Not The Property Owner	28/11/2013	2013
HES95 Senior heating engineer	£0.00	0.00	Not The Property Owner	28/11/2013	2013
HES99 Building works	£0.00	0.00	Not The Property Owner	28/11/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£0.00	0.00	Not The Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£350.00	14.00	Sole Property Owner	20/12/2013	2013
HES04 300mm thick loft insulation quilt	£1,000.00	80.00	Sole Property Owner	20/12/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£750.00	3.00	Sole Property Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Sole Property Owner	20/12/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	20/12/2013	2013
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES72 Storage heater rated 2kW - 3kW	£616.98	2.00	Sole Property Owner	20/12/2013	2013
HES73 Storage heater rated 3kW - 4kW	£375.34	1.00	Sole Property Owner	20/12/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£283.83	1.00	Sole Property Owner	20/12/2013	2013
HES94 Heating engineer	£256.00	8.00	Sole Property Owner	20/12/2013	2013
HES97 Electrician	£384.00	12.00	Sole Property Owner	20/12/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	20/12/2013	2013
HES04 300mm thick loft insulation quilt	£375.00	30.00	Joint Owner	20/12/2013	2013
HES112 HER Survey for House	£0.00	1.00	Joint Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Joint Owner	20/12/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£75.00	3.00	Joint Owner	20/12/2013	2013

HES02 100mm thick loft insulation quilt	£0.00	0.00	Joint Owner	20/12/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	28/11/2013	2013
EES47 Pipework lagging 13mm thick to 22mm pipe	£35.00	5.00	Joint Owner	02/08/2012	2012
EES69 Miscellaneous Charge	£70.00	1.00	Joint Owner	02/08/2012	2012
EES01a Loft Clearance (hourly rate)	£250.00	10.00	Joint Owner	02/08/2012	2012
EES02a Remove and dispose existing insulation (per squire metre)	£135.00	45.00	Joint Owner	02/08/2012	2012
EES03a Remove and replace nailed floor board	£0.00	0.00	Joint Owner	02/08/2012	2012
EES08 300mm thick loft insulation	£540.00	45.00	Joint Owner	02/08/2012	2012
EES10 Cold water tank insulation quilt	£0.00	0.00	Joint Owner	02/08/2012	2012
EES 11 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	02/08/2012	2012
EES12 Cold water tank lid	£0.00	0.00	Joint Owner	02/08/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£0.00	0.00	Joint Owner	02/08/2012	2012
EES33 Replacement hot water cylinder (150L)	£1,200.00	1.00	Joint Owner	02/08/2012	2012
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Joint Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	7.00	Joint Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	02/08/2012	2012
HES101 Asbestos removal & disposal	£300.00	1.00	Joint Owner	02/08/2012	2012
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£451.20	47.00	Joint Owner	02/08/2012	2012
HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner	23/09/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	23/09/2013	2013
HES20 Low energy lamp installation	£0.00	2.00	Joint Owner	23/09/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES19 Draught proofing labour	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES20 Low energy lamp installation	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES21 Smoke detector installation	£0.00	0.00	Not The Property Owner	10/05/2013	2013
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	26/07/2013	2013
HES20 Low energy lamp installation	£0.00	1.00	Not The Property Owner	26/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£300.00	12.00	Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£275.00	22.00	Not The Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£750.00	3.00	Not The Property Owner		0
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner		0
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Not The Property Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Not The Property Owner		0
HES68 28mm thick pipework lagging	£0.00	0.00	Not The Property Owner		0
HES94 Heating engineer	£0.00	0.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	3.00	Not The Property Owner		0
HES13 Miscellaneous items (brush, airbrick, vent etc), please pro	£138.00	1.00	Not The Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatic	£300.00	12.00	Not The Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£750.00	60.00	Not The Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Not The Property Owner	17/03/2014	2014
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£50.00	1.00	Not The Property Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£36.00	12.00	Not The Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£100.00	4.00	Not The Property Owner	17/03/2014	2014
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Not The Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£0.00	0.00	Not The Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£25.32	6.00	Not The Property Owner	17/03/2014	2014
HES94 Heating engineer	£294.40	8.00	Not The Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00	0.00	Not The Property Owner	25/09/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Not The Property Owner	25/09/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Not The Property Owner	25/09/2013	2013
HES20 Low energy lamp installation	£0.00	0.00	Not The Property Owner	25/09/2013	2013
HES21 Smoke detector installation	£0.00	0.00	Not The Property Owner	25/09/2013	2013
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatic	£125.00	5.00	Sole Property Owner	17/03/2014	2014
HES03 200mm thick loft insulation quilt	£285.00	30.00	Sole Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£710.40	74.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/03/2014	2014
HES64 Stainless steel replacement hot water cylinder (170L)	£283.83	1.00	Sole Property Owner	17/03/2014	2014
HES94 Heating engineer	£256.00	8.00	Sole Property Owner	17/03/2014	2014
HES97 Electrician	£64.00	2.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	11.00	Not The Property Owner	11/06/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner	11/06/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Not The Property Owner	11/06/2013	2013
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Not The Property Owner	26/01/2011	2011
EES03a Remove and replace nailed floor board	£200.60	17.00	Not The Property Owner	26/01/2011	2011
EES08 300mm thick loft insulation	£0.00	0.00	Not The Property Owner	26/01/2011	2011
EES07 200mm thick loft insulation	£1,283.04	144.00	Not The Property Owner	26/01/2011	2011
EES12 Cold water tank lid	£0.00	0.00	Not The Property Owner	26/01/2011	2011
EES 11 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	26/01/2011	2011
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Not The Property Owner	26/01/2011	2011
EES69 Miscellaneous Charge	£0.00	0.00	Not The Property Owner	26/01/2011	2011
EES29 Hot water cylinder jacket (30x18 inch)	£0.00	0.00	Not The Property Owner	26/01/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£163.60	20.00	Not The Property Owner	26/01/2011	2011
EES66 Low energy lamp replacement	£63.00	1.00	Not The Property Owner	26/01/2011	2011
EES38a Thermostatic radiator valve (per valve)	£484.00	11.00	Not The Property Owner	26/01/2011	2011

EES27 Draught stripping to letterbox	£66.60	3.00	Not The Property Owner	26/01/2011	2011
EES25 Draught stripping to exterior door	£91.00	10.00	Not The Property Owner	26/01/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	26/01/2011	2011
HES01 Loft preparation labour (clearance, disposal of old insulatio	£50.00	2.00	Joint Owner	28/11/2013	2013
HES03 200mm thick loft insulation quilt	£256.50	27.00	Joint Owner	28/11/2013	2013
HES112 HER Survey for House	£0.00	1.00	Joint Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	2.00	Joint Owner	28/11/2013	2013
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	26/07/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Not The Property Owner	26/07/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner	26/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Not The Property Owner	31/07/2013	2013
HES04 300mm thick loft insulation quilt	£625.00	50.00	Not The Property Owner	31/07/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Not The Property Owner	31/07/2013	2013
HES20 Low energy lamp installation	£0.00	2.00	Not The Property Owner	31/07/2013	2013
HES117 Carbon Monoxide alarm	£0.00	0.00	Not The Property Owner	31/07/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£275.00	11.00	Joint Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£412.50	33.00	Joint Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	9.00	Joint Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	17/03/2014	2014
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Joint Owner	17/03/2014	2014
HES31 16-20kW Oil replacement condensing boiler	£1,725.00	1.00	Joint Owner	17/03/2014	2014
HES40 Flue specification and location	£317.54	1.00	Joint Owner	17/03/2014	2014
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Joint Owner	17/03/2014	2014
HES43 Central heating pump	£92.00	1.00	Joint Owner	17/03/2014	2014
HES44 Pipework / feed modifications	£322.00	1.00	Joint Owner	17/03/2014	2014
HES45 Fire valve	£46.00	1.00	Joint Owner	17/03/2014	2014
HES46 Automatic bypass	£31.05	1.00	Joint Owner	17/03/2014	2014
HES47 Frost thermostat	£23.00	1.00	Joint Owner	17/03/2014	2014
HES48 Power / system flush and treatment	£460.00	1.00	Joint Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	17/03/2014	2014
HES50 Electrical room thermostat	£21.85	1.00	Joint Owner	17/03/2014	2014
HES51 Thermostatic radiator valve	£131.10	6.00	Joint Owner	17/03/2014	2014
HES52 Hot water cylinder thermostat	£23.00	1.00	Joint Owner	17/03/2014	2014
HES53 Two channel heating programmer control	£74.75	1.00	Joint Owner	17/03/2014	2014
HES55 2 port zone valve	£131.10	2.00	Joint Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£32.40	10.00	Joint Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£50.64	12.00	Joint Owner	17/03/2014	2014
HES68 28mm thick pipework lagging	£45.40	10.00	Joint Owner	17/03/2014	2014
HES93 Junior heating engineer	£109.85	5.00	Joint Owner	17/03/2014	2014
HES94 Heating engineer	£1,251.20	34.00	Joint Owner	17/03/2014	2014
HES95 Senior heating engineer	£119.04	3.00	Joint Owner	17/03/2014	2014
HES98 Senior electrician	£396.80	10.00	Joint Owner	17/03/2014	2014
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	17/03/2014	2014
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Joint Owner	17/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£370.30	1.00	Joint Owner	17/03/2014	2014
HES92 Other miscellaneous electrical heating works for EES appr	£480.10	480.10	Joint Owner	17/03/2014	2014
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	17.00	Not The Property Owner	16/05/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner	16/05/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Not The Property Owner	16/05/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Not The Property Owner	16/05/2013	2013
HES112 HER Survey for House	£0.00	1.00	Not The Property Owner		0
LEL 9W SES	£0.00	2.00	Not The Property Owner		0
LEL 20W BC	£0.00	1.00	Not The Property Owner		0
LEL 11W BC	£0.00	4.00	Not The Property Owner		0
LEL 5W LED GU10	£0.00	4.00	Not The Property Owner		0
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	17/03/2014	2014
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£212.50	8.50	Sole Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£500.00	40.00	Sole Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£25.32	6.00	Sole Property Owner	17/03/2014	2014
HES68 28mm thick pipework lagging	£27.24	6.00	Sole Property Owner	17/03/2014	2014
HES38 21-25kW Gas replacement condensing boiler	£1,253.50	1.00	Sole Property Owner	17/03/2014	2014
HES40 Flue specification and location	£103.00	1.00	Sole Property Owner	17/03/2014	2014
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Sole Property Owner	17/03/2014	2014
HES43 Central heating pump	£92.00	1.00	Sole Property Owner	17/03/2014	2014
HES44 Pipework / feed modifications	£230.00	1.00	Sole Property Owner	17/03/2014	2014
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	17/03/2014	2014
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	17/03/2014	2014
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	17/03/2014	2014
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£32.40	1.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£25.32	6.00	Sole Property Owner	17/03/2014	2014
HES93 Junior heating engineer	£87.88	4.00	Sole Property Owner	17/03/2014	2014
HES94 Heating engineer	£883.20	24.00	Sole Property Owner	17/03/2014	2014
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	17/03/2014	2014
HES98 Senior electrician	£396.80	10.00	Sole Property Owner	17/03/2014	2014

HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	17/03/2014	2014
HES91 Other miscellaneous gas heating works for EES approval	£370.30	1.00	Sole Property Owner	17/03/2014	2014
HES92 Other miscellaneous electrical heating works for EES approval	£397.80	1.00	Sole Property Owner	17/03/2014	2014
HES38 21-25kW Gas replacement condensing boiler	£659.00	1.00	Sole Property Owner		0
HES40 Flue specification and location	£102.00	1.00	Sole Property Owner		0
HES41 Condensate pipework (and pump if required)	£12.75	12.75	Sole Property Owner		0
HES42 Purpose built lime soakaway (condensate sump)	£84.73	1.00	Sole Property Owner		0
HES48 Power / system flush and treatment	£250.00	1.00	Sole Property Owner		0
HES51 Thermostatic radiator valve	£216.00	9.00	Sole Property Owner		0
HES94 Heating engineer	£661.50	14.00	Sole Property Owner		0
HES97 Electrician	£94.50	2.00	Sole Property Owner		0
HES88 Commissioning and issue of CD11 and flue gas analysis	£47.25	1.00	Sole Property Owner		0
HES91 Other miscellaneous gas heating works for EES approval	£149.38	149.38	Sole Property Owner		0
HES91 Other miscellaneous gas heating works for EES approval	£313.88	313.88	Sole Property Owner		0
HES102 QA Survey for House/Bungalow/Flat	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£50.00	2.00	Sole Property Owner		0
HES03 200mm thick loft insulation quilt	£133.00	14.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£175.00	7.00	Joint Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£437.50	35.00	Joint Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	28/11/2013	2013
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Joint Owner	28/11/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£748.80	78.00	Joint Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	5.00	Joint Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	28/11/2013	2013
EES51a 16-20kW Oil replacement boiler	£5,380.00	1.00	Sole Property Owner	29/01/2010	2010
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Sole Property Owner	29/01/2010	2010
EES03a Remove and replace nailed floor board	£212.50	85.00	Sole Property Owner	29/01/2010	2010
EES08 300mm thick loft insulation	£1,021.56	85.13	Sole Property Owner	29/01/2010	2010
EES08 300mm thick loft insulation	£226.44	18.87	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	29/01/2010	2010
HES01 Loft preparation labour (clearance, disposal of old insulatic	£300.00	12.00	Not The Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£1,187.50	95.00	Not The Property Owner	17/03/2014	2014
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Not The Property Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£15.00	5.00	Not The Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	18.00	Not The Property Owner	17/03/2014	2014
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£175.00	7.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,420.80	148.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner		0
HES38 21-25kW Gas replacement condensing boiler	£0.00	0.00	Sole Property Owner		0
HES40 Flue specification and location	£103.00	1.00	Sole Property Owner		0
HES41 Condensate pipework (and pump if required)	£276.00	1.00	Sole Property Owner		0
HES44 Pipework / feed modifications	£115.00	1.00	Sole Property Owner		0
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner		0
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner		0
HES51 Thermostatic radiator valve	£21.85	1.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£12.96	4.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner		0
HES93 Junior heating engineer	£65.91	3.00	Sole Property Owner		0
HES94 Heating engineer	£1,177.60	32.00	Sole Property Owner		0
HES95 Senior heating engineer	£79.36	2.00	Sole Property Owner		0
HES98 Senior electrician	£238.08	6.00	Sole Property Owner		0
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner		0
HES91 Other miscellaneous gas heating works for EES approval	£1,181.51	1.00	Sole Property Owner		0
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,334.40	139.00	Joint Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	6.00	Joint Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	28/11/2013	2013
HES111 HER Survey for Flat	£0.00		Not The Property Owner		0
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	6.00	Not The Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00	0.00	Joint Owner	07/09/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Joint Owner	07/09/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Joint Owner	07/09/2013	2013
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Joint Owner	07/09/2013	2013
HES20 Low energy lamp installation	£0.00	0.00	Joint Owner	07/09/2013	2013
HES21 Smoke detector installation	£0.00	0.00	Joint Owner	07/09/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00	0.00	Not The Property Owner	26/11/2013	2013
HES03 200mm thick loft insulation quilt	£0.00	0.00	Not The Property Owner	26/11/2013	2013
HES20 Low energy lamp installation	£0.00	0.00	Not The Property Owner	26/11/2013	2013
HES21 Smoke detector installation	£0.00	0.00	Not The Property Owner	26/11/2013	2013
HES112 HER Survey for House	£0.00	1.00	Not The Property Owner	26/11/2013	2013

HES20 Low energy lamp installation	£0.00	11.00	Not The Property Owner	26/11/2013	2013
HES68 28mm thick pipework lagging	£18.16	4.00	Not The Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£50.00	2.00	Not The Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£525.00	42.00	Not The Property Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Not The Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	16.00	Not The Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner	28/11/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£0.00	0.00	Not The Property Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£19.44	6.00	Not The Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Not The Property Owner	28/11/2013	2013
HES93 Junior heating engineer	£0.00	0.00	Not The Property Owner	28/11/2013	2013
HES94 Heating engineer	£92.00	2.50	Not The Property Owner	28/11/2013	2013
EES50a 12-15kW Oil replacement boiler	£2,620.00	1.00	Sole Property Owner	29/01/2010	2010
EES70 Miscellaneous heating review charge	£475.00	475.00	Sole Property Owner	29/01/2010	2010
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Sole Property Owner	29/01/2010	2010
EES07 200mm thick loft insulation	£643.50	99.00	Sole Property Owner	29/01/2010	2010
EES15 Insulation to 65mm wide cavity wall	£885.00	118.00	Sole Property Owner	29/01/2010	2010
EES00 Property Assessment	£185.00	1.00	Sole Property Owner	29/01/2010	2010
EES69 Miscellaneous Charge	£905.64	1.00	Sole Property Owner	29/01/2010	2010
HES95 Senior heating engineer	£39.68	1.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	29/01/2010	2010
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	29/01/2010	2010
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Not The Property Owner	07/03/2010	2010
EES69 Miscellaneous Charge	£25.00	1.00	Not The Property Owner	07/03/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	07/03/2010	2010
HES112 HER Survey for House	£0.00	1.00	Sole Property Owner	27/06/2013	2013
HES20 Low energy lamp installation	£0.00	4.00	Sole Property Owner	27/06/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£375.00	15.00	Sole Property Owner		0
HES02 100mm thick loft insulation quilt	£60.00	8.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£500.00	40.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,449.60	151.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	14.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES64 Stainless steel replacement hot water cylinder (170L)	£435.60	1.00	Sole Property Owner		0
HES94 Heating engineer	£304.00	8.00	Sole Property Owner		0
HES97 Electrician	£50.00	2.00	Sole Property Owner		0
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner		0
HES51 Thermostatic radiator valve	£135.30	3.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£19.44	6.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	28/11/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£50.00	2.00	Sole Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£350.00	28.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	7.00	Sole Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£75.00	3.00	Not The Property Owner	17/03/2014	2014
HES03 200mm thick loft insulation quilt	£171.00	18.00	Not The Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Not The Property Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Not The Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£54.86	13.00	Not The Property Owner	17/03/2014	2014
HES94 Heating engineer	£55.20	1.50	Not The Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£225.00	9.00	Joint Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£500.00	40.00	Joint Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	28/11/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£729.60	76.00	Joint Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	8.00	Joint Owner	28/11/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner	28/11/2013	2013
HES72 Storage heater rated 2kW - 3kW	£1,026.69	3.00	Joint Owner	28/11/2013	2013
HES97 Electrician	£425.00	17.00	Joint Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Joint Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£16.88	4.00	Joint Owner	28/11/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	4.00	Not The Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£175.00	7.00	Not The Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£562.50	45.00	Not The Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Not The Property Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£15.00	5.00	Not The Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	2.00	Not The Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner	17/03/2014	2014
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Not The Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£0.00	0.00	Not The Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£42.20	10.00	Not The Property Owner	17/03/2014	2014
HES94 Heating engineer	£331.20	9.00	Not The Property Owner	17/03/2014	2014
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£115.00	1.00	Not The Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£725.00	58.00	Not The Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	7.00	Not The Property Owner		0

HES66 15mm thick pipework lagging	£6.48	2.00	Not The Property Owner		0
HES67 22mm thick pipework lagging	£8.44	2.00	Not The Property Owner		0
HES68 28mm thick pipework lagging	£9.08	2.00	Not The Property Owner		0
HES94 Heating engineer	£55.20	1.50	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	6.00	Not The Property Owner		0
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Sole Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£625.00	50.00	Sole Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	17/03/2014	2014
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£969.60	101.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES94 Heating engineer	£228.00	6.00	Sole Property Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES51 Thermostatic radiator valve	£180.40	4.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£25.92	8.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£75.96	18.00	Sole Property Owner	17/03/2014	2014
HES68 28mm thick pipework lagging	£36.32	8.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00	0.00	Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00	0.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	0.00	Not The Property Owner		0
HES21 Smoke detector installation	£0.00	0.00	Not The Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£375.00	30.00	Not The Property Owner		0
HES15 Draught stripping to exterior door	£15.00	5.00	Not The Property Owner		0
HES16 Draught stripping to windows	£45.00	15.00	Not The Property Owner		0
HES19 Draught proofing labour	£75.00	3.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	5.00	Not The Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	16.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/03/2014	2014
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Sole Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£875.00	70.00	Sole Property Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	28/11/2013	2013
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	8.00	Sole Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	28/11/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	28/11/2013	2013
HES97 Electrician	£400.00	16.00	Sole Property Owner	28/11/2013	2013
HES72 Storage heater rated 2kW - 3kW	£684.46	2.00	Sole Property Owner	28/11/2013	2013
HES73 Storage heater rated 3kW - 4kW	£416.82	1.00	Sole Property Owner	28/11/2013	2013
HES79 Heating point twin and earth mini trunk DP switch	£6.56	1.00	Sole Property Owner	28/11/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£225.00	9.00	Sole Property Owner	20/12/2013	2013
HES04 300mm thick loft insulation quilt	£437.50	35.00	Sole Property Owner	20/12/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	20/12/2013	2013
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,046.40	109.00	Sole Property Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Sole Property Owner	20/12/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	20/12/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	20/12/2013	2013
HES94 Heating engineer	£110.40	3.00	Sole Property Owner	20/12/2013	2013
HES44 Pipework / feed modifications	£172.50	1.00	Sole Property Owner	20/12/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	20/12/2013	2013
HES51 Thermostatic radiator valve	£218.50	10.00	Sole Property Owner	20/12/2013	2013
HES65 Stainless steel replacement hot water cylinder (210L)	£349.20	1.00	Sole Property Owner	20/12/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	20/12/2013	2013
HES68 28mm thick pipework lagging	£9.08	2.00	Sole Property Owner	20/12/2013	2013
HES93 Junior heating engineer	£87.88	4.00	Sole Property Owner	20/12/2013	2013
HES94 Heating engineer	£515.20	14.00	Sole Property Owner	20/12/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	20/12/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£25.30	1.00	Sole Property Owner	20/12/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£100.00	1.00	Sole Property Owner	20/12/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00	0.00	Not The Property Owner	05/09/2013	2013
HES03 200mm thick loft insulation quilt	£0.00	0.00	Not The Property Owner	05/09/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Not The Property Owner	05/09/2013	2013
HES20 Low energy lamp installation	£0.00	0.00	Not The Property Owner	05/09/2013	2013
HES21 Smoke detector installation	£0.00	0.00	Not The Property Owner	05/09/2013	2013
HES51 Thermostatic radiator valve	£0.00	0.00	Not The Property Owner	05/09/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Not The Property Owner	05/09/2013	2013
HES67 22mm thick pipework lagging	£0.00	0.00	Not The Property Owner	05/09/2013	2013
HES94 Heating engineer	£0.00	0.00	Not The Property Owner	05/09/2013	2013
HES112 HER Survey for House	£0.00	1.00	Not The Property Owner	26/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£100.00	4.00	Not The Property Owner	17/03/2014	2014
HES02 100mm thick loft insulation quilt	£105.00	14.00	Not The Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£87.50	7.00	Not The Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	4.00	Not The Property Owner	17/03/2014	2014
HES112 HER Survey for House	£0.00	1.00	Not The Property Owner	21/01/2014	2014

HES20 Low energy lamp installation	£0.00	2.00	Not The Property Owner	21/01/2014	2014
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	01/11/2009	2009
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	01/11/2009	2009
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	26/11/2013	2013
HES101 Asbestos removal & disposal	£250.00	1.00	Sole Property Owner	01/04/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£115.00	1.00	Sole Property Owner	01/04/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£175.00	7.00	Sole Property Owner	01/04/2014	2014
HES03 200mm thick loft insulation quilt	£256.50	27.00	Sole Property Owner	01/04/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	01/04/2014	2014
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Sole Property Owner	01/04/2014	2014
HES20 Low energy lamp installation	£0.00	3.00	Sole Property Owner	01/04/2014	2014
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	01/04/2014	2014
HES66 15mm thick pipework lagging	£16.20	5.00	Sole Property Owner	01/04/2014	2014
HES67 22mm thick pipework lagging	£33.76	8.00	Sole Property Owner	01/04/2014	2014
HES100 Asbestos survey & sample	£176.00	1.00	Sole Property Owner	01/04/2014	2014
HES31 16-20kW Oil replacement condensing boiler	£1,725.00	1.00	Sole Property Owner	01/04/2014	2014
HES40 Flue specification and location	£507.67	1.00	Sole Property Owner	01/04/2014	2014
HES41 Condensate pipework (and pump if required)	£92.00	1.00	Sole Property Owner	01/04/2014	2014
HES43 Central heating pump	£92.00	1.00	Sole Property Owner	01/04/2014	2014
HES44 Pipework / feed modifications	£908.50	1.00	Sole Property Owner	01/04/2014	2014
HES45 Fire valve	£46.00	1.00	Sole Property Owner	01/04/2014	2014
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner	01/04/2014	2014
HES47 Frost thermostat	£23.00	1.00	Sole Property Owner	01/04/2014	2014
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	01/04/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	01/04/2014	2014
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	01/04/2014	2014
HES51 Thermostatic radiator valve	£65.55	3.00	Sole Property Owner	01/04/2014	2014
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	01/04/2014	2014
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	01/04/2014	2014
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	01/04/2014	2014
HES64 Stainless steel replacement hot water cylinder (170L)	£304.80	1.00	Sole Property Owner	01/04/2014	2014
HES66 15mm thick pipework lagging	£16.20	5.00	Sole Property Owner	01/04/2014	2014
HES67 22mm thick pipework lagging	£84.40	20.00	Sole Property Owner	01/04/2014	2014
HES68 28mm thick pipework lagging	£45.40	10.00	Sole Property Owner	01/04/2014	2014
HES93 Junior heating engineer	£131.82	6.00	Sole Property Owner	01/04/2014	2014
HES94 Heating engineer	£1,803.20	49.00	Sole Property Owner	01/04/2014	2014
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	01/04/2014	2014
HES98 Senior electrician	£476.16	12.00	Sole Property Owner	01/04/2014	2014
HES99 Building works	£87.99	3.00	Sole Property Owner	01/04/2014	2014
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	01/04/2014	2014
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	01/04/2014	2014
HES92 Other miscellaneous electrical heating works for EES appr	£346.27	1.00	Sole Property Owner	01/04/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£441.80	1.00	Sole Property Owner	01/04/2014	2014
HES101 Asbestos removal & disposal	£3,200.00	1.00	Sole Property Owner	01/04/2014	2014
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	01/04/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£100.00	4.00	Not The Property Owner	28/11/2013	2013
HES03 200mm thick loft insulation quilt	£123.50	13.00	Not The Property Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Not The Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	12.00	Not The Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner	28/11/2013	2013
HES51 Thermostatic radiator valve	£131.10	6.00	Not The Property Owner	28/11/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Not The Property Owner	28/11/2013	2013
HES93 Junior heating engineer	£0.00	0.00	Not The Property Owner	28/11/2013	2013
HES94 Heating engineer	£331.20	9.00	Not The Property Owner	28/11/2013	2013
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£71.30	1.00	Not The Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£175.00	7.00	Joint Owner	20/12/2013	2013
HES04 300mm thick loft insulation quilt	£1,000.00	80.00	Joint Owner	20/12/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£750.00	3.00	Joint Owner	20/12/2013	2013
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Joint Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	2.00	Joint Owner	20/12/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	20/12/2013	2013
HES97 Electrician	£425.00	17.00	Joint Owner	20/12/2013	2013
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Joint Owner	20/12/2013	2013
HES73 Storage heater rated 3kW - 4kW	£416.82	1.00	Joint Owner	20/12/2013	2013
HES76 Storage heater miniature circuit breaker	£21.36	4.00	Joint Owner	20/12/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner	20/12/2013	2013
HES66 15mm thick pipework lagging	£12.96	4.00	Joint Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£25.32	6.00	Joint Owner	20/12/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	6.00	Not The Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£75.00	3.00	Sole Property Owner		0
HES03 200mm thick loft insulation quilt	£665.00	70.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	15.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner		0
HES94 Heating engineer	£18.40	0.50	Sole Property Owner		0
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner		0
HES72 Storage heater rated 2kW - 3kW	£1,368.92	4.00	Sole Property Owner		0
HES75 Storage heater consumer unit	£32.92	1.00	Sole Property Owner		0
HES76 Storage heater miniature circuit breaker	£26.70	5.00	Sole Property Owner		0

HES89 Explanation of controls, manuals, EIC certification and sch	£0.00	1.00	Sole Property Owner		0
HES97 Electrician	£450.00	18.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00	0.00	Not The Property Owner	01/10/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Not The Property Owner	01/10/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Not The Property Owner	01/10/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Not The Property Owner	01/10/2013	2013
HES20 Low energy lamp installation	£0.00	0.00	Not The Property Owner	01/10/2013	2013
HES21 Smoke detector installation	£0.00	0.00	Not The Property Owner	01/10/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£0.00	0.00	Not The Property Owner	01/10/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Not The Property Owner	01/10/2013	2013
HES94 Heating engineer	£0.00	0.00	Not The Property Owner	01/10/2013	2013
HES112 HER Survey for House	£0.00	1.00	Joint Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	20.00	Joint Owner	28/11/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner	28/11/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Joint Owner	28/11/2013	2013
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Sole Property Owner	16/12/2011	2011
EES07 200mm thick loft insulation	£720.00	80.00	Sole Property Owner	16/12/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	16/12/2011	2011
HES112 HER Survey for House	£0.00	1.00	Not The Property Owner	27/06/2013	2013
HES20 Low energy lamp installation	£0.00	4.00	Not The Property Owner	27/06/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£125.00	5.00	Not The Property Owner	17/03/2014	2014
HES03 200mm thick loft insulation quilt	£617.50	65.00	Not The Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Not The Property Owner	17/03/2014	2014
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£50.00	1.00	Not The Property Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£15.00	5.00	Not The Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£0.00	0.00	Not The Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£0.00	0.00	Not The Property Owner	17/03/2014	2014
HES94 Heating engineer	£0.00	0.00	Not The Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	6.00	Not The Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£6.48	2.00	Joint Owner		0
HES67 22mm thick pipework lagging	£8.44	2.00	Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,008.00	105.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	15.00	Joint Owner		0
HES21 Smoke detector installation	£0.00	2.00	Joint Owner		0
HES44 Pipework / feed modifications	£115.00	115.00	Joint Owner		0
HES64 Stainless steel replacement hot water cylinder (170L)	£0.00	0.00	Joint Owner		0
HES94 Heating engineer	£294.40	8.00	Joint Owner		0
HES90 Other miscellaneous oil heating works for EES approval	£0.00	0.00	Joint Owner		0
HES104 Copper replacement hot water cylinder (170L)	£1,045.35	1.00	Joint Owner		0
HES15 Draught stripping to exterior door	£36.00	12.00	Not The Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£75.00	3.00	Not The Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	3.00	Not The Property Owner	17/03/2014	2014
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatic	£250.00	10.00	Sole Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£500.00	40.00	Sole Property Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	16.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/03/2014	2014
HES100 Asbestos survey & sample	£176.00	1.00	Sole Property Owner	17/03/2014	2014
HES71 Storage heater rated 1kW - 2kW	£534.64	2.00	Sole Property Owner	17/03/2014	2014
HES73 Storage heater rated 3kW - 4kW	£416.82	1.00	Sole Property Owner	17/03/2014	2014
HES79 Heating point twin and earth mini trunk DP switch	£13.12	2.00	Sole Property Owner	17/03/2014	2014
HES97 Electrician	£400.00	16.00	Sole Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	6.00	Not The Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatic	£100.00	4.00	Not The Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£1,000.00	80.00	Not The Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Not The Property Owner	17/03/2014	2014
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£50.00	1.00	Not The Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£29.16	9.00	Not The Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£84.40	20.00	Not The Property Owner	17/03/2014	2014
HES94 Heating engineer	£276.00	7.50	Not The Property Owner	17/03/2014	2014
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	17.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	17/03/2014	2014
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Sole Property Owner	17/03/2014	2014
HES40 Flue specification and location	£147.12	147.12	Sole Property Owner	17/03/2014	2014
HES41 Condensate pipework (and pump if required)	£92.00	92.00	Sole Property Owner	17/03/2014	2014
HES44 Pipework / feed modifications	£322.00	322.00	Sole Property Owner	17/03/2014	2014
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner	17/03/2014	2014
HES47 Frost thermostat	£23.00	1.00	Sole Property Owner	17/03/2014	2014
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	17/03/2014	2014
HES52 Hot water cylinder thermostat	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	17/03/2014	2014
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	17/03/2014	2014
HES45 Fire valve	£46.00	1.00	Sole Property Owner	17/03/2014	2014
HES65 Stainless steel replacement hot water cylinder (210L)	£349.20	1.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	17/03/2014	2014

HES67 22mm thick pipework lagging	£59.08	14.00	Sole Property Owner	17/03/2014	2014
HES93 Junior heating engineer	£87.88	4.00	Sole Property Owner	17/03/2014	2014
HES94 Heating engineer	£1,288.00	35.00	Sole Property Owner	17/03/2014	2014
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	17/03/2014	2014
HES98 Senior electrician	£436.48	11.00	Sole Property Owner	17/03/2014	2014
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	17/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£928.97	928.97	Sole Property Owner	17/03/2014	2014
HES92 Other miscellaneous electrical heating works for EES appr	£227.13	227.13	Sole Property Owner	17/03/2014	2014
HES92 Other miscellaneous electrical heating works for EES appr	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£250.00	10.00	Sole Property Owner	20/12/2013	2013
HES03 200mm thick loft insulation quilt	£237.50	25.00	Sole Property Owner	20/12/2013	2013
HES04 300mm thick loft insulation quilt	£437.50	35.00	Sole Property Owner	20/12/2013	2013
HES111 HER Survey for Flat	£0.00	1.00	Sole Property Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	6.00	Sole Property Owner	20/12/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner		0
HES71 Storage heater rated 1kW - 2kW	£0.00		Sole Property Owner		0
HES72 Storage heater rated 2kW - 3kW	£0.00		Sole Property Owner		0
HES97 Electrician	£0.00		Sole Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	26/07/2013	2013
HES20 Low energy lamp installation	£0.00	8.00	Not The Property Owner	26/07/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£425.00	17.00	Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£687.50	55.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	0.00	Not The Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Not The Property Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Not The Property Owner		0
HES15 Draught stripping to exterior door	£15.00	5.00	Not The Property Owner		0
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner		0
HES15 Draught stripping to exterior door	£15.00	5.00	Not The Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£75.00	3.00	Not The Property Owner	28/11/2013	2013
HES03 200mm thick loft insulation quilt	£199.50	21.00	Not The Property Owner	28/11/2013	2013
HES04 300mm thick loft insulation quilt	£700.00	56.00	Not The Property Owner	28/11/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Not The Property Owner	28/11/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Not The Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	9.00	Not The Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner	28/11/2013	2013
HES117 Carbon Monoxide alarm	£0.00	0.00	Not The Property Owner	28/11/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£0.00	0.00	Not The Property Owner	28/11/2013	2013
HES94 Heating engineer	£0.00	0.00	Not The Property Owner	28/11/2013	2013
HES15 Draught stripping to exterior door	£15.00	5.00	Not The Property Owner	28/11/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	28/11/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£12.00	4.00	Sole Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES72 Storage heater rated 2kW - 3kW	£0.00		Sole Property Owner	17/03/2014	2014
HES73 Storage heater rated 3kW - 4kW	£0.00		Sole Property Owner	17/03/2014	2014
HES97 Electrician	£0.00		Sole Property Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	17/03/2014	2014
HES112 HER Survey for House	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	4.00	Not The Property Owner	17/03/2014	2014
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Sole Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£48.60	15.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£25.32	6.00	Sole Property Owner	17/03/2014	2014
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£425.00	1.00	Sole Property Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£988.80	103.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	13.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/03/2014	2014
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	17/03/2014	2014
HES31 16-20kW Oil replacement condensing boiler	£1,725.00	1.00	Sole Property Owner	17/03/2014	2014
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Sole Property Owner	17/03/2014	2014
HES40 Flue specification and location	£207.00	1.00	Sole Property Owner	17/03/2014	2014
HES43 Central heating pump	£92.00	1.00	Sole Property Owner	17/03/2014	2014
HES44 Pipework / feed modifications	£322.00	1.00	Sole Property Owner	17/03/2014	2014
HES45 Fire valve	£46.00	1.00	Sole Property Owner	17/03/2014	2014
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	17/03/2014	2014
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	17/03/2014	2014
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	17/03/2014	2014
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£12.96	4.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£25.32	6.00	Sole Property Owner	17/03/2014	2014
HES93 Junior heating engineer	£65.91	3.00	Sole Property Owner	17/03/2014	2014

HES94 Heating engineer	£883.20	24.00	Sole Property Owner	17/03/2014	2014
HES98 Senior electrician	£396.80	10.00	Sole Property Owner	17/03/2014	2014
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner	17/03/2014	2014
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	17/03/2014	2014
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	17/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£370.30	1.00	Sole Property Owner	17/03/2014	2014
HES92 Other miscellaneous electrical heating works for EES appr	£441.90	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£62.50	2.50	Joint Owner	20/12/2013	2013
HES03 200mm thick loft insulation quilt	£437.00	46.00	Joint Owner	20/12/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	20/12/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Joint Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Joint Owner	20/12/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,257.60	131.00	Joint Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	17.00	Joint Owner	20/12/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	20/12/2013	2013
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Not The Property Owner	16/12/2011	2011
EES07 200mm thick loft insulation	£289.44	36.00	Not The Property Owner	16/12/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	16/12/2011	2011
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Joint Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Joint Owner		0
HES20 Low energy lamp installation	£0.00		Joint Owner		0
HES21 Smoke detector installation	£0.00		Joint Owner		0
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner		0
HES50 Electrical room thermostat	£21.85	1.00	Joint Owner		0
HES95 Senior heating engineer	£79.36	2.00	Joint Owner		0
HES98 Senior electrician	£119.04	3.00	Joint Owner		0
HES73 Storage heater rated 3kW - 4kW	£0.00		Sole Property Owner		0
HES97 Electrician	£0.00		Sole Property Owner		0
HES100 Asbestos survey & sample	£0.00		Sole Property Owner		0
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner		0
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	0.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£12.96	4.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£25.32	6.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,401.60	146.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	23.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	0.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£816.00	85.00	Not The Property Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£15.00	5.00	Not The Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£844.80	88.00	Sole Property Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	1.00	Sole Property Owner	20/12/2013	2013
HES44 Pipework / feed modifications	£172.50	1.00	Sole Property Owner	20/12/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	20/12/2013	2013
HES51 Thermostatic radiator valve	£131.10	6.00	Sole Property Owner	20/12/2013	2013
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Sole Property Owner	20/12/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£0.00	0.00	Sole Property Owner	20/12/2013	2013
HES93 Junior heating engineer	£43.94	2.00	Sole Property Owner	20/12/2013	2013
HES94 Heating engineer	£588.80	16.00	Sole Property Owner	20/12/2013	2013
HES95 Senior heating engineer	£79.36	2.00	Sole Property Owner	20/12/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£97.95	97.95	Sole Property Owner	20/12/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Sole Property Owner	20/12/2013	2013
HES02 100mm thick loft insulation quilt	£300.00	40.00	Sole Property Owner	20/12/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£710.40	74.00	Sole Property Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	20/12/2013	2013
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£488.01	1.00	Not The Property Owner	17/03/2014	2014
HES55 2 port zone valve	£65.55	1.00	Not The Property Owner	17/03/2014	2014
HES68 28mm thick pipework lagging	£9.08	2.00	Not The Property Owner	17/03/2014	2014
HES98 Senior electrician	£138.88	3.50	Not The Property Owner	17/03/2014	2014
HES100 Asbestos survey & sample	£60.00	1.00	Not The Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£250.00	10.00	Not The Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£1,125.00	90.00	Not The Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£750.00	3.00	Not The Property Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£33.00	11.00	Not The Property Owner	17/03/2014	2014
HES16 Draught stripping to windows	£48.00	16.00	Not The Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£150.00	6.00	Not The Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	14.00	Not The Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES64 Stainless steel replacement hot water cylinder (170L)	£304.80	1.00	Not The Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£0.00	0.00	Not The Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£8.44	2.00	Not The Property Owner	17/03/2014	2014
HES94 Heating engineer	£625.60	17.00	Not The Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£425.00	17.00	Sole Property Owner	20/12/2013	2013
HES04 300mm thick loft insulation quilt	£1,250.00	100.00	Sole Property Owner	20/12/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	20/12/2013	2013

HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,401.60	146.00	Sole Property Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	19.00	Sole Property Owner	20/12/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00	0.00	Sole Property Owner	11/12/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Sole Property Owner	11/12/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	11/12/2013	2013
HES20 Low energy lamp installation	£0.00	0.00	Sole Property Owner	11/12/2013	2013
HES21 Smoke detector installation	£0.00	0.00	Sole Property Owner	11/12/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Joint Owner	20/12/2013	2013
HES04 300mm thick loft insulation quilt	£562.50	45.00	Joint Owner	20/12/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	20/12/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£0.00	0.00	Joint Owner	20/12/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,392.00	145.00	Joint Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	2.00	Joint Owner	20/12/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	20/12/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	20/12/2013	2013
HES51 Thermostatic radiator valve	£87.40	4.00	Joint Owner	20/12/2013	2013
HES94 Heating engineer	£220.80	6.00	Joint Owner	20/12/2013	2013
HES95 Senior heating engineer	£79.36	2.00	Joint Owner	20/12/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£42.55	42.55	Joint Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	4.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£275.00	11.00	Joint Owner		0
HES03 200mm thick loft insulation quilt	£361.00	38.00	Joint Owner		0
HES112 HER Survey for House	£0.00	1.00	Not The Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	5.00	Not The Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£125.00	5.00	Not The Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£187.50	15.00	Not The Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00	7.00	Sole Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	28/11/2013	2013
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	28/11/2013	2013
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	28/11/2013	2013
HES20 Low energy lamp installation	£0.00		Joint Owner	11/12/2013	2013
HES21 Smoke detector installation	£0.00		Joint Owner	11/12/2013	2013
HES22 Minimum per property charge	£0.00		Joint Owner	11/12/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Joint Owner	17/03/2014	2014
HES123 BCO Inspection - 2014 Price	£95.00	1.00	Joint Owner	17/03/2014	2014
HES92 Other miscellaneous electrical heating works for EES appr	£59.51	1.00	Joint Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	1.00	Joint Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	17/03/2014	2014
HES40 Flue specification and location	£397.26	1.00	Joint Owner	17/03/2014	2014
HES41 Condensate pipework (and pump if required)	£92.00	1.00	Joint Owner	17/03/2014	2014
HES44 Pipework / feed modifications	£115.00	1.00	Joint Owner	17/03/2014	2014
HES48 Power / system flush and treatment	£460.00	1.00	Joint Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£33.76	8.00	Joint Owner	17/03/2014	2014
HES93 Junior heating engineer	£65.91	3.00	Joint Owner	17/03/2014	2014
HES94 Heating engineer	£736.00	20.00	Joint Owner	17/03/2014	2014
HES95 Senior heating engineer	£79.36	2.00	Joint Owner	17/03/2014	2014
HES98 Senior electrician	£119.04	3.00	Joint Owner	17/03/2014	2014
HES99 Building works	£58.66	2.00	Joint Owner	17/03/2014	2014
HES39 26-35kW Gas replacement condensing boiler	£918.85	1.00	Joint Owner	17/03/2014	2014
HES91 Other miscellaneous gas heating works for EES approval	£225.30	225.30	Joint Owner	17/03/2014	2014
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	13.00	Not The Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner		0
HES73 Storage heater rated 3kW - 4kW	£1,126.02	3.00	Sole Property Owner		0
HES74 Comfort heat main switch	£57.20	1.00	Sole Property Owner		0
HES75 Storage heater consumer unit	£49.40	1.00	Sole Property Owner		0
HES76 Storage heater miniature circuit breaker	£39.00	4.00	Sole Property Owner		0
HES77 Main bonding of necessary services	£109.00	10.00	Sole Property Owner		0
HES78 Twin and earth 16mm cabling with clips and trunking	£56.01	3.00	Sole Property Owner		0
HES80 16mm meter tails	£12.48	1.00	Sole Property Owner		0
HES54 Water heating time clock and boost controller	£58.50	1.00	Sole Property Owner		0
HES64 Stainless steel replacement hot water cylinder (170L)	£283.83	1.00	Sole Property Owner		0
HES94 Heating engineer	£192.00	6.00	Sole Property Owner		0
HES97 Electrician	£672.00	21.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	8.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner		0
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	22/03/2011	2011
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner	20/12/2013	2013
HES97 Electrician	£300.00	12.00	Joint Owner	20/12/2013	2013
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	20/12/2013	2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£38.00	1.00	Joint Owner	20/12/2013	2013

HES01 Loft preparation labour (clearance, disposal of old insulatio	£550.00	22.00	Joint Owner	20/12/2013	2013
HES02 100mm thick loft insulation quilt	£60.00	8.00	Joint Owner	20/12/2013	2013
HES03 200mm thick loft insulation quilt	£266.00	28.00	Joint Owner	20/12/2013	2013
HES04 300mm thick loft insulation quilt	£425.00	34.00	Joint Owner	20/12/2013	2013
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	20/12/2013	2013
HES66 15mm thick pipework lagging	£25.92	8.00	Joint Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£126.60	30.00	Joint Owner	20/12/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,699.20	177.00	Joint Owner	20/12/2013	2013
HES20 Low energy lamp installation	£0.00	46.00	Joint Owner	20/12/2013	2013
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	20/12/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	20/12/2013	2013
HES32 21-25kW Oil replacement condensing boiler	£1,817.37	1.00	Joint Owner	20/12/2013	2013
HES40 Flue specification and location	£563.00	1.00	Joint Owner	20/12/2013	2013
HES41 Condensate pipework (and pump if required)	£95.00	1.00	Joint Owner	20/12/2013	2013
HES42 Purpose built lime soakaway (condensate sump)	£36.23	1.00	Joint Owner	20/12/2013	2013
HES43 Central heating pump	£141.55	1.00	Joint Owner	20/12/2013	2013
HES44 Pipework / feed modifications	£547.16	1.00	Joint Owner	20/12/2013	2013
HES46 Automatic bypass	£46.32	1.00	Joint Owner	20/12/2013	2013
HES48 Power / system flush and treatment	£38.00	1.00	Joint Owner	20/12/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	20/12/2013	2013
HES50 Electrical room thermostat	£53.32	1.00	Joint Owner	20/12/2013	2013
HES51 Thermostatic radiator valve	£541.20	12.00	Joint Owner	20/12/2013	2013
HES52 Hot water cylinder thermostat	£33.21	1.00	Joint Owner	20/12/2013	2013
HES53 Two channel heating programmer control	£85.11	1.00	Joint Owner	20/12/2013	2013
HES55 2 port zone valve	£138.56	2.00	Joint Owner	20/12/2013	2013
HES68 28mm thick pipework lagging	£30.08	8.00	Joint Owner	20/12/2013	2013
HES94 Heating engineer	£1,824.00	48.00	Joint Owner	20/12/2013	2013
HES67 22mm thick pipework lagging	£195.44	56.00	Joint Owner	20/12/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£375.00	30.00	Sole Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£1,265.00	1.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	2.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	0.00	Sole Property Owner		0
HES72 Storage heater rated 2kW - 3kW	£0.00		Sole Property Owner		0
HES97 Electrician	£0.00		Sole Property Owner		0
HES71 Storage heater rated 1kW - 2kW	£0.00		Sole Property Owner		0
HES112 HER Survey for House	£0.00	1.00	Sole Property Owner	27/06/2013	2013
HES20 Low energy lamp installation	£0.00	13.00	Sole Property Owner	27/06/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£8.05	5.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£11.88	6.00	Sole Property Owner	17/03/2014	2014
HES95 Senior heating engineer	£140.00	4.00	Sole Property Owner	17/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£12.80	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£375.00	15.00	Sole Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£562.50	45.00	Sole Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£15.00	5.00	Sole Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00	0.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00	0.00	Sole Property Owner		0
HES15 Draught stripping to exterior door	£0.00	0.00	Sole Property Owner		0
HES19 Draught proofing labour	£0.00	0.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	0.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£100.00	4.00	Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£125.00	10.00	Not The Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Not The Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Not The Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Not The Property Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Not The Property Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Not The Property Owner		0
HES94 Heating engineer	£0.00	0.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	11.00	Not The Property Owner		0
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	17/03/2014	2014
HES32 21-25kW Oil replacement condensing boiler	£1,410.00	1.00	Sole Property Owner	17/03/2014	2014
HES40 Flue specification and location	£542.40	1.00	Sole Property Owner	17/03/2014	2014
HES41 Condensate pipework (and pump if required)	£218.90	1.00	Sole Property Owner	17/03/2014	2014
HES43 Central heating pump	£84.28	1.00	Sole Property Owner	17/03/2014	2014
HES44 Pipework / feed modifications	£328.40	1.00	Sole Property Owner	17/03/2014	2014
HES45 Fire valve	£36.90	1.00	Sole Property Owner	17/03/2014	2014
HES46 Automatic bypass	£27.50	1.00	Sole Property Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES50 Electrical room thermostat	£13.45	1.00	Sole Property Owner	17/03/2014	2014
HES52 Hot water cylinder thermostat	£14.80	1.00	Sole Property Owner	17/03/2014	2014
HES53 Two channel heating programmer control	£33.80	1.00	Sole Property Owner	17/03/2014	2014
HES55 2 port zone valve	£98.00	2.00	Sole Property Owner	17/03/2014	2014
HES63 Stainless steel replacement hot water cylinder (150L)	£391.20	1.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£16.10	10.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£27.72	14.00	Sole Property Owner	17/03/2014	2014

HES68 28mm thick pipework lagging	£7.23	3.00	Sole Property Owner	17/03/2014	2014
HES95 Senior heating engineer	£1,750.00	50.00	Sole Property Owner	17/03/2014	2014
HES97 Electrician	£256.00	8.00	Sole Property Owner	17/03/2014	2014
HES99 Building works	£66.00	3.00	Sole Property Owner	17/03/2014	2014
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Sole Property Owner	17/03/2014	2014
HES48 Power / system flush and treatment	£43.80	1.00	Sole Property Owner	17/03/2014	2014
HES123 BCO Inspection - 2014 Price	£95.00	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Sole Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£937.50	75.00	Sole Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£750.00	3.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£25.92	8.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	28.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Not The Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Not The Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Not The Property Owner		0
HES19 Draught proofing labour	£0.00		Not The Property Owner		0
HES20 Low energy lamp installation	£0.00		Not The Property Owner		0
HES21 Smoke detector installation	£0.00		Not The Property Owner		0
HES117 Carbon Monoxide alarm	£0.00		Not The Property Owner		0
HES95 Senior heating engineer	£0.00		Not The Property Owner		0
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	22/03/2011	2011
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner		0
HES31 16-20kW Oil replacement condensing boiler	£0.00		Joint Owner		0
HES40 Flue specification and location	£0.00		Joint Owner		0
HES42 Purpose built lime soakaway (condensate sump)	£0.00		Joint Owner		0
HES43 Central heating pump	£0.00		Joint Owner		0
HES44 Pipework / feed modifications	£0.00		Joint Owner		0
HES45 Fire valve	£0.00		Joint Owner		0
HES46 Automatic bypass	£0.00		Joint Owner		0
HES48 Power / system flush and treatment	£0.00		Joint Owner		0
HES117 Carbon Monoxide alarm	£0.00		Joint Owner		0
HES50 Electrical room thermostat	£0.00		Joint Owner		0
HES51 Thermostatic radiator valve	£0.00		Joint Owner		0
HES52 Hot water cylinder thermostat	£0.00		Joint Owner		0
HES53 Two channel heating programmer control	£0.00		Joint Owner		0
HES55 2 port zone valve	£0.00		Joint Owner		0
HES66 15mm thick pipework lagging	£0.00		Joint Owner		0
HES67 22mm thick pipework lagging	£0.00		Joint Owner		0
HES68 28mm thick pipework lagging	£0.00		Joint Owner		0
HES95 Senior heating engineer	£0.00		Joint Owner		0
HES98 Senior electrician	£0.00		Joint Owner		0
HES99 Building works	£0.00		Joint Owner		0
HES87 Commissioning and issue of CD10 and Building Control no	£0.00		Joint Owner		0
HES23 Scaffold / cherry picker	£0.00		Joint Owner		0
HES88 Commissioning and issue of CD11 and flue gas analysis	£0.00		Joint Owner		0
HES41 Condensate pipework (and pump if required)	£0.00		Joint Owner		0
HES21 Smoke detector installation	£0.00	2.00	Joint Owner		0
HES123 BCO Inspection - 2014 Price	£0.00		Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£225.00	9.00	Joint Owner		0
HES04 300mm thick loft insulation quilt	£537.50	43.00	Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner		0
HES66 15mm thick pipework lagging	£22.68	7.00	Joint Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner		0
HES15 Draught stripping to exterior door	£21.00	7.00	Joint Owner		0
HES19 Draught proofing labour	£50.00	2.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	8.00	Joint Owner		0
HES101 Asbestos removal & disposal	£0.00		Joint Owner		0
HES02 100mm thick loft insulation quilt	£187.50		Joint Owner	17/03/2014	2014
HES03 200mm thick loft insulation quilt	£171.00	18.00	Joint Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£75.00	3.00	Joint Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£0.00	0.00	Joint Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£604.80	63.00	Joint Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£78.00	26.00	Joint Owner	17/03/2014	2014
HES19 Draught proofing labour	£175.00	7.00	Joint Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	47.00	Joint Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Joint Owner	17/03/2014	2014
HES51 Thermostatic radiator valve	£135.00	9.00	Joint Owner	17/03/2014	2014
HES94 Heating engineer	£396.00	12.00	Joint Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£575.00	23.00	Sole Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£1,750.00	140.00	Sole Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£51.84	16.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£25.32	6.00	Sole Property Owner	17/03/2014	2014
HES68 28mm thick pipework lagging	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,008.00	105.00	Sole Property Owner	17/03/2014	2014
HES51 Thermostatic radiator valve	£105.00	7.00	Sole Property Owner	17/03/2014	2014
HES94 Heating engineer	£330.00	10.00	Sole Property Owner	17/03/2014	2014
HES123 BCO Inspection - 2014 Price	£95.00	1.00	Joint Owner		0

HES124 Central heating pump - 2014 revised	£136.62	1.00	Joint Owner		0
HES16 Draught stripping to windows	£21.00	7.00	Joint Owner		0
HES19 Draught proofing labour	£100.00	4.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	3.00	Joint Owner		0
HES21 Smoke detector installation	£0.00	1.00	Joint Owner		0
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Joint Owner		0
HES40 Flue specification and location	£671.54	671.54	Joint Owner		0
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Joint Owner		0
HES43 Central heating pump	£0.00	0.00	Joint Owner		0
HES44 Pipework / feed modifications	£379.50	379.50	Joint Owner		0
HES45 Fire valve	£46.00	1.00	Joint Owner		0
HES46 Automatic bypass	£31.05	1.00	Joint Owner		0
HES48 Power / system flush and treatment	£460.00	1.00	Joint Owner		0
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner		0
HES50 Electrical room thermostat	£21.85	1.00	Joint Owner		0
HES51 Thermostatic radiator valve	£196.65	9.00	Joint Owner		0
HES52 Hot water cylinder thermostat	£23.00	1.00	Joint Owner		0
HES53 Two channel heating programmer control	£74.75	1.00	Joint Owner		0
HES55 2 port zone valve	£131.10	2.00	Joint Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner		0
HES67 22mm thick pipework lagging	£50.64	12.00	Joint Owner		0
HES68 28mm thick pipework lagging	£18.16	4.00	Joint Owner		0
HES93 Junior heating engineer	£65.91	3.00	Joint Owner		0
HES94 Heating engineer	£1,472.00	40.00	Joint Owner		0
HES95 Senior heating engineer	£119.04	3.00	Joint Owner		0
HES98 Senior electrician	£396.80	10.00	Joint Owner		0
HES99 Building works	£58.66	2.00	Joint Owner		0
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner		0
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Joint Owner		0
HES90 Other miscellaneous oil heating works for EES approval	£450.80	450.80	Joint Owner		0
HES92 Other miscellaneous electrical heating works for EES approval	£93.15	93.15	Joint Owner		0
HES101 Asbestos removal & disposal	£300.00	1.00	Joint Owner		0
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner		0
HES15 Draught stripping to exterior door	£15.00	5.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	2.00	Not The Property Owner	28/11/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner	28/11/2013	2013
HES22 Minimum per property charge	£50.00	1.00	Not The Property Owner	28/11/2013	2013
HES117 Carbon Monoxide alarm	£0.00	1.00	Not The Property Owner	28/11/2013	2013
HES01 Loft preparation labour (clearance, disposal of old insulatic	£150.00	6.00	Joint Owner	17/03/2014	2014
HES03 200mm thick loft insulation quilt	£76.00	8.00	Joint Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£100.00	8.00	Joint Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£6.48	2.00	Joint Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£8.44	2.00	Joint Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	10.00	Joint Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	18.00	Joint Owner		0
HES22 Minimum per property charge	£50.00	1.00	Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner		0
HES48 Power / system flush and treatment	£0.00		Sole Property Owner		0
HES117 Carbon Monoxide alarm	£0.00		Sole Property Owner		0
HES50 Electrical room thermostat	£0.00		Sole Property Owner		0
HES52 Hot water cylinder thermostat	£0.00		Sole Property Owner		0
HES53 Two channel heating programmer control	£0.00		Sole Property Owner		0
HES94 Heating engineer	£0.00		Sole Property Owner		0
HES97 Electrician	£0.00		Sole Property Owner		0
HES91 Other miscellaneous gas heating works for EES approval	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£150.00	6.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£500.00	40.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner		0
HES15 Draught stripping to exterior door	£0.00	0.00	Sole Property Owner		0
HES19 Draught proofing labour	£0.00	0.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	5.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00		Not The Property Owner		0
HES03 200mm thick loft insulation quilt	£0.00		Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Not The Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Not The Property Owner		0
HES19 Draught proofing labour	£0.00		Not The Property Owner		0
HES20 Low energy lamp installation	£0.00		Not The Property Owner		0
HES124 Central heating pump - 2014 revised	£136.62	1.00	Sole Property Owner	31/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatic	£300.00	12.00	Sole Property Owner	31/03/2014	2014
HES04 300mm thick loft insulation quilt	£1,250.00	100.00	Sole Property Owner	31/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	31/03/2014	2014
HES66 15mm thick pipework lagging	£0.00	0.00	Sole Property Owner	31/03/2014	2014
HES67 22mm thick pipework lagging	£0.00	0.00	Sole Property Owner	31/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,036.80	108.00	Sole Property Owner	31/03/2014	2014
HES15 Draught stripping to exterior door	£33.00	11.00	Sole Property Owner	31/03/2014	2014
HES19 Draught proofing labour	£75.00	3.00	Sole Property Owner	31/03/2014	2014
HES20 Low energy lamp installation	£0.00	25.00	Sole Property Owner	31/03/2014	2014
HES31 16-20kW Oil replacement condensing boiler	£1,725.00	1.00	Sole Property Owner	31/03/2014	2014

HES40 Flue specification and location	£788.00	788.00	Sole Property Owner	31/03/2014	2014
HES41 Condensate pipework (and pump if required)	£46.00	1.00	Sole Property Owner	31/03/2014	2014
HES43 Central heating pump	£0.00	0.00	Sole Property Owner	31/03/2014	2014
HES45 Fire valve	£46.00	1.00	Sole Property Owner	31/03/2014	2014
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner	31/03/2014	2014
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	31/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	31/03/2014	2014
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner	31/03/2014	2014
HES52 Hot water cylinder thermostat	£23.00	1.00	Sole Property Owner	31/03/2014	2014
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner	31/03/2014	2014
HES55 2 port zone valve	£131.10	2.00	Sole Property Owner	31/03/2014	2014
HES66 15mm thick pipework lagging	£3.24	1.00	Sole Property Owner	31/03/2014	2014
HES67 22mm thick pipework lagging	£37.98	9.00	Sole Property Owner	31/03/2014	2014
HES68 28mm thick pipework lagging	£13.62	3.00	Sole Property Owner	31/03/2014	2014
HES93 Junior heating engineer	£87.88	4.00	Sole Property Owner	31/03/2014	2014
HES94 Heating engineer	£1,251.20	34.00	Sole Property Owner	31/03/2014	2014
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	31/03/2014	2014
HES98 Senior electrician	£396.80	10.00	Sole Property Owner	31/03/2014	2014
HES99 Building works	£87.99	3.00	Sole Property Owner	31/03/2014	2014
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	31/03/2014	2014
HES92 Other miscellaneous electrical heating works for EES appr	£108.96	108.96	Sole Property Owner	31/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£513.80	513.80	Sole Property Owner	31/03/2014	2014
HES44 Pipework / feed modifications	£322.00	1.00	Sole Property Owner	31/03/2014	2014
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner	31/03/2014	2014
HES101 Asbestos removal & disposal	£348.00	348.00	Sole Property Owner	31/03/2014	2014
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	31/03/2014	2014
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	01/01/2010	2010
EES66 Low energy lamp replacement	£105.06	1.00	Sole Property Owner	01/01/2010	2010
HES90 Other miscellaneous oil heating works for EES approval	£0.00		Joint Owner		0
HES44 Pipework / feed modifications	£0.00		Joint Owner		0
HES117 Carbon Monoxide alarm	£0.00		Joint Owner		0
HES65 Stainless steel replacement hot water cylinder (210L)	£0.00		Joint Owner		0
HES93 Junior heating engineer	£0.00		Joint Owner		0
HES94 Heating engineer	£0.00		Joint Owner		0
HES95 Senior heating engineer	£0.00		Joint Owner		0
HES98 Senior electrician	£0.00		Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£225.00	9.00	Joint Owner		0
HES03 200mm thick loft insulation quilt	£817.00	86.00	Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£750.00	3.00	Joint Owner		0
HES66 15mm thick pipework lagging	£45.36	14.00	Joint Owner		0
HES67 22mm thick pipework lagging	£37.98	9.00	Joint Owner		0
HES68 28mm thick pipework lagging	£63.56	14.00	Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,363.20	142.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	2.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£400.00	16.00	Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£1,187.50	95.00	Not The Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Not The Property Owner		0
HES15 Draught stripping to exterior door	£30.00	10.00	Not The Property Owner		0
HES17 Draught stripping to letter boxes	£12.00	1.00	Not The Property Owner		0
HES19 Draught proofing labour	£75.00	3.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	14.00	Not The Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner		0
HES117 Carbon Monoxide alarm	£0.00	1.00	Not The Property Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Not The Property Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Not The Property Owner		0
HES68 28mm thick pipework lagging	£0.00	0.00	Not The Property Owner		0
HES94 Heating engineer	£0.00	0.00	Not The Property Owner		0
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner	17/03/2014	2014
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	7.00	Joint Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatic	£300.00	12.00	Joint Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£1,050.00	84.00	Joint Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£12.96	4.00	Joint Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£29.54	7.00	Joint Owner	17/03/2014	2014
HES101 Asbestos removal & disposal	£298.00	298.00	Joint Owner	17/03/2014	2014
HES32 21-25kW Oil replacement condensing boiler	£1,817.37	1.00	Joint Owner	17/03/2014	2014
HES40 Flue specification and location	£755.00	1.00	Joint Owner	17/03/2014	2014
HES23 Scaffold / cherry picker	£300.00	1.00	Joint Owner	17/03/2014	2014
HES41 Condensate pipework (and pump if required)	£150.00	1.00	Joint Owner	17/03/2014	2014
HES42 Purpose built lime soakaway (condensate sump)	£36.23	1.00	Joint Owner	17/03/2014	2014
HES44 Pipework / feed modifications	£42.00	1.00	Joint Owner	17/03/2014	2014
HES46 Automatic bypass	£46.32	1.00	Joint Owner	17/03/2014	2014
HES48 Power / system flush and treatment	£38.00	1.00	Joint Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner	17/03/2014	2014
HES50 Electrical room thermostat	£53.32	1.00	Joint Owner	17/03/2014	2014
HES51 Thermostatic radiator valve	£496.10	11.00	Joint Owner	17/03/2014	2014
HES55 2 port zone valve	£138.56	2.00	Joint Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£10.76	4.00	Joint Owner	17/03/2014	2014
HES97 Electrician	£200.00	8.00	Joint Owner	17/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£75.80	75.80	Joint Owner	17/03/2014	2014
HES43 Central heating pump	£141.55	1.00	Joint Owner	17/03/2014	2014
HES45 Fire valve	£42.32	1.00	Joint Owner	17/03/2014	2014

HES53 Two channel heating programmer control	£85.11	1.00	Joint Owner	17/03/2014	2014
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	17/03/2014	2014
HES88 Commissioning and issue of CD11 and flue gas analysis	£38.00	1.00	Joint Owner	17/03/2014	2014
HES94 Heating engineer	£1,748.00	46.00	Joint Owner	17/03/2014	2014
HES68 28mm thick pipework lagging	£37.60	10.00	Joint Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£97.72	28.00	Joint Owner	17/03/2014	2014
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	17/03/2014	2014
HES33 26-35kW Oil replacement condensing boiler	£1,600.75	1,600.75	Sole Property Owner	17/03/2014	2014
HES40 Flue specification and location	£175.00	1.00	Sole Property Owner	17/03/2014	2014
HES44 Pipework / feed modifications	£276.12	1.00	Sole Property Owner	17/03/2014	2014
HES46 Automatic bypass	£46.32	1.00	Sole Property Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES50 Electrical room thermostat	£53.32	1.00	Sole Property Owner	17/03/2014	2014
HES51 Thermostatic radiator valve	£496.10	11.00	Sole Property Owner	17/03/2014	2014
HES52 Hot water cylinder thermostat	£33.21	1.00	Sole Property Owner	17/03/2014	2014
HES53 Two channel heating programmer control	£85.11	1.00	Sole Property Owner	17/03/2014	2014
HES55 2 port zone valve	£138.56	2.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£26.90	10.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£69.80	20.00	Sole Property Owner	17/03/2014	2014
HES68 28mm thick pipework lagging	£60.16	16.00	Sole Property Owner	17/03/2014	2014
HES94 Heating engineer	£1,672.00	44.00	Sole Property Owner	17/03/2014	2014
HES97 Electrician	£200.00	8.00	Sole Property Owner	17/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£125.00	1.00	Sole Property Owner	17/03/2014	2014
HES43 Central heating pump	£141.55	1.00	Sole Property Owner	17/03/2014	2014
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES88 Commissioning and issue of CD11 and flue gas analysis	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES03 200mm thick loft insulation quilt	£218.50	23.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£300.00	12.00	Sole Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£500.00	40.00	Sole Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£12.96	4.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£25.32	6.00	Sole Property Owner	17/03/2014	2014
HES68 28mm thick pipework lagging	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£422.40	44.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/03/2014	2014
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	17/03/2014	2014
HES101 Asbestos removal & disposal	£105.00	1.00	Sole Property Owner	17/03/2014	2014
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner		0
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Joint Owner		0
HES04 300mm thick loft insulation quilt	£462.50	37.00	Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	7.00	Joint Owner		0
HES21 Smoke detector installation	£0.00	2.00	Joint Owner		0
HES101 Asbestos removal & disposal	£298.00	1.00	Joint Owner		0
HES31 16-20kW Oil replacement condensing boiler	£1,476.28	1.00	Joint Owner		0
HES40 Flue specification and location	£456.12	1.00	Joint Owner		0
HES42 Purpose built lime soakaway (condensate sump)	£36.23	1.00	Joint Owner		0
HES43 Central heating pump	£141.55	1.00	Joint Owner		0
HES44 Pipework / feed modifications	£263.04	1.00	Joint Owner		0
HES45 Fire valve	£42.32	1.00	Joint Owner		0
HES46 Automatic bypass	£46.32	1.00	Joint Owner		0
HES117 Carbon Monoxide alarm	£0.00	1.00	Joint Owner		0
HES50 Electrical room thermostat	£53.32	1.00	Joint Owner		0
HES52 Hot water cylinder thermostat	£33.21	1.00	Joint Owner		0
HES53 Two channel heating programmer control	£85.11	1.00	Joint Owner		0
HES55 2 port zone valve	£138.56	2.00	Joint Owner		0
HES64 Stainless steel replacement hot water cylinder (170L)	£435.60	1.00	Joint Owner		0
HES67 22mm thick pipework lagging	£69.80	20.00	Joint Owner		0
HES68 28mm thick pipework lagging	£37.60	10.00	Joint Owner		0
HES94 Heating engineer	£1,596.00	42.00	Joint Owner		0
HES97 Electrician	£300.00	12.00	Joint Owner		0
HES90 Other miscellaneous oil heating works for EES approval	£132.03	1.00	Joint Owner		0
HES90 Other miscellaneous oil heating works for EES approval	£75.00	1.00	Joint Owner		0
HES51 Thermostatic radiator valve	£225.50	5.00	Joint Owner		0
HES41 Condensate pipework (and pump if required)	£150.00	1.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£375.00	15.00	Sole Property Owner	17/03/2014	2014
HES03 200mm thick loft insulation quilt	£684.00	72.00	Sole Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£12.96	4.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	17.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/03/2014	2014
HES101 Asbestos removal & disposal	£298.00	1.00	Sole Property Owner	17/03/2014	2014
HES31 16-20kW Oil replacement condensing boiler	£1,278.00	1.00	Sole Property Owner	17/03/2014	2014
HES40 Flue specification and location	£524.62	524.62	Sole Property Owner	17/03/2014	2014
HES41 Condensate pipework (and pump if required)	£112.40	1.00	Sole Property Owner	17/03/2014	2014
HES42 Purpose built lime soakaway (condensate sump)	£228.00	1.00	Sole Property Owner	17/03/2014	2014
HES43 Central heating pump	£84.28	1.00	Sole Property Owner	17/03/2014	2014
HES44 Pipework / feed modifications	£421.40	1.00	Sole Property Owner	17/03/2014	2014
HES45 Fire valve	£36.90	1.00	Sole Property Owner	17/03/2014	2014
HES46 Automatic bypass	£27.50	1.00	Sole Property Owner	17/03/2014	2014

HES47 Frost thermostat	£16.51	1.00	Sole Property Owner	17/03/2014	2014
HES48 Power / system flush and treatment	£43.80	1.00	Sole Property Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES50 Electrical room thermostat	£13.45	1.00	Sole Property Owner	17/03/2014	2014
HES90 Other miscellaneous oil heating works for EES approval	£154.95	1.00	Sole Property Owner	17/03/2014	2014
HES53 Two channel heating programmer control	£33.80	1.00	Sole Property Owner	17/03/2014	2014
HES54 Water heating time clock and boost controller	£85.90	1.00	Sole Property Owner	17/03/2014	2014
HES55 2 port zone valve	£98.00	2.00	Sole Property Owner	17/03/2014	2014
HES63 Stainless steel replacement hot water cylinder (150L)	£391.20	1.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£32.20	20.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£27.72	14.00	Sole Property Owner	17/03/2014	2014
HES68 28mm thick pipework lagging	£0.00	0.00	Sole Property Owner	17/03/2014	2014
HES95 Senior heating engineer	£2,030.00	58.00	Sole Property Owner	17/03/2014	2014
HES98 Senior electrician	£490.00	14.00	Sole Property Owner	17/03/2014	2014
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Sole Property Owner	17/03/2014	2014
HES92 Other miscellaneous electrical heating works for EES appr	£104.20	1.00	Sole Property Owner	17/03/2014	2014
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	17/03/2014	2014
HES123 BCO Inspection - 2014 Price	£95.00	1.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£375.00	15.00	Joint Owner		0
HES03 200mm thick loft insulation quilt	£418.00	44.00	Joint Owner		0
HES04 300mm thick loft insulation quilt	£337.50	27.00	Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner		0
HES66 15mm thick pipework lagging	£19.44	6.00	Joint Owner		0
HES67 22mm thick pipework lagging	£16.88	4.00	Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£912.00	95.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	13.00	Joint Owner		0
HES21 Smoke detector installation	£0.00	1.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00	0.00	Joint Owner	13/11/2013	2013
HES04 300mm thick loft insulation quilt	£0.00	0.00	Joint Owner	13/11/2013	2013
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner	13/11/2013	2013
HES67 22mm thick pipework lagging	£0.00	0.00	Joint Owner	13/11/2013	2013
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	13/11/2013	2013
HES20 Low energy lamp installation	£0.00	0.00	Joint Owner	13/11/2013	2013
HES21 Smoke detector installation	£0.00	0.00	Joint Owner	13/11/2013	2013
EES07 200mm thick loft insulation	£280.80	27.00	Not The Property Owner	16/12/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£48.54	6.00	Not The Property Owner	16/12/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£110.64	12.00	Not The Property Owner	16/12/2011	2011
EES66 Low energy lamp replacement	£22.74	2.00	Not The Property Owner	16/12/2011	2011
EES00a Full Energy Survey	£246.55	1.00	Not The Property Owner	16/12/2011	2011
EES77 HEC to House	£150.00	1.00	Not The Property Owner	01/02/2010	2010
HES111 HER Survey for Flat	£0.00	1.00	Sole Property Owner	23/12/2013	2013
HES20 Low energy lamp installation	£0.00	8.00	Sole Property Owner	23/12/2013	2013
HES123 BCO Inspection - 2014 Price	£95.00	1.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£499.20	52.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	4.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES101 Asbestos removal & disposal	£0.00		Sole Property Owner		0
HES32 21-25kW Oil replacement condensing boiler	£0.00		Sole Property Owner		0
HES40 Flue specification and location	£0.00		Sole Property Owner		0
HES41 Condensate pipework (and pump if required)	£0.00		Sole Property Owner		0
HES42 Purpose built lime soakaway (condensate sump)	£0.00		Sole Property Owner		0
HES43 Central heating pump	£0.00		Sole Property Owner		0
HES44 Pipework / feed modifications	£0.00		Sole Property Owner		0
HES45 Fire valve	£0.00		Sole Property Owner		0
HES46 Automatic bypass	£0.00		Sole Property Owner		0
HES48 Power / system flush and treatment	£0.00		Sole Property Owner		0
HES117 Carbon Monoxide alarm	£0.00		Sole Property Owner		0
HES50 Electrical room thermostat	£0.00		Sole Property Owner		0
HES52 Hot water cylinder thermostat	£0.00		Sole Property Owner		0
HES53 Two channel heating programmer control	£0.00		Sole Property Owner		0
HES55 2 port zone valve	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES68 28mm thick pipework lagging	£0.00		Sole Property Owner		0
HES95 Senior heating engineer	£0.00		Sole Property Owner		0
HES98 Senior electrician	£0.00		Sole Property Owner		0
HES87 Commissioning and issue of CD10 and Building Control no	£0.00		Sole Property Owner		0
HES88 Commissioning and issue of CD11 and flue gas analysis	£0.00		Sole Property Owner		0
HES23 Scaffold / cherry picker	£0.00		Sole Property Owner		0
HES92 Other miscellaneous electrical heating works for EES appr	£0.00		Sole Property Owner		0
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner		0
HES32 21-25kW Oil replacement condensing boiler	£1,840.00	1.00	Sole Property Owner		0
HES40 Flue specification and location	£191.13	1.00	Sole Property Owner		0
HES41 Condensate pipework (and pump if required)	£92.00	1.00	Sole Property Owner		0
HES44 Pipework / feed modifications	£322.00	1.00	Sole Property Owner		0
HES45 Fire valve	£46.00	1.00	Sole Property Owner		0
HES46 Automatic bypass	£31.05	1.00	Sole Property Owner		0
HES47 Frost thermostat	£23.00	1.00	Sole Property Owner		0
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner		0
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner		0
HES50 Electrical room thermostat	£21.85	1.00	Sole Property Owner		0
HES53 Two channel heating programmer control	£74.75	1.00	Sole Property Owner		0

HES55 2 port zone valve	£131.10	2.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£25.32	6.00	Sole Property Owner		0
HES68 28mm thick pipework lagging	£9.08	2.00	Sole Property Owner		0
HES93 Junior heating engineer	£43.94	2.00	Sole Property Owner		0
HES94 Heating engineer	£883.20	24.00	Sole Property Owner		0
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner		0
HES98 Senior electrician	£436.48	11.00	Sole Property Owner		0
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner		0
HES88 Commissioning and issue of CD11 and flue gas analysis	£92.00	1.00	Sole Property Owner		0
HES90 Other miscellaneous oil heating works for EES approval	£565.80	565.80	Sole Property Owner		0
HES92 Other miscellaneous electrical heating works for EES app	£0.00	0.00	Sole Property Owner		0
HES123 BCO Inspection - 2014 Price	£95.00	1.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£125.00	5.00	Sole Property Owner		0
HES03 200mm thick loft insulation quilt	£1,140.00	120.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	23.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	0.00	Sole Property Owner		0
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£5.38	2.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£6.98	2.00	Sole Property Owner	17/03/2014	2014
HES111 HER Survey for Flat	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	7.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES64 Stainless steel replacement hot water cylinder (170L)	£435.60	1.00	Sole Property Owner	17/03/2014	2014
HES94 Heating engineer	£304.00	8.00	Sole Property Owner	17/03/2014	2014
HES100 Asbestos survey & sample	£0.00		Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£275.00	11.00	Joint Owner		0
HES04 300mm thick loft insulation quilt	£600.00	48.00	Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner		0
HES67 22mm thick pipework lagging	£8.44	2.00	Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner		0
HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner		0
HES19 Draught proofing labour	£50.00	2.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	8.00	Joint Owner		0
HES21 Smoke detector installation	£0.00	1.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£275.00	11.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£500.00	40.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£25.92	8.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£21.10	5.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	11.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner		0
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner		0
HES36 12-15kW Gas replacement condensing boiler	£0.00		Joint Owner		0
HES40 Flue specification and location	£0.00		Joint Owner		0
HES41 Condensate pipework (and pump if required)	£0.00		Joint Owner		0
HES44 Pipework / feed modifications	£0.00		Joint Owner		0
HES48 Power / system flush and treatment	£0.00		Joint Owner		0
HES50 Electrical room thermostat	£0.00		Joint Owner		0
HES52 Hot water cylinder thermostat	£0.00		Joint Owner		0
HES53 Two channel heating programmer control	£0.00		Joint Owner		0
HES55 2 port zone valve	£0.00		Joint Owner		0
HES66 15mm thick pipework lagging	£0.00		Joint Owner		0
HES67 22mm thick pipework lagging	£0.00		Joint Owner		0
HES94 Heating engineer	£0.00		Joint Owner		0
HES97 Electrician	£0.00		Joint Owner		0
HES88 Commissioning and issue of CD11 and flue gas analysis	£0.00		Joint Owner		0
HES91 Other miscellaneous gas heating works for EES approval	£0.00		Joint Owner		0
HES91 Other miscellaneous gas heating works for EES approval	£0.00		Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£225.00	9.00	Joint Owner		0
HES04 300mm thick loft insulation quilt	£562.50	45.00	Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	22.00	Joint Owner		0
HES21 Smoke detector installation	£0.00	1.00	Joint Owner		0
HES68 28mm thick pipework lagging	£27.24	6.00	Sole Property Owner	17/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatic	£350.00	14.00	Sole Property Owner	17/03/2014	2014
HES04 300mm thick loft insulation quilt	£950.00	76.00	Sole Property Owner	17/03/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner	17/03/2014	2014
HES66 15mm thick pipework lagging	£19.44	6.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	17/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£835.20	87.00	Sole Property Owner	17/03/2014	2014
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	17/03/2014	2014
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	17/03/2014	2014
HES20 Low energy lamp installation	£0.00	18.00	Sole Property Owner	17/03/2014	2014
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	17/03/2014	2014
HES51 Thermostatic radiator valve	£360.80	8.00	Sole Property Owner	17/03/2014	2014
HES67 22mm thick pipework lagging	£13.96	4.00	Sole Property Owner	17/03/2014	2014
HES94 Heating engineer	£456.00	12.00	Sole Property Owner	17/03/2014	2014
HES64 Stainless steel replacement hot water cylinder (170L)	£435.60	1.00	Sole Property Owner	17/03/2014	2014
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	27/05/2010	2010
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00	0.00	Joint Owner	08/01/2014	2014

HES04 300mm thick loft insulation quilt	£0.00	0.00	Joint Owner	08/01/2014	2014
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Joint Owner	08/01/2014	2014
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner	08/01/2014	2014
HES67 22mm thick pipework lagging	£0.00	0.00	Joint Owner	08/01/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner	08/01/2014	2014
HES15 Draught stripping to exterior door	£0.00	0.00	Joint Owner	08/01/2014	2014
HES19 Draught proofing labour	£0.00	0.00	Joint Owner	08/01/2014	2014
HES20 Low energy lamp installation	£0.00	0.00	Joint Owner	08/01/2014	2014
HES21 Smoke detector installation	£0.00	0.00	Joint Owner	08/01/2014	2014
HES03 200mm thick loft insulation quilt	£218.50	23.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£50.00	2.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£325.00	13.00	Sole Property Owner		0
HES03 200mm thick loft insulation quilt	£855.00	90.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£312.50	25.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£432.00	45.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	15.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES48 Power / system flush and treatment	£38.00	1.00	Sole Property Owner		0
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner		0
HES51 Thermostatic radiator valve	£360.80	8.00	Sole Property Owner		0
HES94 Heating engineer	£304.00	8.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Not The Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Not The Property Owner		0
HES19 Draught proofing labour	£0.00		Not The Property Owner		0
HES20 Low energy lamp installation	£0.00		Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	9.00	Not The Property Owner		0
HES100 Asbestos survey & sample	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£150.00	6.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£525.00	42.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	10.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Sole Property Owner	23/12/2013	2013
HES20 Low energy lamp installation	£0.00	11.00	Sole Property Owner	23/12/2013	2013
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	23/12/2013	2013
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner		0
HES67 22mm thick pipework lagging	£0.00		Joint Owner		0
HES68 28mm thick pipework lagging	£0.00		Joint Owner		0
HES94 Heating engineer	£0.00		Joint Owner		0
HES97 Electrician	£0.00		Joint Owner		0
HES87 Commissioning and issue of CD10 and Building Control no	£0.00		Joint Owner		0
HES88 Commissioning and issue of CD11 and flue gas analysis	£0.00		Joint Owner		0
HES90 Other miscellaneous oil heating works for EES approval	£0.00		Joint Owner		0
HES31 16-20kW Oil replacement condensing boiler	£0.00		Joint Owner		0
HES40 Flue specification and location	£0.00		Joint Owner		0
HES41 Condensate pipework (and pump if required)	£0.00		Joint Owner		0
HES43 Central heating pump	£0.00		Joint Owner		0
HES44 Pipework / feed modifications	£0.00		Joint Owner		0
HES46 Automatic bypass	£0.00		Joint Owner		0
HES117 Carbon Monoxide alarm	£0.00		Joint Owner		0
HES51 Thermostatic radiator valve	£0.00		Joint Owner		0
HES53 Two channel heating programmer control	£0.00		Joint Owner		0
HES55 2 port zone valve	£0.00		Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£200.00	8.00	Joint Owner		0
HES04 300mm thick loft insulation quilt	£1,000.00	80.00	Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,046.40	109.00	Joint Owner		0
HES21 Smoke detector installation	£0.00	1.00	Joint Owner		0
HES101 Asbestos removal & disposal	£0.00		Joint Owner		0
HES32 21-25kW Oil replacement condensing boiler	£0.00		Joint Owner		0
HES40 Flue specification and location	£0.00		Joint Owner		0
HES41 Condensate pipework (and pump if required)	£0.00		Joint Owner		0
HES43 Central heating pump	£0.00		Joint Owner		0
HES44 Pipework / feed modifications	£0.00		Joint Owner		0
HES46 Automatic bypass	£0.00		Joint Owner		0
HES117 Carbon Monoxide alarm	£0.00		Joint Owner		0
HES50 Electrical room thermostat	£0.00		Joint Owner		0
HES52 Hot water cylinder thermostat	£0.00		Joint Owner		0
HES53 Two channel heating programmer control	£0.00		Joint Owner		0
HES55 2 port zone valve	£0.00		Joint Owner		0
HES67 22mm thick pipework lagging	£0.00		Joint Owner		0
HES68 28mm thick pipework lagging	£0.00		Joint Owner		0
HES94 Heating engineer	£0.00		Joint Owner		0
HES97 Electrician	£0.00		Joint Owner		0
HES87 Commissioning and issue of CD10 and Building Control no	£0.00		Joint Owner		0
HES88 Commissioning and issue of CD11 and flue gas analysis	£0.00		Joint Owner		0
HES90 Other miscellaneous oil heating works for EES approval	£0.00		Joint Owner		0
HES90 Other miscellaneous oil heating works for EES approval	£0.00		Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£883.20	92.00	Joint Owner		0

HES20 Low energy lamp installation	£0.00	3.00	Joint Owner		0
HES21 Smoke detector installation	£0.00	1.00	Joint Owner		0
EES00a Full Energy Survey	£401.67	1.00	Not The Property Owner	22/03/2011	2011
HES100 Asbestos survey & sample	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£425.00	17.00	Sole Property Owner		0
HES03 200mm thick loft insulation quilt	£190.00	20.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£1,325.00	106.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£25.92	8.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,276.80	133.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	16.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner		0
HES19 Draught proofing labour	£50.00	2.00	Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,526.40	159.00	Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Sole Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Sole Property Owner		0
HES19 Draught proofing labour	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
HES23 Scaffold / cherry picker	£0.00		Sole Property Owner		0
HES20 Low energy lamp installation	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Not The Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00		Not The Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Not The Property Owner		0
HES19 Draught proofing labour	£0.00		Not The Property Owner		0
HES20 Low energy lamp installation	£0.00		Not The Property Owner		0
HES101 Asbestos removal & disposal	£0.00		Joint Owner		0
HES32 21-25kW Oil replacement condensing boiler	£0.00		Joint Owner		0
HES40 Flue specification and location	£0.00		Joint Owner		0
HES41 Condensate pipework (and pump if required)	£0.00		Joint Owner		0
HES43 Central heating pump	£0.00		Joint Owner		0
HES44 Pipework / feed modifications	£0.00		Joint Owner		0
HES46 Automatic bypass	£0.00		Joint Owner		0
HES117 Carbon Monoxide alarm	£0.00		Joint Owner		0
HES50 Electrical room thermostat	£0.00		Joint Owner		0
HES52 Hot water cylinder thermostat	£0.00		Joint Owner		0
HES53 Two channel heating programmer control	£0.00		Joint Owner		0
HES55 2 port zone valve	£0.00		Joint Owner		0
HES67 22mm thick pipework lagging	£0.00		Joint Owner		0
HES68 28mm thick pipework lagging	£0.00		Joint Owner		0
HES94 Heating engineer	£0.00		Joint Owner		0
HES97 Electrician	£0.00		Joint Owner		0
HES87 Commissioning and issue of CD10 and Building Control no	£0.00		Joint Owner		0
HES88 Commissioning and issue of CD11 and flue gas analysis	£0.00		Joint Owner		0
HES23 Scaffold / cherry picker	£0.00		Joint Owner		0
HES92 Other miscellaneous electrical heating works for EES appr	£0.00		Joint Owner		0
HES101 Asbestos removal & disposal	£0.00		Joint Owner		0
HES123 BCO Inspection - 2014 Price	£95.00	1.00	Joint Owner		0
HES100 Asbestos survey & sample	£166.00	1.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£425.00	17.00	Joint Owner		0
HES04 300mm thick loft insulation quilt	£1,625.00	130.00	Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner		0
HES66 15mm thick pipework lagging	£12.96	4.00	Joint Owner		0
HES67 22mm thick pipework lagging	£16.88	4.00	Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,084.80	113.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	7.00	Joint Owner		0
HES21 Smoke detector installation	£0.00	2.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Sole Property Owner		0
HES20 Low energy lamp installation	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Joint Owner		0
HES15 Draught stripping to exterior door	£15.00	5.00	Joint Owner		0
HES19 Draught proofing labour	£50.00	2.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	1.00	Joint Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	4.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Sole Property Owner		0
HES20 Low energy lamp installation	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
HES03 200mm thick loft insulation quilt	£855.00	90.00	Joint Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£70.00	1.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£425.00	17.00	Joint Owner		0

HES04 300mm thick loft insulation quilt	£0.00	0.00	Joint Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Joint Owner		0
HES15 Draught stripping to exterior door	£0.00	0.00	Joint Owner		0
HES16 Draught stripping to windows	£60.00	20.00	Joint Owner		0
HES19 Draught proofing labour	£100.00	4.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	23.00	Joint Owner		0
HES21 Smoke detector installation	£0.00	1.00	Joint Owner		0
HES67 22mm thick pipework lagging	£33.76	8.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£425.00	17.00	Joint Owner		0
HES04 300mm thick loft insulation quilt	£900.00	72.00	Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Joint Owner		0
HES66 15mm thick pipework lagging	£25.92	8.00	Joint Owner		0
HES68 28mm thick pipework lagging	£0.00	0.00	Joint Owner		0
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Sole Property Owner	30/03/2010	2010
EES07 200mm thick loft insulation	£305.50	47.00	Sole Property Owner	30/03/2010	2010
EES 11 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	30/03/2010	2010
EES17 Insulation to 90mm wide cavity wall	£0.00	0.00	Sole Property Owner	30/03/2010	2010
EES38a Thermostatic radiator valve (per valve)	£338.64	8.00	Sole Property Owner	30/03/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£39.00	3.00	Sole Property Owner	30/03/2010	2010
EES66 Low energy lamp replacement	£86.40	86.40	Sole Property Owner	30/03/2010	2010
EES67 Smoke detector installation	£15.00	2.00	Sole Property Owner	30/03/2010	2010
EES69 Miscellaneous Charge	£50.00	1.00	Sole Property Owner	30/03/2010	2010
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	30/03/2010	2010
HES15 Draught stripping to exterior door	£0.00		Not The Property Owner		0
HES19 Draught proofing labour	£0.00		Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	11.00	Not The Property Owner		0
HES71 Storage heater rated 1kW - 2kW	£489.06	2.00	Joint Owner		0
HES72 Storage heater rated 2kW - 3kW	£308.49	1.00	Joint Owner		0
HES73 Storage heater rated 3kW - 4kW	£375.34	1.00	Joint Owner		0
HES97 Electrician	£384.00	12.00	Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£393.60	41.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	10.00	Joint Owner		0
HES21 Smoke detector installation	£0.00	0.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00		Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Not The Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Not The Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00		Not The Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Not The Property Owner		0
HES19 Draught proofing labour	£0.00		Not The Property Owner		0
HES53 Two channel heating programmer control	£0.00		Not The Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Not The Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Not The Property Owner		0
HES68 28mm thick pipework lagging	£0.00		Not The Property Owner		0
HES97 Electrician	£0.00		Not The Property Owner		0
HES100 Asbestos survey & sample	£0.00		Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	6.00	Not The Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner		0
HES44 Pipework / feed modifications	£0.00		Sole Property Owner		0
HES51 Thermostatic radiator valve	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES93 Junior heating engineer	£0.00		Sole Property Owner		0
HES94 Heating engineer	£0.00		Sole Property Owner		0
HES95 Senior heating engineer	£0.00		Sole Property Owner		0
HES98 Senior electrician	£0.00		Sole Property Owner		0
HES103 Copper replacement hot water cylinder (150L)	£0.00		Sole Property Owner		0
HES90 Other miscellaneous oil heating works for EES approval	£0.00		Sole Property Owner		0
HES02 100mm thick loft insulation quilt	£75.00	10.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£425.00	17.00	Sole Property Owner		0
HES03 200mm thick loft insulation quilt	£1,197.00	126.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,104.00	115.00	Sole Property Owner		0
HES15 Draught stripping to exterior door	£30.00	10.00	Sole Property Owner		0
HES19 Draught proofing labour	£75.00	3.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	0.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£300.00	12.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£500.00	40.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	12.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Sole Property Owner		0
LEL 20W BC	£0.00	1.00	Sole Property Owner		0
LEL 5W LED GU10	£0.00	8.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£300.00	12.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£500.00	40.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£681.60	71.00	Sole Property Owner		0
HES15 Draught stripping to exterior door	£30.00	10.00	Sole Property Owner		0

HES19 Draught proofing labour	£75.00	3.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	13.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES68 28mm thick pipework lagging	£9.08	2.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£350.00	14.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£750.00	60.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£19.44	6.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner		0
HES15 Draught stripping to exterior door	£15.00	5.00	Sole Property Owner		0
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	13.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00	0.00	Not The Property Owner		0
HES03 200mm thick loft insulation quilt	£0.00	0.00	Not The Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Not The Property Owner		0
HES15 Draught stripping to exterior door	£0.00	0.00	Not The Property Owner		0
HES19 Draught proofing labour	£0.00	0.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	0.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	0.00	Sole Property Owner	10/03/2014	2014
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£643.20	67.00	Sole Property Owner		0
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner		0
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	16.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner		0
HES23 Scaffold / cherry picker	£0.00	0.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£325.00	13.00	Joint Owner		0
HES04 300mm thick loft insulation quilt	£737.50	59.00	Joint Owner		0
HES66 15mm thick pipework lagging	£6.48	2.00	Joint Owner		0
HES67 22mm thick pipework lagging	£16.88	4.00	Joint Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£739.20	77.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	15.00	Joint Owner		0
HES44 Pipework / feed modifications	£0.00		Sole Property Owner		0
HES45 Fire valve	£0.00		Sole Property Owner		0
HES46 Automatic bypass	£0.00		Sole Property Owner		0
HES50 Electrical room thermostat	£0.00		Sole Property Owner		0
HES63 Stainless steel replacement hot water cylinder (150L)	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES95 Senior heating engineer	£0.00		Sole Property Owner		0
HES97 Electrician	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£250.00	10.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£500.00	40.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Sole Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£979.20	102.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	17.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES112 HER Survey for House	£0.00	1.00	Not The Property Owner		0
HES20 Low energy lamp installation	£0.00	16.00	Not The Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Joint Owner		0
HES20 Low energy lamp installation	£0.00		Joint Owner		0
HES21 Smoke detector installation	£0.00		Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£375.00	15.00	Sole Property Owner		0
HES02 100mm thick loft insulation quilt	£525.00	70.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£512.50	41.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner		0
HES15 Draught stripping to exterior door	£15.00	5.00	Sole Property Owner		0
HES16 Draught stripping to windows	£72.00	24.00	Sole Property Owner		0
HES19 Draught proofing labour	£150.00	6.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	31.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£425.00	17.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£875.00	70.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£500.00	2.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£25.32	6.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£288.00	30.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	4.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner		0
HES100 Asbestos survey & sample	£60.00	1.00	Sole Property Owner		0
EES66 Low energy lamp replacement	£57.60	9.00	Not The Property Owner	22/03/2011	2011
HES13 Miscellaneous items (brush, airbrick, vent etc), please pro	£77.00	1.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£425.00	17.00	Joint Owner		0
HES04 300mm thick loft insulation quilt	£787.50	63.00	Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Joint Owner		0
HES66 15mm thick pipework lagging	£25.92	8.00	Joint Owner		0
HES67 22mm thick pipework lagging	£8.44	2.00	Joint Owner		0

HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£1,555.20	162.00	Joint Owner		0
HES15 Draught stripping to exterior door	£18.00	6.00	Joint Owner		0
HES19 Draught proofing labour	£50.00	2.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	10.00	Joint Owner		0
HES21 Smoke detector installation	£0.00	1.00	Joint Owner		0
HES51 Thermostatic radiator valve	£0.00		Sole Property Owner		0
HES93 Junior heating engineer	£0.00		Sole Property Owner		0
HES94 Heating engineer	£0.00		Sole Property Owner		0
HES95 Senior heating engineer	£0.00		Sole Property Owner		0
HES90 Other miscellaneous oil heating works for EES approval	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	13.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner		0
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00		Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Not The Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Not The Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00		Not The Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Not The Property Owner		0
HES17 Draught stripping to letter boxes	£0.00		Not The Property Owner		0
HES19 Draught proofing labour	£0.00		Not The Property Owner		0
HES20 Low energy lamp installation	£0.00		Not The Property Owner		0
HES21 Smoke detector installation	£0.00		Not The Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Not The Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Not The Property Owner		0
HES68 28mm thick pipework lagging	£0.00		Not The Property Owner		0
HES94 Heating engineer	£0.00		Not The Property Owner		0
HES100 Asbestos survey & sample	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES68 28mm thick pipework lagging	£0.00		Sole Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00		Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Sole Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Sole Property Owner		0
HES19 Draught proofing labour	£0.00		Sole Property Owner		0
HES20 Low energy lamp installation	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
HES16 Draught stripping to windows	£72.00	24.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£100.00	4.00	Joint Owner		0
HES03 200mm thick loft insulation quilt	£285.00	30.00	Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Joint Owner		0
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner		0
HES67 22mm thick pipework lagging	£0.00	0.00	Joint Owner		0
HES15 Draught stripping to exterior door	£36.00	12.00	Joint Owner		0
HES19 Draught proofing labour	£150.00	6.00	Joint Owner		0
HES20 Low energy lamp installation	£0.00	21.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00		Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Not The Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Not The Property Owner		0
HES19 Draught proofing labour	£0.00		Not The Property Owner		0
HES117 Carbon Monoxide alarm	£0.00		Not The Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£375.00	15.00	Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£937.50	75.00	Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£250.00	1.00	Sole Property Owner		0
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£835.20	87.00	Sole Property Owner		0
HES20 Low energy lamp installation	£0.00	12.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00		Joint Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Joint Owner		0
HES66 15mm thick pipework lagging	£0.00		Joint Owner		0
HES67 22mm thick pipework lagging	£0.00		Joint Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00		Joint Owner		0
HES15 Draught stripping to exterior door	£0.00		Joint Owner		0
HES16 Draught stripping to windows	£0.00		Joint Owner		0
HES19 Draught proofing labour	£0.00		Joint Owner		0
LEL 20W BC	£0.00		Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatic	£0.00		Joint Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Joint Owner		0
LEL 9W BC Candle	£0.00		Joint Owner		0
LEL 11W BC	£0.00		Joint Owner		0
LEL 20W BC	£0.00		Joint Owner		0
HES21 Smoke detector installation	£0.00		Joint Owner		0
EES51b 16-20kW Gas replacement boiler	£2,724.00	1.00	Sole Property Owner	28/09/2011	2011
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	28/09/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	28/09/2011	2011
HES121 Boiler QA Check	£165.00	1.00	Sole Property Owner	28/09/2011	2011
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner		0
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner		0

HES20 Low energy lamp installation	£0.00	18.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Sole Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Sole Property Owner		0
HES17 Draught stripping to letter boxes	£0.00		Sole Property Owner		0
HES19 Draught proofing labour	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
HES23 Scaffold / cherry picker	£0.00		Sole Property Owner		0
LEL 20W ES	£0.00	1.00	Sole Property Owner		0
LEL 9W SES	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Sole Property Owner		0
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Sole Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Sole Property Owner		0
HES19 Draught proofing labour	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner		0
LEL 9W BC	£0.00	4.00	Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Sole Property Owner		0
LEL 11W BC	£0.00	1.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner		0
LEL 5W LED GU10	£0.00	10.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
EES69 Miscellaneous Charge	£50.00	1.00	Sole Property Owner	25/01/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	25/01/2010	2010
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
LEL 9W SBC	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
HES112 HER Survey for House	£0.00	1.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Sole Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Sole Property Owner		0
HES19 Draught proofing labour	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES68 28mm thick pipework lagging	£0.00		Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Sole Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Sole Property Owner		0
HES19 Draught proofing labour	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Sole Property Owner		0
HES16 Draught stripping to windows	£0.00		Sole Property Owner		0
HES19 Draught proofing labour	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0

HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Sole Property Owner		0
HES19 Draught proofing labour	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00		Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Sole Property Owner		0
LEL 9W SBC	£0.00		Sole Property Owner		0
LEL 9W SES Candle	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
EES08 300mm thick loft insulation	£577.92	42.00	Not The Property Owner	29/12/2009	2009
EES25 Draught stripping to exterior door	£72.80	8.00	Not The Property Owner	29/12/2009	2009
EES48 Pipework lagging 19mm thick to 22mm pipe	£80.16	6.00	Not The Property Owner	29/12/2009	2009
EES47 Pipework lagging 13mm thick to 22mm pipe	£28.42	2.40	Not The Property Owner	29/12/2009	2009
EES66 Low energy lamp replacement	£19.25	11.00	Not The Property Owner	29/12/2009	2009
EES00a Full Energy Survey	£309.66	1.00	Not The Property Owner	29/12/2009	2009
HES111 HER Survey for Flat	£0.00	1.00	Sole Property Owner		0
LEL 11W BC	£0.00	4.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Not The Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Not The Property Owner		0
LEL 20W BC	£0.00		Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
LEL 11W ES	£0.00	1.00	Not The Property Owner		0
LEL 11W BC	£0.00	2.00	Not The Property Owner		0
LEL 5W LED GU10	£0.00	6.00	Not The Property Owner		0
LEL 9W SES	£0.00	2.00	Not The Property Owner		0
HES112 HER Survey for House	£0.00	1.00	Sole Property Owner	25/03/2014	2014
LEL 11W BC	£0.00	2.00	Sole Property Owner	25/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Not The Property Owner		0
HES03 200mm thick loft insulation quilt	£0.00		Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Not The Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Not The Property Owner		0
HES21 Smoke detector installation	£0.00		Not The Property Owner		0
LEL 11W BC	£0.00		Not The Property Owner		0
LEL 20W BC	£0.00		Not The Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Joint Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Joint Owner		0
HES66 15mm thick pipework lagging	£0.00		Joint Owner		0
HES67 22mm thick pipework lagging	£0.00		Joint Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00		Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Joint Owner		0
LEL 9W BC Candle	£0.00		Joint Owner		0
LEL 11W BC	£0.00		Joint Owner		0
LEL 20W BC	£0.00		Joint Owner		0
HES21 Smoke detector installation	£0.00		Joint Owner		0
LEL 5W LED GU10	£0.00	6.00	Sole Property Owner	25/03/2014	2014
HES111 HER Survey for Flat	£0.00	1.00	Sole Property Owner	25/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
LEL 20W BC	£0.00	1.00	Not The Property Owner		0
LEL 9W SES	£0.00	1.00	Not The Property Owner		0
LEL 11W BC	£0.00	3.00	Not The Property Owner		0
LEL 11W ES	£0.00	1.00	Not The Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Joint Owner		0
HES02 100mm thick loft insulation quilt	£0.00		Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Joint Owner		0
HES21 Smoke detector installation	£0.00		Joint Owner		0
LEL 9W BC Candle	£0.00		Joint Owner		0
LEL 11W BC	£0.00		Joint Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
LEL 9W SES	£0.00	1.00	Not The Property Owner		0
LEL 11W BC	£0.00	3.00	Not The Property Owner		0
LEL 11W ES	£0.00	1.00	Not The Property Owner		0
LEL 5W LED GU10	£0.00	4.00	Not The Property Owner		0
LEL 20W ES	£0.00	5.00	Not The Property Owner		0
LEL 5W LED GU10	£0.00	4.00	Sole Property Owner		0
LEL 11W BC	£0.00	1.00	Sole Property Owner		0

HES112 HER Survey for House	£0.00	1.00	Sole Property Owner		0
HES111 HER Survey for Flat	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Joint Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Joint Owner		0
HES66 15mm thick pipework lagging	£0.00		Joint Owner		0
HES67 22mm thick pipework lagging	£0.00		Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Joint Owner		0
LEL 11W BC	£0.00		Joint Owner		0
EES51b 16-20kW Gas replacement boiler	£2,333.74	1.00	Sole Property Owner	27/01/2011	2011
EES42 Two channel programmable heating controller	£0.00	1.00	Sole Property Owner	27/01/2011	2011
EES40 Hot water cylinder thermostat	£0.00	1.00	Sole Property Owner	27/01/2011	2011
EES01a Loft Clearance (hourly rate)	£187.20	4.00	Sole Property Owner	27/01/2011	2011
EES07 200mm thick loft insulation	£509.60	49.00	Sole Property Owner	27/01/2011	2011
EES66 Low energy lamp replacement	£125.07	11.00	Sole Property Owner	27/01/2011	2011
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	27/01/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	27/01/2011	2011
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	27/01/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	27/01/2011	2011
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Not The Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Not The Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Not The Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Not The Property Owner		0
HES19 Draught proofing labour	£0.00		Not The Property Owner		0
HES21 Smoke detector installation	£0.00		Not The Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Not The Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Not The Property Owner		0
HES94 Heating engineer	£0.00		Not The Property Owner		0
LEL 20W BC	£0.00		Not The Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Not The Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Not The Property Owner		0
HES21 Smoke detector installation	£0.00		Not The Property Owner		0
LEL 11W BC	£0.00		Not The Property Owner		0
LEL 20W BC	£0.00		Not The Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES03 200mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00		Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Sole Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Sole Property Owner		0
HES19 Draught proofing labour	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
LEL 9W BC Candle	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Joint Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Joint Owner		0
HES66 15mm thick pipework lagging	£0.00		Joint Owner		0
HES67 22mm thick pipework lagging	£0.00		Joint Owner		0
LEL 11W BC	£0.00		Joint Owner		0
LEL 20W BC	£0.00		Joint Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Sole Property Owner		0
LEL 11W ES	£0.00	1.00	Sole Property Owner		0
LEL 5W LED GU10	£0.00	7.00	Sole Property Owner		0
LEL 11W BC	£0.00	1.00	Sole Property Owner		0
LEL 9W SES	£0.00	1.00	Sole Property Owner		0
LEL 20W BC	£0.00	1.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner		0
LEL 9W SES Candle	£0.00	5.00	Sole Property Owner		0
LEL 20W BC	£0.00	1.00	Sole Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Sole Property Owner		0
LEL 20W BC	£0.00	2.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
LEL 9W SBC	£0.00	2.00	Not The Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Not The Property Owner		0
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00		Not The Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Not The Property Owner		0
HES19 Draught proofing labour	£0.00		Not The Property Owner		0
LEL 11W BC	£0.00		Not The Property Owner		0
LEL 20W BC	£0.00		Not The Property Owner		0
EES50c Replacement electrical storage heater	£677.12	1.00	Sole Property Owner	16/12/2011	2011
EES50c Replacement electrical storage heater	£463.07	1.00	Sole Property Owner	16/12/2011	2011
EES50c Replacement electrical storage heater	£534.86	1.00	Sole Property Owner	16/12/2011	2011
EES70 Miscellaneous heating review charge	£801.06	1.00	Sole Property Owner	16/12/2011	2011
EES44 Water heating time clock and boost	£0.00	1.00	Sole Property Owner	16/12/2011	2011
EES25 Draught stripping to exterior door	£50.00	5.00	Sole Property Owner	16/12/2011	2011

EES27 Draught stripping to letterbox	£40.00	1.00	Sole Property Owner	16/12/2011	2011
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	16/12/2011	2011
LEL 5W LED GU10	£0.00	15.00	Joint Owner		0
LEL 11W BC	£0.00	2.00	Joint Owner		0
LEL 11W ES	£0.00	5.00	Joint Owner		0
HES112 HER Survey for House	£0.00	1.00	Joint Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Not The Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Not The Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Not The Property Owner		0
HES19 Draught proofing labour	£0.00		Not The Property Owner		0
LEL 9W BC Candle	£0.00		Not The Property Owner		0
LEL 9W SBC Candle	£0.00		Not The Property Owner		0
LEL 5W LED GU10	£0.00	12.00	Not The Property Owner	25/03/2014	2014
LEL 9W BC	£0.00	2.00	Not The Property Owner	25/03/2014	2014
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner	25/03/2014	2014
HES112 HER Survey for House	£0.00	1.00	Not The Property Owner	25/03/2014	2014
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Joint Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Not The Property Owner		0
LEL 9W BC Candle	£0.00		Not The Property Owner		0
LEL 11W BC	£0.00		Not The Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Sole Property Owner		0
HES19 Draught proofing labour	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00	1.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Joint Owner		0
LEL 9W SES	£0.00	1.00	Joint Owner		0
LEL 5W LED GU10	£0.00	4.00	Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Not The Property Owner		0
LEL 20W BC	£0.00		Not The Property Owner		0
EES01a Loft Clearance (hourly rate)	£140.40	3.00	Sole Property Owner	29/04/2010	2010
EES06 100mm thick loft insulation	£328.24	44.00	Sole Property Owner	29/04/2010	2010
EES03a Remove and replace nailed floor board	£114.40	44.00	Sole Property Owner	29/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	29/04/2010	2010
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	29/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£239.72	26.00	Sole Property Owner	29/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	29/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	29/04/2010	2010
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Not The Property Owner		0
HES03 200mm thick loft insulation quilt	£0.00		Not The Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Not The Property Owner		0
HES21 Smoke detector installation	£0.00		Not The Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Joint Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Joint Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Joint Owner		0
HES66 15mm thick pipework lagging	£0.00		Joint Owner		0
HES67 22mm thick pipework lagging	£0.00		Joint Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Joint Owner		0
HES21 Smoke detector installation	£0.00		Joint Owner		0
LEL 9W BC Candle	£0.00		Joint Owner		0
LEL 20W BC	£0.00		Joint Owner		0
HES111 HER Survey for Flat	£0.00		Not The Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
LEL 9W BC Candle	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Joint Owner		0
LEL 5W LED GU10	£0.00	7.00	Joint Owner		0
LEL 9W BC Candle	£0.00	9.00	Joint Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
HES22 Minimum per property charge	£0.00		Sole Property Owner		0
LEL 9W BC Candle	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
HES15 Draught stripping to exterior door	£0.00		Joint Owner		0
HES19 Draught proofing labour	£0.00		Joint Owner		0
LEL 9W BC Candle	£0.00		Joint Owner		0
LEL 11W BC	£0.00		Joint Owner		0
LEL 20W BC	£0.00		Joint Owner		0

LEL 9W BC	£0.00	1.00	Not The Property Owner		0
LEL 11W BC	£0.00	1.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Not The Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Not The Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Not The Property Owner		0
HES16 Draught stripping to windows	£0.00		Not The Property Owner		0
HES19 Draught proofing labour	£0.00		Not The Property Owner		0
LEL 11W BC	£0.00		Not The Property Owner		0
LEL 20W BC	£0.00		Not The Property Owner		0
EES34 Replacement hot water cylinder (170l)	£715.00	1.00	Sole Property Owner	27/03/2012	2012
EES15 Insulation to 65mm wide cavity wall	£201.60	20.16	Sole Property Owner	27/03/2012	2012
EES35 Replacement hot water cylinder (210l)	£0.00	0.00	Sole Property Owner	27/03/2012	2012
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Sole Property Owner	27/03/2012	2012
EES67 Smoke detector installation	£0.00	0.00	Sole Property Owner	27/03/2012	2012
EES07 200mm thick loft insulation	£208.00	20.00	Sole Property Owner	27/03/2012	2012
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	27/03/2012	2012
EES 11 Cold water tank insulation jacket	£129.78	2.00	Sole Property Owner	27/03/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£32.36	4.00	Sole Property Owner	27/03/2012	2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£36.88	4.00	Sole Property Owner	27/03/2012	2012
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	27/03/2012	2012
EES26 Draught stripping to windows	£113.40	20.00	Sole Property Owner	27/03/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	27/03/2012	2012
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	27/03/2012	2012
EES69 Miscellaneous Charge	£172.13	1.00	Sole Property Owner	27/03/2012	2012
HES32 21-25kW Oil replacement condensing boiler	£1,817.37	1.00	Sole Property Owner		0
HES40 Flue specification and location	£848.00	1.00	Sole Property Owner		0
HES42 Purpose built lime soakaway (condensate sump)	£0.00	0.00	Sole Property Owner		0
HES43 Central heating pump	£141.55	1.00	Sole Property Owner		0
HES44 Pipework / feed modifications	£275.00	1.00	Sole Property Owner		0
HES45 Fire valve	£0.00	0.00	Sole Property Owner		0
HES46 Automatic bypass	£46.32	1.00	Sole Property Owner		0
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner		0
HES50 Electrical room thermostat	£53.32	1.00	Sole Property Owner		0
HES52 Hot water cylinder thermostat	£33.21	1.00	Sole Property Owner		0
HES53 Two channel heating programmer control	£85.11	1.00	Sole Property Owner		0
HES55 2 port zone valve	£138.56	2.00	Sole Property Owner		0
HES67 22mm thick pipework lagging	£69.80	20.00	Sole Property Owner		0
HES68 28mm thick pipework lagging	£67.68	18.00	Sole Property Owner		0
HES94 Heating engineer	£1,748.00	46.00	Sole Property Owner		0
HES97 Electrician	£200.00	8.00	Sole Property Owner		0
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner		0
HES88 Commissioning and issue of CD11 and flue gas analysis	£38.00	1.00	Sole Property Owner		0
HES90 Other miscellaneous oil heating works for EES approval	£37.00	1.00	Sole Property Owner		0
HES90 Other miscellaneous oil heating works for EES approval	£80.00	1.00	Sole Property Owner		0
HES41 Condensate pipework (and pump if required)	£100.00	1.00	Sole Property Owner		0
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner		0
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00		Sole Property Owner		0
LEL 9W SBC Candle	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
HES01 Loft preparation labour (clearance, disposal of old insulatio	£0.00		Sole Property Owner		0
HES04 300mm thick loft insulation quilt	£0.00		Sole Property Owner		0
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Sole Property Owner		0
HES66 15mm thick pipework lagging	£0.00		Sole Property Owner		0
HES67 22mm thick pipework lagging	£0.00		Sole Property Owner		0
HES21 Smoke detector installation	£0.00		Sole Property Owner		0
LEL 11W BC	£0.00		Sole Property Owner		0
LEL 20W BC	£0.00		Sole Property Owner		0
LEL 9W BC	£0.00	4.00	Not The Property Owner		0
LEL 11W BC	£0.00	4.00	Not The Property Owner		0
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
LEL 11W BC	£0.00	1.00	Not The Property Owner		0
LEL 5W LED GU10	£0.00	7.00	Not The Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner		0
LEL 20W BC	£0.00	3.00	Not The Property Owner		0
LEL 9W BC Candle	£0.00	8.00	Not The Property Owner		0
LEL 11W BC	£0.00	3.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
LEL 5W LED GU10	£0.00	7.00	Not The Property Owner		0
LEL 9W SES	£0.00	7.00	Not The Property Owner		0
LEL 11W BC	£0.00	3.00	Not The Property Owner		0
EES01a Loft Clearance (hourly rate)	£31.63	1.00	Sole Property Owner	29/01/2010	2010
EES07 200mm thick loft insulation	£1,018.24	74.00	Sole Property Owner	29/01/2010	2010
EES09 Intumescent bag/fire hood to downlighter	£172.00	8.00	Sole Property Owner	29/01/2010	2010

EES10 Cold water tank insulation quilt	£103.86	3.00	Sole Property Owner	29/01/2010	2010
EES69 Miscellaneous Charge	£36.40	4.00	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£49.00	28.00	Sole Property Owner	29/01/2010	2010
EES67 Smoke detector installation	£9.80	1.00	Sole Property Owner	29/01/2010	2010
EES38a Thermostatic radiator valve (per valve)	£484.00	11.00	Sole Property Owner	29/01/2010	2010
EES44 Water heating time clock and boost	£111.00	1.00	Sole Property Owner	29/01/2010	2010
EES38a Thermostatic radiator valve (per valve)	£484.00	11.00	Sole Property Owner	29/01/2010	2010
EES44 Water heating time clock and boost	£89.30	1.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	29/01/2010	2010
LEL 20W BC	£0.00	5.00	Not The Property Owner		0
LEL 11W BC	£0.00	2.00	Not The Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES112 HER Survey for House	£0.00		Joint Owner		0
HES111 HER Survey for Flat	£0.00		Not The Property Owner		0
EES07 200mm thick loft insulation	£525.69	59.00	Sole Property Owner	12/11/2009	2009
EES10 Cold water tank insulation quilt	£49.24	1.00	Sole Property Owner	12/11/2009	2009
EES12 Cold water tank lid	£20.00	1.00	Sole Property Owner	12/11/2009	2009
EES25 Draught stripping to exterior door	£111.02	12.20	Sole Property Owner	12/11/2009	2009
EES66 Low energy lamp replacement	£19.25	11.00	Sole Property Owner	12/11/2009	2009
EES69 Miscellaneous Charge	£379.50	1.00	Sole Property Owner	12/11/2009	2009
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	12/11/2009	2009
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	12/11/2009	2009
EES44 Water heating time clock and boost	£134.21	1.00	Sole Property Owner	12/11/2009	2009
EES42 Two channel programmable heating controller	£125.69	1.00	Sole Property Owner	12/11/2009	2009
EES38a Thermostatic radiator valve (per valve)	£532.51	11.00	Sole Property Owner	12/11/2009	2009
LEL 20W BC	£0.00	1.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00		Joint Owner		0
EES01a Loft Clearance (hourly rate)	£126.50	2.00	Sole Property Owner	18/02/2010	2010
EES02a Remove and dispose existing insulation (per squire metre)	£189.00	45.00	Sole Property Owner	18/02/2010	2010
EES03a Remove and replace nailed floor board	£413.00	35.00	Sole Property Owner	18/02/2010	2010
EES08 300mm thick loft insulation	£710.55	45.00	Sole Property Owner	18/02/2010	2010
EES 11 Cold water tank insulation jacket	£42.62	1.00	Sole Property Owner	18/02/2010	2010
EES15 Insulation to 65mm wide cavity wall	£348.45	50.50	Sole Property Owner	18/02/2010	2010
EES69 Miscellaneous Charge	£350.00	350.00	Sole Property Owner	18/02/2010	2010
EES25 Draught stripping to exterior door	£154.70	17.00	Sole Property Owner	18/02/2010	2010
EES27 Draught stripping to letterbox	£9.10	1.00	Sole Property Owner	18/02/2010	2010
EES36 Electrical room thermostat	£103.40	1.00	Sole Property Owner	18/02/2010	2010
EES38a Thermostatic radiator valve (per valve)	£352.00	8.00	Sole Property Owner	18/02/2010	2010
EES42 Two channel programmable heating controller	£111.00	1.00	Sole Property Owner	18/02/2010	2010
EES44 Water heating time clock and boost	£111.00	1.00	Sole Property Owner	18/02/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£230.20	20.00	Sole Property Owner	18/02/2010	2010
EES66 Low energy lamp replacement	£29.75	1.00	Sole Property Owner	18/02/2010	2010
EES67 Smoke detector installation	£29.40	3.00	Sole Property Owner	18/02/2010	2010
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	18/02/2010	2010
HES111 HER Survey for Flat	£0.00		Not The Property Owner		0
HES111 HER Survey for Flat	£0.00		Not The Property Owner		0
HES111 HER Survey for Flat	£0.00		Sole Property Owner		0
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Joint Owner	12/03/2012	2012
EES03a Remove and replace nailed floor board	£0.00	0.00	Joint Owner	12/03/2012	2012
EES08 300mm thick loft insulation	£0.00	0.00	Joint Owner	12/03/2012	2012
EES10 Cold water tank insulation quilt	£0.00	0.00	Joint Owner	12/03/2012	2012
EES 11 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	12/03/2012	2012
EES12 Cold water tank lid	£0.00	0.00	Joint Owner	12/03/2012	2012
EES13a Cold water tank bye law kit (including associated product)	£0.00	0.00	Joint Owner	12/03/2012	2012
EES25 Draught stripping to exterior door	£70.00	7.00	Joint Owner	12/03/2012	2012
EES27 Draught stripping to letterbox	£40.00	1.00	Joint Owner	12/03/2012	2012
EES66 Low energy lamp replacement	£0.00	20.00	Joint Owner	12/03/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	12/03/2012	2012
EES29 Hot water cylinder jacket (30x18 inch)	£90.00	1.00	Joint Owner	12/03/2012	2012
HES111 HER Survey for Flat	£0.00		Not The Property Owner		0
HES111 HER Survey for Flat	£0.00		Not The Property Owner		0
HES111 HER Survey for Flat	£0.00		Not The Property Owner		0
LEL 11W ES	£0.00	2.00	Not The Property Owner		0
LEL 5W LED GU10	£0.00	4.00	Not The Property Owner		0
LEL 11W BC	£0.00	2.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
HES111 HER Survey for Flat	£0.00	1.00	Not The Property Owner		0
LEL 20W BC	£0.00	2.00	Not The Property Owner		0
LEL 9W SBC Candle	£0.00	4.00	Not The Property Owner		0
LEL 11W BC	£0.00	5.00	Not The Property Owner		0
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner		0
EES66 Low energy lamp replacement	£0.00	6.00	Not The Property Owner	06/11/2011	2011
EES67 Smoke detector installation	£0.00	4.00	Not The Property Owner	06/11/2011	2011
EES15 Insulation to 65mm wide cavity wall	£174.00	174.00	Not The Property Owner	06/11/2011	2011
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Not The Property Owner	06/11/2011	2011
EES08 300mm thick loft insulation	£0.00	0.00	Not The Property Owner	06/11/2011	2011
EES81 Insulation to 50mm cavity	£0.00	0.00	Not The Property Owner	06/11/2011	2011
EES69 Miscellaneous Charge	£0.00	0.00	Not The Property Owner	06/11/2011	2011
EES25 Draught stripping to exterior door	£0.00	0.00	Not The Property Owner	06/11/2011	2011
EES36 Electrical room thermostat	£0.00	0.00	Not The Property Owner	06/11/2011	2011
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Not The Property Owner	06/11/2011	2011
EES42 Two channel programmable heating controller	£0.00	0.00	Not The Property Owner	06/11/2011	2011

EES44 Water heating time clock and boost	£0.00	0.00	Not The Property Owner	06/11/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£0.00	0.00	Not The Property Owner	06/11/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£0.00	0.00	Not The Property Owner	06/11/2011	2011
EES66 Low energy lamp replacement	£0.00	1.00	Not The Property Owner	06/11/2011	2011
EES67 Smoke detector installation	£0.00	0.00	Not The Property Owner	06/11/2011	2011
EES00a Full Energy Survey	£300.42	1.00	Not The Property Owner	06/11/2011	2011
HES111 HER Survey for Flat	£0.00		Not The Property Owner		0
HES111 HER Survey for Flat	£0.00		Not The Property Owner		0
EES01a Loft Clearance (hourly rate)	£126.50	2.00	Sole Property Owner	29/01/2010	2010
EES06 100mm thick loft insulation	£302.72	44.00	Sole Property Owner	29/01/2010	2010
EES03a Remove and replace nailed floor board	£59.00	5.00	Sole Property Owner	29/01/2010	2010
EES09 Intumescent bag/fire hood to downlighter	£63.75	3.00	Sole Property Owner	29/01/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£66.80	5.00	Sole Property Owner	29/01/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£28.42	2.40	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£22.75	13.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	29/01/2010	2010
EES38a Thermostatic radiator valve (per valve)	£145.23	3.00	Sole Property Owner	29/01/2010	2010
EES44 Water heating time clock and boost	£134.21	1.00	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£34.11	3.00	Not The Property Owner	15/12/2009	2009
EES00a Full Energy Survey	£246.55	1.00	Not The Property Owner	15/12/2009	2009
EES69 Miscellaneous Charge	£50.00	1.00	Sole Property Owner	16/12/2011	2011
EES66 Low energy lamp replacement	£0.00	12.00	Sole Property Owner	16/12/2011	2011
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	16/12/2011	2011
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	16/12/2011	2011
HES111 HER Survey for Flat	£0.00		Not The Property Owner		0
HES111 HER Survey for Flat	£0.00		Not The Property Owner		0
HES111 HER Survey for Flat	£0.00		Joint Owner		0
EES69 Miscellaneous Charge	£0.00	0.00	Not The Property Owner	03/08/2010	2010
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Not The Property Owner	03/08/2010	2010
EES25 Draught stripping to exterior door	£0.00	0.00	Not The Property Owner	03/08/2010	2010
EES27 Draught stripping to letterbox	£0.00	0.00	Not The Property Owner	03/08/2010	2010
EES66 Low energy lamp replacement	£0.00	0.00	Not The Property Owner	03/08/2010	2010
EES67 Smoke detector installation	£0.00	0.00	Not The Property Owner	03/08/2010	2010
EES69 Miscellaneous Charge	£100.00	1.00	Not The Property Owner	03/08/2010	2010
EES00a Full Energy Survey	£300.42	1.00	Not The Property Owner	03/08/2010	2010
EES02a Remove and dispose existing insulation (per squire metre	£75.60	36.00	Sole Property Owner	29/01/2010	2010
EES08 300mm thick loft insulation	£363.96	36.00	Sole Property Owner	29/01/2010	2010
EES12 Cold water tank lid	£38.63	1.00	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£15.75	9.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	29/01/2010	2010
EES 30 Hot water cylinder jacket (46x18 inch)	£47.04	1.00	Sole Property Owner	29/01/2010	2010
EES44 Water heating time clock and boost	£134.21	1.00	Sole Property Owner	29/01/2010	2010
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	02/08/2011	2011
EES07 200mm thick loft insulation	£540.00	60.00	Sole Property Owner	02/08/2011	2011
EES13a Cold water tank bye law kit (including associated product	£150.00	1.00	Sole Property Owner	02/08/2011	2011
EES12 Cold water tank lid	£280.00	1.00	Sole Property Owner	02/08/2011	2011
EES36 Electrical room thermostat	£50.00	1.00	Sole Property Owner	02/08/2011	2011
EES38a Thermostatic radiator valve (per valve)	£341.25	7.00	Sole Property Owner	02/08/2011	2011
EES69 Miscellaneous Charge	£25.00	1.00	Sole Property Owner	02/08/2011	2011
EES51b 16-20kW Gas replacement boiler	£3,538.84	1.00	Sole Property Owner	02/08/2011	2011
EES42 Two channel programmable heating controller	£0.00	1.00	Sole Property Owner	02/08/2011	2011
EES40 Hot water cylinder thermostat	£0.00	1.00	Sole Property Owner	02/08/2011	2011
EES36 Electrical room thermostat	£0.00	1.00	Sole Property Owner	02/08/2011	2011
EES69 Miscellaneous Charge	£402.50	1.00	Sole Property Owner	02/08/2011	2011
EES16 Insulation to 75mm wide cavity wall	£1,606.45	181.11	Sole Property Owner	02/08/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	02/08/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	02/08/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	02/08/2011	2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	22/03/2011	2011
EES25 Draught stripping to exterior door	£67.70	7.44	Not The Property Owner	22/03/2011	2011
EES67 Smoke detector installation	£25.00	1.00	Not The Property Owner	22/03/2011	2011
EES66 Low energy lamp replacement	£25.00	1.00	Not The Property Owner	22/03/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	22/03/2011	2011
EES01a Loft Clearance (hourly rate)	£253.00	4.00	Sole Property Owner	29/01/2010	2010
EES08 300mm thick loft insulation	£2,036.91	129.00	Sole Property Owner	29/01/2010	2010
EES15 Insulation to 65mm wide cavity wall	£1,111.54	149.00	Sole Property Owner	29/01/2010	2010
EES25 Draught stripping to exterior door	£127.40	14.00	Sole Property Owner	29/01/2010	2010
EES 30 Hot water cylinder jacket (46x18 inch)	£42.62	1.00	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£68.25	39.00	Sole Property Owner	29/01/2010	2010
EES67 Smoke detector installation	£9.80	1.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	29/01/2010	2010
EES01a Loft Clearance (hourly rate)	£400.00	16.00	Sole Property Owner	27/09/2012	2012
EES02a Remove and dispose existing insulation (per squire metre	£180.00	60.00	Sole Property Owner	27/09/2012	2012
EES08 300mm thick loft insulation	£840.00	70.00	Sole Property Owner	27/09/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	27/09/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	27/09/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	27/09/2012	2012
EES13a Cold water tank bye law kit (including associated product	£100.00	2.00	Sole Property Owner	27/09/2012	2012
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Sole Property Owner	27/09/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£70.00	10.00	Sole Property Owner	27/09/2012	2012
EES66 Low energy lamp replacement	£0.00	15.00	Sole Property Owner	27/09/2012	2012
EES67 Smoke detector installation	£0.00	0.00	Sole Property Owner	27/09/2012	2012
HES120 Standard QA check	£102.00	1.00	Sole Property Owner	27/09/2012	2012
EES08 300mm thick loft insulation	£1,036.00	148.00	Sole Property Owner	29/01/2010	2010

EES15 Insulation to 65mm wide cavity wall	£825.97	110.13	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	29/01/2010	2010
EES50c Replacement electrical storage heater	£411.00	1.00	Sole Property Owner	26/01/2012	2012
EES50c Replacement electrical storage heater	£788.37	3.00	Sole Property Owner	26/01/2012	2012
EES50c Replacement electrical storage heater	£475.00	1.00	Sole Property Owner	26/01/2012	2012
EES50c Replacement electrical storage heater	£207.00	1.00	Sole Property Owner	26/01/2012	2012
EES07 200mm thick loft insulation	£534.60	60.00	Sole Property Owner	26/01/2012	2012
EES01a Loft Clearance (hourly rate)	£126.50	2.00	Sole Property Owner	26/01/2012	2012
EES02a Remove and dispose existing insulation (per squire metre)	£126.00	30.00	Sole Property Owner	26/01/2012	2012
EES69 Miscellaneous Charge	£41.00	5.00	Sole Property Owner	26/01/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	26/01/2012	2012
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	26/01/2012	2012
EES25 Draught stripping to exterior door	£40.00	4.00	Sole Property Owner	07/03/2010	2010
EES31 Hot water cylinder jacket (58x20 inch)	£1,240.00	1.00	Sole Property Owner	07/03/2010	2010
EES38a Thermostatic radiator valve (per valve)	£487.50	10.00	Sole Property Owner	07/03/2010	2010
EES69 Miscellaneous Charge	£60.00	1.00	Sole Property Owner	07/03/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	07/03/2010	2010
EES50a 12-15kW Oil replacement boiler	£1,700.00	1.00	Sole Property Owner	13/07/2011	2011
EES07 200mm thick loft insulation	£517.50	69.00	Sole Property Owner	13/07/2011	2011
EES 11 Cold water tank insulation jacket	£64.57	1.00	Sole Property Owner	13/07/2011	2011
EES12 Cold water tank lid	£226.20	2.00	Sole Property Owner	13/07/2011	2011
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Sole Property Owner	13/07/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	13/07/2011	2011
EES66 Low energy lamp replacement	£63.84	1.00	Sole Property Owner	13/07/2011	2011
EES17 Insulation to 90mm wide cavity wall	£1,014.76	110.30	Sole Property Owner	13/07/2011	2011
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	13/07/2011	2011
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	09/09/2011	2011
EES38a Thermostatic radiator valve (per valve)	£63.69	1.00	Sole Property Owner	09/09/2011	2011
EES42 Two channel programmable heating controller	£139.50	1.00	Sole Property Owner	09/09/2011	2011
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	09/09/2011	2011
EES70 Miscellaneous heating review charge	£630.00	1.00	Sole Property Owner	09/09/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	1.00	Sole Property Owner	09/09/2011	2011
EES70 Miscellaneous heating review charge	£1,537.78	1,537.78	Sole Property Owner	09/09/2011	2011
EES15 Insulation to 65mm wide cavity wall	£1,856.65	201.81	Sole Property Owner	09/09/2011	2011
EES38a Thermostatic radiator valve (per valve)	£296.31	7.00	Sole Property Owner	09/09/2011	2011
EES42 Two channel programmable heating controller	£95.53	1.00	Sole Property Owner	09/09/2011	2011
EES44 Water heating time clock and boost	£122.15	1.00	Sole Property Owner	09/09/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£65.00	5.00	Sole Property Owner	09/09/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£13.00	1.00	Sole Property Owner	09/09/2011	2011
EES66 Low energy lamp replacement	£105.60	22.00	Sole Property Owner	09/09/2011	2011
EES66 Low energy lamp replacement	£32.00	4.00	Sole Property Owner	09/09/2011	2011
EES67 Smoke detector installation	£0.00	0.00	Sole Property Owner	09/09/2011	2011
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	09/09/2011	2011
HES85 Building Control Officer inspection undertaken	£103.85	1.00	Sole Property Owner	09/09/2011	2011
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Not The Property Owner	29/01/2010	2010
EES07 200mm thick loft insulation	£324.00	36.00	Not The Property Owner	29/01/2010	2010
EES42 Two channel programmable heating controller	£95.59	1.00	Not The Property Owner	29/01/2010	2010
EES44 Water heating time clock and boost	£50.00	1.00	Not The Property Owner	29/01/2010	2010
EES13a Cold water tank bye law kit (including associated products)	£560.00	2.00	Not The Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£300.42	1.00	Not The Property Owner	29/01/2010	2010
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	07/06/2011	2011
EES02a Remove and dispose existing insulation (per squire metre)	£276.00	92.00	Sole Property Owner	07/06/2011	2011
EES08 300mm thick loft insulation	£1,104.00	92.00	Sole Property Owner	07/06/2011	2011
EES13a Cold water tank bye law kit (including associated products)	£280.00	1.00	Sole Property Owner	07/06/2011	2011
EES69 Miscellaneous Charge	£150.00	150.00	Sole Property Owner	07/06/2011	2011
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	07/06/2011	2011
EES69 Miscellaneous Charge	£85.00	85.00	Sole Property Owner	07/06/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£168.00	24.00	Sole Property Owner	07/06/2011	2011
EES69 Miscellaneous Charge	£150.00	1.00	Sole Property Owner	07/06/2011	2011
EES13a Cold water tank bye law kit (including associated products)	£280.00	1.00	Sole Property Owner	07/06/2011	2011
EES69 Miscellaneous Charge	£50.00	2.00	Sole Property Owner	07/06/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	07/06/2011	2011
EES44 Water heating time clock and boost	£122.15	1.00	Not The Property Owner	01/11/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£26.00	2.00	Not The Property Owner	01/11/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£11.45	1.00	Not The Property Owner	01/11/2010	2010
EES66 Low energy lamp replacement	£32.00	5.00	Not The Property Owner	01/11/2010	2010
EES00a Full Energy Survey	£309.66	1.00	Not The Property Owner	01/11/2010	2010
EES07 200mm thick loft insulation	£325.00	50.00	Sole Property Owner	18/02/2010	2010
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	18/02/2010	2010
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	19/10/2012	2012
EES08 300mm thick loft insulation	£180.00	15.00	Sole Property Owner	19/10/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	19/10/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	19/10/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	19/10/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Sole Property Owner	19/10/2012	2012
EES25 Draught stripping to exterior door	£60.00	6.00	Sole Property Owner	19/10/2012	2012
EES35 Replacement hot water cylinder (210l)	£0.00	0.00	Sole Property Owner	19/10/2012	2012
EES15 Insulation to 65mm wide cavity wall	£209.00	209.00	Sole Property Owner	19/10/2012	2012
EES66 Low energy lamp replacement	£0.00	18.00	Sole Property Owner	19/10/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	19/10/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	19/10/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	19/10/2012	2012
EES38a Thermostatic radiator valve (per valve)	£1,105.00	13.00	Sole Property Owner	19/10/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	19/10/2012	2012

EES70 Miscellaneous heating review charge	£1,916.30	1.00	Sole Property Owner	19/10/2012	2012
EES51b 16-20kW Gas replacement boiler	£1,308.00	1.00	Sole Property Owner	19/10/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	19/10/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	15/03/2010	2010
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Sole Property Owner	29/01/2010	2010
EES02a Remove and dispose existing insulation (per squire metre)	£25.00	1.00	Sole Property Owner	29/01/2010	2010
EES08 300mm thick loft insulation	£504.00	72.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	29/01/2010	2010
EES03b Remove and replace nailed floor board (hourly rate)	£12.50	5.00	Sole Property Owner	16/12/2011	2011
EES02b Remove and dispose existing insulation (hourly rate)	£135.00	45.00	Sole Property Owner	16/12/2011	2011
EES07 200mm thick loft insulation	£540.00	60.00	Sole Property Owner	16/12/2011	2011
EES10 Cold water tank insulation quilt	£280.00	3.50	Sole Property Owner	16/12/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	16/12/2011	2011
EES15 Insulation to 65mm wide cavity wall	£795.00	106.00	Sole Property Owner	30/03/2010	2010
EES38a Thermostatic radiator valve (per valve)	£296.31	7.00	Sole Property Owner	30/03/2010	2010
EES42 Two channel programmable heating controller	£95.53	1.00	Sole Property Owner	30/03/2010	2010
EES44 Water heating time clock and boost	£122.15	1.00	Sole Property Owner	30/03/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£26.00	2.00	Sole Property Owner	30/03/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£13.00	1.00	Sole Property Owner	30/03/2010	2010
EES10 Cold water tank insulation quilt	£136.99	1.00	Sole Property Owner	30/03/2010	2010
EES66 Low energy lamp replacement	£120.00	25.00	Sole Property Owner	30/03/2010	2010
EES66 Low energy lamp replacement	£64.00	64.00	Sole Property Owner	30/03/2010	2010
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	30/03/2010	2010
EES52a 21-25kW Oil replacement boiler	£3,250.80	1.00	Sole Property Owner	23/03/2011	2011
EES70 Miscellaneous heating review charge	£913.57	1.00	Sole Property Owner	23/03/2011	2011
EES38a Thermostatic radiator valve (per valve)	£423.30	10.00	Sole Property Owner	23/03/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£52.00	4.00	Sole Property Owner	23/03/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£11.45	1.00	Sole Property Owner	23/03/2011	2011
EES67 Smoke detector installation	£22.50	3.00	Sole Property Owner	23/03/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	23/03/2011	2011
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	23/03/2011	2011
EES51a 16-20kW Oil replacement boiler	£2,684.52	1.00	Sole Property Owner	29/01/2010	2010
EES21 Scaffold	£402.50	50.00	Sole Property Owner	29/01/2010	2010
EES19 Airbrick	£55.20	6.00	Sole Property Owner	29/01/2010	2010
EES18b Cavity brush (per metre)	£42.84	10.20	Sole Property Owner	29/01/2010	2010
EES16 Insulation to 75mm wide cavity wall	£1,065.02	132.30	Sole Property Owner	29/01/2010	2010
EES67 Smoke detector installation	£9.80	1.00	Sole Property Owner	29/01/2010	2010
EES70 Miscellaneous heating review charge	£372.16	1.00	Sole Property Owner	29/01/2010	2010
EES69 Miscellaneous Charge	£37.42	1.00	Sole Property Owner	29/01/2010	2010
EES01a Loft Clearance (hourly rate)	£31.63	0.50	Sole Property Owner	29/01/2010	2010
EES07 200mm thick loft insulation	£619.20	45.00	Sole Property Owner	29/01/2010	2010
EES10 Cold water tank insulation quilt	£34.62	1.00	Sole Property Owner	29/01/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£80.16	6.00	Sole Property Owner	29/01/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£28.42	2.40	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£38.50	22.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	29/01/2010	2010
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	29/01/2010	2010
EES35 Replacement hot water cylinder (210l)	£544.43	1.00	Sole Property Owner	29/01/2010	2010
EES38a Thermostatic radiator valve (per valve)	£360.48	6.00	Sole Property Owner	29/01/2010	2010
EES44 Water heating time clock and boost	£134.21	1.00	Sole Property Owner	29/01/2010	2010
EES69 Miscellaneous Charge	£113.83	1.00	Sole Property Owner	29/01/2010	2010
EES69 Miscellaneous Charge	£1,609.31	1.00	Sole Property Owner	29/01/2010	2010
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	16/12/2011	2011
EES08 300mm thick loft insulation	£1,824.00	152.00	Sole Property Owner	16/12/2011	2011
EES12 Cold water tank lid	£280.00	1.00	Sole Property Owner	16/12/2011	2011
EES38a Thermostatic radiator valve (per valve)	£536.25	11.00	Sole Property Owner	16/12/2011	2011
EES19 Airbrick	£73.60	8.00	Sole Property Owner	16/12/2011	2011
EES15 Insulation to 65mm wide cavity wall	£1,108.80	154.00	Sole Property Owner	16/12/2011	2011
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	16/12/2011	2011
EES07 200mm thick loft insulation	£611.04	76.00	Sole Property Owner	29/01/2010	2010
EES10 Cold water tank insulation quilt	£840.00	2.50	Sole Property Owner	29/01/2010	2010
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	29/01/2010	2010
EES38a Thermostatic radiator valve (per valve)	£180.00	3.00	Sole Property Owner	29/01/2010	2010
EES12 Cold water tank lid	£130.00	1.00	Sole Property Owner	29/01/2010	2010
EES69 Miscellaneous Charge	£817.66	1.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	29/01/2010	2010
EES50c Replacement electrical storage heater	£822.00	2.00	Sole Property Owner	26/01/2012	2012
EES70 Miscellaneous heating review charge	£216.67	1.00	Sole Property Owner	26/01/2012	2012
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Sole Property Owner	26/01/2012	2012
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	26/01/2012	2012
EES36 Electrical room thermostat	£103.40	1.00	Sole Property Owner	04/04/2010	2010
EES68 Minimum charge for lamps and detectors	£26.25	1.00	Sole Property Owner	04/04/2010	2010
EES38a Thermostatic radiator valve (per valve)	£440.00	10.00	Sole Property Owner	04/04/2010	2010
EES53a 26-35kW Oil replacement boiler	£4,368.00	4,368.00	Sole Property Owner	10/10/2011	2011
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	10/10/2011	2011
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	10/10/2011	2011
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	10/10/2011	2011
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	10/10/2011	2011
EES38a Thermostatic radiator valve (per valve)	£595.00	7.00	Sole Property Owner	10/10/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£112.00	16.00	Sole Property Owner	10/10/2011	2011
EES01a Loft Clearance (hourly rate)	£187.20	4.00	Sole Property Owner	10/10/2011	2011
EES08 300mm thick loft insulation	£889.84	49.00	Sole Property Owner	10/10/2011	2011
EES15 Insulation to 65mm wide cavity wall	£367.01	49.00	Sole Property Owner	10/10/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£48.54	6.00	Sole Property Owner	10/10/2011	2011

EES48 Pipework lagging 19mm thick to 22mm pipe	£110.64	12.00	Sole Property Owner	10/10/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£85.62	6.00	Sole Property Owner	10/10/2011	2011
EES66 Low energy lamp replacement	£227.40	20.00	Sole Property Owner	10/10/2011	2011
EES38a Thermostatic radiator valve (per valve)	£264.40	8.00	Sole Property Owner	10/10/2011	2011
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	10/10/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	10/10/2011	2011
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	10/10/2011	2011
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	10/10/2011	2011
EES53a 26-35kW Oil replacement boiler	£3,436.00	1.00	Sole Property Owner	02/03/2012	2012
EES70 Miscellaneous heating review charge	£876.12	1.00	Sole Property Owner	02/03/2012	2012
EES49 Pipework lagging 25mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	02/03/2012	2012
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Sole Property Owner	02/03/2012	2012
EES07 200mm thick loft insulation	£273.00	42.00	Sole Property Owner	02/03/2012	2012
EES15 Insulation to 65mm wide cavity wall	£1,170.00	156.00	Sole Property Owner	02/03/2012	2012
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	02/03/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	02/03/2012	2012
EES38a Thermostatic radiator valve (per valve)	£765.00	9.00	Sole Property Owner	06/01/2012	2012
EES10 Cold water tank insulation quilt	£0.00	0.00	Sole Property Owner	06/01/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£0.00	0.00	Sole Property Owner	06/01/2012	2012
EES53a 26-35kW Oil replacement boiler	£5,328.00	1.00	Sole Property Owner	06/01/2012	2012
EES12 Cold water tank lid	£0.00	0.00	Sole Property Owner	06/01/2012	2012
EES 11 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	06/01/2012	2012
EES01a Loft Clearance (hourly rate)	£187.20	4.00	Sole Property Owner	06/01/2012	2012
EES07 200mm thick loft insulation	£582.40	56.00	Sole Property Owner	06/01/2012	2012
EES03a Remove and replace nailed floor board	£145.60	56.00	Sole Property Owner	06/01/2012	2012
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	06/01/2012	2012
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	06/01/2012	2012
EES49 Pipework lagging 25mm thick to 22mm pipe	£202.84	22.00	Sole Property Owner	06/01/2012	2012
EES66 Low energy lamp replacement	£55.80	15.00	Sole Property Owner	06/01/2012	2012
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	06/01/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	06/01/2012	2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Sole Property Owner	16/12/2011	2011
EES03a Remove and replace nailed floor board	£20.00	8.00	Sole Property Owner	16/12/2011	2011
EES08 300mm thick loft insulation	£576.00	48.00	Sole Property Owner	16/12/2011	2011
EES 11 Cold water tank insulation jacket	£280.00	3.50	Sole Property Owner	16/12/2011	2011
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Sole Property Owner	16/12/2011	2011
EES34 Replacement hot water cylinder (170l)	£1,200.00	1.00	Sole Property Owner	16/12/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	16/12/2011	2011
EES01a Loft Clearance (hourly rate)	£126.50	2.00	Sole Property Owner	29/01/2010	2010
EES07 200mm thick loft insulation	£641.52	72.00	Sole Property Owner	29/01/2010	2010
EES 11 Cold water tank insulation jacket	£37.42	1.00	Sole Property Owner	29/01/2010	2010
EES15 Insulation to 65mm wide cavity wall	£1,048.80	152.00	Sole Property Owner	29/01/2010	2010
EES38a Thermostatic radiator valve (per valve)	£484.00	11.00	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£47.25	27.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	29/01/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	01/03/2010	2010
EES40 Hot water cylinder thermostat	£59.86	1.00	Sole Property Owner	18/04/2013	2013
EES44 Water heating time clock and boost	£152.46	1.00	Sole Property Owner	18/04/2013	2013
EES42 Two channel programmable heating controller	£119.70	1.00	Sole Property Owner	18/04/2013	2013
EES36 Electrical room thermostat	£85.68	1.00	Sole Property Owner	18/04/2013	2013
EES52a 21-25kW Oil replacement boiler	£3,250.80	1.00	Sole Property Owner	18/04/2013	2013
EES70 Miscellaneous heating review charge	£495.87	1.00	Sole Property Owner	18/04/2013	2013
EES70 Miscellaneous heating review charge	£0.00	0.00	Sole Property Owner	18/04/2013	2013
EES82 Boiler replacement miscellaneous works	£873.60	1.00	Sole Property Owner	18/04/2013	2013
EES08 300mm thick loft insulation	£189.28	26.00	Sole Property Owner	18/04/2013	2013
EES38a Thermostatic radiator valve (per valve)	£42.33	1.00	Sole Property Owner	18/04/2013	2013
EES47 Pipework lagging 13mm thick to 22mm pipe	£37.87	7.20	Sole Property Owner	18/04/2013	2013
EES48 Pipework lagging 19mm thick to 22mm pipe	£9.89	2.40	Sole Property Owner	18/04/2013	2013
EES66 Low energy lamp replacement	£46.65	15.00	Sole Property Owner	18/04/2013	2013
EES67 Smoke detector installation	£7.28	1.00	Sole Property Owner	18/04/2013	2013
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	18/04/2013	2013
HES40 Flue specification and location	£402.50	1.00	Sole Property Owner	18/04/2013	2013
HES41 Condensate pipework (and pump if required)	£23.00	1.00	Sole Property Owner	18/04/2013	2013
HES44 Pipework / feed modifications	£69.00	1.00	Sole Property Owner	18/04/2013	2013
HES48 Power / system flush and treatment	£460.00	1.00	Sole Property Owner	18/04/2013	2013
HES49 Carbon Monoxide alarm	£42.00	1.00	Sole Property Owner	18/04/2013	2013
HES66 15mm thick pipework lagging	£3.24	1.00	Sole Property Owner	18/04/2013	2013
HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	18/04/2013	2013
HES68 28mm thick pipework lagging	£0.00	0.00	Sole Property Owner	18/04/2013	2013
HES93 Junior heating engineer	£21.97	1.00	Sole Property Owner	18/04/2013	2013
HES94 Heating engineer	£920.00	25.00	Sole Property Owner	18/04/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	18/04/2013	2013
HES99 Building works	£29.33	1.00	Sole Property Owner	18/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£832.30	832.30	Sole Property Owner	18/04/2013	2013
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	18/04/2013	2013
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	18/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£387.47	1.00	Sole Property Owner	18/04/2013	2013
HES43 Central heating pump	£92.00	1.00	Sole Property Owner	18/04/2013	2013
EES50b 12-15kW Gas replacement boiler	£971.00	1.00	Sole Property Owner	24/02/2011	2011
EES70 Miscellaneous heating review charge	£1,877.17	1,877.17	Sole Property Owner	24/02/2011	2011
EES01a Loft Clearance (hourly rate)	£187.20	4.00	Sole Property Owner	24/02/2011	2011
EES08 300mm thick loft insulation	£386.14	43.00	Sole Property Owner	24/02/2011	2011
EES15 Insulation to 65mm wide cavity wall	£614.18	82.00	Sole Property Owner	24/02/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£80.90	10.00	Sole Property Owner	24/02/2011	2011

EES48 Pipework lagging 19mm thick to 22mm pipe	£110.64	12.00	Sole Property Owner	24/02/2011	2011
EES66 Low energy lamp replacement	£170.55	15.00	Sole Property Owner	24/02/2011	2011
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	24/02/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	24/02/2011	2011
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	24/02/2011	2011
EES77 HEC to House	£150.00	1.00	Not The Property Owner	07/11/2009	2009
EES00a Full Energy Survey	£300.42	1.00	Not The Property Owner	26/10/2009	2009
EES01a Loft Clearance (hourly rate)	£94.88	1.50	Not The Property Owner	29/01/2010	2010
EES03a Remove and replace nailed floor board	£118.00	10.00	Not The Property Owner	29/01/2010	2010
EES07 200mm thick loft insulation	£1,113.75	125.00	Not The Property Owner	29/01/2010	2010
EES15 Insulation to 65mm wide cavity wall	£883.20	128.00	Not The Property Owner	29/01/2010	2010
EES22 Mastic pointing	£15.60	4.00	Not The Property Owner	29/01/2010	2010
EES25 Draught stripping to exterior door	£100.10	11.00	Not The Property Owner	29/01/2010	2010
EES26 Draught stripping to windows	£36.40	4.00	Not The Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£21.00	12.00	Not The Property Owner	29/01/2010	2010
EES67 Smoke detector installation	£29.40	3.00	Not The Property Owner	29/01/2010	2010
EES40 Hot water cylinder thermostat	£74.40	1.00	Not The Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£300.42	1.00	Not The Property Owner	29/01/2010	2010
EES06 100mm thick loft insulation	£152.90	27.80	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	29/01/2010	2010
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Not The Property Owner	29/01/2010	2010
EES08 300mm thick loft insulation	£180.00	15.00	Not The Property Owner	29/01/2010	2010
EES10 Cold water tank insulation quilt	£840.00	4.00	Not The Property Owner	29/01/2010	2010
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	29/01/2010	2010
EES26 Draught stripping to windows	£180.00	18.00	Not The Property Owner	29/01/2010	2010
EES38a Thermostatic radiator valve (per valve)	£180.00	3.00	Not The Property Owner	29/01/2010	2010
EES44 Water heating time clock and boost	£95.59	1.00	Not The Property Owner	29/01/2010	2010
EES69 Miscellaneous Charge	£45.00	1.00	Not The Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£300.42	1.00	Not The Property Owner	29/01/2010	2010
EES01a Loft Clearance (hourly rate)	£189.75	3.00	Sole Property Owner	29/01/2010	2010
EES07 200mm thick loft insulation	£846.45	95.00	Sole Property Owner	29/01/2010	2010
EES 11 Cold water tank insulation jacket	£69.24	2.00	Sole Property Owner	29/01/2010	2010
EES25 Draught stripping to exterior door	£167.44	18.40	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£43.75	25.00	Sole Property Owner	29/01/2010	2010
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	29/01/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£128.26	9.60	Sole Property Owner	29/01/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£28.42	2.40	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	29/01/2010	2010
EES38a Thermostatic radiator valve (per valve)	£387.30	10.00	Sole Property Owner	29/01/2010	2010
EES26 Draught stripping to windows	£50.00	5.00	Sole Property Owner	31/01/2012	2012
EES50c Replacement electrical storage heater	£580.26	2.00	Sole Property Owner	31/01/2012	2012
EES34 Replacement hot water cylinder (170)	£1,029.44	1.00	Sole Property Owner	31/01/2012	2012
EES70 Miscellaneous heating review charge	£624.30	62.43	Sole Property Owner	31/01/2012	2012
EES69 Miscellaneous Charge	£30.00	1.00	Sole Property Owner	31/01/2012	2012
EES66 Low energy lamp replacement	£21.00	12.00	Sole Property Owner	31/01/2012	2012
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	31/01/2012	2012
EES00a Full Energy Survey	£309.66	1.00	Not The Property Owner	25/08/2009	2009
EES15 Insulation to 65mm wide cavity wall	£569.24	76.00	Sole Property Owner	30/10/2009	2009
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	30/10/2009	2009
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	30/10/2009	2009
EES66 Low energy lamp replacement	£159.18	14.00	Sole Property Owner	30/10/2009	2009
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	30/10/2009	2009
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	30/10/2009	2009
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	30/10/2009	2009
EES25 Draught stripping to exterior door	£43.76	1.00	Sole Property Owner	30/03/2010	2010
EES44 Water heating time clock and boost	£122.15	1.00	Sole Property Owner	30/03/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£52.00	4.00	Sole Property Owner	30/03/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£11.45	1.00	Sole Property Owner	30/03/2010	2010
EES66 Low energy lamp replacement	£52.80	11.00	Sole Property Owner	30/03/2010	2010
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	30/03/2010	2010
EES07 200mm thick loft insulation	£765.00	85.00	Sole Property Owner	07/11/2012	2012
EES07 200mm thick loft insulation	£150.00	3.00	Sole Property Owner	07/11/2012	2012
EES51a 16-20kW Oil replacement boiler	£2,900.00	1.00	Sole Property Owner	07/11/2012	2012
EES70 Miscellaneous heating review charge	£445.00	1.00	Sole Property Owner	07/11/2012	2012
EES00 Property Assessment	£185.00	1.00	Sole Property Owner	07/11/2012	2012
EES69 Miscellaneous Charge	£1,464.20	1.00	Sole Property Owner	07/11/2012	2012
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	07/11/2012	2012
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	07/11/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	01/01/2010	2010
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	01/01/2010	2010
EES54a 36-45kW Oil replacement boiler	£2,938.00	1.00	Sole Property Owner	08/09/2011	2011
EES40 Hot water cylinder thermostat	£60.19	1.00	Sole Property Owner	08/09/2011	2011
EES42 Two channel programmable heating controller	£139.50	1.00	Sole Property Owner	08/09/2011	2011
EES70 Miscellaneous heating review charge	£175.62	1.00	Sole Property Owner	08/09/2011	2011
EES70 Miscellaneous heating review charge	£630.00	1.00	Sole Property Owner	08/09/2011	2011
EES70 Miscellaneous heating review charge	£42.00	1.00	Sole Property Owner	08/09/2011	2011
EES70 Miscellaneous heating review charge	£355.00	1.00	Sole Property Owner	08/09/2011	2011
EES70 Miscellaneous heating review charge	£723.16	1.00	Sole Property Owner	08/09/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	1.00	Sole Property Owner	08/09/2011	2011
EES07 200mm thick loft insulation	£525.00	75.00	Sole Property Owner	08/09/2011	2011
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Sole Property Owner	08/09/2011	2011
EES15 Insulation to 65mm wide cavity wall	£1,020.00	136.00	Sole Property Owner	08/09/2011	2011
EES66 Low energy lamp replacement	£153.60	32.00	Sole Property Owner	08/09/2011	2011
EES69 Miscellaneous Charge	£64.00	1.00	Sole Property Owner	08/09/2011	2011

EES67 Smoke detector installation	£15.00	2.00	Sole Property Owner	08/09/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	08/09/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	08/09/2011	2011
HES101 Asbestos removal & disposal	£550.00	1.00	Sole Property Owner	08/09/2011	2011
EES55a 46-55kW Oil replacement boiler	£3,162.53	1.00	Sole Property Owner	22/06/2011	2011
EES70 Miscellaneous heating review charge	£1,636.12	1,636.12	Sole Property Owner	22/06/2011	2011
EES07 200mm thick loft insulation	£2,025.00	225.00	Sole Property Owner	22/06/2011	2011
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	22/06/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	22/06/2011	2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	01/04/2010	2010
EES01a Loft Clearance (hourly rate)	£63.25	1.00	Sole Property Owner	20/11/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£638.40	152.00	Sole Property Owner	20/11/2012	2012
EES08 300mm thick loft insulation	£2,331.24	147.64	Sole Property Owner	20/11/2012	2012
EES 11 Cold water tank insulation jacket	£42.62	1.00	Sole Property Owner	20/11/2012	2012
EES25 Draught stripping to exterior door	£72.80	8.00	Sole Property Owner	20/11/2012	2012
EES26 Draught stripping to windows	£72.80	8.00	Sole Property Owner	20/11/2012	2012
EES36 Electrical room thermostat	£103.40	1.00	Sole Property Owner	20/11/2012	2012
EES33 Replacement hot water cylinder (150l)	£605.00	1.00	Sole Property Owner	20/11/2012	2012
EES38a Thermostatic radiator valve (per valve)	£352.00	8.00	Sole Property Owner	20/11/2012	2012
EES42 Two channel programmable heating controller	£111.00	1.00	Sole Property Owner	20/11/2012	2012
EES44 Water heating time clock and boost	£111.00	1.00	Sole Property Owner	20/11/2012	2012
EES49 Pipework lagging 25mm thick to 22mm pipe	£57.55	5.00	Sole Property Owner	20/11/2012	2012
EES49 Pipework lagging 25mm thick to 22mm pipe	£54.25	5.00	Sole Property Owner	20/11/2012	2012
EES66 Low energy lamp replacement	£28.00	16.00	Sole Property Owner	20/11/2012	2012
EES67 Smoke detector installation	£29.40	3.00	Sole Property Owner	20/11/2012	2012
EES69 Miscellaneous Charge	£30.00	1.00	Sole Property Owner	20/11/2012	2012
EES52a 21-25kW Oil replacement boiler	£2,909.50	1.00	Sole Property Owner	20/11/2012	2012
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	20/11/2012	2012
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	20/11/2012	2012
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Not The Property Owner	16/12/2011	2011
EES03a Remove and replace nailed floor board	£25.00	10.00	Not The Property Owner	16/12/2011	2011
EES07 200mm thick loft insulation	£459.00	51.00	Not The Property Owner	16/12/2011	2011
EES69 Miscellaneous Charge	£282.89	1.00	Not The Property Owner	16/12/2011	2011
EES00a Full Energy Survey	£309.66	1.00	Not The Property Owner	16/12/2011	2011
EES12 Cold water tank lid	£0.00	0.00	Not The Property Owner	07/04/2010	2010
EES33 Replacement hot water cylinder (150l)	£0.00	0.00	Not The Property Owner	07/04/2010	2010
EES69 Miscellaneous Charge	£93.85	93.85	Not The Property Owner	07/04/2010	2010
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Not The Property Owner	07/04/2010	2010
EES08 300mm thick loft insulation	£962.48	53.00	Not The Property Owner	07/04/2010	2010
EES15 Insulation to 65mm wide cavity wall	£224.70	30.00	Not The Property Owner	07/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Not The Property Owner	07/04/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£32.36	4.00	Not The Property Owner	07/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£36.88	4.00	Not The Property Owner	07/04/2010	2010
EES66 Low energy lamp replacement	£90.96	8.00	Not The Property Owner	07/04/2010	2010
EES69 Miscellaneous Charge	£112.50	1.00	Not The Property Owner	07/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Not The Property Owner	07/04/2010	2010
EES12 Cold water tank lid	£35.70	1.00	Not The Property Owner	07/04/2010	2010
EES33 Replacement hot water cylinder (150l)	£532.93	1.00	Not The Property Owner	07/04/2010	2010
EES00a Full Energy Survey	£246.55	1.00	Not The Property Owner	07/04/2010	2010
EES06 100mm thick loft insulation	£565.50	87.00	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£48.00	15.00	Sole Property Owner	29/01/2010	2010
EES10 Cold water tank insulation quilt	£64.57	1.00	Sole Property Owner	29/01/2010	2010
EES67 Smoke detector installation	£7.50	1.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	29/01/2010	2010
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Sole Property Owner	23/11/2012	2012
EES08 300mm thick loft insulation	£540.00	45.00	Sole Property Owner	23/11/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	23/11/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	23/11/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	23/11/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	23/11/2012	2012
EES27 Draught stripping to letterbox	£40.00	1.00	Sole Property Owner	23/11/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	23/11/2012	2012
EES38a Thermostatic radiator valve (per valve)	£680.00	8.00	Sole Property Owner	23/11/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	23/11/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£196.00	28.00	Sole Property Owner	23/11/2012	2012
EES66 Low energy lamp replacement	£0.00	12.00	Sole Property Owner	23/11/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	23/11/2012	2012
HES100 Asbestos survey & sample	£20.00	1.00	Sole Property Owner	23/11/2012	2012
HES101 Asbestos removal & disposal	£390.00	1.00	Sole Property Owner	23/11/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	23/11/2012	2012
EES70 Miscellaneous heating review charge	£133.42	1.00	Sole Property Owner	23/11/2012	2012
HES31 16-20kW Oil replacement condensing boiler	£1,278.00	1.00	Sole Property Owner	23/11/2012	2012
HES40 Flue specification and location	£1,113.00	1.00	Sole Property Owner	23/11/2012	2012
HES41 Condensate pipework (and pump if required)	£198.20	1.00	Sole Property Owner	23/11/2012	2012
HES43 Central heating pump	£84.28	1.00	Sole Property Owner	23/11/2012	2012
HES44 Pipework / feed modifications	£210.60	1.00	Sole Property Owner	23/11/2012	2012
HES46 Automatic bypass	£27.50	1.00	Sole Property Owner	23/11/2012	2012
HES48 Power / system flush and treatment	£43.80	1.00	Sole Property Owner	23/11/2012	2012
HES51 Thermostatic radiator valve	£12.90	1.00	Sole Property Owner	23/11/2012	2012
HES52 Hot water cylinder thermostat	£14.80	1.00	Sole Property Owner	23/11/2012	2012
HES55 2 port zone valve	£98.00	2.00	Sole Property Owner	23/11/2012	2012
HES67 22mm thick pipework lagging	£31.68	16.00	Sole Property Owner	23/11/2012	2012
HES95 Senior heating engineer	£1,225.00	35.00	Sole Property Owner	23/11/2012	2012
HES98 Senior electrician	£175.00	5.00	Sole Property Owner	23/11/2012	2012

HES99 Building works	£110.00	5.00	Sole Property Owner	23/11/2012	2012
HES88 Commissioning and issue of CD11 and flue gas analysis	£78.00	1.00	Sole Property Owner	23/11/2012	2012
HES23 Scaffold / cherry picker	£250.00	1.00	Sole Property Owner	23/11/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	23/11/2012	2012
HES49 Carbon Monoxide alarm	£68.40	1.00	Sole Property Owner	23/11/2012	2012
HES95 Senior heating engineer	£70.00	2.00	Sole Property Owner	23/11/2012	2012
HES90 Other miscellaneous oil heating works for EES approval	£39.22	1.00	Sole Property Owner	23/11/2012	2012
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Sole Property Owner	29/02/2012	2012
EES03a Remove and replace nailed floor board	£65.00	26.00	Sole Property Owner	29/02/2012	2012
EES08 300mm thick loft insulation	£727.02	63.00	Sole Property Owner	29/02/2012	2012
EES10 Cold water tank insulation quilt	£560.00	3.50	Sole Property Owner	29/02/2012	2012
EES38a Thermostatic radiator valve (per valve)	£300.00	5.00	Sole Property Owner	29/02/2012	2012
EES51a 16-20kW Oil replacement boiler	£2,900.00	1.00	Sole Property Owner	29/02/2012	2012
EES70 Miscellaneous heating review charge	£450.00	1.00	Sole Property Owner	29/02/2012	2012
EES70 Miscellaneous heating review charge	£105.00	1.00	Sole Property Owner	29/02/2012	2012
EES00 Property Assessment	£185.00	1.00	Sole Property Owner	29/02/2012	2012
EES69 Miscellaneous Charge	£1,292.48	1.00	Sole Property Owner	29/02/2012	2012
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	29/02/2012	2012
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	29/02/2012	2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	31/07/2013	2013
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	31/07/2013	2013
HES72 Storage heater rated 2kW - 3kW	£308.49	1.00	Sole Property Owner	31/07/2013	2013
HES97 Electrician	£160.00	5.00	Sole Property Owner	31/07/2013	2013
HES92 Other miscellaneous electrical heating works for EES approval	£121.63	1.00	Sole Property Owner	31/07/2013	2013
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	04/08/2011	2011
EES08 300mm thick loft insulation	£792.00	66.00	Sole Property Owner	04/08/2011	2011
EES10 Cold water tank insulation quilt	£280.00	3.50	Sole Property Owner	04/08/2011	2011
EES25 Draught stripping to exterior door	£10.00	1.00	Sole Property Owner	04/08/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	04/08/2011	2011
EES31 Hot water cylinder jacket (58x20 inch)	£130.00	1.00	Not The Property Owner	29/01/2010	2010
EES38a Thermostatic radiator valve (per valve)	£390.00	8.00	Not The Property Owner	29/01/2010	2010
EES69 Miscellaneous Charge	£328.78	328.78	Not The Property Owner	29/01/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£110.70	10.00	Not The Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	02/10/2010	2010
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	01/02/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	01/02/2010	2010
EES69 Miscellaneous Charge	£30.00	1.00	Not The Property Owner	15/12/2009	2009
EES15 Insulation to 65mm wide cavity wall	£358.80	52.00	Not The Property Owner	15/12/2009	2009
EES36 Electrical room thermostat	£206.80	2.00	Not The Property Owner	15/12/2009	2009
EES38a Thermostatic radiator valve (per valve)	£132.00	3.00	Not The Property Owner	15/12/2009	2009
EES66 Low energy lamp replacement	£29.75	17.00	Not The Property Owner	15/12/2009	2009
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	15/12/2009	2009
EES15 Insulation to 65mm wide cavity wall	£524.30	70.00	Sole Property Owner	30/10/2009	2009
EES66 Low energy lamp replacement	£136.44	12.00	Sole Property Owner	30/10/2009	2009
EES01a Loft Clearance (hourly rate)	£93.60	4.00	Sole Property Owner	30/10/2009	2009
EES08 300mm thick loft insulation	£359.20	40.00	Sole Property Owner	30/10/2009	2009
EES03a Remove and replace nailed floor board	£104.00	40.00	Sole Property Owner	30/10/2009	2009
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	30/10/2009	2009
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	30/10/2009	2009
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	30/10/2009	2009
EES05 50mm thick loft insulation	£462.00	77.00	Sole Property Owner	30/03/2010	2010
EES01b Loft Clearance (per square metre)	£77.00	77.00	Sole Property Owner	30/03/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£65.00	5.00	Sole Property Owner	30/03/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£11.45	1.00	Sole Property Owner	30/03/2010	2010
EES67 Smoke detector installation	£7.50	1.00	Sole Property Owner	30/03/2010	2010
EES66 Low energy lamp replacement	£96.00	20.00	Sole Property Owner	30/03/2010	2010
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	30/03/2010	2010
EES07 200mm thick loft insulation	£441.00	49.00	Sole Property Owner	05/12/2011	2011
EES52b 21-25kW Gas replacement boiler	£2,274.00	1.00	Sole Property Owner	05/12/2011	2011
EES69 Miscellaneous Charge	£50.00	1.00	Sole Property Owner	05/12/2011	2011
EES12 Cold water tank lid	£0.00	0.00	Sole Property Owner	05/12/2011	2011
EES66 Low energy lamp replacement	£0.00	0.00	Sole Property Owner	05/12/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	05/12/2011	2011
EES69 Miscellaneous Charge	£25.00	1.00	Not The Property Owner	25/01/2010	2010
EES01a Loft Clearance (hourly rate)	£46.80	1.00	Sole Property Owner	01/04/2010	2010
EES07 200mm thick loft insulation	£83.20	8.00	Sole Property Owner	01/04/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£64.72	8.00	Sole Property Owner	01/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£55.32	6.00	Sole Property Owner	01/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	01/04/2010	2010
EES38a Thermostatic radiator valve (per valve)	£132.20	4.00	Sole Property Owner	01/04/2010	2010
EES26 Draught stripping to windows	£28.35	5.00	Sole Property Owner	01/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	01/04/2010	2010
EES69 Miscellaneous Charge	£4.39	1.00	Sole Property Owner	01/04/2010	2010
EES69 Miscellaneous Charge	£2.24	1.00	Sole Property Owner	01/04/2010	2010
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	02/08/2012	2012
EES03a Remove and replace nailed floor board	£37.50	15.00	Sole Property Owner	02/08/2012	2012
EES08 300mm thick loft insulation	£747.00	62.25	Sole Property Owner	02/08/2012	2012
EES25 Draught stripping to exterior door	£60.00	6.00	Sole Property Owner	02/08/2012	2012
EES26 Draught stripping to windows	£180.00	18.00	Sole Property Owner	02/08/2012	2012
EES50b 12-15kW Gas replacement boiler	£1,163.74	1.00	Sole Property Owner	02/08/2012	2012
HES72 Storage heater rated 2kW - 3kW	£308.49	1.00	Sole Property Owner	02/08/2012	2012
HES73 Storage heater rated 3kW - 4kW	£750.68	2.00	Sole Property Owner	02/08/2012	2012
HES97 Electrician	£288.00	9.00	Sole Property Owner	02/08/2012	2012

EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	02/08/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	02/08/2012	2012
EES38a Thermostatic radiator valve (per valve)	£63.69	1.00	Sole Property Owner	02/08/2012	2012
EES40 Hot water cylinder thermostat	£60.19	1.00	Sole Property Owner	02/08/2012	2012
EES42 Two channel programmable heating controller	£139.50	1.00	Sole Property Owner	02/08/2012	2012
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	02/08/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	02/08/2012	2012
EES21 Scaffold	£700.00	7.00	Sole Property Owner	02/08/2012	2012
EES70 Miscellaneous heating review charge	£2,638.18	1.00	Sole Property Owner	02/08/2012	2012
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Sole Property Owner	02/08/2012	2012
EES07 200mm thick loft insulation	£422.50	65.00	Sole Property Owner	02/08/2012	2012
EES15 Insulation to 65mm wide cavity wall	£900.00	120.00	Sole Property Owner	02/08/2012	2012
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	02/08/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	02/08/2012	2012
EES70 Miscellaneous heating review charge	£639.00	1.00	Sole Property Owner	26/01/2012	2012
EES50c Replacement electrical storage heater	£911.00	2.00	Sole Property Owner	26/01/2012	2012
EES01a Loft Clearance (hourly rate)	£94.89	3.00	Sole Property Owner	26/01/2012	2012
EES07 200mm thick loft insulation	£490.05	55.00	Sole Property Owner	26/01/2012	2012
EES15 Insulation to 65mm wide cavity wall	£68.60	7.00	Sole Property Owner	26/01/2012	2012
EES66 Low energy lamp replacement	£28.00	16.00	Sole Property Owner	26/01/2012	2012
EES67 Smoke detector installation	£19.60	2.00	Sole Property Owner	26/01/2012	2012
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	26/01/2012	2012
EES69 Miscellaneous Charge	£147.25	1.00	Sole Property Owner	26/01/2012	2012
EES07 200mm thick loft insulation	£396.00	44.00	Not The Property Owner	16/12/2011	2011
EES31 Hot water cylinder jacket (58x20 inch)	£130.00	1.00	Not The Property Owner	16/12/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	16/12/2011	2011
EES08 300mm thick loft insulation	£1,004.40	60.00	Not The Property Owner	16/12/2011	2011
EES38a Thermostatic radiator valve (per valve)	£396.60	12.00	Not The Property Owner	16/12/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£16.18	2.00	Not The Property Owner	16/12/2011	2011
EES 11 Cold water tank insulation jacket	£64.89	1.00	Not The Property Owner	16/12/2011	2011
EES12 Cold water tank lid	£35.70	1.00	Not The Property Owner	16/12/2011	2011
EES66 Low energy lamp replacement	£409.32	36.00	Not The Property Owner	16/12/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Not The Property Owner	16/12/2011	2011
EES00a Full Energy Survey	£246.55	1.00	Not The Property Owner	16/12/2011	2011
EES50b 12-15kW Gas replacement boiler	£1,178.00	1.00	Sole Property Owner	16/12/2011	2011
EES70 Miscellaneous heating review charge	£620.00	620.00	Sole Property Owner	16/12/2011	2011
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Sole Property Owner	16/12/2011	2011
EES08 300mm thick loft insulation	£540.00	45.00	Sole Property Owner	16/12/2011	2011
EES38a Thermostatic radiator valve (per valve)	£490.00	10.00	Sole Property Owner	16/12/2011	2011
EES13a Cold water tank bye law kit (including associated products)	£560.00	2.00	Sole Property Owner	16/12/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£66.42	6.00	Sole Property Owner	16/12/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£66.42	6.00	Sole Property Owner	16/12/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	16/12/2011	2011
EES01a Loft Clearance (hourly rate)	£189.78	6.00	Sole Property Owner	29/01/2010	2010
EES07 200mm thick loft insulation	£311.85	35.00	Sole Property Owner	29/01/2010	2010
EES12 Cold water tank lid	£69.24	2.00	Sole Property Owner	29/01/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£59.20	5.00	Sole Property Owner	29/01/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£26.72	2.00	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£21.00	12.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	29/01/2010	2010
EES 30 Hot water cylinder jacket (46x18 inch)	£81.62	1.00	Sole Property Owner	29/01/2010	2010
EES44 Water heating time clock and boost	£134.21	1.00	Sole Property Owner	29/01/2010	2010
EES01a Loft Clearance (hourly rate)	£126.50	2.00	Sole Property Owner	29/01/2010	2010
EES03a Remove and replace nailed floor board	£94.40	8.00	Sole Property Owner	29/01/2010	2010
EES02a Remove and dispose existing insulation (per square metre)	£399.00	95.00	Sole Property Owner	29/01/2010	2010
EES08 300mm thick loft insulation	£1,500.05	95.00	Sole Property Owner	29/01/2010	2010
EES16 Insulation to 75mm wide cavity wall	£1,070.47	128.20	Sole Property Owner	29/01/2010	2010
EES25 Draught stripping to exterior door	£54.60	6.00	Sole Property Owner	29/01/2010	2010
EES36 Electrical room thermostat	£103.40	1.00	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£47.25	27.00	Sole Property Owner	29/01/2010	2010
EES67 Smoke detector installation	£19.60	2.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	29/01/2010	2010
EES07 200mm thick loft insulation	£702.00	78.00	Not The Property Owner	16/12/2011	2011
EES25 Draught stripping to exterior door	£20.00	2.00	Not The Property Owner	16/12/2011	2011
EES12 Cold water tank lid	£180.00	1.00	Not The Property Owner	16/12/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	16/12/2011	2011
EES10 Cold water tank insulation quilt	£100.00	1.00	Not The Property Owner	16/12/2011	2011
EES15 Insulation to 65mm wide cavity wall	£123.84	14.40	Sole Property Owner	01/02/2011	2011
EES38a Thermostatic radiator valve (per valve)	£169.32	4.00	Sole Property Owner	01/02/2011	2011
EES66 Low energy lamp replacement	£64.00	1.00	Sole Property Owner	01/02/2011	2011
EES00a Full Energy Survey	£309.66	1.00	Sole Property Owner	01/02/2011	2011
EES66 Low energy lamp replacement	£38.40	8.00	Sole Property Owner	01/02/2011	2011
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	01/03/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	01/03/2010	2010
EES06 100mm thick loft insulation	£693.00	99.00	Not The Property Owner	30/03/2010	2010
EES38a Thermostatic radiator valve (per valve)	£507.96	12.00	Not The Property Owner	30/03/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£65.00	5.00	Not The Property Owner	30/03/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£0.00	3.00	Not The Property Owner	30/03/2010	2010
EES66 Low energy lamp replacement	£54.60	26.00	Not The Property Owner	30/03/2010	2010
EES00a Full Energy Survey	£309.66	1.00	Not The Property Owner	30/03/2010	2010
EES01a Loft Clearance (hourly rate)	£400.00	16.00	Sole Property Owner	01/11/2009	2009
EES03a Remove and replace nailed floor board	£12.50	5.00	Sole Property Owner	01/11/2009	2009
EES08 300mm thick loft insulation	£360.00	30.00	Sole Property Owner	01/11/2009	2009
EES10 Cold water tank insulation quilt	£130.00	1.00	Sole Property Owner	01/11/2009	2009

EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	01/11/2009	2009
EES51a 16-20kW Oil replacement boiler	£2,746.80	1.00	Sole Property Owner	22/06/2011	2011
EES70 Miscellaneous heating review charge	£1,428.20	1,428.20	Sole Property Owner	22/06/2011	2011
EES01a Loft Clearance (hourly rate)	£280.80	12.00	Sole Property Owner	22/06/2011	2011
EES03a Remove and replace nailed floor board	£252.20	97.00	Sole Property Owner	22/06/2011	2011
EES06 100mm thick loft insulation	£752.72	97.00	Sole Property Owner	22/06/2011	2011
EES15 Insulation to 65mm wide cavity wall	£719.04	96.00	Sole Property Owner	22/06/2011	2011
EES66 Low energy lamp replacement	£250.14	22.00	Sole Property Owner	22/06/2011	2011
EES38a Thermostatic radiator valve (per valve)	£231.35	7.00	Sole Property Owner	22/06/2011	2011
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	22/06/2011	2011
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	22/06/2011	2011
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	22/06/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	22/06/2011	2011
EES69 Miscellaneous Charge	£138.64	1.00	Sole Property Owner	22/06/2011	2011
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	22/06/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	22/06/2011	2011
EES06 100mm thick loft insulation	£620.55	98.50	Not The Property Owner	30/03/2010	2010
EES66 Low energy lamp replacement	£62.40	13.00	Not The Property Owner	30/03/2010	2010
EES69 Miscellaneous Charge	£50.00	1.00	Not The Property Owner	30/03/2010	2010
EES00a Full Energy Survey	£315.00	1.00	Not The Property Owner	30/03/2010	2010
EES68 Minimum charge for lamps and detectors	£64.00	1.00	Sole Property Owner	30/03/2010	2010
EES67 Smoke detector installation	£7.50	1.00	Sole Property Owner	30/03/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	30/03/2010	2010
EES01a Loft Clearance (hourly rate)	£46.80	2.00	Sole Property Owner	13/01/2011	2011
EES03a Remove and replace nailed floor board	£7.80	3.00	Sole Property Owner	13/01/2011	2011
EES06 100mm thick loft insulation	£325.92	42.00	Sole Property Owner	13/01/2011	2011
EES13a Cold water tank bye law kit (including associated product	£0.00	0.00	Sole Property Owner	13/01/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£40.45	5.00	Sole Property Owner	13/01/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£55.32	6.00	Sole Property Owner	13/01/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	13/01/2011	2011
EES67 Smoke detector installation	£0.00	0.00	Sole Property Owner	13/01/2011	2011
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	01/04/2010	2010
HES15 Draught stripping to exterior door	£18.00	6.00	Sole Property Owner	01/04/2010	2010
HES19 Draught proofing labour	£50.00	2.00	Sole Property Owner	01/04/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	01/04/2010	2010
HES111 HER Survey for Flat	£136.00	1.00	Sole Property Owner	01/04/2010	2010
HES20 Low energy lamp installation	£0.00	13.00	Sole Property Owner	01/04/2010	2010
HES21 Smoke detector installation	£0.00	1.00	Sole Property Owner	01/04/2010	2010
EES07 200mm thick loft insulation	£147.94	22.76	Sole Property Owner	29/01/2010	2010
EES69 Miscellaneous Charge	£50.20	50.20	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£315.00	1.00	Sole Property Owner	29/01/2010	2010
EES38a Thermostatic radiator valve (per valve)	£765.00	9.00	Sole Property Owner	16/12/2011	2011
EES54a 36-45kW Oil replacement boiler	£5,116.80	1.00	Sole Property Owner	16/12/2011	2011
EES35 Replacement hot water cylinder (210l)	£1,450.00	1.00	Sole Property Owner	16/12/2011	2011
EES70 Miscellaneous heating review charge	£1,370.00	1.00	Sole Property Owner	16/12/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£92.20	10.00	Sole Property Owner	16/12/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	16/12/2011	2011
EES26 Draught stripping to windows	£28.35	5.00	Sole Property Owner	16/12/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	16/12/2011	2011
EES07 200mm thick loft insulation	£936.00	90.00	Sole Property Owner	16/12/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	16/12/2011	2011
EES66 Low energy lamp replacement	£90.96	8.00	Sole Property Owner	15/12/2009	2009
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	15/12/2009	2009
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	01/05/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	01/05/2010	2010
EES01a Loft Clearance (hourly rate)	£158.13	2.50	Sole Property Owner	01/08/2011	2011
EES03a Remove and replace nailed floor board	£590.00	50.00	Sole Property Owner	01/08/2011	2011
EES06 100mm thick loft insulation	£1,224.64	178.00	Sole Property Owner	01/08/2011	2011
EES16 Insulation to 75mm wide cavity wall	£384.94	46.10	Sole Property Owner	01/08/2011	2011
EES25 Draught stripping to exterior door	£145.60	16.00	Sole Property Owner	01/08/2011	2011
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	01/08/2011	2011
EES66 Low energy lamp replacement	£35.00	20.00	Sole Property Owner	01/08/2011	2011
EES67 Smoke detector installation	£39.20	4.00	Sole Property Owner	01/08/2011	2011
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	01/08/2011	2011
EES70 Miscellaneous heating review charge	£911.12	1.00	Sole Property Owner	01/08/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	1.00	Sole Property Owner	01/08/2011	2011
EES70 Miscellaneous heating review charge	£92.46	1.00	Sole Property Owner	01/08/2011	2011
EES42 Two channel programmable heating controller	£100.00	1.00	Sole Property Owner	01/08/2011	2011
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	01/08/2011	2011
HES85 Building Control Officer inspection undertaken	£103.85	1.00	Sole Property Owner	01/08/2011	2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	28/01/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£3.27	3.00	Not The Property Owner	28/01/2010	2010
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Not The Property Owner	26/01/2011	2011
EES02a Remove and dispose existing insulation (per square metre	£210.00	70.00	Not The Property Owner	26/01/2011	2011
EES06 100mm thick loft insulation	£0.00	0.00	Not The Property Owner	26/01/2011	2011
EES 11 Cold water tank insulation jacket	£90.00	1.00	Not The Property Owner	26/01/2011	2011
EES69 Miscellaneous Charge	£0.00	0.00	Not The Property Owner	26/01/2011	2011
EES38a Thermostatic radiator valve (per valve)	£510.00	6.00	Not The Property Owner	26/01/2011	2011
EES69 Miscellaneous Charge	£0.00	0.00	Not The Property Owner	26/01/2011	2011
EES15 Insulation to 65mm wide cavity wall	£744.30	90.00	Not The Property Owner	26/01/2011	2011
EES69 Miscellaneous Charge	£45.80	1.00	Not The Property Owner	26/01/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£172.65	15.00	Not The Property Owner	26/01/2011	2011
EES66 Low energy lamp replacement	£26.25	1.00	Not The Property Owner	26/01/2011	2011

EES67 Smoke detector installation	£19.60	2.00	Not The Property Owner	26/01/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£162.75	15.00	Not The Property Owner	26/01/2011	2011
EES03a Remove and replace nailed floor board	£54.00	18.00	Not The Property Owner	26/01/2011	2011
EES07 200mm thick loft insulation	£162.00	18.00	Not The Property Owner	26/01/2011	2011
EES08 300mm thick loft insulation	£600.00	50.00	Not The Property Owner	26/01/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	26/01/2011	2011
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Sole Property Owner	15/04/2010	2010
EES03a Remove and replace nailed floor board	£50.00	20.00	Sole Property Owner	15/04/2010	2010
EES02a Remove and dispose existing insulation (per squire metre)	£135.00	45.00	Sole Property Owner	15/04/2010	2010
EES08 300mm thick loft insulation	£540.00	45.00	Sole Property Owner	15/04/2010	2010
EES12 Cold water tank lid	£560.00	2.00	Sole Property Owner	15/04/2010	2010
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Sole Property Owner	15/04/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	21/10/2009	2009
EES50c Replacement electrical storage heater	£788.37	3.00	Sole Property Owner	03/02/2012	2012
EES50c Replacement electrical storage heater	£475.00	1.00	Sole Property Owner	03/02/2012	2012
EES44 Water heating time clock and boost	£108.48	1.00	Sole Property Owner	03/02/2012	2012
EES34 Replacement hot water cylinder (170l)	£880.00	1.00	Sole Property Owner	03/02/2012	2012
EES01a Loft Clearance (hourly rate)	£94.89	3.00	Sole Property Owner	03/02/2012	2012
EES07 200mm thick loft insulation	£490.05	55.00	Sole Property Owner	03/02/2012	2012
EES69 Miscellaneous Charge	£30.00	1.00	Sole Property Owner	03/02/2012	2012
EES25 Draught stripping to exterior door	£91.00	10.00	Sole Property Owner	03/02/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£49.08	6.00	Sole Property Owner	03/02/2012	2012
EES66 Low energy lamp replacement	£10.50	6.00	Sole Property Owner	03/02/2012	2012
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	03/02/2012	2012
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	01/06/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	01/06/2010	2010
EES01a Loft Clearance (hourly rate)	£253.00	4.00	Sole Property Owner	18/10/2011	2011
EES03a Remove and replace nailed floor board	£1,121.00	95.00	Sole Property Owner	18/10/2011	2011
EES08 300mm thick loft insulation	£1,657.95	105.00	Sole Property Owner	18/10/2011	2011
EES10 Cold water tank insulation quilt	£37.42	1.00	Sole Property Owner	18/10/2011	2011
EES69 Miscellaneous Charge	£30.00	1.00	Sole Property Owner	18/10/2011	2011
EES38a Thermostatic radiator valve (per valve)	£308.00	7.00	Sole Property Owner	18/10/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£43.40	4.00	Sole Property Owner	18/10/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£46.04	4.00	Sole Property Owner	18/10/2011	2011
EES66 Low energy lamp replacement	£21.00	12.00	Sole Property Owner	18/10/2011	2011
EES70 Miscellaneous heating review charge	£86.56	1.00	Sole Property Owner	18/10/2011	2011
EES40 Hot water cylinder thermostat	£60.19	1.00	Sole Property Owner	18/10/2011	2011
EES42 Two channel programmable heating controller	£139.50	1.00	Sole Property Owner	18/10/2011	2011
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	18/10/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£10.00	1.00	Sole Property Owner	18/10/2011	2011
EES70 Miscellaneous heating review charge	£2,495.36	1.00	Sole Property Owner	18/10/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	18/10/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	18/10/2011	2011
EES66 Low energy lamp replacement	£45.48	4.00	Not The Property Owner	15/12/2009	2009
EES00a Full Energy Survey	£246.55	1.00	Not The Property Owner	15/12/2009	2009
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	01/07/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	01/07/2010	2010
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Not The Property Owner	07/03/2010	2010
EES03a Remove and replace nailed floor board	£120.00	48.00	Not The Property Owner	07/03/2010	2010
EES08 300mm thick loft insulation	£576.00	48.00	Not The Property Owner	07/03/2010	2010
EES10 Cold water tank insulation quilt	£100.00	2.00	Not The Property Owner	07/03/2010	2010
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	07/03/2010	2010
EES01a Loft Clearance (hourly rate)	£31.63	1.00	Sole Property Owner	29/11/2011	2011
EES08 300mm thick loft insulation	£773.71	49.00	Sole Property Owner	29/11/2011	2011
EES10 Cold water tank insulation quilt	£37.42	1.00	Sole Property Owner	29/11/2011	2011
EES12 Cold water tank lid	£32.03	1.00	Sole Property Owner	29/11/2011	2011
EES15 Insulation to 65mm wide cavity wall	£966.00	140.00	Sole Property Owner	29/11/2011	2011
EES21 Scaffold	£400.00	1.00	Sole Property Owner	29/11/2011	2011
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	29/11/2011	2011
EES38a Thermostatic radiator valve (per valve)	£396.00	9.00	Sole Property Owner	29/11/2011	2011
EES66 Low energy lamp replacement	£19.25	11.00	Sole Property Owner	29/11/2011	2011
EES34 Replacement hot water cylinder (170l)	£953.16	1.00	Sole Property Owner	29/11/2011	2011
EES53a 26-35kW Oil replacement boiler	£2,684.52	1.00	Sole Property Owner	29/11/2011	2011
EES70 Miscellaneous heating review charge	£1,666.71	1,666.71	Sole Property Owner	29/11/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	29/11/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Sole Property Owner	29/11/2011	2011
HES85 Building Control Officer inspection undertaken	£103.85	1.00	Sole Property Owner	29/11/2011	2011
EES01a Loft Clearance (hourly rate)	£63.25	1.00	Sole Property Owner	29/01/2010	2010
EES03a Remove and replace nailed floor board	£472.00	40.00	Sole Property Owner	29/01/2010	2010
EES07 200mm thick loft insulation	£463.32	52.00	Sole Property Owner	29/01/2010	2010
EES69 Miscellaneous Charge	£30.00	1.00	Sole Property Owner	29/01/2010	2010
EES36 Electrical room thermostat	£103.40	1.00	Sole Property Owner	29/01/2010	2010
EES38a Thermostatic radiator valve (per valve)	£220.00	5.00	Sole Property Owner	29/01/2010	2010
EES42 Two channel programmable heating controller	£111.00	1.00	Sole Property Owner	29/01/2010	2010
EES44 Water heating time clock and boost	£111.00	1.00	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£29.75	17.00	Sole Property Owner	29/01/2010	2010
EES67 Smoke detector installation	£19.60	2.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	29/01/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	28/01/2010	2010
EES01a Loft Clearance (hourly rate)	£316.25	5.00	Sole Property Owner	29/01/2010	2010
EES02a Remove and dispose existing insulation (per squire metre)	£260.40	62.00	Sole Property Owner	29/01/2010	2010
EES03a Remove and replace nailed floor board	£59.00	5.00	Sole Property Owner	29/01/2010	2010
EES08 300mm thick loft insulation	£978.98	62.00	Sole Property Owner	29/01/2010	2010
EES10 Cold water tank insulation quilt	£85.24	2.00	Sole Property Owner	29/01/2010	2010

EES15 Insulation to 65mm wide cavity wall	£1,445.22	186.00	Sole Property Owner	29/01/2010	2010
EES25 Draught stripping to exterior door	£91.00	10.00	Sole Property Owner	29/01/2010	2010
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£33.25	19.00	Sole Property Owner	29/01/2010	2010
EES67 Smoke detector installation	£29.40	3.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	29/01/2010	2010
EES51a 16-20kW Oil replacement boiler	£3,498.43	1.00	Sole Property Owner	22/06/2011	2011
EES69 Miscellaneous Charge	£78.16	1.00	Sole Property Owner	22/06/2011	2011
EES01a Loft Clearance (hourly rate)	£94.89	3.00	Sole Property Owner	22/06/2011	2011
EES02a Remove and dispose existing insulation (per squire metre)	£141.60	12.00	Sole Property Owner	22/06/2011	2011
EES07 200mm thick loft insulation	£579.15	65.00	Sole Property Owner	22/06/2011	2011
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	22/06/2011	2011
EES27 Draught stripping to letterbox	£9.10	1.00	Sole Property Owner	22/06/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£230.20	20.00	Sole Property Owner	22/06/2011	2011
EES66 Low energy lamp replacement	£45.50	26.00	Sole Property Owner	22/06/2011	2011
EES00a Full Energy Survey	£300.42	1.00	Sole Property Owner	22/06/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	22/06/2011	2011
EES00a Full Energy Survey	£290.32	1.00	Not The Property Owner	01/08/2009	2009
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	30/03/2010	2010
EES66 Low energy lamp replacement	£36.80	1.00	Sole Property Owner	30/03/2010	2010
EES25 Draught stripping to exterior door	£43.76	1.00	Sole Property Owner	30/03/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£10.00	1.00	Sole Property Owner	30/03/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£11.63	1.00	Sole Property Owner	30/03/2010	2010
EES66 Low energy lamp replacement	£22.74	2.00	Sole Property Owner	15/12/2009	2009
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	15/12/2009	2009
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	29/01/2010	2010
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	29/01/2010	2010
EES15 Insulation to 65mm wide cavity wall	£352.50	47.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£48.00	10.00	Not The Property Owner	01/11/2009	2009
EES49 Pipework lagging 25mm thick to 22mm pipe	£39.00	1.00	Not The Property Owner	01/11/2009	2009
EES66 Low energy lamp replacement	£36.40	1.00	Not The Property Owner	09/01/2010	2010
EES67 Smoke detector installation	£7.50	1.00	Not The Property Owner	09/01/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£26.00	1.00	Not The Property Owner	09/01/2010	2010
EES01a Loft Clearance (hourly rate)	£63.26	2.00	Not The Property Owner	06/06/2010	2010
EES02a Remove and dispose existing insulation (per squire metre)	£176.40	42.00	Not The Property Owner	06/06/2010	2010
EES07 200mm thick loft insulation	£374.22	42.00	Not The Property Owner	06/06/2010	2010
EES06 100mm thick loft insulation	£288.96	42.00	Not The Property Owner	06/06/2010	2010
EES66 Low energy lamp replacement	£14.00	8.00	Not The Property Owner	06/06/2010	2010
EES67 Smoke detector installation	£9.80	1.00	Not The Property Owner	06/06/2010	2010
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	01/04/2010	2010
EES07 200mm thick loft insulation	£447.60	60.00	Sole Property Owner	01/04/2010	2010
EES03a Remove and replace nailed floor board	£46.80	18.00	Sole Property Owner	01/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	01/04/2010	2010
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	01/04/2010	2010
EES66 Low energy lamp replacement	£58.50	1.00	Sole Property Owner	01/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	01/04/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	01/05/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	28/01/2010	2010
EES67 Smoke detector installation	£50.00	1.00	Not The Property Owner	04/04/2011	2011
EES81 Insulation to 50mm cavity	£198.75	26.50	Not The Property Owner	04/04/2011	2011
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Not The Property Owner	04/04/2011	2011
EES02a Remove and dispose existing insulation (per squire metre)	£0.00	0.00	Not The Property Owner	04/04/2011	2011
EES08 300mm thick loft insulation	£252.00	21.00	Not The Property Owner	04/04/2011	2011
EES10 Cold water tank insulation quilt	£100.00	1.00	Not The Property Owner	04/04/2011	2011
EES13a Cold water tank bye law kit (including associated product)	£280.00	1.00	Not The Property Owner	04/04/2011	2011
EES38a Thermostatic radiator valve (per valve)	£341.25	7.00	Not The Property Owner	04/04/2011	2011
EES36 Electrical room thermostat	£50.00	1.00	Not The Property Owner	04/04/2011	2011
EES42 Two channel programmable heating controller	£95.59	1.00	Not The Property Owner	04/04/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£54.00	6.00	Not The Property Owner	04/04/2011	2011
EES69 Miscellaneous Charge	£204.27	204.27	Not The Property Owner	04/04/2011	2011
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Sole Property Owner	29/01/2010	2010
EES07 200mm thick loft insulation	£721.50	111.00	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£0.00	17.00	Sole Property Owner	29/01/2010	2010
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£57.60	1.00	Not The Property Owner	28/01/2010	2010
EES01a Loft Clearance (hourly rate)	£140.40	3.00	Sole Property Owner	09/04/2010	2010
EES06 100mm thick loft insulation	£723.62	97.00	Sole Property Owner	09/04/2010	2010
EES07 200mm thick loft insulation	£1,008.80	97.00	Sole Property Owner	09/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	09/04/2010	2010
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	09/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£36.88	4.00	Sole Property Owner	09/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	09/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	09/04/2010	2010
EES25 Draught stripping to exterior door	£0.00	0.00	Not The Property Owner	15/04/2010	2010
EES42 Two channel programmable heating controller	£0.00	0.00	Not The Property Owner	15/04/2010	2010
EES07 200mm thick loft insulation	£570.24	64.00	Not The Property Owner	15/04/2010	2010
EES 11 Cold water tank insulation jacket	£74.84	2.00	Not The Property Owner	15/04/2010	2010
EES16 Insulation to 75mm wide cavity wall	£676.35	81.00	Not The Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£30.00	1.00	Not The Property Owner	15/04/2010	2010
EES66 Low energy lamp replacement	£61.25	35.00	Not The Property Owner	15/04/2010	2010
EES50c Replacement electrical storage heater	£207.00	1.00	Sole Property Owner	27/01/2012	2012
EES50c Replacement electrical storage heater	£950.00	2.00	Sole Property Owner	27/01/2012	2012

EES01a Loft Clearance (hourly rate)	£46.80	1.00	Sole Property Owner	27/01/2012	2012
EES07 200mm thick loft insulation	£156.00	15.00	Sole Property Owner	27/01/2012	2012
EES15 Insulation to 65mm wide cavity wall	£539.28	72.00	Sole Property Owner	27/01/2012	2012
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	27/01/2012	2012
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	27/01/2012	2012
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	27/01/2012	2012
EES49 Pipework lagging 25mm thick to 22mm pipe	£92.20	10.00	Sole Property Owner	27/01/2012	2012
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	27/01/2012	2012
EES33 Replacement hot water cylinder (150l)	£532.93	1.00	Sole Property Owner	27/01/2012	2012
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	27/01/2012	2012
EES66 Low energy lamp replacement	£32.00	5.00	Not The Property Owner	01/11/2009	2009
EES67 Smoke detector installation	£7.50	1.00	Not The Property Owner	01/11/2009	2009
EES22 Mastic pointing	£89.70	23.00	Not The Property Owner	03/08/2010	2010
EES26 Draught stripping to windows	£72.80	8.00	Not The Property Owner	03/08/2010	2010
EES38a Thermostatic radiator valve (per valve)	£352.00	8.00	Not The Property Owner	03/08/2010	2010
EES36 Electrical room thermostat	£103.40	1.00	Not The Property Owner	03/08/2010	2010
EES44 Water heating time clock and boost	£111.00	1.00	Not The Property Owner	03/08/2010	2010
EES66 Low energy lamp replacement	£21.00	12.00	Not The Property Owner	03/08/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£129.08	14.00	Sole Property Owner	27/01/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	27/01/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	27/01/2010	2010
EES53a 26-35kW Oil replacement boiler	£2,684.52	1.00	Sole Property Owner	04/04/2012	2012
EES49 Pipework lagging 25mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	04/04/2012	2012
EES82 Boiler replacement miscellaneous works	£1,426.22	1.00	Sole Property Owner	04/04/2012	2012
EES40 Hot water cylinder thermostat	£0.00	1.00	Sole Property Owner	04/04/2012	2012
EES38a Thermostatic radiator valve (per valve)	£509.52	8.00	Sole Property Owner	04/04/2012	2012
EES77 HEC to House	£150.00	1.00	Sole Property Owner	04/04/2012	2012
EES01a Loft Clearance (hourly rate)	£63.26	2.00	Sole Property Owner	04/04/2012	2012
EES07 200mm thick loft insulation	£215.62	24.20	Sole Property Owner	04/04/2012	2012
EES 11 Cold water tank insulation jacket	£37.42	1.00	Sole Property Owner	04/04/2012	2012
EES10 Cold water tank insulation quilt	£32.03	1.00	Sole Property Owner	04/04/2012	2012
EES21 Scaffold	£805.00	100.00	Sole Property Owner	04/04/2012	2012
EES15 Insulation to 65mm wide cavity wall	£425.22	57.00	Sole Property Owner	04/04/2012	2012
EES36 Electrical room thermostat	£103.40	1.00	Sole Property Owner	04/04/2012	2012
EES38a Thermostatic radiator valve (per valve)	£352.00	8.00	Sole Property Owner	04/04/2012	2012
EES67 Smoke detector installation	£9.80	1.00	Sole Property Owner	04/04/2012	2012
HES100 Asbestos survey & sample	£65.00	1.00	Sole Property Owner	04/04/2012	2012
HES100 Asbestos survey & sample	£65.00	1.00	Sole Property Owner	04/04/2012	2012
HES101 Asbestos removal & disposal	£762.00	1.00	Sole Property Owner	04/04/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	04/04/2012	2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£73.76	8.00	Sole Property Owner	01/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	01/04/2010	2010
EES33 Replacement hot water cylinder (150l)	£532.93	1.00	Sole Property Owner	01/04/2010	2010
EES26 Draught stripping to windows	£56.70	10.00	Sole Property Owner	01/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	01/04/2010	2010
EES 83 Powerflush central heating system	£0.00	1.00	Sole Property Owner	16/03/2012	2012
EES51a 16-20kW Oil replacement boiler	£3,450.00	1.00	Sole Property Owner	16/03/2012	2012
EES 84 Magnetic filtration unit	£0.00	1.00	Sole Property Owner	16/03/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	16/03/2012	2012
EES38a Thermostatic radiator valve (per valve)	£510.00	6.00	Sole Property Owner	16/03/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	16/03/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	16/03/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	16/03/2012	2012
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Sole Property Owner	16/03/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	16/03/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	16/03/2012	2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£180.00	20.00	Sole Property Owner	16/03/2012	2012
EES82 Boiler replacement miscellaneous works	£1,411.56	1.00	Sole Property Owner	16/03/2012	2012
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Sole Property Owner	16/03/2012	2012
EES07 200mm thick loft insulation	£0.00	0.00	Sole Property Owner	16/03/2012	2012
EES10 Cold water tank insulation quilt	£0.00	0.00	Sole Property Owner	16/03/2012	2012
EES 11 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	16/03/2012	2012
EES12 Cold water tank lid	£0.00	0.00	Sole Property Owner	16/03/2012	2012
EES13a Cold water tank bye law kit (including associated product)	£0.00	0.00	Sole Property Owner	16/03/2012	2012
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Sole Property Owner	16/03/2012	2012
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	16/03/2012	2012
EES08 300mm thick loft insulation	£1,020.00	85.00	Sole Property Owner	16/03/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	16/03/2012	2012
EES07 200mm thick loft insulation	£280.80	27.00	Sole Property Owner	27/01/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	27/01/2010	2010
EES33 Replacement hot water cylinder (150l)	£532.93	1.00	Sole Property Owner	27/01/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	27/01/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	05/08/2010	2010
EES01a Loft Clearance (hourly rate)	£126.50	2.00	Not The Property Owner	15/04/2010	2010
EES03a Remove and replace nailed floor board	£424.80	36.00	Not The Property Owner	15/04/2010	2010
EES07 200mm thick loft insulation	£347.49	39.00	Not The Property Owner	15/04/2010	2010
EES06 100mm thick loft insulation	£268.32	39.00	Not The Property Owner	15/04/2010	2010
EES10 Cold water tank insulation quilt	£69.24	2.00	Not The Property Owner	15/04/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£13.10	2.00	Not The Property Owner	15/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£17.07	2.30	Not The Property Owner	15/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£18.81	2.30	Not The Property Owner	15/04/2010	2010
EES66 Low energy lamp replacement	£29.75	17.00	Not The Property Owner	15/04/2010	2010
EES67 Smoke detector installation	£1.75	1.00	Not The Property Owner	15/04/2010	2010
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00		Not The Property Owner	15/04/2010	2010

HES20 Low energy lamp installation	£0.00		Not The Property Owner	15/04/2010	2010
HES51 Thermostatic radiator valve	£0.00		Not The Property Owner	15/04/2010	2010
HES52 Hot water cylinder thermostat	£0.00		Not The Property Owner	15/04/2010	2010
HES66 15mm thick pipework lagging	£0.00		Not The Property Owner	15/04/2010	2010
HES67 22mm thick pipework lagging	£0.00		Not The Property Owner	15/04/2010	2010
HES94 Heating engineer	£0.00		Not The Property Owner	15/04/2010	2010
HES97 Electrician	£0.00		Not The Property Owner	15/04/2010	2010
HES103 Copper replacement hot water cylinder (150L)	£0.00		Not The Property Owner	15/04/2010	2010
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	26/01/2011	2011
EES07 200mm thick loft insulation	£268.56	36.00	Sole Property Owner	26/01/2011	2011
EES03a Remove and replace nailed floor board	£62.40	24.00	Sole Property Owner	26/01/2011	2011
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	26/01/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£32.36	4.00	Sole Property Owner	26/01/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£92.20	10.00	Sole Property Owner	26/01/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	26/01/2011	2011
EES33 Replacement hot water cylinder (150l)	£532.93	1.00	Sole Property Owner	26/01/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	26/01/2011	2011
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	26/01/2011	2011
HES120 Standard QA check	£100.00	1.00	Sole Property Owner	26/01/2011	2011
EES15 Insulation to 65mm wide cavity wall	£526.88	70.25	Sole Property Owner	15/04/2010	2010
EES50a 12-15kW Oil replacement boiler	£2,620.80	1.00	Sole Property Owner	15/04/2010	2010
EES70 Miscellaneous heating review charge	£1,004.20	1,004.20	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£60.00	1.00	Sole Property Owner	15/04/2010	2010
EES51a 16-20kW Oil replacement boiler	£3,417.60	1.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£1,164.88	1.00	Sole Property Owner	15/04/2010	2010
EES06 100mm thick loft insulation	£619.18	83.00	Sole Property Owner	15/04/2010	2010
EES07 200mm thick loft insulation	£863.20	83.00	Sole Property Owner	15/04/2010	2010
EES03a Remove and replace nailed floor board	£104.00	40.00	Sole Property Owner	15/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	15/04/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£92.20	10.00	Sole Property Owner	15/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	15/04/2010	2010
EES38a Thermostatic radiator valve (per valve)	£264.40	8.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£393.49	1.00	Sole Property Owner	15/04/2010	2010
EES70 Miscellaneous heating review charge	£3,630.60	1.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£551.00	551.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£460.00	1.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£55.00	1.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£356.35	1.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£311.00	1.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£128.75	1.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£611.24	1.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£99.41	1.00	Sole Property Owner	15/04/2010	2010
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	15/04/2010	2010
EES07 200mm thick loft insulation	£185.22	17.81	Sole Property Owner	19/05/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	19/05/2010	2010
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	19/05/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£24.27	3.00	Sole Property Owner	19/05/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£119.86	13.00	Sole Property Owner	19/05/2010	2010
EES26 Draught stripping to windows	£45.36	8.00	Sole Property Owner	19/05/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	19/05/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	19/05/2010	2010
EES07 200mm thick loft insulation	£282.78	27.19	Sole Property Owner	19/05/2010	2010
EES69 Miscellaneous Charge	£30.00	1.00	Sole Property Owner	15/04/2010	2010
EES15 Insulation to 65mm wide cavity wall	£1,186.75	143.50	Sole Property Owner	15/04/2010	2010
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	15/04/2010	2010
EES07 200mm thick loft insulation	£634.40	61.00	Sole Property Owner	15/04/2010	2010
EES03a Remove and replace nailed floor board	£78.00	30.00	Sole Property Owner	15/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	15/04/2010	2010
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	15/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£239.72	26.00	Sole Property Owner	15/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£437.50	14.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£50.00	1.00	Sole Property Owner	15/04/2010	2010
EES15 Insulation to 65mm wide cavity wall	£455.63	60.75	Sole Property Owner	29/01/2010	2010
EES33 Replacement hot water cylinder (150l)	£980.00	1.00	Sole Property Owner	29/01/2010	2010
EES51a 16-20kW Oil replacement boiler	£2,900.00	1.00	Sole Property Owner	29/01/2010	2010
EES70 Miscellaneous heating review charge	£710.00	710.00	Sole Property Owner	29/01/2010	2010
EES69 Miscellaneous Charge	£270.00	1.00	Sole Property Owner	29/01/2010	2010
EES69 Miscellaneous Charge	£1,909.94	1.00	Sole Property Owner	29/01/2010	2010
EES00 Property Assessment	£185.00	1.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	29/01/2010	2010
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	29/01/2010	2010
EES15 Insulation to 65mm wide cavity wall	£522.90	69.72	Sole Property Owner	08/02/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£42.00	6.00	Sole Property Owner	08/02/2012	2012
EES52a 21-25kW Oil replacement boiler	£3,633.00	1.00	Sole Property Owner	08/02/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	08/02/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	08/02/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	08/02/2012	2012
EES70 Miscellaneous heating review charge	£2,304.00	2,304.00	Sole Property Owner	08/02/2012	2012
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	08/02/2012	2012
EES07 200mm thick loft insulation	£509.60	49.00	Sole Property Owner	08/02/2012	2012
EES03a Remove and replace nailed floor board	£39.00	15.00	Sole Property Owner	08/02/2012	2012
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	08/02/2012	2012

EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	08/02/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£64.72	8.00	Sole Property Owner	08/02/2012	2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£73.76	8.00	Sole Property Owner	08/02/2012	2012
EES66 Low energy lamp replacement	£125.07	11.00	Sole Property Owner	08/02/2012	2012
EES38a Thermostatic radiator valve (per valve)	£198.30	6.00	Sole Property Owner	08/02/2012	2012
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	08/02/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	08/02/2012	2012
EES06 100mm thick loft insulation	£149.20	20.00	Sole Property Owner	01/04/2010	2010
EES07 200mm thick loft insulation	£208.00	20.00	Sole Property Owner	01/04/2010	2010
EES03a Remove and replace nailed floor board	£52.00	20.00	Sole Property Owner	01/04/2010	2010
EES 11 Cold water tank insulation jacket	£129.78	2.00	Sole Property Owner	01/04/2010	2010
EES12 Cold water tank lid	£71.40	2.00	Sole Property Owner	01/04/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£276.60	30.00	Sole Property Owner	01/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	01/04/2010	2010
EES38a Thermostatic radiator valve (per valve)	£165.25	5.00	Sole Property Owner	01/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	01/04/2010	2010
EES06 100mm thick loft insulation	£268.32	39.00	Not The Property Owner	15/04/2010	2010
EES07 200mm thick loft insulation	£347.49	39.00	Not The Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£36.40	4.00	Not The Property Owner	15/04/2010	2010
EES34 Replacement hot water cylinder (170L)	£605.00	1.00	Not The Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£70.00	1.00	Not The Property Owner	15/04/2010	2010
EES66 Low energy lamp replacement	£21.00	12.00	Not The Property Owner	15/04/2010	2010
EES67 Smoke detector installation	£1.75	1.00	Not The Property Owner	15/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£22.26	3.00	Not The Property Owner	15/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£73.62	9.00	Not The Property Owner	15/04/2010	2010
EES10 Cold water tank insulation quilt	£37.42	1.00	Not The Property Owner	15/04/2010	2010
EES66 Low energy lamp replacement	£64.00	16.00	Not The Property Owner	09/01/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£13.00	1.00	Not The Property Owner	09/01/2010	2010
EES25 Draught stripping to exterior door	£43.76	1.00	Not The Property Owner	01/11/2009	2009
EES66 Low energy lamp replacement	£86.36	17.00	Not The Property Owner	01/11/2009	2009
EES67 Smoke detector installation	£7.50	1.00	Not The Property Owner	01/11/2009	2009
EES49 Pipework lagging 25mm thick to 22mm pipe	£26.00	2.00	Not The Property Owner	01/11/2009	2009
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/03/2010	2010
EES33 Replacement hot water cylinder (150L)	£1,273.55	1.00	Sole Property Owner	04/08/2011	2011
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	04/08/2011	2011
EES03a Remove and replace nailed floor board	£10.00	4.00	Sole Property Owner	04/08/2011	2011
EES08 300mm thick loft insulation	£600.00	50.00	Sole Property Owner	04/08/2011	2011
EES12 Cold water tank lid	£280.00	1.00	Sole Property Owner	04/08/2011	2011
EES15 Insulation to 65mm wide cavity wall	£367.01	49.00	Not The Property Owner	14/01/2011	2011
EES69 Miscellaneous Charge	£112.50	1.00	Not The Property Owner	14/01/2011	2011
EES66 Low energy lamp replacement	£159.18	14.00	Not The Property Owner	14/01/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Not The Property Owner	14/01/2011	2011
EES00a Full Energy Survey	£246.55	1.00	Not The Property Owner	14/01/2011	2011
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Sole Property Owner	03/04/2012	2012
EES08 300mm thick loft insulation	£0.00	0.00	Sole Property Owner	03/04/2012	2012
EES10 Cold water tank insulation quilt	£0.00	0.00	Sole Property Owner	03/04/2012	2012
EES 11 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	03/04/2012	2012
EES12 Cold water tank lid	£0.00	0.00	Sole Property Owner	03/04/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£0.00	0.00	Sole Property Owner	03/04/2012	2012
EES33 Replacement hot water cylinder (150L)	£0.00	0.00	Sole Property Owner	03/04/2012	2012
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Sole Property Owner	03/04/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	03/04/2012	2012
EES66 Low energy lamp replacement	£0.00	0.00	Sole Property Owner	03/04/2012	2012
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	03/04/2012	2012
EES07 200mm thick loft insulation	£162.00	18.00	Sole Property Owner	01/03/2013	2013
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	01/03/2013	2013
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	01/03/2013	2013
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	01/03/2013	2013
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	01/03/2013	2013
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	01/03/2013	2013
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	01/03/2013	2013
EES47 Pipework lagging 13mm thick to 22mm pipe	£98.00	14.00	Sole Property Owner	01/03/2013	2013
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	01/03/2013	2013
EES66 Low energy lamp replacement	£0.00	7.00	Sole Property Owner	01/03/2013	2013
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	01/03/2013	2013
HES40 Flue specification and location	£536.40	1.00	Sole Property Owner	01/03/2013	2013
HES43 Central heating pump	£96.00	1.00	Sole Property Owner	01/03/2013	2013
HES44 Pipework / feed modifications	£180.00	1.00	Sole Property Owner	01/03/2013	2013
HES46 Automatic bypass	£0.00	0.00	Sole Property Owner	01/03/2013	2013
HES48 Power / system flush and treatment	£480.00	1.00	Sole Property Owner	01/03/2013	2013
HES51 Thermostatic radiator valve	£22.80	1.00	Sole Property Owner	01/03/2013	2013
HES93 Junior heating engineer	£400.00	16.00	Sole Property Owner	01/03/2013	2013
HES95 Senior heating engineer	£858.00	22.00	Sole Property Owner	01/03/2013	2013
HES98 Senior electrician	£117.00	3.00	Sole Property Owner	01/03/2013	2013
HES23 Scaffold / cherry picker	£844.20	844.20	Sole Property Owner	01/03/2013	2013
HES64 Stainless steel replacement hot water cylinder (170L)	£0.00	0.00	Sole Property Owner	01/03/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£42.00	42.00	Sole Property Owner	01/03/2013	2013
HES36 12-15kW Gas replacement condensing boiler	£872.00	1.00	Sole Property Owner	01/03/2013	2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	01/03/2013	2013
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	01/03/2013	2013
EES69 Miscellaneous Charge	£29.86	1.00	Sole Property Owner	01/03/2013	2013
HES66 15mm thick pipework lagging	£6.48	2.00	Sole Property Owner	01/03/2013	2013
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	01/03/2013	2013
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	01/03/2013	2013

HES104 Copper replacement hot water cylinder (170L)	£747.42	1.00	Sole Property Owner	01/03/2013	2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	05/08/2010	2010
EES75 HEC to Flat or Bedsit	£64.00	1.00	Not The Property Owner	27/05/2010	2010
EES52a 21-25kW Oil replacement boiler	£3,250.80	1.00	Sole Property Owner	07/02/2011	2011
EES36 Electrical room thermostat	£85.68	1.00	Sole Property Owner	07/02/2011	2011
EES40 Hot water cylinder thermostat	£59.86	1.00	Sole Property Owner	07/02/2011	2011
EES42 Two channel programmable heating controller	£119.70	1.00	Sole Property Owner	07/02/2011	2011
EES44 Water heating time clock and boost	£152.46	1.00	Sole Property Owner	07/02/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£108.30	10.00	Sole Property Owner	07/02/2011	2011
EES70 Miscellaneous heating review charge	£1,043.79	1.00	Sole Property Owner	07/02/2011	2011
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	07/02/2011	2011
EES07 200mm thick loft insulation	£811.20	78.00	Sole Property Owner	07/02/2011	2011
EES03a Remove and replace nailed floor board	£78.00	30.00	Sole Property Owner	07/02/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£184.40	20.00	Sole Property Owner	07/02/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	07/02/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	07/02/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	07/02/2011	2011
EES01a Loft Clearance (hourly rate)	£374.40	8.00	Sole Property Owner	16/12/2009	2009
EES07 200mm thick loft insulation	£416.00	40.00	Sole Property Owner	16/12/2009	2009
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	16/12/2009	2009
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	16/12/2009	2009
EES49 Pipework lagging 25mm thick to 22mm pipe	£442.56	48.00	Sole Property Owner	16/12/2009	2009
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	16/12/2009	2009
EES69 Miscellaneous Charge	£190.00	1.00	Sole Property Owner	16/12/2009	2009
EES26 Draught stripping to windows	£85.05	15.00	Sole Property Owner	16/12/2009	2009
EES25 Draught stripping to exterior door	£56.70	10.00	Sole Property Owner	16/12/2009	2009
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	16/12/2009	2009
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	16/11/2009	2009
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	16/11/2009	2009
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	16/11/2009	2009
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	16/11/2009	2009
EES51b 16-20kW Gas replacement boiler	£2,058.28	1.00	Sole Property Owner	08/08/2011	2011
EES42 Two channel programmable heating controller	£0.00	1.00	Sole Property Owner	08/08/2011	2011
EES36 Electrical room thermostat	£0.00	1.00	Sole Property Owner	08/08/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	08/08/2011	2011
EES38a Thermostatic radiator valve (per valve)	£66.10	2.00	Sole Property Owner	08/08/2011	2011
EES26 Draught stripping to windows	£170.10	30.00	Sole Property Owner	08/08/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	08/08/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	08/08/2011	2011
EES53a 26-35kW Oil replacement boiler	£3,782.00	1.00	Sole Property Owner	02/08/2012	2012
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	02/08/2012	2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	02/08/2012	2012
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	02/08/2012	2012
EES70 Miscellaneous heating review charge	£1,211.79	1,211.79	Sole Property Owner	02/08/2012	2012
EES33 Replacement hot water cylinder (150L)	£1,200.00	1.00	Sole Property Owner	02/08/2012	2012
EES12 Cold water tank lid	£0.00	0.00	Sole Property Owner	02/08/2012	2012
EES13a Cold water tank bye law kit (including associated products)	£0.00	0.00	Sole Property Owner	02/08/2012	2012
EES38a Thermostatic radiator valve (per valve)	£297.45	9.00	Sole Property Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£227.40	20.00	Sole Property Owner	02/08/2012	2012
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	02/08/2012	2012
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	02/08/2012	2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	02/08/2012	2012
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Sole Property Owner	26/04/2013	2013
EES07 200mm thick loft insulation	£720.00	80.00	Sole Property Owner	26/04/2013	2013
EES10 Cold water tank insulation quilt	£0.00	0.00	Sole Property Owner	26/04/2013	2013
EES 11 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	26/04/2013	2013
EES12 Cold water tank lid	£0.00	0.00	Sole Property Owner	26/04/2013	2013
EES13a Cold water tank bye law kit (including associated products)	£0.00	0.00	Sole Property Owner	26/04/2013	2013
EES69 Miscellaneous Charge	£1,032.56	1,032.56	Sole Property Owner	26/04/2013	2013
EES34 Replacement hot water cylinder (170L)	£1,119.40	1.00	Sole Property Owner	26/04/2013	2013
EES40 Hot water cylinder thermostat	£59.86	1.00	Sole Property Owner	26/04/2013	2013
EES42 Two channel programmable heating controller	£119.70	1.00	Sole Property Owner	26/04/2013	2013
EES36 Electrical room thermostat	£85.68	1.00	Sole Property Owner	26/04/2013	2013
EES44 Water heating time clock and boost	£152.46	1.00	Sole Property Owner	26/04/2013	2013
EES47 Pipework lagging 13mm thick to 22mm pipe	£108.30	10.00	Sole Property Owner	26/04/2013	2013
EES52a 21-25kW Oil replacement boiler	£3,250.80	1.00	Sole Property Owner	26/04/2013	2013
EES70 Miscellaneous heating review charge	£1,166.61	1.00	Sole Property Owner	26/04/2013	2013
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	26/04/2013	2013
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	26/04/2013	2013
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	26/04/2013	2013
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	26/04/2013	2013
EES47 Pipework lagging 13mm thick to 22mm pipe	£210.00	30.00	Sole Property Owner	26/04/2013	2013
EES70 Miscellaneous heating review charge	£1,495.06	1,495.06	Sole Property Owner	26/04/2013	2013
EES69 Miscellaneous Charge	£195.00	195.00	Sole Property Owner	26/04/2013	2013
EES01a Loft Clearance (hourly rate)	£280.80	6.00	Sole Property Owner	26/04/2013	2013
EES07 200mm thick loft insulation	£596.80	80.00	Sole Property Owner	26/04/2013	2013
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	26/04/2013	2013
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	26/04/2013	2013
EES47 Pipework lagging 13mm thick to 22mm pipe	£40.45	5.00	Sole Property Owner	26/04/2013	2013
EES48 Pipework lagging 19mm thick to 22mm pipe	£138.30	15.00	Sole Property Owner	26/04/2013	2013
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	26/04/2013	2013
EES38a Thermostatic radiator valve (per valve)	£264.40	8.00	Sole Property Owner	26/04/2013	2013
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	26/04/2013	2013

HES67 22mm thick pipework lagging	£16.88	4.00	Sole Property Owner	26/04/2013	2013
HES68 28mm thick pipework lagging	£18.16	4.00	Sole Property Owner	26/04/2013	2013
HES93 Junior heating engineer	£175.76	8.00	Sole Property Owner	26/04/2013	2013
HES94 Heating engineer	£883.20	24.00	Sole Property Owner	26/04/2013	2013
HES95 Senior heating engineer	£119.04	3.00	Sole Property Owner	26/04/2013	2013
HES98 Senior electrician	£238.08	6.00	Sole Property Owner	26/04/2013	2013
HES90 Other miscellaneous oil heating works for EES approval	£760.00	1.00	Sole Property Owner	26/04/2013	2013
HES100 Asbestos survey & sample	£60.00	1.00	Sole Property Owner	26/04/2013	2013
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	26/04/2013	2013
HES101 Asbestos removal & disposal	£298.96	1.00	Sole Property Owner	26/04/2013	2013
EES26 Draught stripping to windows	£0.00	0.00	Sole Property Owner	30/03/2010	2010
EES07 200mm thick loft insulation	£838.43	94.10	Sole Property Owner	30/03/2010	2010
EES06 100mm thick loft insulation	£647.41	94.10	Sole Property Owner	30/03/2010	2010
EES16 Insulation to 75mm wide cavity wall	£862.56	103.30	Sole Property Owner	30/03/2010	2010
EES66 Low energy lamp replacement	£38.50	22.00	Sole Property Owner	30/03/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	16/12/2009	2009
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	13/12/2009	2009
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	01/04/2010	2010
EES06 100mm thick loft insulation	£193.96	26.00	Sole Property Owner	01/04/2010	2010
EES07 200mm thick loft insulation	£270.40	26.00	Sole Property Owner	01/04/2010	2010
EES03a Remove and replace nailed floor board	£52.00	20.00	Sole Property Owner	01/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	01/04/2010	2010
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	01/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£165.96	18.00	Sole Property Owner	01/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	01/04/2010	2010
EES26 Draught stripping to windows	£226.80	40.00	Sole Property Owner	01/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	01/04/2010	2010
EES01a Loft Clearance (hourly rate)	£46.80	1.00	Sole Property Owner	27/01/2010	2010
EES07 200mm thick loft insulation	£520.00	50.00	Sole Property Owner	27/01/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	27/01/2010	2010
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	27/01/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£92.20	10.00	Sole Property Owner	27/01/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	27/01/2010	2010
EES26 Draught stripping to windows	£453.60	80.00	Sole Property Owner	27/01/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	27/01/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	11/11/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£28.00	4.00	Sole Property Owner	11/11/2011	2011
EES10 Cold water tank insulation quilt	£0.00	0.00	Sole Property Owner	11/11/2011	2011
EES 11 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	11/11/2011	2011
EES12 Cold water tank lid	£0.00	0.00	Sole Property Owner	11/11/2011	2011
EES13a Cold water tank bye law kit (including associated product)	£0.00	0.00	Sole Property Owner	11/11/2011	2011
EES38a Thermostatic radiator valve (per valve)	£255.00	3.00	Sole Property Owner	11/11/2011	2011
EES51a 16-20kW Oil replacement boiler	£5,346.00	1.00	Sole Property Owner	11/11/2011	2011
EES15 Insulation to 65mm wide cavity wall	£566.48	65.87	Sole Property Owner	11/11/2011	2011
EES08 300mm thick loft insulation	£259.88	34.65	Sole Property Owner	11/11/2011	2011
EES66 Low energy lamp replacement	£101.40	20.00	Sole Property Owner	11/11/2011	2011
EES69 Miscellaneous Charge	£140.00	1.00	Sole Property Owner	11/11/2011	2011
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	11/11/2011	2011
EES07 200mm thick loft insulation	£403.00	62.00	Sole Property Owner	29/01/2010	2010
EES10 Cold water tank insulation quilt	£20.00	1.00	Sole Property Owner	29/01/2010	2010
EES66 Low energy lamp replacement	£0.00	17.00	Sole Property Owner	29/01/2010	2010
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	29/01/2010	2010
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	29/01/2010	2010
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	12/03/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£144.00	48.00	Sole Property Owner	12/03/2012	2012
EES03a Remove and replace nailed floor board	£24.00	8.00	Sole Property Owner	12/03/2012	2012
EES08 300mm thick loft insulation	£576.00	48.00	Sole Property Owner	12/03/2012	2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	12/03/2012	2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	12/03/2012	2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	12/03/2012	2012
EES13a Cold water tank bye law kit (including associated product)	£100.00	2.00	Sole Property Owner	12/03/2012	2012
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Sole Property Owner	12/03/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£49.00	7.00	Sole Property Owner	12/03/2012	2012
EES66 Low energy lamp replacement	£0.00	13.00	Sole Property Owner	12/03/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	12/03/2012	2012
EES75 HEC to Flat or Bedsit	£0.00	1.00	Not The Property Owner	27/05/2010	2010
EES15 Insulation to 65mm wide cavity wall	£790.28	95.56	Sole Property Owner	26/01/2011	2011
EES01a Loft Clearance (hourly rate)	£140.40	3.00	Sole Property Owner	26/01/2011	2011
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	26/01/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£184.40	20.00	Sole Property Owner	26/01/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	26/01/2011	2011
EES36 Electrical room thermostat	£64.42	1.00	Sole Property Owner	26/01/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	26/01/2011	2011
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	26/01/2011	2011
HES120 Standard QA check	£100.00	1.00	Sole Property Owner	26/01/2011	2011
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	25/01/2010	2010
EES08 300mm thick loft insulation	£1,032.00	86.00	Sole Property Owner	25/01/2010	2010
EES13a Cold water tank bye law kit (including associated product)	£560.00	2.00	Sole Property Owner	25/01/2010	2010
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	25/01/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£35.00	5.00	Sole Property Owner	25/01/2010	2010
EES51a 16-20kW Oil replacement boiler	£3,100.00	1.00	Sole Property Owner	25/01/2010	2010
EES70 Miscellaneous heating review charge	£745.00	1.00	Sole Property Owner	25/01/2010	2010
EES42 Two channel programmable heating controller	£105.00	1.00	Sole Property Owner	25/01/2010	2010
EES69 Miscellaneous Charge	£50.00	1.00	Sole Property Owner	25/01/2010	2010

EES49 Pipework lagging 25mm thick to 22mm pipe	£64.72	8.00	Sole Property Owner	25/01/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£36.88	4.00	Sole Property Owner	25/01/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	25/01/2010	2010
EES38a Thermostatic radiator valve (per valve)	£363.55	11.00	Sole Property Owner	25/01/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	25/01/2010	2010
EES00 Property Assessment	£185.00	1.00	Sole Property Owner	25/01/2010	2010
EES69 Miscellaneous Charge	£889.73	1.00	Sole Property Owner	25/01/2010	2010
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	25/01/2010	2010
EES33 Replacement hot water cylinder (150l)	£532.93	1.00	Sole Property Owner	25/01/2010	2010
EES69 Miscellaneous Charge	£52.00	1.00	Sole Property Owner	25/01/2010	2010
EES01a Loft Clearance (hourly rate)	£46.80	1.00	Sole Property Owner	29/04/2010	2010
EES07 200mm thick loft insulation	£332.80	32.00	Sole Property Owner	29/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	29/04/2010	2010
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	29/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£36.88	4.00	Sole Property Owner	29/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	29/04/2010	2010
EES33 Replacement hot water cylinder (150l)	£532.93	1.00	Sole Property Owner	29/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	29/04/2010	2010
EES07 200mm thick loft insulation	£297.00	33.00	Not The Property Owner	25/01/2010	2010
EES12 Cold water tank lid	£280.00	1.00	Not The Property Owner	25/01/2010	2010
EES69 Miscellaneous Charge	£26.00	1.00	Not The Property Owner	25/01/2010	2010
EES25 Draught stripping to exterior door	£20.00	2.00	Not The Property Owner	25/01/2010	2010
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Not The Property Owner	25/01/2010	2010
EES69 Miscellaneous Charge	£50.00	1.00	Not The Property Owner	25/01/2010	2010
EES01a Loft Clearance (hourly rate)	£189.75	3.00	Not The Property Owner	15/04/2010	2010
EES03a Remove and replace nailed floor board	£295.00	25.00	Not The Property Owner	15/04/2010	2010
EES07 200mm thick loft insulation	£365.31	41.00	Not The Property Owner	15/04/2010	2010
EES10 Cold water tank insulation quilt	£74.84	2.00	Not The Property Owner	15/04/2010	2010
EES22 Mastic pointing	£39.00	10.00	Not The Property Owner	15/04/2010	2010
EES25 Draught stripping to exterior door	£45.50	5.00	Not The Property Owner	15/04/2010	2010
EES34 Replacement hot water cylinder (170l)	£715.00	1.00	Not The Property Owner	15/04/2010	2010
EES36 Electrical room thermostat	£103.40	1.00	Not The Property Owner	15/04/2010	2010
EES38a Thermostatic radiator valve (per valve)	£440.00	10.00	Not The Property Owner	15/04/2010	2010
EES40 Hot water cylinder thermostat	£74.70	1.00	Not The Property Owner	15/04/2010	2010
EES42 Two channel programmable heating controller	£111.00	1.00	Not The Property Owner	15/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£122.70	15.00	Not The Property Owner	15/04/2010	2010
EES66 Low energy lamp replacement	£26.25	15.00	Not The Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£30.00	1.00	Sole Property Owner	15/04/2010	2010
EES15 Insulation to 65mm wide cavity wall	£827.00	100.00	Sole Property Owner	15/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	15/04/2010	2010
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	15/04/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£165.96	18.00	Sole Property Owner	15/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	15/04/2010	2010
EES38a Thermostatic radiator valve (per valve)	£297.45	9.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	15/04/2010	2010
EES06 100mm thick loft insulation	£223.80	30.00	Sole Property Owner	29/04/2010	2010
EES07 200mm thick loft insulation	£478.40	46.00	Sole Property Owner	29/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	29/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£147.52	16.00	Sole Property Owner	29/04/2010	2010
EES69 Miscellaneous Charge	£108.00	1.00	Sole Property Owner	29/04/2010	2010
EES69 Miscellaneous Charge	£325.00	1.00	Sole Property Owner	29/04/2010	2010
EES15 Insulation to 65mm wide cavity wall	£779.85	103.98	Sole Property Owner	02/08/2010	2010
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	02/08/2010	2010
EES07 200mm thick loft insulation	£416.00	40.00	Sole Property Owner	02/08/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	02/08/2010	2010
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	02/08/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£55.32	6.00	Sole Property Owner	02/08/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	02/08/2010	2010
EES38a Thermostatic radiator valve (per valve)	£165.25	5.00	Sole Property Owner	02/08/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	02/08/2010	2010
EES25 Draught stripping to exterior door	£60.00	6.00	Joint Owner	02/08/2012	2012
EES66 Low energy lamp replacement	£0.00	7.00	Joint Owner	02/08/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Joint Owner	02/08/2012	2012
EES50a 12-15kW Oil replacement boiler	£3,250.00	1.00	Sole Property Owner	01/04/2010	2010
EES01a Loft Clearance (hourly rate)	£468.00	10.00	Sole Property Owner	01/04/2010	2010
EES07 200mm thick loft insulation	£780.00	75.00	Sole Property Owner	01/04/2010	2010
EES03a Remove and replace nailed floor board	£104.00	40.00	Sole Property Owner	01/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	01/04/2010	2010
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	01/04/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£368.80	40.00	Sole Property Owner	01/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	01/04/2010	2010
EES42 Two channel programmable heating controller	£90.31	1.00	Sole Property Owner	01/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	01/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	26/03/2010	2010
EES10 Cold water tank insulation quilt	£64.89	1.00	Sole Property Owner	26/03/2010	2010
EES12 Cold water tank lid	£71.40	2.00	Sole Property Owner	26/03/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£165.96	18.00	Sole Property Owner	26/03/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	26/03/2010	2010
HES120 Standard QA check	£100.00	1.00	Sole Property Owner	26/03/2010	2010
EES26 Draught stripping to windows	£226.80	40.00	Joint Owner	29/04/2010	2010
EES01a Loft Clearance (hourly rate)	£140.40	3.00	Joint Owner	29/04/2010	2010
EES07 200mm thick loft insulation	£624.00	60.00	Joint Owner	29/04/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£276.60	30.00	Joint Owner	29/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Joint Owner	29/04/2010	2010

EES33 Replacement hot water cylinder (150l)	£532.93	1.00	Joint Owner	29/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Joint Owner	29/04/2010	2010
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	27/01/2010	2010
EES07 200mm thick loft insulation	£395.20	38.00	Sole Property Owner	27/01/2010	2010
EES03a Remove and replace nailed floor board	£65.00	25.00	Sole Property Owner	27/01/2010	2010
EES 11 Cold water tank insulation jacket	£129.78	2.00	Sole Property Owner	27/01/2010	2010
EES12 Cold water tank lid	£71.40	2.00	Sole Property Owner	27/01/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£73.76	8.00	Sole Property Owner	27/01/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	27/01/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	27/01/2010	2010
EES66 Low energy lamp replacement	£51.20	8.00	Not The Property Owner	01/11/2009	2009
EES67 Smoke detector installation	£7.50	1.00	Not The Property Owner	01/11/2009	2009
EES25 Draught stripping to exterior door	£43.76	1.00	Not The Property Owner	01/11/2009	2009
EES50b 12-15kW Gas replacement boiler	£2,132.39	1.00	Sole Property Owner	22/06/2011	2011
EES40 Hot water cylinder thermostat	£0.00	1.00	Sole Property Owner	22/06/2011	2011
EES36 Electrical room thermostat	£0.00	1.00	Sole Property Owner	22/06/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£0.00	1.00	Sole Property Owner	22/06/2011	2011
EES33 Replacement hot water cylinder (150l)	£413.59	1.00	Sole Property Owner	22/06/2011	2011
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	22/06/2011	2011
EES07 200mm thick loft insulation	£530.40	51.00	Sole Property Owner	22/06/2011	2011
EES03a Remove and replace nailed floor board	£39.00	15.00	Sole Property Owner	22/06/2011	2011
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	22/06/2011	2011
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	22/06/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£55.32	6.00	Sole Property Owner	22/06/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	22/06/2011	2011
EES38a Thermostatic radiator valve (per valve)	£297.45	9.00	Sole Property Owner	22/06/2011	2011
EES69 Miscellaneous Charge	£41.00	41.00	Sole Property Owner	22/06/2011	2011
EES70 Miscellaneous heating review charge	£75.00	1.00	Sole Property Owner	22/06/2011	2011
EES69 Miscellaneous Charge	£94.69	94.69	Sole Property Owner	22/06/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	22/06/2011	2011
HES120 Standard QA check	£100.00	1.00	Sole Property Owner	22/06/2011	2011
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Sole Property Owner	27/09/2012	2012
EES03a Remove and replace nailed floor board	£54.00	18.00	Sole Property Owner	27/09/2012	2012
EES08 300mm thick loft insulation	£480.00	40.00	Sole Property Owner	27/09/2012	2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	27/09/2012	2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	27/09/2012	2012
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	27/09/2012	2012
EES13a Cold water tank bye law kit (including associated product)	£50.00	1.00	Sole Property Owner	27/09/2012	2012
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	27/09/2012	2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	27/09/2012	2012
HES72 Storage heater rated 2kW - 3kW	£616.98	2.00	Sole Property Owner	27/09/2012	2012
HES97 Electrician	£320.00	10.00	Sole Property Owner	27/09/2012	2012
HES92 Other miscellaneous electrical heating works for EES appr	£57.68	1.00	Sole Property Owner	27/09/2012	2012
HES92 Other miscellaneous electrical heating works for EES appr	£243.26	1.00	Sole Property Owner	27/09/2012	2012
HES66 15mm thick pipework lagging	£12.96	4.00	Sole Property Owner	27/09/2012	2012
HES67 22mm thick pipework lagging	£4.22	1.00	Sole Property Owner	27/09/2012	2012
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	27/09/2012	2012
EES01a Loft Clearance (hourly rate)	£140.40	3.00	Sole Property Owner	29/04/2010	2010
EES07 200mm thick loft insulation	£717.60	69.00	Sole Property Owner	29/04/2010	2010
EES03a Remove and replace nailed floor board	£39.00	15.00	Sole Property Owner	29/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	29/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£147.52	16.00	Sole Property Owner	29/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	29/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	29/04/2010	2010
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	27/01/2010	2010
EES06 100mm thick loft insulation	£328.24	44.00	Sole Property Owner	27/01/2010	2010
EES07 200mm thick loft insulation	£457.60	44.00	Sole Property Owner	27/01/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£230.50	25.00	Sole Property Owner	27/01/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	27/01/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	27/01/2010	2010
EES33 Replacement hot water cylinder (150l)	£532.93	1.00	Sole Property Owner	27/01/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	01/06/2010	2010
EES66 Low energy lamp replacement	£3.81	1.00	Sole Property Owner	01/06/2010	2010
EES66 Low energy lamp replacement	£3.81	1.00	Sole Property Owner	01/06/2010	2010
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	01/08/2010	2010
EES42 Two channel programmable heating controller	£119.70	1.00	Sole Property Owner	13/09/2011	2011
EES36 Electrical room thermostat	£85.68	1.00	Sole Property Owner	13/09/2011	2011
EES44 Water heating time clock and boost	£152.46	1.00	Sole Property Owner	13/09/2011	2011
EES52a 21-25kW Oil replacement boiler	£3,250.80	1.00	Sole Property Owner	13/09/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£108.30	10.00	Sole Property Owner	13/09/2011	2011
EES70 Miscellaneous heating review charge	£880.61	1.00	Sole Property Owner	13/09/2011	2011
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	13/09/2011	2011
EES06 100mm thick loft insulation	£298.40	40.00	Sole Property Owner	13/09/2011	2011
EES07 200mm thick loft insulation	£208.00	20.00	Sole Property Owner	13/09/2011	2011
EES 11 Cold water tank insulation jacket	£129.78	2.00	Sole Property Owner	13/09/2011	2011
EES12 Cold water tank lid	£71.40	2.00	Sole Property Owner	13/09/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£110.64	12.00	Sole Property Owner	13/09/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	13/09/2011	2011
EES26 Draught stripping to windows	£62.37	11.00	Sole Property Owner	13/09/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	13/09/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	13/09/2011	2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	26/01/2010	2010
EES15 Insulation to 65mm wide cavity wall	£566.48	65.87	Sole Property Owner	26/01/2010	2010
EES66 Low energy lamp replacement	£45.34	1.00	Sole Property Owner	26/01/2010	2010

EES49 Pipework lagging 25mm thick to 22mm pipe	£4.76	4.00	Sole Property Owner	26/01/2010	2010
EES08 300mm thick loft insulation	£259.88	34.65	Sole Property Owner	26/01/2010	2010
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	27/01/2010	2010
EES07 200mm thick loft insulation	£468.00	45.00	Sole Property Owner	27/01/2010	2010
EES03a Remove and replace nailed floor board	£117.00	45.00	Sole Property Owner	27/01/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	27/01/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	27/01/2010	2010
EES15 Insulation to 65mm wide cavity wall	£937.88	125.05	Sole Property Owner	07/02/2013	2013
EES25 Draught stripping to exterior door	£50.00	5.00	Sole Property Owner	07/02/2013	2013
EES36 Electrical room thermostat	£105.00	1.00	Sole Property Owner	07/02/2013	2013
EES42 Two channel programmable heating controller	£105.00	1.00	Sole Property Owner	07/02/2013	2013
EES51a 16-20kW Oil replacement boiler	£2,900.00	1.00	Sole Property Owner	07/02/2013	2013
EES70 Miscellaneous heating review charge	£1,230.00	1.00	Sole Property Owner	07/02/2013	2013
EES70 Miscellaneous heating review charge	£397.34	1.00	Sole Property Owner	07/02/2013	2013
EES01a Loft Clearance (hourly rate)	£187.20	4.00	Sole Property Owner	07/02/2013	2013
EES07 200mm thick loft insulation	£811.20	78.00	Sole Property Owner	07/02/2013	2013
EES03a Remove and replace nailed floor board	£93.60	36.00	Sole Property Owner	07/02/2013	2013
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	07/02/2013	2013
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	07/02/2013	2013
EES00 Property Assessment	£185.00	1.00	Sole Property Owner	07/02/2013	2013
EES69 Miscellaneous Charge	£1,753.15	1.00	Sole Property Owner	07/02/2013	2013
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	07/02/2013	2013
HES94 Heating engineer	£184.00	5.00	Sole Property Owner	07/02/2013	2013
HES91 Other miscellaneous gas heating works for EES approval	£36.80	36.80	Sole Property Owner	07/02/2013	2013
EES66 Low energy lamp replacement	£11.37	1.00	Not The Property Owner	15/12/2009	2009
EES00a Full Energy Survey	£246.55	1.00	Not The Property Owner	15/12/2009	2009
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	19/10/2011	2011
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	19/10/2011	2011
EES51a 16-20kW Oil replacement boiler	£4,080.00	1.00	Sole Property Owner	19/10/2011	2011
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	19/10/2011	2011
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	19/10/2011	2011
EES06 100mm thick loft insulation	£462.52	62.00	Sole Property Owner	19/10/2011	2011
EES07 200mm thick loft insulation	£644.80	62.00	Sole Property Owner	19/10/2011	2011
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	19/10/2011	2011
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	19/10/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£110.64	12.00	Sole Property Owner	19/10/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	19/10/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	19/10/2011	2011
EES03a Remove and replace nailed floor board	£213.20	82.00	Sole Property Owner	19/10/2011	2011
EES38a Thermostatic radiator valve (per valve)	£231.35	7.00	Sole Property Owner	19/10/2011	2011
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	19/10/2011	2011
EES44 Water heating time clock and boost	£152.46	1.00	Sole Property Owner	16/11/2011	2011
EES42 Two channel programmable heating controller	£119.70	1.00	Sole Property Owner	16/11/2011	2011
EES36 Electrical room thermostat	£85.68	1.00	Sole Property Owner	16/11/2011	2011
EES40 Hot water cylinder thermostat	£59.86	1.00	Sole Property Owner	16/11/2011	2011
EES51a 16-20kW Oil replacement boiler	£2,746.80	1.00	Sole Property Owner	16/11/2011	2011
EES70 Miscellaneous heating review charge	£1,195.59	1.00	Sole Property Owner	16/11/2011	2011
EES06 100mm thick loft insulation	£333.68	43.00	Sole Property Owner	16/11/2011	2011
EES07 200mm thick loft insulation	£447.20	43.00	Sole Property Owner	16/11/2011	2011
EES 11 Cold water tank insulation jacket	£129.78	2.00	Sole Property Owner	16/11/2011	2011
EES12 Cold water tank lid	£71.40	2.00	Sole Property Owner	16/11/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£110.64	12.00	Sole Property Owner	16/11/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	16/11/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	16/11/2011	2011
HES101 Asbestos removal & disposal	£550.00	1.00	Sole Property Owner	16/11/2011	2011
HES120 Standard QA check	£75.00	1.00	Sole Property Owner	16/11/2011	2011
HES121 Boiler QA Check	£90.00	1.00	Sole Property Owner	16/11/2011	2011
HES100 Asbestos survey & sample	£320.00	1.00	Sole Property Owner	16/11/2011	2011
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	29/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£73.76	8.00	Sole Property Owner	29/04/2010	2010
EES33 Replacement hot water cylinder (150l)	£532.93	1.00	Sole Property Owner	29/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	29/04/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	01/07/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£2.34	2.00	Sole Property Owner	01/07/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£3.07	1.00	Sole Property Owner	01/07/2010	2010
EES69 Miscellaneous Charge	£0.89	1.00	Sole Property Owner	01/07/2010	2010
EES66 Low energy lamp replacement	£5.07	1.00	Sole Property Owner	01/07/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£110.64	12.00	Sole Property Owner	02/08/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	02/08/2010	2010
EES01a Loft Clearance (hourly rate)	£126.50	2.00	Not The Property Owner	15/04/2010	2010
EES03a Remove and replace nailed floor board	£1,156.40	98.00	Not The Property Owner	15/04/2010	2010
EES06 100mm thick loft insulation	£337.12	49.00	Not The Property Owner	15/04/2010	2010
EES07 200mm thick loft insulation	£436.59	49.00	Not The Property Owner	15/04/2010	2010
EES10 Cold water tank insulation quilt	£37.42	1.00	Not The Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£36.40	4.00	Not The Property Owner	15/04/2010	2010
EES67 Smoke detector installation	£3.50	2.00	Not The Property Owner	15/04/2010	2010
EES66 Low energy lamp replacement	£33.25	19.00	Not The Property Owner	15/04/2010	2010
EES15 Insulation to 65mm wide cavity wall	£780.00	104.00	Sole Property Owner	15/04/2010	2010
EES21 Scaffold	£72.50	72.50	Sole Property Owner	15/04/2010	2010
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	15/04/2010	2010
EES06 100mm thick loft insulation	£328.24	44.00	Sole Property Owner	15/04/2010	2010
EES07 200mm thick loft insulation	£457.60	44.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	15/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	15/04/2010	2010

EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	15/04/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£184.40	20.00	Sole Property Owner	15/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	15/04/2010	2010
EES38a Thermostatic radiator valve (per valve)	£264.40	8.00	Sole Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	15/04/2010	2010
EES77 HEC to House	£150.00	1.00	Sole Property Owner	03/12/2009	2009
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	01/04/2010	2010
EES06 100mm thick loft insulation	£93.12	12.00	Sole Property Owner	01/04/2010	2010
EES07 200mm thick loft insulation	£312.00	30.00	Sole Property Owner	01/04/2010	2010
EES03a Remove and replace nailed floor board	£117.00	45.00	Sole Property Owner	01/04/2010	2010
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	01/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£55.32	6.00	Sole Property Owner	01/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	01/04/2010	2010
EES33 Replacement hot water cylinder (150L)	£0.00	0.00	Sole Property Owner	01/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	01/04/2010	2010
HES63 Stainless steel replacement hot water cylinder (150L)	£793.28	1.00	Sole Property Owner	01/04/2010	2010
EES25 Draught stripping to exterior door	£37.65	5.00	Not The Property Owner	15/12/2009	2009
EES66 Low energy lamp replacement	£159.18	14.00	Not The Property Owner	15/12/2009	2009
EES69 Miscellaneous Charge	£41.00	1.00	Not The Property Owner	15/12/2009	2009
EES00a Full Energy Survey	£246.55	1.00	Not The Property Owner	15/12/2009	2009
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	16/12/2011	2011
EES07 200mm thick loft insulation	£233.48	26.00	Sole Property Owner	16/12/2011	2011
EES69 Miscellaneous Charge	£462.75	1.00	Sole Property Owner	16/12/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£32.36	4.00	Sole Property Owner	16/12/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£36.88	4.00	Sole Property Owner	16/12/2011	2011
EES66 Low energy lamp replacement	£352.47	31.00	Sole Property Owner	16/12/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	16/12/2011	2011
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	16/12/2011	2011
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	16/12/2011	2011
EES66 Low energy lamp replacement	£19.20	3.00	Not The Property Owner	01/11/2009	2009
EES67 Smoke detector installation	£15.00	2.00	Not The Property Owner	01/11/2009	2009
EES01a Loft Clearance (hourly rate)	£187.20	4.00	Sole Property Owner	26/01/2011	2011
EES07 200mm thick loft insulation	£1,508.00	145.00	Sole Property Owner	26/01/2011	2011
EES03a Remove and replace nailed floor board	£104.00	40.00	Sole Property Owner	26/01/2011	2011
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	26/01/2011	2011
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	26/01/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£497.88	54.00	Sole Property Owner	26/01/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	26/01/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	26/01/2011	2011
EES19 Airbrick	£101.20	11.00	Sole Property Owner	26/01/2011	2011
EES15 Insulation to 65mm wide cavity wall	£1,383.06	178.00	Sole Property Owner	26/01/2011	2011
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	26/01/2011	2011
HES120 Standard QA check	£100.00	1.00	Sole Property Owner	26/01/2011	2011
EES51a 16-20kW Oil replacement boiler	£2,746.80	1.00	Joint Owner	22/06/2011	2011
EES70 Miscellaneous heating review charge	£392.00	392.00	Joint Owner	22/06/2011	2011
EES 11 Cold water tank insulation jacket	£64.89	1.00	Joint Owner	22/06/2011	2011
EES12 Cold water tank lid	£35.70	1.00	Joint Owner	22/06/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£36.88	4.00	Joint Owner	22/06/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Joint Owner	22/06/2011	2011
EES38a Thermostatic radiator valve (per valve)	£198.30	6.00	Joint Owner	22/06/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Joint Owner	22/06/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Joint Owner	22/06/2011	2011
EES15 Insulation to 65mm wide cavity wall	£793.73	105.83	Sole Property Owner	02/08/2011	2011
EES52a 21-25kW Oil replacement boiler	£3,250.80	1.00	Sole Property Owner	02/08/2011	2011
EES42 Two channel programmable heating controller	£119.70	1.00	Sole Property Owner	02/08/2011	2011
EES36 Electrical room thermostat	£85.68	1.00	Sole Property Owner	02/08/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£108.30	10.00	Sole Property Owner	02/08/2011	2011
EES70 Miscellaneous heating review charge	£829.09	1.00	Sole Property Owner	02/08/2011	2011
EES06 100mm thick loft insulation	£671.40	90.00	Sole Property Owner	02/08/2011	2011
EES07 200mm thick loft insulation	£416.00	40.00	Sole Property Owner	02/08/2011	2011
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	02/08/2011	2011
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	02/08/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£230.50	25.00	Sole Property Owner	02/08/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	02/08/2011	2011
EES38a Thermostatic radiator valve (per valve)	£198.30	6.00	Sole Property Owner	02/08/2011	2011
EES33 Replacement hot water cylinder (150L)	£532.93	1.00	Sole Property Owner	02/08/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	02/08/2011	2011
EES69 Miscellaneous Charge	£186.35	1.00	Sole Property Owner	02/08/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	02/08/2011	2011
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	01/04/2010	2010
EES07 200mm thick loft insulation	£728.00	70.00	Sole Property Owner	01/04/2010	2010
EES03a Remove and replace nailed floor board	£104.00	40.00	Sole Property Owner	01/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	01/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£258.16	28.00	Sole Property Owner	01/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	01/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	01/04/2010	2010
EES01a Loft Clearance (hourly rate)	£46.80	1.00	Sole Property Owner	01/04/2010	2010
EES07 200mm thick loft insulation	£416.00	40.00	Sole Property Owner	01/04/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	01/04/2010	2010
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	01/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	01/04/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	01/04/2010	2010
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Not The Property Owner	26/01/2011	2011
EES03a Remove and replace nailed floor board	£0.00	0.00	Not The Property Owner	26/01/2011	2011

EES08 300mm thick loft insulation	£0.00	0.00	Not The Property Owner	26/01/2011	2011
EES35 Replacement hot water cylinder (210l)	£1,402.89	1.00	Not The Property Owner	26/01/2011	2011
EES69 Miscellaneous Charge	£92.00	92.00	Not The Property Owner	26/01/2011	2011
EES69 Miscellaneous Charge	£321.80	1.00	Sole Property Owner	26/03/2010	2010
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Not The Property Owner	28/01/2010	2010
EES66 Low energy lamp replacement	£32.00	8.00	Not The Property Owner	28/01/2010	2010
EES01a Loft Clearance (hourly rate)	£46.80	1.00	Sole Property Owner	30/10/2009	2009
EES08 300mm thick loft insulation	£1,102.40	106.00	Sole Property Owner	30/10/2009	2009
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	30/10/2009	2009
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	30/10/2009	2009
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	30/10/2009	2009
EES07 200mm thick loft insulation	£530.40	51.00	Sole Property Owner	26/01/2011	2011
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	26/01/2011	2011
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	26/01/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£64.54	7.00	Sole Property Owner	26/01/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	26/01/2011	2011
EES69 Miscellaneous Charge	£41.00	41.00	Sole Property Owner	26/01/2011	2011
HES120 Standard QA check	£100.00	1.00	Sole Property Owner	26/01/2011	2011
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	26/01/2011	2011
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	26/01/2011	2011
EES08 300mm thick loft insulation	£480.00	40.00	Sole Property Owner	26/01/2011	2011
EES38a Thermostatic radiator valve (per valve)	£487.50	10.00	Sole Property Owner	26/01/2011	2011
EES36 Electrical room thermostat	£50.00	1.00	Sole Property Owner	26/01/2011	2011
EES69 Miscellaneous Charge	£195.00	1.00	Sole Property Owner	26/01/2011	2011
EES69 Miscellaneous Charge	£50.00	2.00	Sole Property Owner	26/01/2011	2011
EES70 Miscellaneous heating review charge	£237.00	1.00	Not The Property Owner	15/04/2010	2010
EES38a Thermostatic radiator valve (per valve)	£341.25	7.00	Not The Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£153.75	1.00	Not The Property Owner	15/04/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	28/01/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£1.09	1.00	Not The Property Owner	28/01/2010	2010
EES50c Replacement electrical storage heater	£886.00	2.00	Sole Property Owner	26/01/2012	2012
EES02a Remove and dispose existing insulation (per square metre)	£126.00	30.00	Sole Property Owner	26/01/2012	2012
EES01a Loft Clearance (hourly rate)	£63.25	1.00	Sole Property Owner	26/01/2012	2012
EES03a Remove and replace nailed floor board	£354.00	30.00	Sole Property Owner	26/01/2012	2012
EES07 200mm thick loft insulation	£507.87	57.00	Sole Property Owner	26/01/2012	2012
EES10 Cold water tank insulation quilt	£34.62	1.00	Sole Property Owner	26/01/2012	2012
EES69 Miscellaneous Charge	£30.00	1.00	Sole Property Owner	26/01/2012	2012
EES15 Insulation to 65mm wide cavity wall	£543.90	70.00	Sole Property Owner	26/01/2012	2012
EES22 Mastic pointing	£23.40	6.00	Sole Property Owner	26/01/2012	2012
EES25 Draught stripping to exterior door	£100.10	11.00	Sole Property Owner	26/01/2012	2012
EES69 Miscellaneous Charge	£66.60	3.00	Sole Property Owner	26/01/2012	2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£8.18	1.00	Sole Property Owner	26/01/2012	2012
EES66 Low energy lamp replacement	£24.50	14.00	Sole Property Owner	26/01/2012	2012
EES67 Smoke detector installation	£1.75	1.00	Sole Property Owner	26/01/2012	2012
EES25 Draught stripping to exterior door	£100.00	10.00	Not The Property Owner	18/12/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	18/12/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	05/09/2010	2010
EES50c Replacement electrical storage heater	£525.58	2.00	Sole Property Owner	26/01/2012	2012
EES50c Replacement electrical storage heater	£475.00	1.00	Sole Property Owner	26/01/2012	2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	26/01/2012	2012
EES07 200mm thick loft insulation	£315.00	35.00	Sole Property Owner	26/01/2012	2012
EES10 Cold water tank insulation quilt	£280.00	1.00	Sole Property Owner	26/01/2012	2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	26/01/2012	2012
EES36 Electrical room thermostat	£60.43	1.00	Sole Property Owner	26/01/2012	2012
EES69 Miscellaneous Charge	£26.00	1.00	Sole Property Owner	26/01/2012	2012
EES21 Scaffold	£1,265.00	1.00	Sole Property Owner	30/10/2009	2009
EES38a Thermostatic radiator valve (per valve)	£264.40	8.00	Sole Property Owner	30/10/2009	2009
EES15 Insulation to 65mm wide cavity wall	£861.35	115.00	Sole Property Owner	30/10/2009	2009
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	30/10/2009	2009
EES10 Cold water tank insulation quilt	£64.89	1.00	Sole Property Owner	30/10/2009	2009
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	30/10/2009	2009
EES66 Low energy lamp replacement	£113.70	10.00	Sole Property Owner	30/10/2009	2009
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	30/10/2009	2009
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	30/10/2009	2009
EES15 Insulation to 65mm wide cavity wall	£1,320.88	159.72	Sole Property Owner	05/04/2010	2010
EES01a Loft Clearance (hourly rate)	£31.63	0.50	Sole Property Owner	05/04/2010	2010
EES06 100mm thick loft insulation	£346.06	50.30	Sole Property Owner	05/04/2010	2010
EES07 200mm thick loft insulation	£448.17	50.30	Sole Property Owner	05/04/2010	2010
EES10 Cold water tank insulation quilt	£37.42	1.00	Sole Property Owner	05/04/2010	2010
EES10 Cold water tank insulation quilt	£32.03	1.00	Sole Property Owner	05/04/2010	2010
EES69 Miscellaneous Charge	£36.40	4.00	Sole Property Owner	05/04/2010	2010
EES38a Thermostatic radiator valve (per valve)	£176.00	4.00	Sole Property Owner	05/04/2010	2010
EES69 Miscellaneous Charge	£74.20	10.00	Sole Property Owner	05/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£57.26	7.00	Sole Property Owner	05/04/2010	2010
EES66 Low energy lamp replacement	£31.50	18.00	Sole Property Owner	05/04/2010	2010
EES52a 21-25kW Oil replacement boiler	£3,083.00	1.00	Sole Property Owner	08/08/2011	2011
EES70 Miscellaneous heating review charge	£917.00	1.00	Sole Property Owner	08/08/2011	2011
EES15 Insulation to 65mm wide cavity wall	£838.88	112.00	Sole Property Owner	08/08/2011	2011
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	08/08/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£32.36	4.00	Sole Property Owner	08/08/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£165.96	18.00	Sole Property Owner	08/08/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	08/08/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	08/08/2011	2011
EES00 Property Assessment	£185.00	1.00	Sole Property Owner	08/08/2011	2011

EES69 Miscellaneous Charge	£2,630.88	1.00	Sole Property Owner	08/08/2011	2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	08/08/2011	2011
EES17 Insulation to 90mm wide cavity wall	£0.00	0.00	Not The Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£0.00	0.00	Not The Property Owner	15/04/2010	2010
EES01a Loft Clearance (hourly rate)	£126.52	4.00	Not The Property Owner	15/04/2010	2010
EES03a Remove and replace nailed floor board	£236.00	20.00	Not The Property Owner	15/04/2010	2010
EES07 200mm thick loft insulation	£1,109.30	124.50	Not The Property Owner	15/04/2010	2010
EES 11 Cold water tank insulation jacket	£69.44	2.00	Not The Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£30.00	1.00	Not The Property Owner	15/04/2010	2010
EES25 Draught stripping to exterior door	£81.90	9.00	Not The Property Owner	15/04/2010	2010
EES27 Draught stripping to letterbox	£44.40	2.00	Not The Property Owner	15/04/2010	2010
EES38a Thermostatic radiator valve (per valve)	£616.00	14.00	Not The Property Owner	15/04/2010	2010
EES69 Miscellaneous Charge	£77.00	44.00	Not The Property Owner	15/04/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	05/02/2010	2010
EES77 HEC to House	£165.00	1.00	Not The Property Owner	28/01/2010	2010
EES77 HEC to House	£150.00	1.00	Sole Property Owner	28/01/2010	2010
EES01a Loft Clearance (hourly rate)	£187.20	4.00	Sole Property Owner	02/02/2011	2011
EES07 200mm thick loft insulation	£478.40	46.00	Sole Property Owner	02/02/2011	2011
EES15 Insulation to 65mm wide cavity wall	£838.88	112.00	Sole Property Owner	02/02/2011	2011
EES69 Miscellaneous Charge	£112.50	112.50	Sole Property Owner	02/02/2011	2011
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	02/02/2011	2011
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	02/02/2011	2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£553.20	60.00	Sole Property Owner	02/02/2011	2011
EES38a Thermostatic radiator valve (per valve)	£264.40	8.00	Sole Property Owner	02/02/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	02/02/2011	2011
EES69 Miscellaneous Charge	£41.00	41.00	Sole Property Owner	02/02/2011	2011
HES120 Standard QA check	£100.00	1.00	Sole Property Owner	02/02/2011	2011
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	02/02/2011	2011
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	19/05/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	19/05/2010	2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£36.88	4.00	Sole Property Owner	19/05/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	19/05/2010	2010
EES38a Thermostatic radiator valve (per valve)	£231.35	7.00	Sole Property Owner	19/05/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	19/05/2010	2010
EES01a Loft Clearance (hourly rate)	£187.20	4.00	Sole Property Owner	01/07/2011	2011
EES08 300mm thick loft insulation	£1,016.96	56.00	Sole Property Owner	01/07/2011	2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£40.45	5.00	Sole Property Owner	01/07/2011	2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£64.54	7.00	Sole Property Owner	01/07/2011	2011
EES66 Low energy lamp replacement	£45.48	4.00	Sole Property Owner	01/07/2011	2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	01/07/2011	2011
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	01/07/2011	2011
EES68 Minimum charge for lamps and detectors	£0.00	1.00	Sole Property Owner	04/06/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	15/04/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£15.20	16.00	Joint Owner	15/04/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£0.54	1.00	Joint Owner	15/04/2010	2010
EES15 Insulation to 65mm wide cavity wall	£181.46	21.10	Joint Owner	15/04/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	19/05/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	19/05/2010	2010
EES07 200mm thick loft insulation	£665.60	64.00	Sole Property Owner	19/05/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£16.18	2.00	Sole Property Owner	19/05/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£46.10	5.00	Sole Property Owner	19/05/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	13/12/2009	2009
EES15 Insulation to 65mm wide cavity wall	£621.67	83.00	Joint Owner	02/08/2010	2010
EES69 Miscellaneous Charge	£112.50	1.00	Joint Owner	02/08/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£16.18	2.00	Joint Owner	02/08/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£18.44	2.00	Joint Owner	02/08/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Joint Owner	02/08/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Joint Owner	02/08/2010	2010
EES07 200mm thick loft insulation	£790.40	76.00	Sole Property Owner	19/05/2010	2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	19/05/2010	2010
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	19/05/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£36.88	4.00	Sole Property Owner	19/05/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£32.36	4.00	Sole Property Owner	19/05/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	19/05/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	19/05/2010	2010
EES07 200mm thick loft insulation	£208.00	20.00	Joint Owner	19/05/2010	2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£40.45	5.00	Joint Owner	19/05/2010	2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£18.44	2.00	Joint Owner	19/05/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Joint Owner	19/05/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Joint Owner	19/05/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	28/01/2010	2010
EES07 200mm thick loft insulation	£52.00	5.00	Sole Property Owner	02/08/2010	2010
EES03a Remove and replace nailed floor board	£13.00	5.00	Sole Property Owner	02/08/2010	2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	02/08/2010	2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	02/08/2010	2010
EES66 Low energy lamp replacement	£0.00	14.00	Sole Property Owner	13/01/2012	2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	13/01/2012	2012
EES15 Insulation to 65mm wide cavity wall	£262.50	35.00	Sole Property Owner	13/01/2012	2012
EES66 Low energy lamp replacement	£0.00	6.00	Sole Property Owner	13/01/2012	2012
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	13/01/2012	2012
EES50c Replacement electrical storage heater	£411.00	1.00	Sole Property Owner	26/01/2012	2012
EES50c Replacement electrical storage heater	£475.00	1.00	Sole Property Owner	26/01/2012	2012
EES44 Water heating time clock and boost	£108.48	1.00	Sole Property Owner	26/01/2012	2012
EES34 Replacement hot water cylinder (170l)	£880.00	1.00	Sole Property Owner	26/01/2012	2012

EES70 Miscellaneous heating review charge	£635.49	1.00	Sole Property Owner	26/01/2012	2012
EES07 200mm thick loft insulation	£696.80	67.00	Sole Property Owner	26/01/2012	2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£16.18	2.00	Sole Property Owner	26/01/2012	2012
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	26/01/2012	2012
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	26/01/2012	2012
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	26/01/2012	2012
EES25 Draught stripping to exterior door	£60.00	6.00	Sole Property Owner	07/07/2010	2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	07/07/2010	2010
EES50c Replacement electrical storage heater	£262.79	1.00	Joint Owner	02/08/2012	
EES50c Replacement electrical storage heater	£822.00	2.00	Joint Owner	02/08/2012	
EES50c Replacement electrical storage heater	£436.00	1.00	Joint Owner	02/08/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	02/08/2012	
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	19/05/2010	
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	19/05/2010	
EES48 Pipework lagging 19mm thick to 22mm pipe	£18.44	2.00	Sole Property Owner	19/05/2010	
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	19/05/2010	
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	19/05/2010	
EES06 100mm thick loft insulation	£571.04	83.00	Sole Property Owner	05/08/2010	
EES09 Intumescent bag/fire hood to downlighter	£0.00	0.00	Sole Property Owner	05/08/2010	
EES36 Electrical room thermostat	£103.40	1.00	Sole Property Owner	05/08/2010	
EES38a Thermostatic radiator valve (per valve)	£396.00	9.00	Sole Property Owner	05/08/2010	
EES44 Water heating time clock and boost	£111.00	1.00	Sole Property Owner	05/08/2010	
EES66 Low energy lamp replacement	£7.00	4.00	Sole Property Owner	05/08/2010	
EES49 Pipework lagging 25mm thick to 22mm pipe	£46.10	5.00	Sole Property Owner	19/05/2010	
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	19/05/2010	
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	19/05/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	01/02/2010	
EES07 200mm thick loft insulation	£225.00	25.00	Sole Property Owner	02/08/2010	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	02/08/2010	
EES66 Low energy lamp replacement	£0.00	12.00	Sole Property Owner	02/08/2010	
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Sole Property Owner	02/08/2010	
EES16 Insulation to 75mm wide cavity wall	£708.00	80.00	Sole Property Owner	02/08/2010	
EES18a Cavity brush (per brush)	£80.00	10.00	Sole Property Owner	02/08/2010	
EES21 Scaffold	£328.00	32.00	Sole Property Owner	02/08/2010	
EES69 Miscellaneous Charge	£150.00	1.00	Sole Property Owner	02/08/2010	
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Sole Property Owner	02/08/2010	
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	02/08/2010	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	02/08/2010	
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	02/08/2010	
EES07 200mm thick loft insulation	£312.00	30.00	Sole Property Owner	02/08/2010	
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	02/08/2010	
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	02/08/2010	
EES47 Pipework lagging 13mm thick to 22mm pipe	£32.36	4.00	Sole Property Owner	02/08/2010	
EES48 Pipework lagging 19mm thick to 22mm pipe	£36.88	4.00	Sole Property Owner	02/08/2010	
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	02/08/2010	
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	02/08/2010	
EES01a Loft Clearance (hourly rate)	£175.00	7.00	Sole Property Owner	26/01/2011	
EES03a Remove and replace nailed floor board	£37.50	15.00	Sole Property Owner	26/01/2011	
EES08 300mm thick loft insulation	£912.00	76.00	Sole Property Owner	26/01/2011	
EES38a Thermostatic radiator valve (per valve)	£495.00	5.00	Sole Property Owner	26/01/2011	
EES69 Miscellaneous Charge	£70.00	2.00	Sole Property Owner	26/01/2011	
EES16 Insulation to 75mm wide cavity wall	£589.26	64.05	Sole Property Owner	26/01/2011	
EES66 Low energy lamp replacement	£56.85	5.00	Not The Property Owner	15/12/2009	
EES00a Full Energy Survey	£246.55	1.00	Not The Property Owner	15/12/2009	
EES15 Insulation to 65mm wide cavity wall	£508.65	67.82	Sole Property Owner	15/04/2010	
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Sole Property Owner	15/04/2010	
EES08 300mm thick loft insulation	£924.00	77.00	Sole Property Owner	15/04/2010	
EES13a Cold water tank bye law kit (including associated products)	£280.00	1.00	Sole Property Owner	15/04/2010	
EES38a Thermostatic radiator valve (per valve)	£300.00	5.00	Sole Property Owner	15/04/2010	
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Joint Owner	29/04/2010	
EES08 300mm thick loft insulation	£600.00	50.00	Joint Owner	29/04/2010	
EES08 300mm thick loft insulation	£1,008.00	84.00	Joint Owner	29/04/2010	
EES69 Miscellaneous Charge	£177.47	177.47	Joint Owner	29/04/2010	
EES69 Miscellaneous Charge	£11.50	11.50	Joint Owner	29/04/2010	
HES15 Draught stripping to exterior door	£21.00	7.00	Joint Owner	29/04/2010	
HES16 Draught stripping to windows	£75.00	25.00	Joint Owner	29/04/2010	
EES69 Miscellaneous Charge	£3.03	3.03	Joint Owner	29/04/2010	
HES01 Loft preparation labour (clearance, disposal of old insulation)	£162.50	6.50	Joint Owner	29/04/2010	
HES08 Other insulation works (e.g. rafters, garages, floors) for EE	£0.00	0.00	Joint Owner	29/04/2010	
HES66 15mm thick pipework lagging	£0.00	0.00	Joint Owner	29/04/2010	
EES08 300mm thick loft insulation	£1,008.00	84.00	Joint Owner	25/01/2010	
EES12 Cold water tank lid	£280.00	1.00	Joint Owner	25/01/2010	
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Sole Property Owner	26/01/2011	
EES02a Remove and dispose existing insulation (per square metre)	£20.00	8.00	Sole Property Owner	26/01/2011	
EES08 300mm thick loft insulation	£540.00	45.00	Sole Property Owner	26/01/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	13/01/2010	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	18/10/2012	
EES53a 26-35kW Oil replacement boiler	£4,500.00	1.00	Sole Property Owner	18/10/2012	
EES69 Miscellaneous Charge	£575.00	1.00	Sole Property Owner	18/10/2012	
EES42 Two channel programmable heating controller	£0.00	1.00	Sole Property Owner	18/10/2012	
EES02a Remove and dispose existing insulation (per square metre)	£135.00	45.00	Sole Property Owner	18/10/2012	
EES08 300mm thick loft insulation	£540.00	45.00	Sole Property Owner	18/10/2012	
EES38a Thermostatic radiator valve (per valve)	£341.25	7.00	Sole Property Owner	18/10/2012	
EES00 Property Assessment	£185.00	1.00	Sole Property Owner	18/10/2012	

EES69 Miscellaneous Charge	£668.00	1.00	Sole Property Owner	18/10/2012	
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	18/10/2012	
EES69 Miscellaneous Charge	£575.00	1.00	Sole Property Owner	18/10/2012	
EES70 Miscellaneous heating review charge	£1,036.12	1.00	Sole Property Owner	26/01/2012	
EES44 Water heating time clock and boost	£108.48	1.00	Sole Property Owner	26/01/2012	
EES50c Replacement electrical storage heater	£411.00	1.00	Sole Property Owner	26/01/2012	
EES50c Replacement electrical storage heater	£475.00	1.00	Sole Property Owner	26/01/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	26/01/2012	
EES51a 16-20kW Oil replacement boiler	£2,900.00	1.00	Sole Property Owner	29/04/2010	
EES70 Miscellaneous heating review charge	£605.00	605.00	Sole Property Owner	29/04/2010	
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	29/04/2010	
EES07 200mm thick loft insulation	£279.00	31.00	Sole Property Owner	29/04/2010	
EES12 Cold water tank lid	£560.00	2.00	Sole Property Owner	29/04/2010	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	29/04/2010	
EES69 Miscellaneous Charge	£80.00	1.00	Sole Property Owner	29/04/2010	
EES38a Thermostatic radiator valve (per valve)	£682.50	14.00	Sole Property Owner	29/04/2010	
EES69 Miscellaneous Charge	£60.00	1.00	Sole Property Owner	29/04/2010	
EES00 Property Assessment	£185.00	1.00	Sole Property Owner	29/04/2010	
EES69 Miscellaneous Charge	£1,874.15	1.00	Sole Property Owner	29/04/2010	
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	29/04/2010	
EES70 Miscellaneous heating review charge	£140.00	1.00	Sole Property Owner	29/04/2010	
EES12 Cold water tank lid	£280.00	1.00	Joint Owner	15/04/2010	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Joint Owner	15/04/2010	
EES47 Pipework lagging 13mm thick to 22mm pipe	£42.00	6.00	Joint Owner	15/04/2010	
EES16 Insulation to 75mm wide cavity wall	£0.00	0.00	Sole Property Owner	16/11/2011	
EES52a 21-25kW Oil replacement boiler	£3,083.00	1.00	Sole Property Owner	16/11/2011	
EES70 Miscellaneous heating review charge	£392.00	1.00	Sole Property Owner	16/11/2011	
EES70 Miscellaneous heating review charge	£2,367.18	1.00	Sole Property Owner	16/11/2011	
EES66 Low energy lamp replacement	£261.51	23.00	Sole Property Owner	16/11/2011	
EES00 Property Assessment	£185.00	1.00	Sole Property Owner	16/11/2011	
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	16/11/2011	
HES90 Other miscellaneous oil heating works for EES approval	£210.00	1.00	Sole Property Owner	16/11/2011	
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	16/11/2011	
EES69 Miscellaneous Charge	£375.00	1.00	Sole Property Owner	16/11/2011	
EES08 300mm thick loft insulation	£540.00	45.00	Sole Property Owner	25/01/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	28/01/2010	
EES48 Pipework lagging 19mm thick to 22mm pipe	£6.54	6.00	Not The Property Owner	28/01/2010	
EES75 HEC to Flat or Bedsit	£180.00	1.00	Sole Property Owner	01/10/2010	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	01/10/2010	
EES15 Insulation to 65mm wide cavity wall	£844.28	112.57	Joint Owner	15/04/2010	
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Joint Owner	15/04/2010	
EES03a Remove and replace nailed floor board	£25.00	10.00	Joint Owner	15/04/2010	
EES08 300mm thick loft insulation	£540.00	45.00	Joint Owner	15/04/2010	
EES67 Smoke detector installation	£8.05	1.00	Sole Property Owner	30/03/2010	
EES01a Loft Clearance (hourly rate)	£63.25	1.00	Sole Property Owner	30/03/2010	
EES03a Remove and replace nailed floor board	£424.80	36.00	Sole Property Owner	30/03/2010	
EES02a Remove and dispose existing insulation (per square metre)	£155.40	37.00	Sole Property Owner	30/03/2010	
EES07 200mm thick loft insulation	£694.98	78.00	Sole Property Owner	30/03/2010	
EES06 100mm thick loft insulation	£254.56	37.00	Sole Property Owner	30/03/2010	
EES10 Cold water tank insulation quilt	£69.45	1.00	Sole Property Owner	30/03/2010	
EES81 Insulation to 50mm cavity	£1,380.00	200.00	Sole Property Owner	30/03/2010	
EES22 Mastic pointing	£11.70	3.00	Sole Property Owner	30/03/2010	
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	30/03/2010	
EES38a Thermostatic radiator valve (per valve)	£308.00	7.00	Sole Property Owner	30/03/2010	
EES66 Low energy lamp replacement	£15.75	1.00	Sole Property Owner	30/03/2010	
EES68 Minimum charge for lamps and detectors	£100.00	1.00	Not The Property Owner	10/12/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	10/12/2010	
EES01a Loft Clearance (hourly rate)	£126.50	2.00	Joint Owner	30/03/2010	
EES03a Remove and replace nailed floor board	£118.00	10.00	Joint Owner	30/03/2010	
EES07 200mm thick loft insulation	£249.48	28.00	Joint Owner	30/03/2010	
EES06 100mm thick loft insulation	£261.44	38.00	Joint Owner	30/03/2010	
EES66 Low energy lamp replacement	£31.50	18.00	Joint Owner	30/03/2010	
EES67 Smoke detector installation	£1.75	1.00	Joint Owner	30/03/2010	
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00		20/11/2010	
EES68 Minimum charge for lamps and detectors	£50.00	1.00		20/11/2010	
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Not The Property Owner	29/04/2010	
EES08 300mm thick loft insulation	£600.00	50.00	Not The Property Owner	29/04/2010	
EES12 Cold water tank lid	£280.00	1.00	Not The Property Owner	29/04/2010	
EES 30 Hot water cylinder jacket (46x18 inch)	£200.00	2.00	Not The Property Owner	29/04/2010	
EES69 Miscellaneous Charge	£70.34	1.00	Not The Property Owner	29/04/2010	
EES69 Miscellaneous Charge	£9.66	1.00	Not The Property Owner	29/04/2010	
EES01a Loft Clearance (hourly rate)	£126.50	2.00	Not The Property Owner	15/04/2010	
EES03a Remove and replace nailed floor board	£466.10	39.50	Not The Property Owner	15/04/2010	
EES07 200mm thick loft insulation	£351.95	39.50	Not The Property Owner	15/04/2010	
EES10 Cold water tank insulation quilt	£37.42	1.00	Not The Property Owner	15/04/2010	
EES 11 Cold water tank insulation jacket	£32.03	1.00	Not The Property Owner	15/04/2010	
EES21 Scaffold	£305.90	38.00	Not The Property Owner	15/04/2010	
EES69 Miscellaneous Charge	£42.00	10.00	Not The Property Owner	15/04/2010	
EES15 Insulation to 65mm wide cavity wall	£584.30	75.20	Not The Property Owner	15/04/2010	
EES69 Miscellaneous Charge	£36.40	4.00	Not The Property Owner	15/04/2010	
EES36 Electrical room thermostat	£103.40	1.00	Not The Property Owner	15/04/2010	
EES38a Thermostatic radiator valve (per valve)	£528.00	12.00	Not The Property Owner	15/04/2010	
EES42 Two channel programmable heating controller	£111.00	1.00	Not The Property Owner	15/04/2010	
EES48 Pipework lagging 19mm thick to 22mm pipe	£32.72	4.00	Not The Property Owner	15/04/2010	

EES47 Pipework lagging 13mm thick to 22mm pipe	£29.68	4.00	Not The Property Owner	15/04/2010
EES66 Low energy lamp replacement	£33.25	19.00	Not The Property Owner	15/04/2010
EES67 Smoke detector installation	£3.50	2.00	Not The Property Owner	15/04/2010
EES01a Loft Clearance (hourly rate)	£280.80	6.00	Sole Property Owner	16/12/2011
EES08 300mm thick loft insulation	£413.08	46.00	Sole Property Owner	16/12/2011
EES10 Cold water tank insulation quilt	£64.59	1.00	Sole Property Owner	16/12/2011
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	16/12/2011
EES66 Low energy lamp replacement	£113.70	10.00	Sole Property Owner	16/12/2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	16/12/2011
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	16/12/2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	28/01/2010
EES53a 26-35kW Oil replacement boiler	£3,265.00	1.00	Sole Property Owner	05/08/2011
EES70 Miscellaneous heating review charge	£229.87	1.00	Sole Property Owner	05/08/2011
EES07 200mm thick loft insulation	£8.91	1.00	Sole Property Owner	05/08/2011
EES69 Miscellaneous Charge	£35.66	1.00	Sole Property Owner	05/08/2011
EES69 Miscellaneous Charge	£30.74	1.00	Sole Property Owner	05/08/2011
EES38a Thermostatic radiator valve (per valve)	£220.00	5.00	Sole Property Owner	05/08/2011
EES42 Two channel programmable heating controller	£111.00	1.00	Sole Property Owner	05/08/2011
EES44 Water heating time clock and boost	£111.00	1.00	Sole Property Owner	05/08/2011
EES66 Low energy lamp replacement	£43.75	25.00	Sole Property Owner	05/08/2011
EES70 Miscellaneous heating review charge	£212.73	1.00	Sole Property Owner	05/08/2011
EES38a Thermostatic radiator valve (per valve)	£44.00	1.00	Sole Property Owner	05/08/2011
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	05/08/2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£32.72	4.00	Joint Owner	30/03/2010
EES66 Low energy lamp replacement	£28.00	16.00	Joint Owner	30/03/2010
EES67 Smoke detector installation	£1.75	1.00	Joint Owner	30/03/2010
EES25 Draught stripping to exterior door	£91.00	10.00	Sole Property Owner	30/03/2010
EES69 Miscellaneous Charge	£44.40	2.00	Sole Property Owner	30/03/2010
EES66 Low energy lamp replacement	£26.25	15.00	Sole Property Owner	30/03/2010
EES01a Loft Clearance (hourly rate)	£175.00	7.00	Not The Property Owner	29/04/2010
EES03a Remove and replace nailed floor board	£75.00	30.00	Not The Property Owner	29/04/2010
EES08 300mm thick loft insulation	£492.00	41.00	Not The Property Owner	29/04/2010
EES38a Thermostatic radiator valve (per valve)	£495.00	10.00	Not The Property Owner	29/04/2010
EES02a Remove and dispose existing insulation (per squire metre)	£90.00	30.00	Not The Property Owner	29/04/2010
EES01a Loft Clearance (hourly rate)	£253.00	4.00	Joint Owner	30/03/2010
EES03a Remove and replace nailed floor board	£259.60	22.00	Joint Owner	30/03/2010
EES07 200mm thick loft insulation	£810.81	91.00	Joint Owner	30/03/2010
EES69 Miscellaneous Charge	£212.50	10.00	Joint Owner	30/03/2010
EES10 Cold water tank insulation quilt	£37.42	1.00	Joint Owner	30/03/2010
EES15 Insulation to 65mm wide cavity wall	£786.60	114.00	Joint Owner	30/03/2010
EES36 Electrical room thermostat	£103.40	1.00	Joint Owner	30/03/2010
EES38a Thermostatic radiator valve (per valve)	£440.00	10.00	Joint Owner	30/03/2010
EES42 Two channel programmable heating controller	£111.00	1.00	Joint Owner	30/03/2010
EES44 Water heating time clock and boost	£111.00	1.00	Joint Owner	30/03/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£40.90	5.00	Joint Owner	30/03/2010
EES66 Low energy lamp replacement	£21.00	12.00	Joint Owner	30/03/2010
EES67 Smoke detector installation	£1.75	1.00	Joint Owner	30/03/2010
HES52 Hot water cylinder thermostat	£33.21	1.00	Joint Owner	30/03/2010
HES68 28mm thick pipework lagging	£37.60	10.00	Joint Owner	30/03/2010
HES94 Heating engineer	£1,216.00	32.00	Joint Owner	30/03/2010
HES97 Electrician	£150.00	6.00	Joint Owner	30/03/2010
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	30/03/2010
HES33 26-35kW Oil replacement condensing boiler	£1,817.37	1.00	Joint Owner	30/03/2010
HES41 Condensate pipework (and pump if required)	£100.00	1.00	Joint Owner	30/03/2010
HES43 Central heating pump	£141.55	1.00	Joint Owner	30/03/2010
HES44 Pipework / feed modifications	£425.00	1.00	Joint Owner	30/03/2010
HES46 Automatic bypass	£46.32	1.00	Joint Owner	30/03/2010
HES49 Carbon Monoxide alarm	£0.00	0.00	Joint Owner	30/03/2010
HES50 Electrical room thermostat	£53.32	1.00	Joint Owner	30/03/2010
HES53 Two channel heating programmer control	£85.11	1.00	Joint Owner	30/03/2010
HES55 2 port zone valve	£138.56	2.00	Joint Owner	30/03/2010
HES40 Flue specification and location	£475.00	475.00	Joint Owner	30/03/2010
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	30/03/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	01/02/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	28/01/2010
EES25 Draught stripping to exterior door	£120.00	12.00	Sole Property Owner	14/02/2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	14/02/2012
EES66 Low energy lamp replacement	£30.00	2.00	Sole Property Owner	14/02/2012
EES50c Replacement electrical storage heater	£727.86	2.00	Sole Property Owner	14/02/2012
EES70 Miscellaneous heating review charge	£371.15	1.00	Sole Property Owner	14/02/2012
EES08 300mm thick loft insulation	£1,064.00	106.40	Sole Property Owner	24/12/2010
EES17 Insulation to 90mm wide cavity wall	£1,242.00	124.20	Sole Property Owner	24/12/2010
EES35 Replacement hot water cylinder (210l)	£1,320.00	1.00	Joint Owner	12/03/2012
EES33 Replacement hot water cylinder (150l)	£0.00	0.00	Joint Owner	12/03/2012
EES15 Insulation to 65mm wide cavity wall	£1,371.60	1,371.60	Joint Owner	12/03/2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	28/01/2010
EES07 200mm thick loft insulation	£356.40	40.00	Joint Owner	30/03/2010
EES06 100mm thick loft insulation	£275.20	40.00	Joint Owner	30/03/2010
EES10 Cold water tank insulation quilt	£37.42	1.00	Joint Owner	30/03/2010
EES69 Miscellaneous Charge	£36.40	4.00	Joint Owner	30/03/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£32.72	4.00	Joint Owner	30/03/2010
EES66 Low energy lamp replacement	£17.50	10.00	Joint Owner	30/03/2010
EES67 Smoke detector installation	£1.75	1.00	Joint Owner	30/03/2010
EES69 Miscellaneous Charge	£30.00	1.00	Joint Owner	30/03/2010

EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	02/08/2010
EES07 200mm thick loft insulation	£765.00	85.00	Sole Property Owner	02/08/2010
EES13a Cold water tank bye law kit (including associated products)	£560.00	2.00	Sole Property Owner	02/08/2010
EES25 Draught stripping to exterior door	£10.00	1.00	Sole Property Owner	02/08/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	01/06/2010
EES50c Replacement electrical storage heater	£822.00	2.00	Joint Owner	26/01/2012
EES25 Draught stripping to exterior door	£60.00	6.00	Joint Owner	26/01/2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	01/11/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	16/12/2009
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	16/12/2009
EES51b 16-20kW Gas replacement boiler	£2,694.77	1.00	Sole Property Owner	23/06/2011
EES42 Two channel programmable heating controller	£0.00	1.00	Sole Property Owner	23/06/2011
EES36 Electrical room thermostat	£0.00	1.00	Sole Property Owner	23/06/2011
EES40 Hot water cylinder thermostat	£0.00	1.00	Sole Property Owner	23/06/2011
EES01a Loft Clearance (hourly rate)	£187.20	4.00	Sole Property Owner	23/06/2011
EES08 300mm thick loft insulation	£305.32	34.00	Sole Property Owner	23/06/2011
EES15 Insulation to 65mm wide cavity wall	£299.60	40.00	Sole Property Owner	23/06/2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£48.54	6.00	Sole Property Owner	23/06/2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£110.64	12.00	Sole Property Owner	23/06/2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£85.62	6.00	Sole Property Owner	23/06/2011
EES66 Low energy lamp replacement	£125.07	11.00	Sole Property Owner	23/06/2011
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	23/06/2011
EES69 Miscellaneous Charge	£46.80	2.00	Sole Property Owner	23/06/2011
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	23/06/2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	23/06/2011
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	23/06/2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	23/06/2011
EES07 200mm thick loft insulation	£445.50	50.00	Joint Owner	24/03/2012
EES21 Scaffold	£805.00	100.00	Joint Owner	24/03/2012
EES19 Airbrick	£92.00	10.00	Joint Owner	24/03/2012
EES25 Draught stripping to exterior door	£45.50	5.00	Joint Owner	24/03/2012
EES69 Miscellaneous Charge	£36.40	4.00	Joint Owner	24/03/2012
EES34 Replacement hot water cylinder (170l)	£715.00	1.00	Joint Owner	24/03/2012
EES66 Low energy lamp replacement	£43.75	25.00	Joint Owner	24/03/2012
EES67 Smoke detector installation	£9.80	1.00	Joint Owner	24/03/2012
EES15 Insulation to 65mm wide cavity wall	£1,152.57	154.50	Joint Owner	24/03/2012
EES36 Electrical room thermostat	£103.40	1.00	Joint Owner	24/03/2012
EES70 Miscellaneous heating review charge	£201.00	1.00	Joint Owner	24/03/2012
EES51a 16-20kW Oil replacement boiler	£2,909.50	1.00	Joint Owner	24/03/2012
HES121 Boiler QA Check	£105.00	1.00	Joint Owner	24/03/2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	03/01/2010
EES69 Miscellaneous Charge	£50.00	1.00	Sole Property Owner	03/01/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	19/05/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£1.09	1.00	Not The Property Owner	19/05/2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£9.99	3.00	Not The Property Owner	19/05/2010
EES01a Loft Clearance (hourly rate)	£94.88	1.50	Sole Property Owner	30/03/2010
EES07 200mm thick loft insulation	£218.30	24.50	Sole Property Owner	30/03/2010
EES 11 Cold water tank insulation jacket	£37.42	1.00	Sole Property Owner	30/03/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£32.72	4.00	Sole Property Owner	30/03/2010
EES66 Low energy lamp replacement	£26.25	1.00	Sole Property Owner	30/03/2010
EES03a Remove and replace nailed floor board	£236.00	20.00	Sole Property Owner	30/03/2010
EES01a Loft Clearance (hourly rate)	£250.00	10.00	Sole Property Owner	02/08/2010
EES08 300mm thick loft insulation	£402.00	33.50	Sole Property Owner	02/08/2010
EES13a Cold water tank bye law kit (including associated products)	£280.00	1.00	Sole Property Owner	02/08/2010
EES25 Draught stripping to exterior door	£136.50	15.00	Not The Property Owner	15/04/2010
EES69 Miscellaneous Charge	£66.60	3.00	Not The Property Owner	15/04/2010
EES38a Thermostatic radiator valve (per valve)	£440.05	13.00	Not The Property Owner	15/04/2010
EES44 Water heating time clock and boost	£111.00	1.00	Not The Property Owner	15/04/2010
EES66 Low energy lamp replacement	£38.50	22.00	Not The Property Owner	15/04/2010
EES67 Smoke detector installation	£1.75	1.00	Not The Property Owner	15/04/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	13/02/2010
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Joint Owner	15/07/2011
EES03a Remove and replace nailed floor board	£150.00	60.00	Joint Owner	15/07/2011
EES08 300mm thick loft insulation	£540.00	60.00	Joint Owner	15/07/2011
EES13a Cold water tank bye law kit (including associated products)	£840.00	3.00	Joint Owner	15/07/2011
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Joint Owner	15/07/2011
EES69 Miscellaneous Charge	£0.00	0.00	Joint Owner	15/07/2011
HES120 Standard QA check	£90.00	1.00	Joint Owner	15/07/2011
EES25 Draught stripping to exterior door	£100.00	10.00	Not The Property Owner	10/02/2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	10/02/2011
EES01a Loft Clearance (hourly rate)	£253.00	4.00	Not The Property Owner	15/04/2010
EES03a Remove and replace nailed floor board	£778.80	66.00	Not The Property Owner	15/04/2010
EES02a Remove and dispose existing insulation (per square metre)	£102.90	24.50	Not The Property Owner	15/04/2010
EES07 200mm thick loft insulation	£1,226.91	137.70	Not The Property Owner	15/04/2010
EES10 Cold water tank insulation quilt	£37.42	1.00	Not The Property Owner	15/04/2010
EES25 Draught stripping to exterior door	£36.36	6.00	Not The Property Owner	15/04/2010
EES42 Two channel programmable heating controller	£111.00	1.00	Not The Property Owner	15/04/2010
EES66 Low energy lamp replacement	£47.25	27.00	Not The Property Owner	15/04/2010
EES09 Intumescent bag/fire hood to downlighter	£85.00	4.00	Not The Property Owner	15/04/2010
EES01a Loft Clearance (hourly rate)	£163.80	7.00	Sole Property Owner	01/11/2009
EES08 300mm thick loft insulation	£386.14	43.00	Sole Property Owner	01/11/2009
EES06 100mm thick loft insulation	£527.68	68.00	Sole Property Owner	01/11/2009
EES03a Remove and replace nailed floor board	£106.60	41.00	Sole Property Owner	01/11/2009
EES47 Pipework lagging 13mm thick to 22mm pipe	£97.08	12.00	Sole Property Owner	01/11/2009

EES48 Pipework lagging 19mm thick to 22mm pipe	£110.64	12.00	Sole Property Owner	01/11/2009
EES49 Pipework lagging 25mm thick to 22mm pipe	£28.54	2.00	Sole Property Owner	01/11/2009
EES15 Insulation to 65mm wide cavity wall	£689.08	92.00	Sole Property Owner	01/11/2009
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	01/11/2009
EES10 Cold water tank insulation quilt	£64.89	1.00	Sole Property Owner	01/11/2009
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	01/11/2009
EES66 Low energy lamp replacement	£125.07	11.00	Sole Property Owner	01/11/2009
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	01/11/2009
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	01/11/2009
EES21 Scaffold	£1,694.00	1.00	Not The Property Owner	29/01/2010
EES15 Insulation to 65mm wide cavity wall	£1,355.69	181.00	Not The Property Owner	29/01/2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£129.44	16.00	Not The Property Owner	29/01/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£184.40	20.00	Not The Property Owner	29/01/2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Not The Property Owner	29/01/2010
EES12 Cold water tank lid	£35.70	1.00	Not The Property Owner	29/01/2010
EES 11 Cold water tank insulation jacket	£51.12	1.00	Not The Property Owner	29/01/2010
EES12 Cold water tank lid	£23.46	1.00	Not The Property Owner	29/01/2010
EES66 Low energy lamp replacement	£250.14	22.00	Not The Property Owner	29/01/2010
EES69 Miscellaneous Charge	£41.00	1.00	Not The Property Owner	29/01/2010
EES69 Miscellaneous Charge	£112.50	1.00	Not The Property Owner	29/01/2010
EES00a Full Energy Survey	£246.55	1.00	Not The Property Owner	29/01/2010
EES07 200mm thick loft insulation	£445.50	50.00	Not The Property Owner	15/04/2010
EES36 Electrical room thermostat	£103.40	1.00	Not The Property Owner	15/04/2010
EES44 Water heating time clock and boost	£111.00	1.00	Not The Property Owner	15/04/2010
EES66 Low energy lamp replacement	£19.25	11.00	Not The Property Owner	15/04/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	15/03/2010
EES51b 16-20kW Gas replacement boiler	£2,969.29	1.00	Sole Property Owner	12/08/2011
EES36 Electrical room thermostat	£0.00	1.00	Sole Property Owner	12/08/2011
EES42 Two channel programmable heating controller	£0.00	1.00	Sole Property Owner	12/08/2011
EES01a Loft Clearance (hourly rate)	£31.63	1.00	Sole Property Owner	12/08/2011
EES07 200mm thick loft insulation	£436.59	49.00	Sole Property Owner	12/08/2011
EES21 Scaffold	£905.63	112.50	Sole Property Owner	12/08/2011
EES19 Airbrick	£18.40	2.00	Sole Property Owner	12/08/2011
EES15 Insulation to 65mm wide cavity wall	£1,404.00	195.00	Sole Property Owner	12/08/2011
EES69 Miscellaneous Charge	£36.40	4.00	Sole Property Owner	12/08/2011
EES66 Low energy lamp replacement	£29.75	17.00	Sole Property Owner	12/08/2011
EES67 Smoke detector installation	£9.80	1.00	Sole Property Owner	12/08/2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	12/08/2011
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Not The Property Owner	02/08/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	16/12/2009
EES01a Loft Clearance (hourly rate)	£253.00	4.00	Sole Property Owner	26/01/2011
EES03a Remove and replace nailed floor board	£391.76	33.20	Sole Property Owner	26/01/2011
EES07 200mm thick loft insulation	£230.86	25.91	Sole Property Owner	26/01/2011
EES10 Cold water tank insulation quilt	£74.84	2.00	Sole Property Owner	26/01/2011
EES33 Replacement hot water cylinder (150l)	£605.00	1.00	Sole Property Owner	26/01/2011
EES36 Electrical room thermostat	£103.40	1.00	Sole Property Owner	26/01/2011
EES66 Low energy lamp replacement	£7.00	4.00	Sole Property Owner	26/01/2011
EES07 200mm thick loft insulation	£64.95	7.29	Sole Property Owner	26/01/2011
EES19 Airbrick	£0.00	0.00	Not The Property Owner	15/04/2010
EES16 Insulation to 75mm wide cavity wall	£0.00	0.00	Not The Property Owner	15/04/2010
EES36 Electrical room thermostat	£103.40	1.00	Not The Property Owner	15/04/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£40.90	5.00	Not The Property Owner	15/04/2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£14.84	2.00	Not The Property Owner	15/04/2010
EES66 Low energy lamp replacement	£28.00	16.00	Not The Property Owner	15/04/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	16/12/2009
EES38a Thermostatic radiator valve (per valve)	£301.00	7.00	Sole Property Owner	04/08/2011
EES51a 16-20kW Oil replacement boiler	£2,900.00	1.00	Sole Property Owner	04/08/2011
EES70 Miscellaneous heating review charge	£645.00	1.00	Sole Property Owner	04/08/2011
EES36 Electrical room thermostat	£105.00	1.00	Sole Property Owner	04/08/2011
EES69 Miscellaneous Charge	£0.00	1.00	Sole Property Owner	04/08/2011
EES15 Insulation to 65mm wide cavity wall	£682.50	91.00	Sole Property Owner	04/08/2011
EES66 Low energy lamp replacement	£0.00	17.00	Sole Property Owner	04/08/2011
EES00 Property Assessment	£185.00	1.00	Sole Property Owner	04/08/2011
EES69 Miscellaneous Charge	£1,081.14	1.00	Sole Property Owner	04/08/2011
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	04/08/2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	04/08/2011
EES50c Replacement electrical storage heater	£1,738.35	5.00	Sole Property Owner	26/01/2012
EES01a Loft Clearance (hourly rate)	£94.89	3.00	Sole Property Owner	26/01/2012
EES03a Remove and replace nailed floor board	£295.00	25.00	Sole Property Owner	26/01/2012
EES10 Cold water tank insulation quilt	£37.42	1.00	Sole Property Owner	26/01/2012
EES07 200mm thick loft insulation	£176.69	19.83	Sole Property Owner	26/01/2012
EES44 Water heating time clock and boost	£111.00	1.00	Sole Property Owner	26/01/2012
EES66 Low energy lamp replacement	£0.00	23.00	Sole Property Owner	26/01/2012
EES66 Low energy lamp replacement	£1.75	1.00	Sole Property Owner	26/01/2012
EES07 200mm thick loft insulation	£161.89	18.17	Sole Property Owner	26/01/2012
EES69 Miscellaneous Charge	£147.25	1.00	Sole Property Owner	26/01/2012
EES01a Loft Clearance (hourly rate)	£189.75	3.00	Sole Property Owner	30/03/2010
EES06 100mm thick loft insulation	£264.88	38.50	Sole Property Owner	30/03/2010
EES07 200mm thick loft insulation	£343.04	38.50	Sole Property Owner	30/03/2010
EES10 Cold water tank insulation quilt	£37.42	1.00	Sole Property Owner	30/03/2010
EES18a Cavity brush (per brush)	£42.00	10.00	Sole Property Owner	30/03/2010
EES20 Core vent	£54.00	1.00	Sole Property Owner	30/03/2010
EES15 Insulation to 65mm wide cavity wall	£652.75	87.50	Sole Property Owner	30/03/2010
EES66 Low energy lamp replacement	£29.75	17.00	Sole Property Owner	30/03/2010

EES67 Smoke detector installation	£3.50	2.00	Sole Property Owner	30/03/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	16/12/2009
EES48 Pipework lagging 19mm thick to 22mm pipe	£2.18	2.00	Not The Property Owner	16/12/2009
EES69 Miscellaneous Charge	£50.00	1.00	Sole Property Owner	30/03/2010
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	30/03/2010
EES26 Draught stripping to windows	£45.50	5.00	Sole Property Owner	30/03/2010
EES69 Miscellaneous Charge	£44.40	2.00	Sole Property Owner	30/03/2010
EES66 Low energy lamp replacement	£29.75	17.00	Sole Property Owner	30/03/2010
EES07 200mm thick loft insulation	£650.43	73.00	Sole Property Owner	30/03/2010
EES66 Low energy lamp replacement	£26.25	15.00	Sole Property Owner	30/03/2010
EES67 Smoke detector installation	£1.75	1.00	Sole Property Owner	30/03/2010
EES15 Insulation to 65mm wide cavity wall	£824.55	119.50	Sole Property Owner	30/03/2010
EES19 Airbrick	£9.20	1.00	Sole Property Owner	30/03/2010
EES33 Replacement hot water cylinder (150l)	£715.00	1.00	Sole Property Owner	30/03/2010
EES36 Electrical room thermostat	£103.40	1.00	Sole Property Owner	30/03/2010
EES38a Thermostatic radiator valve (per valve)	£352.00	8.00	Sole Property Owner	30/03/2010
EES42 Two channel programmable heating controller	£111.00	1.00	Sole Property Owner	30/03/2010
EES44 Water heating time clock and boost	£111.00	1.00	Sole Property Owner	30/03/2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£154.00	22.00	Sole Property Owner	30/03/2010
EES10 Cold water tank insulation quilt	£0.00	0.00	Sole Property Owner	30/03/2010
EES 11 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	30/03/2010
EES12 Cold water tank lid	£0.00	0.00	Sole Property Owner	30/03/2010
EES13a Cold water tank bye law kit (including associated product)	£0.00	0.00	Sole Property Owner	30/03/2010
EES36 Electrical room thermostat	£0.00	0.00	Sole Property Owner	30/03/2010
EES40 Hot water cylinder thermostat	£0.00	0.00	Sole Property Owner	30/03/2010
EES52a 21-25kW Oil replacement boiler	£6,047.60	6,047.60	Sole Property Owner	30/03/2010
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	30/03/2010
EES08 300mm thick loft insulation	£2,496.00	208.00	Not The Property Owner	29/04/2010
EES69 Miscellaneous Charge	£4.00	1.00	Not The Property Owner	29/04/2010
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Joint Owner	15/04/2010
EES08 300mm thick loft insulation	£360.00	30.00	Joint Owner	15/04/2010
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Joint Owner	15/04/2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£70.00	10.00	Joint Owner	15/04/2010
EES01a Loft Clearance (hourly rate)	£126.50	2.00	Sole Property Owner	30/03/2010
EES03a Remove and replace nailed floor board	£1,004.18	85.10	Sole Property Owner	30/03/2010
EES07 200mm thick loft insulation	£758.24	85.10	Sole Property Owner	30/03/2010
EES10 Cold water tank insulation quilt	£37.42	1.00	Sole Property Owner	30/03/2010
EES 11 Cold water tank insulation jacket	£32.03	1.00	Sole Property Owner	30/03/2010
EES36 Electrical room thermostat	£103.40	1.00	Sole Property Owner	30/03/2010
EES38a Thermostatic radiator valve (per valve)	£484.00	11.00	Sole Property Owner	30/03/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£163.60	20.00	Sole Property Owner	30/03/2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£148.40	20.00	Sole Property Owner	30/03/2010
EES66 Low energy lamp replacement	£36.75	21.00	Sole Property Owner	30/03/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	13/02/2010
EES01a Loft Clearance (hourly rate)	£31.63	1.00	Not The Property Owner	15/04/2010
EES07 200mm thick loft insulation	£101.57	11.40	Not The Property Owner	15/04/2010
EES10 Cold water tank insulation quilt	£37.42	1.00	Not The Property Owner	15/04/2010
EES25 Draught stripping to exterior door	£45.50	5.00	Not The Property Owner	15/04/2010
EES26 Draught stripping to windows	£72.80	8.00	Not The Property Owner	15/04/2010
EES27 Draught stripping to letterbox	£22.20	1.00	Not The Property Owner	15/04/2010
EES69 Miscellaneous Charge	£44.40	2.00	Not The Property Owner	15/04/2010
EES36 Electrical room thermostat	£103.40	1.00	Not The Property Owner	15/04/2010
EES38a Thermostatic radiator valve (per valve)	£308.00	7.00	Not The Property Owner	15/04/2010
EES66 Low energy lamp replacement	£12.25	7.00	Not The Property Owner	15/04/2010
EES15 Insulation to 65mm wide cavity wall	£149.25	19.90	Sole Property Owner	10/02/2012
EES33 Replacement hot water cylinder (150l)	£880.00	1.00	Sole Property Owner	10/02/2012
EES01a Loft Clearance (hourly rate)	£575.00	23.00	Sole Property Owner	10/02/2012
EES03a Remove and replace nailed floor board	£65.00	26.00	Sole Property Owner	10/02/2012
EES08 300mm thick loft insulation	£540.00	45.00	Sole Property Owner	10/02/2012
EES21 Scaffold	£1,207.50	150.00	Sole Property Owner	30/03/2010
EES15 Insulation to 65mm wide cavity wall	£1,274.17	170.80	Sole Property Owner	30/03/2010
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	30/03/2010
EES36 Electrical room thermostat	£220.00	1.00	Sole Property Owner	30/03/2010
EES66 Low energy lamp replacement	£92.75	53.00	Sole Property Owner	30/03/2010
EES67 Smoke detector installation	£1.75	1.00	Sole Property Owner	30/03/2010
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	15/04/2010
EES08 300mm thick loft insulation	£288.00	24.00	Sole Property Owner	15/04/2010
EES25 Draught stripping to exterior door	£70.00	7.00	Sole Property Owner	15/04/2010
EES01a Loft Clearance (hourly rate)	£126.50	2.00	Not The Property Owner	04/05/2010
EES06 100mm thick loft insulation	£137.60	20.00	Not The Property Owner	04/05/2010
EES15 Insulation to 65mm wide cavity wall	£1,380.00	200.00	Not The Property Owner	04/05/2010
EES25 Draught stripping to exterior door	£136.50	15.00	Not The Property Owner	04/05/2010
EES26 Draught stripping to windows	£54.60	6.00	Not The Property Owner	04/05/2010
EES27 Draught stripping to letterbox	£44.40	2.00	Not The Property Owner	04/05/2010
EES34 Replacement hot water cylinder (170l)	£715.00	1.00	Not The Property Owner	04/05/2010
EES36 Electrical room thermostat	£101.40	1.00	Not The Property Owner	04/05/2010
EES66 Low energy lamp replacement	£26.25	15.00	Not The Property Owner	04/05/2010
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Joint Owner	29/04/2010
EES03a Remove and replace nailed floor board	£25.00	10.00	Joint Owner	29/04/2010
EES02a Remove and dispose existing insulation (per square metre)	£186.00	62.00	Joint Owner	29/04/2010
EES08 300mm thick loft insulation	£744.00	62.00	Joint Owner	29/04/2010
EES27 Draught stripping to letterbox	£80.00	2.00	Joint Owner	29/04/2010
EES 30 Hot water cylinder jacket (46x18 inch)	£200.00	2.00	Joint Owner	29/04/2010
EES25 Draught stripping to exterior door	£60.00	6.00	Sole Property Owner	02/08/2010

EES27 Draught stripping to letterbox	£40.00	1.00	Sole Property Owner	02/08/2010	
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Sole Property Owner	02/08/2010	
EES40 Hot water cylinder thermostat	£60.19	1.00	Sole Property Owner	16/10/2011	
EES21 Scaffold	£1,265.32	1.00	Sole Property Owner	16/10/2011	
EES01a Loft Clearance (hourly rate)	£126.50	2.00	Sole Property Owner	16/10/2011	
EES03a Remove and replace nailed floor board	£454.30	38.50	Sole Property Owner	16/10/2011	
EES07 200mm thick loft insulation	£343.04	38.50	Sole Property Owner	16/10/2011	
EES10 Cold water tank insulation quilt	£32.03	1.00	Sole Property Owner	16/10/2011	
EES69 Miscellaneous Charge	£30.00	1.00	Sole Property Owner	16/10/2011	
EES21 Scaffold	£603.75	75.00	Sole Property Owner	16/10/2011	
EES19 Airbrick	£64.40	7.00	Sole Property Owner	16/10/2011	
EES18a Cavity brush (per brush)	£42.00	10.00	Sole Property Owner	16/10/2011	
EES15 Insulation to 65mm wide cavity wall	£649.77	87.10	Sole Property Owner	16/10/2011	
EES38a Thermostatic radiator valve (per valve)	£308.00	7.00	Sole Property Owner	16/10/2011	
EES42 Two channel programmable heating controller	£111.00	1.00	Sole Property Owner	16/10/2011	
EES44 Water heating time clock and boost	£111.00	1.00	Sole Property Owner	16/10/2011	
EES48 Pipework lagging 19mm thick to 22mm pipe	£16.36	2.00	Sole Property Owner	16/10/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£29.68	4.00	Sole Property Owner	16/10/2011	
EES66 Low energy lamp replacement	£22.75	13.00	Sole Property Owner	16/10/2011	
EES36 Electrical room thermostat	£61.60	1.00	Sole Property Owner	16/10/2011	
EES42 Two channel programmable heating controller	£139.50	1.00	Sole Property Owner	16/10/2011	
EES70 Miscellaneous heating review charge	£444.45	1.00	Sole Property Owner	16/10/2011	
EES53a 26-35kW Oil replacement boiler	£2,684.52	1.00	Sole Property Owner	16/10/2011	
EES70 Miscellaneous heating review charge	£1,137.63	1.00	Sole Property Owner	16/10/2011	
HES85 Building Control Officer inspection undertaken	£103.85	1.00	Sole Property Owner	16/10/2011	
EES50c Replacement electrical storage heater	£262.79	1.00	Joint Owner	26/01/2012	
EES50c Replacement electrical storage heater	£475.00	1.00	Joint Owner	26/01/2012	
EES70 Miscellaneous heating review charge	£322.45	1.00	Joint Owner	26/01/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	26/01/2012	
EES66 Low energy lamp replacement	£250.14	22.00	Sole Property Owner	15/12/2009	
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	15/12/2009	
EES25 Draught stripping to exterior door	£60.00	6.00	Sole Property Owner	02/08/2012	
EES70 Miscellaneous heating review charge	£1,033.25	1.00	Sole Property Owner	02/08/2012	
EES50c Replacement electrical storage heater	£262.79	1.00	Sole Property Owner	02/08/2012	
EES50c Replacement electrical storage heater	£414.00	2.00	Sole Property Owner	02/08/2012	
EES50c Replacement electrical storage heater	£475.00	1.00	Sole Property Owner	02/08/2012	
EES44 Water heating time clock and boost	£108.48	1.00	Sole Property Owner	02/08/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	02/08/2012	
EES27 Draught stripping to letterbox	£40.00	1.00	Sole Property Owner	02/08/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	16/12/2009	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	28/01/2010	
EES06 100mm thick loft insulation	£391.50	50.00	Not The Property Owner	15/04/2010	
EES07 200mm thick loft insulation	£329.67	37.00	Not The Property Owner	15/04/2010	
EES10 Cold water tank insulation quilt	£37.42	1.00	Not The Property Owner	15/04/2010	
EES69 Miscellaneous Charge	£30.00	1.00	Not The Property Owner	15/04/2010	
EES21 Scaffold	£805.00	100.00	Not The Property Owner	15/04/2010	
EES16 Insulation to 75mm wide cavity wall	£1,223.60	152.00	Not The Property Owner	15/04/2010	
EES25 Draught stripping to exterior door	£136.50	15.00	Not The Property Owner	15/04/2010	
EES27 Draught stripping to letterbox	£22.20	1.00	Not The Property Owner	15/04/2010	
EES69 Miscellaneous Charge	£36.40	4.00	Not The Property Owner	15/04/2010	
EES69 Miscellaneous Charge	£66.60	3.00	Not The Property Owner	15/04/2010	
EES36 Electrical room thermostat	£446.16	1.00	Not The Property Owner	15/04/2010	
EES44 Water heating time clock and boost	£111.00	1.00	Not The Property Owner	15/04/2010	
EES47 Pipework lagging 13mm thick to 22mm pipe	£14.84	2.00	Not The Property Owner	15/04/2010	
EES66 Low energy lamp replacement	£68.25	39.00	Not The Property Owner	15/04/2010	
EES67 Smoke detector installation	£9.80	1.00	Not The Property Owner	15/04/2010	
EES01a Loft Clearance (hourly rate)	£63.25	1.00	Joint Owner	30/03/2010	
EES03a Remove and replace nailed floor board	£231.28	19.60	Joint Owner	30/03/2010	
EES07 200mm thick loft insulation	£576.48	64.70	Joint Owner	30/03/2010	
EES06 100mm thick loft insulation	£247.68	36.00	Joint Owner	30/03/2010	
EES10 Cold water tank insulation quilt	£37.42	1.00	Joint Owner	30/03/2010	
EES69 Miscellaneous Charge	£30.00	1.00	Joint Owner	30/03/2010	
EES25 Draught stripping to exterior door	£45.50	5.00	Joint Owner	30/03/2010	
EES69 Miscellaneous Charge	£22.20	1.00	Joint Owner	30/03/2010	
EES33 Replacement hot water cylinder (150l)	£605.00	1.00	Joint Owner	30/03/2010	
EES38a Thermostatic radiator valve (per valve)	£704.00	16.00	Joint Owner	30/03/2010	
EES40 Hot water cylinder thermostat	£74.70	1.00	Joint Owner	30/03/2010	
EES42 Two channel programmable heating controller	£111.00	1.00	Joint Owner	30/03/2010	
EES66 Low energy lamp replacement	£40.25	23.00	Joint Owner	30/03/2010	
EES67 Smoke detector installation	£3.50	2.00	Joint Owner	30/03/2010	
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Not The Property Owner	15/04/2010	
EES03a Remove and replace nailed floor board	£87.50	35.00	Not The Property Owner	15/04/2010	
EES02a Remove and dispose existing insulation (per squire metre)	£174.00	58.00	Not The Property Owner	15/04/2010	
EES08 300mm thick loft insulation	£696.00	58.00	Not The Property Owner	15/04/2010	
EES13a Cold water tank bye law kit (including associated products)	£280.00	1.00	Not The Property Owner	15/04/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	28/01/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	28/01/2009	
EES51b 16-20kW Gas replacement boiler	£1,730.61	1.00	Joint Owner	02/08/2011	
EES70 Miscellaneous heating review charge	£155.69	155.69	Joint Owner	02/08/2011	
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Joint Owner	02/08/2011	
EES02a Remove and dispose existing insulation (per squire metre)	£180.00	60.00	Joint Owner	02/08/2011	
EES08 300mm thick loft insulation	£720.00	60.00	Joint Owner	02/08/2011	
HES85 Building Control Officer inspection undertaken	£103.85	1.00	Joint Owner	02/08/2011	
EES29 Hot water cylinder jacket (30x18 inch)	£100.00	1.00	Sole Property Owner	05/07/2011	

EES26 Draught stripping to windows	£0.00	0.00	Sole Property Owner	05/07/2011	
EES66 Low energy lamp replacement	£0.00	11.00	Sole Property Owner	05/07/2011	
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	05/07/2011	
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	05/07/2011	
EES06 100mm thick loft insulation	£379.78	55.20	Sole Property Owner	30/03/2010	
EES07 200mm thick loft insulation	£491.83	55.20	Sole Property Owner	30/03/2010	
EES10 Cold water tank insulation quilt	£32.03	1.00	Sole Property Owner	30/03/2010	
EES 11 Cold water tank insulation jacket	£37.42	1.00	Sole Property Owner	30/03/2010	
EES69 Miscellaneous Charge	£30.00	1.00	Sole Property Owner	30/03/2010	
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	30/03/2010	
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	30/03/2010	
EES69 Miscellaneous Charge	£36.40	4.00	Sole Property Owner	30/03/2010	
EES69 Miscellaneous Charge	£22.20	1.00	Sole Property Owner	30/03/2010	
EES48 Pipework lagging 19mm thick to 22mm pipe	£163.60	20.00	Sole Property Owner	30/03/2010	
EES66 Low energy lamp replacement	£19.25	11.00	Sole Property Owner	30/03/2010	
EES25 Draught stripping to exterior door	£45.50	5.00	Joint Owner	30/03/2010	
EES26 Draught stripping to windows	£45.50	5.00	Joint Owner	30/03/2010	
EES27 Draught stripping to letterbox	£22.20	1.00	Joint Owner	30/03/2010	
EES69 Miscellaneous Charge	£22.20	1.00	Joint Owner	30/03/2010	
EES66 Low energy lamp replacement	£15.75	9.00	Joint Owner	30/03/2010	
EES67 Smoke detector installation	£3.50	2.00	Joint Owner	30/03/2010	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	15/08/2010	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Joint Owner	02/08/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	28/01/2010	
EES01a Loft Clearance (hourly rate)	£94.88	1.50	Joint Owner	30/03/2010	
EES02a Remove and dispose existing insulation (per squire metre)	£102.90	24.50	Joint Owner	30/03/2010	
EES07 200mm thick loft insulation	£593.41	66.60	Joint Owner	30/03/2010	
EES06 100mm thick loft insulation	£168.56	24.50	Joint Owner	30/03/2010	
EES09 Intumescent bag/fire hood to downlighter	£191.25	9.00	Joint Owner	30/03/2010	
EES26 Draught stripping to windows	£45.50	5.00	Joint Owner	30/03/2010	
EES69 Miscellaneous Charge	£18.20	2.00	Joint Owner	30/03/2010	
EES69 Miscellaneous Charge	£22.20	1.00	Joint Owner	30/03/2010	
EES38a Thermostatic radiator valve (per valve)	£440.00	10.00	Joint Owner	30/03/2010	
EES42 Two channel programmable heating controller	£111.00	1.00	Joint Owner	30/03/2010	
EES48 Pipework lagging 19mm thick to 22mm pipe	£32.72	4.00	Joint Owner	30/03/2010	
EES66 Low energy lamp replacement	£36.75	21.00	Joint Owner	30/03/2010	
EES67 Smoke detector installation	£19.60	2.00	Joint Owner	30/03/2010	
EES10 Cold water tank insulation quilt	£32.03	1.00	Joint Owner	30/03/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	13/01/2009	
EES50c Replacement electrical storage heater	£262.79	1.00	Sole Property Owner	26/01/2012	
EES50c Replacement electrical storage heater	£822.00	2.00	Sole Property Owner	26/01/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	26/01/2012	
EES09 Intumescent bag/fire hood to downlighter	£0.00	0.00	Sole Property Owner	26/01/2012	
EES 11 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	26/01/2012	
EES15 Insulation to 65mm wide cavity wall	£578.90	70.00	Sole Property Owner	26/01/2012	
EES18a Cavity brush (per brush)	£80.00	10.00	Sole Property Owner	26/01/2012	
EES48 Pipework lagging 19mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	26/01/2012	
EES66 Low energy lamp replacement	£63.00	1.00	Sole Property Owner	26/01/2012	
EES67 Smoke detector installation	£9.80	1.00	Sole Property Owner	26/01/2012	
EES69 Miscellaneous Charge	£712.68	712.68	Sole Property Owner	26/01/2012	
EES01a Loft Clearance (hourly rate)	£63.25	1.00	Sole Property Owner	30/03/2010	
EES03a Remove and replace nailed floor board	£47.20	4.00	Sole Property Owner	30/03/2010	
EES02a Remove and dispose existing insulation (per squire metre)	£189.42	45.10	Sole Property Owner	30/03/2010	
EES07 200mm thick loft insulation	£401.84	45.10	Sole Property Owner	30/03/2010	
EES06 100mm thick loft insulation	£310.29	45.10	Sole Property Owner	30/03/2010	
EES 11 Cold water tank insulation jacket	£37.42	1.00	Sole Property Owner	30/03/2010	
EES10 Cold water tank insulation quilt	£32.03	1.00	Sole Property Owner	30/03/2010	
EES36 Electrical room thermostat	£103.40	1.00	Sole Property Owner	30/03/2010	
EES38a Thermostatic radiator valve (per valve)	£220.00	5.00	Sole Property Owner	30/03/2010	
EES44 Water heating time clock and boost	£111.00	1.00	Sole Property Owner	30/03/2010	
EES48 Pipework lagging 19mm thick to 22mm pipe	£49.08	6.00	Sole Property Owner	30/03/2010	
EES66 Low energy lamp replacement	£29.75	17.00	Sole Property Owner	30/03/2010	
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	30/03/2010	
EES69 Miscellaneous Charge	£36.40	4.00	Sole Property Owner	30/03/2010	
EES69 Miscellaneous Charge	£22.20	1.00	Sole Property Owner	30/03/2010	
EES25 Draught stripping to exterior door	£87.52	2.00	Sole Property Owner	12/03/2010	
EES26 Draught stripping to windows	£298.50	50.00	Sole Property Owner	12/03/2010	
EES27 Draught stripping to letterbox	£18.45	1.00	Sole Property Owner	12/03/2010	
EES33 Replacement hot water cylinder (150l)	£644.57	1.00	Sole Property Owner	12/03/2010	
EES66 Low energy lamp replacement	£19.20	3.00	Sole Property Owner	12/03/2010	
EES67 Smoke detector installation	£15.00	2.00	Sole Property Owner	12/03/2010	
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	12/03/2010	
EES16 Insulation to 75mm wide cavity wall	£1,239.00	140.00	Not The Property Owner	01/03/2011	
EES21 Scaffold	£492.00	48.00	Not The Property Owner	01/03/2011	
EES01a Loft Clearance (hourly rate)	£31.63	0.50	Not The Property Owner	01/03/2011	
EES07 200mm thick loft insulation	£89.10	10.00	Not The Property Owner	01/03/2011	
EES09 Intumescent bag/fire hood to downlighter	£63.75	3.00	Not The Property Owner	01/03/2011	
EES 11 Cold water tank insulation jacket	£37.42	1.00	Not The Property Owner	01/03/2011	
EES27 Draught stripping to letterbox	£22.20	1.00	Not The Property Owner	01/03/2011	
EES66 Low energy lamp replacement	£22.75	13.00	Not The Property Owner	01/03/2011	
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	06/06/2011	
EES02a Remove and dispose existing insulation (per squire metre)	£111.00	37.00	Sole Property Owner	06/06/2011	
EES08 300mm thick loft insulation	£444.00	37.00	Sole Property Owner	06/06/2011	
EES25 Draught stripping to exterior door	£60.00	6.00	Sole Property Owner	06/06/2011	

EES44 Water heating time clock and boost	£95.59	1.00	Sole Property Owner	06/06/2011	
HES120 Standard QA check	£100.00	1.00	Sole Property Owner	06/06/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	28/01/2010	
EES48 Pipework lagging 19mm thick to 22mm pipe	£2.18	2.00	Not The Property Owner	28/01/2010	
EES49 Pipework lagging 25mm thick to 22mm pipe	£3.33	1.00	Not The Property Owner	28/01/2010	
EES67 Smoke detector installation	£0.00	1.00	Not The Property Owner	28/01/2010	
EES77 HEC to House	£150.00	1.00	Not The Property Owner	28/01/2010	
EES78 Home Energy Assessor hourly rate	£60.00	1.00	Sole Property Owner	05/07/2011	
EES16 Insulation to 75mm wide cavity wall	£845.25	105.00	Sole Property Owner	05/07/2011	
EES75 HEC to Flat or Bedsit	£150.00	1.00	Sole Property Owner	05/07/2011	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	05/07/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	28/01/2010	
EES01a Loft Clearance (hourly rate)	£160.00	6.40	Not The Property Owner	03/08/2010	
EES03a Remove and replace nailed floor board	£15.00	6.00	Not The Property Owner	03/08/2010	
EES02a Remove and dispose existing insulation (per squire metre)	£195.00	65.00	Not The Property Owner	03/08/2010	
EES08 300mm thick loft insulation	£780.00	65.00	Not The Property Owner	03/08/2010	
EES13a Cold water tank bye law kit (including associated products)	£180.00	1.00	Not The Property Owner	03/08/2010	
EES35 Replacement hot water cylinder (210l)	£1,355.00	1.00	Not The Property Owner	03/08/2010	
EES01a Loft Clearance (hourly rate)	£175.00	7.00	Joint Owner	29/04/2010	
EES08 300mm thick loft insulation	£225.00	25.00	Joint Owner	29/04/2010	
EES25 Draught stripping to exterior door	£280.00	28.00	Joint Owner	29/04/2010	
EES26 Draught stripping to windows	£40.00	4.00	Joint Owner	29/04/2010	
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Joint Owner	29/04/2010	
EES69 Miscellaneous Charge	£197.00	1.00	Joint Owner	29/04/2010	
EES25 Draught stripping to exterior door	£10.00	1.00	Sole Property Owner	02/08/2010	
EES27 Draught stripping to letterbox	£40.00	1.00	Sole Property Owner	02/08/2010	
HES120 Standard QA check	£100.00	1.00	Sole Property Owner	02/08/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	05/09/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	04/03/2010	
EES15 Insulation to 65mm wide cavity wall	£1,165.50	150.00	Not The Property Owner	15/04/2010	
EES69 Miscellaneous Charge	£30.00	1.00	Not The Property Owner	15/04/2010	
EES34 Replacement hot water cylinder (170l)	£715.00	1.00	Not The Property Owner	15/04/2010	
EES66 Low energy lamp replacement	£21.00	1.00	Not The Property Owner	15/04/2010	
EES69 Miscellaneous Charge	£70.00	1.00	Not The Property Owner	15/04/2010	
HES03 200mm thick loft insulation quilt	£592.96	69.76	Not The Property Owner	15/04/2010	
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Not The Property Owner	16/07/2011	
EES03a Remove and replace nailed floor board	£50.00	20.00	Not The Property Owner	16/07/2011	
EES02a Remove and dispose existing insulation (per squire metre)	£120.00	40.00	Not The Property Owner	16/07/2011	
EES08 300mm thick loft insulation	£480.00	40.00	Not The Property Owner	16/07/2011	
EES13a Cold water tank bye law kit (including associated products)	£280.00	1.00	Not The Property Owner	16/07/2011	
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Not The Property Owner	16/07/2011	
EES15 Insulation to 65mm wide cavity wall	£485.70	64.76	Not The Property Owner	16/07/2011	
EES50b 12-15kW Gas replacement boiler	£971.00	1.00	Sole Property Owner	09/06/2011	
EES70 Miscellaneous heating review charge	£1,676.91	1,676.91	Sole Property Owner	09/06/2011	
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	09/06/2011	
EES03a Remove and replace nailed floor board	£75.00	30.00	Sole Property Owner	09/06/2011	
EES02a Remove and dispose existing insulation (per squire metre)	£135.00	45.00	Sole Property Owner	09/06/2011	
EES08 300mm thick loft insulation	£480.00	40.00	Sole Property Owner	09/06/2011	
EES13a Cold water tank bye law kit (including associated products)	£560.00	2.00	Sole Property Owner	09/06/2011	
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Sole Property Owner	09/06/2011	
EES38a Thermostatic radiator valve (per valve)	£341.25	7.00	Sole Property Owner	09/06/2011	
EES69 Miscellaneous Charge	£162.00	1.00	Sole Property Owner	09/06/2011	
EES69 Miscellaneous Charge	£153.75	1.00	Sole Property Owner	09/06/2011	
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	09/06/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	10/07/2010	
EES01a Loft Clearance (hourly rate)	£63.26	2.00	Sole Property Owner	10/07/2010	
EES07 200mm thick loft insulation	£213.84	24.00	Sole Property Owner	10/07/2010	
EES66 Low energy lamp replacement	£1.75	1.00	Sole Property Owner	10/07/2010	
EES67 Smoke detector installation	£9.80	1.00	Sole Property Owner	10/07/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	05/04/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	05/08/2010	
EES26 Draught stripping to windows	£100.00	5.00	Not The Property Owner	05/08/2010	
EES02a Remove and dispose existing insulation (per squire metre)	£94.08	22.40	Sole Property Owner	30/03/2010	
EES06 100mm thick loft insulation	£154.11	22.40	Sole Property Owner	30/03/2010	
EES07 200mm thick loft insulation	£199.58	22.40	Sole Property Owner	30/03/2010	
EES 11 Cold water tank insulation jacket	£37.42	1.00	Sole Property Owner	30/03/2010	
EES 11 Cold water tank insulation jacket	£32.03	1.00	Sole Property Owner	30/03/2010	
EES34 Replacement hot water cylinder (170l)	£715.00	1.00	Sole Property Owner	30/03/2010	
EES38a Thermostatic radiator valve (per valve)	£352.00	8.00	Sole Property Owner	30/03/2010	
EES66 Low energy lamp replacement	£40.25	1.00	Sole Property Owner	30/03/2010	
EES00a Full Energy Survey	£401.68	1.00	Not The Property Owner	03/08/2009	
EES25 Draught stripping to exterior door	£100.00	10.00	Not The Property Owner	10/02/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	10/02/2011	
EES48 Pipework lagging 19mm thick to 22mm pipe	£4.36	4.00	Not The Property Owner	10/02/2011	
EES49 Pipework lagging 25mm thick to 22mm pipe	£2.38	2.00	Not The Property Owner	10/02/2011	
EES49 Pipework lagging 25mm thick to 22mm pipe	£6.66	2.00	Not The Property Owner	10/02/2011	
EES77 HEC to House	£150.00	1.00	Sole Property Owner	10/06/2010	
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	10/06/2010	
EES69 Miscellaneous Charge	£133.20	6.00	Sole Property Owner	10/06/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/03/2010	
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Sole Property Owner	02/08/2010	
EES02a Remove and dispose existing insulation (per squire metre)	£162.00	54.00	Sole Property Owner	02/08/2010	
EES03a Remove and replace nailed floor board	£87.50	35.00	Sole Property Owner	02/08/2010	
EES07 200mm thick loft insulation	£434.16	54.00	Sole Property Owner	02/08/2010	

EES69 Miscellaneous Charge	£48.00	2.00	Sole Property Owner	02/08/2010	
EES69 Miscellaneous Charge	£135.00	1.00	Sole Property Owner	02/08/2010	
EES38a Thermostatic radiator valve (per valve)	£487.50	10.00	Sole Property Owner	02/08/2010	
EES69 Miscellaneous Charge	£7.50	1.00	Sole Property Owner	02/08/2010	
EES44 Water heating time clock and boost	£95.59	1.00	Sole Property Owner	02/08/2010	
EES47 Pipework lagging 13mm thick to 22mm pipe	£140.00	7.00	Sole Property Owner	02/08/2010	
HES120 Standard QA check	£100.00	1.00	Sole Property Owner	02/08/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/03/2010	
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	11/06/2012	
EES07 200mm thick loft insulation	£324.00	36.00	Not The Property Owner	11/06/2012	
EES13a Cold water tank bye law kit (including associated products)	£560.00	2.00	Not The Property Owner	11/06/2012	
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Not The Property Owner	11/06/2012	
EES38a Thermostatic radiator valve (per valve)	£300.00	5.00	Not The Property Owner	11/06/2012	
EES69 Miscellaneous Charge	£195.00	1.00	Not The Property Owner	11/06/2012	
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Not The Property Owner	02/08/2010	
EES03a Remove and replace nailed floor board	£22.50	9.00	Not The Property Owner	02/08/2010	
EES08 300mm thick loft insulation	£612.00	51.00	Not The Property Owner	02/08/2010	
EES13a Cold water tank bye law kit (including associated products)	£280.00	1.00	Not The Property Owner	02/08/2010	
EES25 Draught stripping to exterior door	£100.00	10.00	Not The Property Owner	10/12/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	10/12/2010	
EES48 Pipework lagging 19mm thick to 22mm pipe	£4.36	4.00	Not The Property Owner	10/12/2010	
EES49 Pipework lagging 25mm thick to 22mm pipe	£2.38	2.00	Not The Property Owner	10/12/2010	
EES49 Pipework lagging 25mm thick to 22mm pipe	£9.99	3.00	Not The Property Owner	10/12/2010	
EES07 200mm thick loft insulation	£324.00	36.00	Not The Property Owner	15/04/2010	
EES13a Cold water tank bye law kit (including associated products)	£560.00	2.00	Not The Property Owner	15/04/2010	
EES38a Thermostatic radiator valve (per valve)	£480.00	8.00	Not The Property Owner	15/04/2010	
EES69 Miscellaneous Charge	£15.00	1.00	Not The Property Owner	15/04/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/03/2010	
EES50c Replacement electrical storage heater	£207.00	1.00	Sole Property Owner	26/01/2012	
EES50c Replacement electrical storage heater	£262.79	1.00	Sole Property Owner	26/01/2012	
EES50c Replacement electrical storage heater	£822.00	2.00	Sole Property Owner	26/01/2012	
EES50c Replacement electrical storage heater	£475.00	1.00	Sole Property Owner	26/01/2012	
EES29 Hot water cylinder jacket (30x18 inch)	£200.00	2.00	Sole Property Owner	26/01/2012	
EES00a Full Energy Survey	£401.70	1.00	Sole Property Owner	26/01/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/03/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	05/04/2010	
EES48 Pipework lagging 19mm thick to 22mm pipe	£4.36	4.00	Not The Property Owner	05/04/2010	
EES49 Pipework lagging 25mm thick to 22mm pipe	£2.38	2.00	Not The Property Owner	05/04/2010	
EES49 Pipework lagging 25mm thick to 22mm pipe	£26.64	8.00	Not The Property Owner	05/04/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/03/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/03/2010	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Not The Property Owner	02/08/2010	
EES78 Home Energy Assessor hourly rate	£60.00	1.00	Not The Property Owner	23/04/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	23/04/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/03/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/03/2010	
EES02a Remove and dispose existing insulation (per square metre)	£201.60	48.00	Not The Property Owner	15/04/2010	
EES07 200mm thick loft insulation	£427.68	48.00	Not The Property Owner	15/04/2010	
EES10 Cold water tank insulation quilt	£32.03	1.00	Not The Property Owner	15/04/2010	
EES 11 Cold water tank insulation jacket	£37.42	1.00	Not The Property Owner	15/04/2010	
EES26 Draught stripping to windows	£27.30	3.00	Not The Property Owner	15/04/2010	
EES69 Miscellaneous Charge	£36.40	4.00	Not The Property Owner	15/04/2010	
EES38a Thermostatic radiator valve (per valve)	£264.00	6.00	Not The Property Owner	15/04/2010	
EES66 Low energy lamp replacement	£15.75	9.00	Not The Property Owner	15/04/2010	
EES00a Full Energy Survey	£401.68	1.00	Not The Property Owner	26/07/2009	
EES01a Loft Clearance (hourly rate)	£316.25	5.00	Sole Property Owner	01/07/2011	
EES03a Remove and replace nailed floor board	£842.52	71.40	Sole Property Owner	01/07/2011	
EES07 200mm thick loft insulation	£636.17	71.40	Sole Property Owner	01/07/2011	
EES06 100mm thick loft insulation	£339.18	49.30	Sole Property Owner	01/07/2011	
EES19 Airbrick	£9.20	1.00	Sole Property Owner	01/07/2011	
EES15 Insulation to 65mm wide cavity wall	£144.90	21.00	Sole Property Owner	01/07/2011	
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	01/07/2011	
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	01/07/2011	
EES35 Replacement hot water cylinder (210l)	£1,760.00	1.00	Sole Property Owner	01/07/2011	
EES40 Hot water cylinder thermostat	£74.70	1.00	Sole Property Owner	01/07/2011	
EES42 Two channel programmable heating controller	£111.00	1.00	Sole Property Owner	01/07/2011	
EES66 Low energy lamp replacement	£49.00	1.00	Sole Property Owner	01/07/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	15/03/2010	
EES01a Loft Clearance (hourly rate)	£400.00	16.00	Joint Owner	02/08/2012	
EES02a Remove and dispose existing insulation (per square metre)	£360.00	120.00	Joint Owner	02/08/2012	
EES03a Remove and replace nailed floor board	£30.00	10.00	Joint Owner	02/08/2012	
EES08 300mm thick loft insulation	£1,440.00	120.00	Joint Owner	02/08/2012	
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	02/08/2012	
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	02/08/2012	
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	02/08/2012	
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Joint Owner	02/08/2012	
EES38a Thermostatic radiator valve (per valve)	£510.00	6.00	Joint Owner	02/08/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£616.00	88.00	Joint Owner	02/08/2012	
EES66 Low energy lamp replacement	£0.00	30.00	Joint Owner	02/08/2012	
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	02/08/2012	
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	02/08/2012	
EES38a Thermostatic radiator valve (per valve)	£93.69	1.00	Joint Owner	02/08/2012	
EES40 Hot water cylinder thermostat	£60.19	1.00	Joint Owner	02/08/2012	
EES42 Two channel programmable heating controller	£139.59	1.00	Joint Owner	02/08/2012	

EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Joint Owner	02/08/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	1.00	Joint Owner	02/08/2012
EES70 Miscellaneous heating review charge	£2,351.56	1.00	Joint Owner	02/08/2012
EES33 Replacement hot water cylinder (150L)	£1,200.00	1.00	Joint Owner	02/08/2012
EES36 Electrical room thermostat	£103.40	1.00	Joint Owner	02/08/2012
EES38a Thermostatic radiator valve (per valve)	£440.00	10.00	Joint Owner	02/08/2012
EES66 Low energy lamp replacement	£22.75	13.00	Joint Owner	02/08/2012
EES67 Smoke detector installation	£3.50	2.00	Joint Owner	02/08/2012
EES82 Boiler replacement miscellaneous works	£172.62	1.00	Joint Owner	02/08/2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	11/12/2010
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	11/12/2010
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Not The Property Owner	11/12/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	15/03/2010
EES51a 16-20kW Oil replacement boiler	£3,846.45	1.00	Sole Property Owner	22/06/2011
EES07 200mm thick loft insulation	£1,104.84	124.00	Sole Property Owner	22/06/2011
EES25 Draught stripping to exterior door	£91.00	10.00	Sole Property Owner	22/06/2011
EES26 Draught stripping to windows	£45.50	5.00	Sole Property Owner	22/06/2011
EES38a Thermostatic radiator valve (per valve)	£396.00	9.00	Sole Property Owner	22/06/2011
EES40 Hot water cylinder thermostat	£74.40	1.00	Sole Property Owner	22/06/2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£61.35	7.50	Sole Property Owner	22/06/2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£17.81	2.40	Sole Property Owner	22/06/2011
EES66 Low energy lamp replacement	£29.75	1.00	Sole Property Owner	22/06/2011
HES120 Standard QA check	£100.00	1.00	Sole Property Owner	22/06/2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	22/06/2011
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	06/07/2010
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	06/07/2010
EES69 Miscellaneous Charge	£126.00	126.00	Sole Property Owner	06/07/2010
EES66 Low energy lamp replacement	£35.00	1.00	Sole Property Owner	06/07/2010
HES120 Standard QA check	£100.00	1.00	Sole Property Owner	06/07/2010
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	27/09/2012
EES07 200mm thick loft insulation	£405.00	45.00	Sole Property Owner	27/09/2012
EES66 Low energy lamp replacement	£0.00	22.00	Sole Property Owner	27/09/2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	27/09/2012
HES73 Storage heater rated 3kW - 4kW	£750.68	2.00	Sole Property Owner	27/09/2012
HES75 Storage heater consumer unit	£49.40	1.00	Sole Property Owner	27/09/2012
HES76 Storage heater miniature circuit breaker	£29.25	3.00	Sole Property Owner	27/09/2012
HES77 Main bonding of necessary services	£54.50	5.00	Sole Property Owner	27/09/2012
HES79 Heating point twin and earth mini trunk DP switch	£152.84	1.00	Sole Property Owner	27/09/2012
HES80 16mm meter tails	£12.48	1.00	Sole Property Owner	27/09/2012
HES64 Stainless steel replacement hot water cylinder (170L)	£351.61	1.00	Sole Property Owner	27/09/2012
HES97 Electrician	£448.00	14.00	Sole Property Owner	27/09/2012
HES94 Heating engineer	£192.00	6.00	Sole Property Owner	27/09/2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	30/03/2010
EES15 Insulation to 65mm wide cavity wall	£479.36	64.00	Sole Property Owner	07/10/2009
EES66 Low energy lamp replacement	£204.66	18.00	Sole Property Owner	07/10/2009
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	07/10/2009
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	07/10/2009
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	07/10/2009
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	07/10/2009
EES01a Loft Clearance (hourly rate)	£31.63	1.00	Sole Property Owner	01/02/2010
EES03a Remove and replace nailed floor board	£35.40	3.00	Sole Property Owner	01/02/2010
EES07 200mm thick loft insulation	£472.23	53.00	Sole Property Owner	01/02/2010
EES12 Cold water tank lid	£69.24	2.00	Sole Property Owner	01/02/2010
EES25 Draught stripping to exterior door	£54.60	6.00	Sole Property Owner	01/02/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£106.88	8.00	Sole Property Owner	01/02/2010
EES66 Low energy lamp replacement	£28.00	16.00	Sole Property Owner	01/02/2010
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	01/02/2010
EES 30 Hot water cylinder jacket (46x18 inch)	£47.04	1.00	Sole Property Owner	01/02/2010
EES50c Replacement electrical storage heater	£207.00	1.00	Sole Property Owner	26/01/2012
EES50c Replacement electrical storage heater	£411.00	1.00	Sole Property Owner	26/01/2012
EES50c Replacement electrical storage heater	£475.00	1.00	Sole Property Owner	26/01/2012
EES07 200mm thick loft insulation	£8.91	1.00	Sole Property Owner	26/01/2012
EES26 Draught stripping to windows	£45.50	5.00	Sole Property Owner	26/01/2012
EES69 Miscellaneous Charge	£36.40	4.00	Sole Property Owner	26/01/2012
EES66 Low energy lamp replacement	£15.75	9.00	Sole Property Owner	26/01/2012
EES02a Remove and dispose existing insulation (per squire metre)	£184.80	44.00	Joint Owner	30/03/2010
EES07 200mm thick loft insulation	£392.04	44.00	Joint Owner	30/03/2010
EES06 100mm thick loft insulation	£302.72	44.00	Joint Owner	30/03/2010
EES 11 Cold water tank insulation jacket	£37.42	1.00	Joint Owner	30/03/2010
EES25 Draught stripping to exterior door	£91.00	10.00	Joint Owner	30/03/2010
EES69 Miscellaneous Charge	£18.20	2.00	Joint Owner	30/03/2010
EES69 Miscellaneous Charge	£44.40	2.00	Joint Owner	30/03/2010
EES36 Electrical room thermostat	£103.40	1.00	Joint Owner	30/03/2010
EES66 Low energy lamp replacement	£22.75	13.00	Joint Owner	30/03/2010
EES67 Smoke detector installation	£1.75	1.00	Joint Owner	30/03/2010
EES38a Thermostatic radiator valve (per valve)	£176.00	4.00	Sole Property Owner	26/01/2011
EES66 Low energy lamp replacement	£39.55	1.00	Sole Property Owner	26/01/2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	30/03/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	15/03/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	30/03/2010
EES01a Loft Clearance (hourly rate)	£63.25	1.00	Sole Property Owner	06/07/2010
EES03a Remove and replace nailed floor board	£221.84	18.80	Sole Property Owner	06/07/2010
EES02a Remove and dispose existing insulation (per squire metre)	£302.40	72.00	Sole Property Owner	06/07/2010
EES07 200mm thick loft insulation	£641.52	72.00	Sole Property Owner	06/07/2010

EES06 100mm thick loft insulation	£366.02	53.20	Sole Property Owner	06/07/2010
EES 11 Cold water tank insulation jacket	£74.84	2.00	Sole Property Owner	06/07/2010
EES15 Insulation to 65mm wide cavity wall	£725.86	97.30	Sole Property Owner	06/07/2010
EES69 Miscellaneous Charge	£30.00	1.00	Sole Property Owner	06/07/2010
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	06/07/2010
EES69 Miscellaneous Charge	£36.40	4.00	Sole Property Owner	06/07/2010
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	06/07/2010
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Sole Property Owner	06/07/2010
EES40 Hot water cylinder thermostat	£0.00	0.00	Sole Property Owner	06/07/2010
EES42 Two channel programmable heating controller	£0.00	0.00	Sole Property Owner	06/07/2010
EES66 Low energy lamp replacement	£49.00	28.00	Sole Property Owner	06/07/2010
EES67 Smoke detector installation	£3.50	2.00	Sole Property Owner	06/07/2010
EES34 Replacement hot water cylinder (170L)	£715.00	1.00	Sole Property Owner	06/07/2010
HES120 Standard QA check	£100.00	1.00	Sole Property Owner	06/07/2010
EES36 Electrical room thermostat	£0.00	0.00	Joint Owner	23/11/2012
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Joint Owner	23/11/2012
EES15 Insulation to 65mm wide cavity wall	£1,711.20	1,711.20	Joint Owner	23/11/2012
EES66 Low energy lamp replacement	£0.00	15.00	Joint Owner	23/11/2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	23/11/2012
HES32 21-25kW Oil replacement condensing boiler	£1,920.00	1.00	Joint Owner	23/11/2012
HES40 Flue specification and location	£510.25	1.00	Joint Owner	23/11/2012
HES41 Condensate pipework (and pump if required)	£41.40	1.00	Joint Owner	23/11/2012
HES45 Fire valve	£48.00	1.00	Joint Owner	23/11/2012
HES46 Automatic bypass	£32.40	1.00	Joint Owner	23/11/2012
HES48 Power / system flush and treatment	£480.00	1.00	Joint Owner	23/11/2012
HES49 Carbon Monoxide alarm	£42.00	1.00	Joint Owner	23/11/2012
HES52 Hot water cylinder thermostat	£24.00	1.00	Joint Owner	23/11/2012
HES53 Two channel heating programmer control	£78.00	1.00	Joint Owner	23/11/2012
HES55 2 port zone valve	£136.80	2.00	Joint Owner	23/11/2012
HES66 15mm thick pipework lagging	£3.38	1.00	Joint Owner	23/11/2012
HES68 28mm thick pipework lagging	£14.22	3.00	Joint Owner	23/11/2012
HES95 Senior heating engineer	£0.00	0.00	Joint Owner	23/11/2012
HES97 Electrician	£380.00	10.00	Joint Owner	23/11/2012
HES99 Building works	£120.00	4.00	Joint Owner	23/11/2012
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Joint Owner	23/11/2012
HES88 Commissioning and issue of CD11 and flue gas analysis	£96.00	1.00	Joint Owner	23/11/2012
HES90 Other miscellaneous oil heating works for EES approval	£1,685.60	1.00	Joint Owner	23/11/2012
HES50 Electrical room thermostat	£22.80	1.00	Joint Owner	23/11/2012
HES67 22mm thick pipework lagging	£24.20	5.50	Joint Owner	23/11/2012
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Joint Owner	23/11/2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	23/11/2012
HES94 Heating engineer	£1,330.00	35.00	Joint Owner	23/11/2012
HES122 Consultancy Fees	£65.00	1.00	Joint Owner	23/11/2012
EES07 200mm thick loft insulation	£374.22	42.00	Joint Owner	30/03/2010
EES06 100mm thick loft insulation	£288.96	42.00	Joint Owner	30/03/2010
EES66 Low energy lamp replacement	£26.25	15.00	Joint Owner	30/03/2010
EES67 Smoke detector installation	£1.75	1.00	Joint Owner	30/03/2010
EES01a Loft Clearance (hourly rate)	£284.63	4.50	Sole Property Owner	06/07/2010
EES03a Remove and replace nailed floor board	£354.00	30.00	Sole Property Owner	06/07/2010
EES02a Remove and dispose existing insulation (per squire metre)	£336.00	80.00	Sole Property Owner	06/07/2010
EES07 200mm thick loft insulation	£712.80	80.00	Sole Property Owner	06/07/2010
EES06 100mm thick loft insulation	£550.40	80.00	Sole Property Owner	06/07/2010
EES09 Intumescent bag/fire hood to downlighter	£127.50	6.00	Sole Property Owner	06/07/2010
EES10 Cold water tank insulation quilt	£37.42	1.00	Sole Property Owner	06/07/2010
EES15 Insulation to 65mm wide cavity wall	£660.45	85.00	Sole Property Owner	06/07/2010
EES34 Replacement hot water cylinder (170L)	£715.00	1.00	Sole Property Owner	06/07/2010
EES69 Miscellaneous Charge	£93.50	1.00	Sole Property Owner	06/07/2010
EES40 Hot water cylinder thermostat	£74.70	1.00	Sole Property Owner	06/07/2010
EES66 Low energy lamp replacement	£31.50	18.00	Sole Property Owner	06/07/2010
EES67 Smoke detector installation	£1.75	1.00	Sole Property Owner	06/07/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£163.60	20.00	Sole Property Owner	06/07/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£148.40	20.00	Sole Property Owner	06/07/2010
EES26 Draught stripping to windows	£45.50	5.00	Sole Property Owner	06/07/2010
HES120 Standard QA check	£100.00	1.00	Sole Property Owner	06/07/2010
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	06/07/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	08/08/2010
EES25 Draught stripping to exterior door	£181.36	19.93	Not The Property Owner	08/08/2010
EES26 Draught stripping to windows	£181.36	19.93	Not The Property Owner	08/08/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	15/03/2010
EES01a Loft Clearance (hourly rate)	£31.63	1.00	Joint Owner	30/03/2010
EES07 200mm thick loft insulation	£171.07	19.20	Joint Owner	30/03/2010
EES27 Draught stripping to letterbox	£22.20	1.00	Joint Owner	30/03/2010
EES69 Miscellaneous Charge	£44.40	2.00	Joint Owner	30/03/2010
EES38a Thermostatic radiator valve (per valve)	£572.00	13.00	Joint Owner	30/03/2010
EES66 Low energy lamp replacement	£43.75	25.00	Joint Owner	30/03/2010
EES01a Loft Clearance (hourly rate)	£189.75	3.00	Sole Property Owner	30/03/2010
EES03a Remove and replace nailed floor board	£236.00	20.00	Sole Property Owner	30/03/2010
EES07 200mm thick loft insulation	£356.40	40.00	Sole Property Owner	30/03/2010
EES27 Draught stripping to letterbox	£66.60	3.00	Sole Property Owner	30/03/2010
EES66 Low energy lamp replacement	£21.00	12.00	Sole Property Owner	30/03/2010
EES69 Miscellaneous Charge	£1.10	1.00	Sole Property Owner	30/03/2010
EES01a Loft Clearance (hourly rate)	£94.88	1.50	Joint Owner	30/03/2010
EES07 200mm thick loft insulation	£320.76	36.00	Joint Owner	30/03/2010
EES06 100mm thick loft insulation	£247.68	36.00	Joint Owner	30/03/2010

EES10 Cold water tank insulation quilt	£32.03	1.00	Joint Owner	30/03/2010
EES19 Airbrick	£147.20	16.00	Joint Owner	30/03/2010
EES15 Insulation to 65mm wide cavity wall	£1,156.30	155.00	Joint Owner	30/03/2010
EES36 Electrical room thermostat	£103.40	1.00	Joint Owner	30/03/2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£29.68	4.00	Joint Owner	30/03/2010
EES66 Low energy lamp replacement	£52.50	30.00	Joint Owner	30/03/2010
EES69 Miscellaneous Charge	£18.20	2.00	Joint Owner	30/03/2010
EES66 Low energy lamp replacement	£24.50	14.00	Joint Owner	30/03/2010
EES07 200mm thick loft insulation	£8.91	1.00	Joint Owner	30/03/2010
EES69 Miscellaneous Charge	£36.40	4.00	Joint Owner	30/03/2010
EES66 Low energy lamp replacement	£21.00	12.00	Joint Owner	30/03/2010
EES67 Smoke detector installation	£9.80	1.00	Joint Owner	30/03/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/06/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£1.09	1.00	Not The Property Owner	30/06/2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£2.38	2.00	Not The Property Owner	30/06/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	24/05/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£2.18	2.00	Not The Property Owner	24/05/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£3.33	1.00	Not The Property Owner	24/05/2010
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Not The Property Owner	05/01/2011
EES18a Cavity brush (per brush)	£0.00	0.00	Not The Property Owner	05/01/2011
EES21 Scaffold	£0.00	0.00	Not The Property Owner	05/01/2011
EES66 Low energy lamp replacement	£0.00	0.00	Not The Property Owner	05/01/2011
EES08 300mm thick loft insulation	£491.84	88.94	Joint Owner	14/07/2010
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Joint Owner	14/07/2010
EES66 Low energy lamp replacement	£45.00	1.00	Joint Owner	14/07/2010
EES01a Loft Clearance (hourly rate)	£31.63	1.00	Sole Property Owner	30/03/2010
EES02a Remove and dispose existing insulation (per squire metre	£180.60	43.00	Sole Property Owner	30/03/2010
EES07 200mm thick loft insulation	£383.13	43.00	Sole Property Owner	30/03/2010
EES06 100mm thick loft insulation	£295.84	43.00	Sole Property Owner	30/03/2010
EES10 Cold water tank insulation quilt	£32.03	1.00	Sole Property Owner	30/03/2010
EES69 Miscellaneous Charge	£18.20	2.00	Sole Property Owner	30/03/2010
EES66 Low energy lamp replacement	£17.50	10.00	Sole Property Owner	30/03/2010
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Sole Property Owner	02/08/2010
EES02a Remove and dispose existing insulation (per squire metre	£144.00	48.00	Sole Property Owner	02/08/2010
EES08 300mm thick loft insulation	£576.00	48.00	Sole Property Owner	02/08/2010
EES01a Loft Clearance (hourly rate)	£253.04	8.00	Sole Property Owner	01/02/2010
EES03a Remove and replace nailed floor board	£283.20	24.00	Sole Property Owner	01/02/2010
EES02a Remove and dispose existing insulation (per squire metre	£50.40	24.00	Sole Property Owner	01/02/2010
EES08 300mm thick loft insulation	£378.96	24.00	Sole Property Owner	01/02/2010
EES09 Intumescent bag/fire hood to downlighter	£191.25	9.00	Sole Property Owner	01/02/2010
EES22 Mastic pointing	£19.50	5.00	Sole Property Owner	01/02/2010
EES25 Draught stripping to exterior door	£54.60	6.00	Sole Property Owner	01/02/2010
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	01/02/2010
EES66 Low energy lamp replacement	£5.25	3.00	Sole Property Owner	01/02/2010
EES67 Smoke detector installation	£9.80	1.00	Sole Property Owner	01/02/2010
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	01/02/2010
EES77 HEC to House	£120.00	1.00	Not The Property Owner	02/08/2010
EES01a Loft Clearance (hourly rate)	£192.00	8.00	Not The Property Owner	10/01/2011
EES03a Remove and replace nailed floor board	£224.20	19.00	Not The Property Owner	10/01/2011
EES07 200mm thick loft insulation	£427.68	48.00	Not The Property Owner	10/01/2011
EES27 Draught stripping to letterbox	£17.58	6.00	Not The Property Owner	10/01/2011
EES67 Smoke detector installation	£0.00	2.00	Not The Property Owner	10/01/2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	10/01/2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£4.36	4.00	Not The Property Owner	10/01/2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£13.32	4.00	Not The Property Owner	10/01/2011
EES69 Miscellaneous Charge	£19.62	1.00	Not The Property Owner	10/01/2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/03/2010
EES50c Replacement electrical storage heater	£822.00	2.00	Joint Owner	26/01/2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	26/01/2012
EES69 Miscellaneous Charge	£147.25	1.00	Joint Owner	26/01/2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£38.20	10.00	Joint Owner	05/07/2011
EES44 Water heating time clock and boost	£107.39	1.00	Joint Owner	05/07/2011
EES07 200mm thick loft insulation	£304.40	57.11	Joint Owner	05/07/2011
EES66 Low energy lamp replacement	£45.00	1.00	Joint Owner	05/07/2011
EES69 Miscellaneous Charge	£35.80	1.00	Joint Owner	05/07/2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	15/03/2010
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	16/12/2011
EES07 200mm thick loft insulation	£251.44	28.00	Sole Property Owner	16/12/2011
EES03a Remove and replace nailed floor board	£72.80	28.00	Sole Property Owner	16/12/2011
EES66 Low energy lamp replacement	£238.77	21.00	Sole Property Owner	16/12/2011
EES10 Cold water tank insulation quilt	£64.59	1.00	Sole Property Owner	16/12/2011
EES 11 Cold water tank insulation jacket	£51.12	1.00	Sole Property Owner	16/12/2011
EES12 Cold water tank lid	£23.46	1.00	Sole Property Owner	16/12/2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£177.98	22.00	Sole Property Owner	16/12/2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£129.08	14.00	Sole Property Owner	16/12/2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£14.27	1.00	Sole Property Owner	16/12/2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	16/12/2011
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	16/12/2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	15/03/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/03/2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.95	1.00	Not The Property Owner	30/03/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/03/2010
EES51a 16-20kW Oil replacement boiler	£2,900.00	1.00	Joint Owner	10/10/2012
EES70 Miscellaneous heating review charge	£510.00	510.00	Joint Owner	10/10/2012

EES01a Loft Clearance (hourly rate)	£175.00	7.00	Joint Owner	10/10/2012	
EES03a Remove and replace nailed floor board	£50.00	20.00	Joint Owner	10/10/2012	
EES02a Remove and dispose existing insulation (per squire metre)	£168.00	56.00	Joint Owner	10/10/2012	
EES08 300mm thick loft insulation	£672.00	56.00	Joint Owner	10/10/2012	
EES13a Cold water tank bye law kit (including associated products)	£180.00	1.00	Joint Owner	10/10/2012	
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Joint Owner	10/10/2012	
EES38a Thermostatic radiator valve (per valve)	£495.00	9.00	Joint Owner	10/10/2012	
EES00 Property Assessment	£185.00	1.00	Joint Owner	10/10/2012	
EES69 Miscellaneous Charge	£1,894.67	1.00	Joint Owner	10/10/2012	
HES121 Boiler QA Check	£105.00	1.00	Joint Owner	10/10/2012	
EES82 Boiler replacement miscellaneous works	£105.00	1.00	Joint Owner	10/10/2012	
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Sole Property Owner	28/11/2013	
EES02a Remove and dispose existing insulation (per squire metre)	£165.00	55.00	Sole Property Owner	28/11/2013	
EES08 300mm thick loft insulation	£600.00	50.00	Sole Property Owner	28/11/2013	
EES38a Thermostatic radiator valve (per valve)	£480.00	8.00	Sole Property Owner	28/11/2013	
EES68 Minimum charge for lamps and detectors	£15.00	1.00	Sole Property Owner	28/11/2013	
HES117 Carbon Monoxide alarm	£0.00	1.00	Sole Property Owner	28/11/2013	
HES51 Thermostatic radiator valve	£21.85	1.00	Sole Property Owner	28/11/2013	
HES67 22mm thick pipework lagging	£50.64	12.00	Sole Property Owner	28/11/2013	
HES68 28mm thick pipework lagging	£9.08	2.00	Sole Property Owner	28/11/2013	
HES93 Junior heating engineer	£65.91	3.00	Sole Property Owner	28/11/2013	
HES94 Heating engineer	£147.20	4.00	Sole Property Owner	28/11/2013	
HES95 Senior heating engineer	£79.36	2.00	Sole Property Owner	28/11/2013	
HES90 Other miscellaneous oil heating works for EES approval	£25.30	1.00	Sole Property Owner	28/11/2013	
HES66 15mm thick pipework lagging	£12.96	4.00	Sole Property Owner	28/11/2013	
EES06 100mm thick loft insulation	£1,126.94	163.80	Joint Owner	30/03/2010	
EES66 Low energy lamp replacement	£35.00	20.00	Joint Owner	30/03/2010	
EES01a Loft Clearance (hourly rate)	£189.75	3.00	Sole Property Owner	03/08/2010	
EES03a Remove and replace nailed floor board	£318.60	27.00	Sole Property Owner	03/08/2010	
EES02a Remove and dispose existing insulation (per squire metre)	£113.40	27.00	Sole Property Owner	03/08/2010	
EES06 100mm thick loft insulation	£185.76	27.00	Sole Property Owner	03/08/2010	
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	03/08/2010	
EES38a Thermostatic radiator valve (per valve)	£308.00	7.00	Sole Property Owner	03/08/2010	
EES66 Low energy lamp replacement	£36.75	21.00	Sole Property Owner	03/08/2010	
EES67 Smoke detector installation	£1.75	1.00	Sole Property Owner	03/08/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	15/03/2010	
EES00a Full Energy Survey	£246.55	1.00	Not The Property Owner	19/08/2009	
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Not The Property Owner	15/04/2010	
EES66 Low energy lamp replacement	£31.50	18.00	Not The Property Owner	15/04/2010	
EES68 Minimum charge for lamps and detectors	£0.00	1.00	Sole Property Owner	25/01/2012	
EES40 Hot water cylinder thermostat	£60.19	1.00	Sole Property Owner	25/01/2012	
EES42 Two channel programmable heating controller	£139.59	1.00	Sole Property Owner	25/01/2012	
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	25/01/2012	
EES70 Miscellaneous heating review charge	£1,960.80	1.00	Sole Property Owner	25/01/2012	
EES48 Pipework lagging 19mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	25/01/2012	
HES85 Building Control Officer inspection undertaken	£103.85	1.00	Sole Property Owner	25/01/2012	
EES49 Pipework lagging 25mm thick to 22mm pipe	£185.20	20.00	Sole Property Owner	25/01/2012	
EES44 Water heating time clock and boost	£107.39	1.00	Sole Property Owner	25/01/2012	
EES38a Thermostatic radiator valve (per valve)	£425.70	11.00	Sole Property Owner	25/01/2012	
EES67 Smoke detector installation	£50.00	2.00	Not The Property Owner	02/08/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	23/04/2010	
EES50c Replacement electrical storage heater	£262.79	1.00	Sole Property Owner	26/01/2012	
EES50c Replacement electrical storage heater	£1,233.00	3.00	Sole Property Owner	26/01/2012	
EES 30 Hot water cylinder jacket (46x18 inch)	£81.62	1.00	Sole Property Owner	26/01/2012	
HES07 Cold water tank bye-law kit (including insulation & lid)	£451.43	1.00	Sole Property Owner	26/01/2012	
EES07 200mm thick loft insulation	£391.25	70.75	Sole Property Owner	26/01/2012	
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Sole Property Owner	26/01/2012	
EES66 Low energy lamp replacement	£45.00	1.00	Sole Property Owner	26/01/2012	
HES90 Other miscellaneous oil heating works for EES approval	£1,380.00	1.00	Sole Property Owner	25/03/2013	
EES07 200mm thick loft insulation	£180.05	27.70	Sole Property Owner	25/03/2013	
EES69 Miscellaneous Charge	£50.00	50.00	Sole Property Owner	25/03/2013	
EES51a 16-20kW Oil replacement boiler	£2,870.00	1.00	Sole Property Owner	25/03/2013	
EES38a Thermostatic radiator valve (per valve)	£34.00	1.00	Sole Property Owner	25/03/2013	
EES38a Thermostatic radiator valve (per valve)	£495.00	9.00	Sole Property Owner	25/03/2013	
EES00 Property Assessment	£185.00	1.00	Sole Property Owner	25/03/2013	
HES90 Other miscellaneous oil heating works for EES approval	£48.00	1.00	Sole Property Owner	25/03/2013	
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	25/03/2013	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	02/08/2010	
EES48 Pipework lagging 19mm thick to 22mm pipe	£57.31	6.02	Sole Property Owner	10/08/2010	
HES07 Cold water tank bye-law kit (including insulation & lid)	£160.14	1.00	Sole Property Owner	10/08/2010	
EES07 200mm thick loft insulation	£255.47	47.93	Sole Property Owner	10/08/2010	
EES01a Loft Clearance (hourly rate)	£60.00	2.00	Sole Property Owner	10/08/2010	
EES66 Low energy lamp replacement	£45.00	1.00	Sole Property Owner	10/08/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	01/11/2009	
EES01a Loft Clearance (hourly rate)	£63.25	1.00	Joint Owner	30/03/2010	
EES07 200mm thick loft insulation	£276.21	31.00	Joint Owner	30/03/2010	
EES66 Low energy lamp replacement	£29.75	17.00	Joint Owner	30/03/2010	
EES07 200mm thick loft insulation	£641.52	72.00	Sole Property Owner	30/03/2010	
EES06 100mm thick loft insulation	£495.36	72.00	Sole Property Owner	30/03/2010	
EES21 Scaffold	£80.50	10.00	Sole Property Owner	30/03/2010	
EES15 Insulation to 65mm wide cavity wall	£591.33	85.70	Sole Property Owner	30/03/2010	
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	30/03/2010	
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	30/03/2010	
EES69 Miscellaneous Charge	£44.40	2.00	Sole Property Owner	30/03/2010	

EES34 Replacement hot water cylinder (170L)	£715.00	1.00	Sole Property Owner	30/03/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£81.80	10.00	Sole Property Owner	30/03/2010
EES66 Low energy lamp replacement	£33.25	19.00	Sole Property Owner	30/03/2010
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Joint Owner	02/08/2010
EES02a Remove and dispose existing insulation (per square metre)	£66.00	22.00	Joint Owner	02/08/2010
EES08 300mm thick loft insulation	£264.00	22.00	Joint Owner	02/08/2010
EES13a Cold water tank bye law kit (including associated products)	£280.00	1.00	Joint Owner	02/08/2010
EES33 Replacement hot water cylinder (150L)	£1,200.00	1.00	Joint Owner	02/08/2010
EES69 Miscellaneous Charge	£195.00	1.00	Joint Owner	02/08/2010
EES38a Thermostatic radiator valve (per valve)	£360.00	6.00	Joint Owner	02/08/2010
EES69 Miscellaneous Charge	£135.00	1.00	Joint Owner	02/08/2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£35.00	5.00	Joint Owner	02/08/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	15/03/2010
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Joint Owner	03/08/2010
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	03/08/2010
EES10 Cold water tank insulation quilt	£0.00	0.00	Joint Owner	03/08/2010
EES02a Remove and dispose existing insulation (per square metre)	£120.00	40.00	Joint Owner	03/08/2010
EES03a Remove and replace nailed floor board	£60.00	20.00	Joint Owner	03/08/2010
EES06 100mm thick loft insulation	£0.00	0.00	Joint Owner	03/08/2010
EES08 300mm thick loft insulation	£420.00	35.00	Joint Owner	03/08/2010
EES 11 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	03/08/2010
EES12 Cold water tank lid	£0.00	0.00	Joint Owner	03/08/2010
EES13b Cold water tank bye law kit (excluding associated products)	£0.00	0.00	Joint Owner	03/08/2010
EES66 Low energy lamp replacement	£0.00	25.00	Joint Owner	03/08/2010
EES68 Minimum charge for lamps and detectors	£100.00	1.00	Joint Owner	03/08/2010
EES08 300mm thick loft insulation	£240.00	32.00	Sole Property Owner	22/02/2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	15/03/2010
EES66 Low energy lamp replacement	£57.75	33.00	Joint Owner	30/03/2010
EES15 Insulation to 65mm wide cavity wall	£860.77	100.09	Joint Owner	12/07/2011
EES07 200mm thick loft insulation	£845.00	130.00	Joint Owner	12/07/2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£96.04	6.86	Joint Owner	12/07/2011
EES38a Thermostatic radiator valve (per valve)	£301.00	7.00	Joint Owner	12/07/2011
EES07 200mm thick loft insulation	£828.63	93.00	Not The Property Owner	19/04/2013
EES09 Intumescent bag/fire hood to downlighter	£21.25	1.00	Not The Property Owner	19/04/2013
EES69 Miscellaneous Charge	£30.00	1.00	Not The Property Owner	19/04/2013
EES18b Cavity brush (per metre)	£73.08	17.40	Not The Property Owner	19/04/2013
EES15 Insulation to 65mm wide cavity wall	£522.14	67.20	Not The Property Owner	19/04/2013
EES22 Mastic pointing	£3.90	1.00	Not The Property Owner	19/04/2013
EES26 Draught stripping to windows	£36.40	4.00	Not The Property Owner	19/04/2013
EES66 Low energy lamp replacement	£33.25	19.00	Not The Property Owner	19/04/2013
HES52 Hot water cylinder thermostat	£17.00	1.00	Not The Property Owner	19/04/2013
HES65 Stainless steel replacement hot water cylinder (210L)	£0.00	0.00	Not The Property Owner	19/04/2013
HES94 Heating engineer	£264.00	8.00	Not The Property Owner	19/04/2013
HES97 Electrician	£33.00	1.00	Not The Property Owner	19/04/2013
HES90 Other miscellaneous oil heating works for EES approval	£631.00	631.00	Not The Property Owner	19/04/2013
EES66 Low energy lamp replacement	£12.80	2.00	Sole Property Owner	01/11/2009
EES69 Miscellaneous Charge	£9.62	1.00	Sole Property Owner	01/11/2009
EES07 200mm thick loft insulation	£356.40	40.00	Not The Property Owner	30/03/2010
EES22 Mastic pointing	£30.00	1.00	Not The Property Owner	30/03/2010
EES66 Low energy lamp replacement	£56.00	32.00	Not The Property Owner	30/03/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	15/03/2010
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	18/07/2011
EES13a Cold water tank bye law kit (including associated products)	£280.00	1.00	Sole Property Owner	18/07/2011
EES33 Replacement hot water cylinder (150L)	£1,200.00	1.00	Sole Property Owner	18/07/2011
EES07 200mm thick loft insulation	£617.50	95.00	Sole Property Owner	18/07/2011
EES16 Insulation to 75mm wide cavity wall	£611.43	66.46	Sole Property Owner	18/07/2011
EES66 Low energy lamp replacement	£9.80	1.00	Sole Property Owner	05/07/2011
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	05/07/2011
EES69 Miscellaneous Charge	£22.20	1.00	Sole Property Owner	05/07/2011
EES38a Thermostatic radiator valve (per valve)	£595.00	7.00	Not The Property Owner	21/04/2011
EES52a 21-25kW Oil replacement boiler	£0.00	0.00	Not The Property Owner	21/04/2011
EES08 300mm thick loft insulation	£450.00	60.00	Not The Property Owner	21/04/2011
EES75 HEC to Flat or Bedsit	£150.00	1.00	Joint Owner	30/06/2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.60	1.00	Joint Owner	30/06/2010
EES07 200mm thick loft insulation	£418.77	47.00	Not The Property Owner	25/07/2011
EES06 100mm thick loft insulation	£213.28	31.00	Not The Property Owner	25/07/2011
EES25 Draught stripping to exterior door	£163.80	18.00	Not The Property Owner	25/07/2011
HES111 HER Survey for Flat	£120.00	1.00	Not The Property Owner	25/07/2011
EES50b 12-15kW Gas replacement boiler	£971.00	1.00	Sole Property Owner	28/02/2011
EES70 Miscellaneous heating review charge	£1,899.11	1,899.11	Sole Property Owner	28/02/2011
EES40 Hot water cylinder thermostat	£0.00	1.00	Sole Property Owner	28/02/2011
EES42 Two channel programmable heating controller	£0.00	1.00	Sole Property Owner	28/02/2011
EES66 Low energy lamp replacement	£96.00	10.00	Sole Property Owner	28/02/2011
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	28/02/2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	28/02/2011
EES06 100mm thick loft insulation	£330.00	44.00	Sole Property Owner	05/07/2011
EES 11 Cold water tank insulation jacket	£100.00	1.00	Sole Property Owner	05/07/2011
EES66 Low energy lamp replacement	£55.80	1.00	Joint Owner	25/05/2010
EES38a Thermostatic radiator valve (per valve)	£99.15	3.00	Joint Owner	25/05/2010
EES69 Miscellaneous Charge	£41.00	1.00	Joint Owner	25/05/2010
EES69 Miscellaneous Charge	£0.00	1.00	Joint Owner	30/01/2012
EES33 Replacement hot water cylinder (150L)	£1,538.40	1.00	Joint Owner	30/01/2012
EES 11 Cold water tank insulation jacket	£64.89	1.00	Joint Owner	30/01/2012
EES12 Cold water tank lid	£35.70	1.00	Joint Owner	30/01/2012

EES66 Low energy lamp replacement	£55.80	1.00	Joint Owner	30/01/2012	
EES25 Draught stripping to exterior door	£113.40	20.00	Joint Owner	30/01/2012	
EES69 Miscellaneous Charge	£41.00	1.00	Joint Owner	30/01/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	06/08/2010	
EES25 Draught stripping to exterior door	£100.10	11.00	Joint Owner	06/08/2010	
EES50b 12-15kW Gas replacement boiler	£1,221.93	1.00	Joint Owner	01/08/2011	
EES01a Loft Clearance (hourly rate)	£126.52	4.00	Joint Owner	01/08/2011	
EES03a Remove and replace nailed floor board	£118.00	10.00	Joint Owner	01/08/2011	
EES07 200mm thick loft insulation	£347.49	39.00	Joint Owner	01/08/2011	
EES06 100mm thick loft insulation	£268.32	39.00	Joint Owner	01/08/2011	
EES25 Draught stripping to exterior door	£109.20	12.00	Joint Owner	01/08/2011	
EES66 Low energy lamp replacement	£29.75	17.00	Joint Owner	01/08/2011	
EES67 Smoke detector installation	£9.80	1.00	Joint Owner	01/08/2011	
HES120 Standard QA check	£90.00	1.00	Joint Owner	01/08/2011	
HES85 Building Control Officer inspection undertaken	£103.85	1.00	Joint Owner	01/08/2011	
HES91 Other miscellaneous gas heating works for EES approval	£370.08	1.00	Joint Owner	01/08/2011	
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	14/03/2011	
EES69 Miscellaneous Charge	£18.20	2.00	Sole Property Owner	14/03/2011	
EES69 Miscellaneous Charge	£22.20	1.00	Sole Property Owner	14/03/2011	
EES34 Replacement hot water cylinder (170l)	£715.00	1.00	Sole Property Owner	14/03/2011	
EES66 Low energy lamp replacement	£3.50	2.00	Sole Property Owner	14/03/2011	
EES67 Smoke detector installation	£19.60	2.00	Sole Property Owner	14/03/2011	
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	14/03/2011	
EES01a Loft Clearance (hourly rate)	£189.78	6.00	Joint Owner	06/07/2010	
EES07 200mm thick loft insulation	£485.60	54.50	Joint Owner	06/07/2010	
EES06 100mm thick loft insulation	£374.96	54.50	Joint Owner	06/07/2010	
EES25 Draught stripping to exterior door	£227.50	25.00	Joint Owner	06/07/2010	
EES34 Replacement hot water cylinder (170l)	£715.00	1.00	Joint Owner	06/07/2010	
EES66 Low energy lamp replacement	£28.00	16.00	Joint Owner	06/07/2010	
EES67 Smoke detector installation	£9.80	1.00	Joint Owner	06/07/2010	
EES69 Miscellaneous Charge	£9.80	1.00	Joint Owner	06/07/2010	
HES120 Standard QA check	£90.00	1.00	Joint Owner	06/07/2010	
EES07 200mm thick loft insulation	£509.41	78.37	Sole Property Owner	02/08/2011	
EES51b 16-20kW Gas replacement boiler	£2,206.43	1.00	Sole Property Owner	02/08/2011	
EES42 Two channel programmable heating controller	£0.00	1.00	Sole Property Owner	02/08/2011	
EES40 Hot water cylinder thermostat	£0.00	1.00	Sole Property Owner	02/08/2011	
EES36 Electrical room thermostat	£0.00	1.00	Sole Property Owner	02/08/2011	
EES34 Replacement hot water cylinder (170l)	£1,200.00	1.00	Sole Property Owner	02/08/2011	
EES69 Miscellaneous Charge	£330.00	1.00	Sole Property Owner	02/08/2011	
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	02/08/2011	
EES69 Miscellaneous Charge	£250.00	10.00	Not The Property Owner	06/10/2011	
EES06 100mm thick loft insulation	£425.10	65.00	Not The Property Owner	06/10/2011	
EES75 HEC to Flat or Bedsit	£150.00	1.00	Not The Property Owner	06/10/2011	
EES25 Draught stripping to exterior door	£10.00	1.00	Not The Property Owner	06/10/2011	
EES34 Replacement hot water cylinder (170l)	£1,152.90	1.00	Sole Property Owner	22/06/2011	
EES52a 21-25kW Oil replacement boiler	£3,250.80	1.00	Sole Property Owner	22/06/2011	
EES42 Two channel programmable heating controller	£119.70	1.00	Sole Property Owner	22/06/2011	
EES36 Electrical room thermostat	£85.68	1.00	Sole Property Owner	22/06/2011	
EES44 Water heating time clock and boost	£152.46	1.00	Sole Property Owner	22/06/2011	
EES48 Pipework lagging 19mm thick to 22mm pipe	£108.30	10.00	Sole Property Owner	22/06/2011	
EES70 Miscellaneous heating review charge	£644.61	644.61	Sole Property Owner	22/06/2011	
EES07 200mm thick loft insulation	£127.50	17.00	Sole Property Owner	22/06/2011	
EES15 Insulation to 65mm wide cavity wall	£1,207.50	161.00	Sole Property Owner	22/06/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	22/06/2011	
EES66 Low energy lamp replacement	£0.00	1.00	Sole Property Owner	22/06/2011	
EES66 Low energy lamp replacement	£39.00	39.00	Sole Property Owner	22/06/2011	
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	22/06/2011	
HES101 Asbestos removal & disposal	£550.00	1.00	Sole Property Owner	22/06/2011	
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	22/06/2011	
HES72 Storage heater rated 2kW - 3kW	£430.12	1.00	Sole Property Owner	02/08/2012	
HES73 Storage heater rated 3kW - 4kW	£534.13	1.00	Sole Property Owner	02/08/2012	
HES97 Electrician	£224.00	7.00	Sole Property Owner	02/08/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	02/08/2012	
EES25 Draught stripping to exterior door	£100.10	11.00	Sole Property Owner	02/08/2012	
EES01a Loft Clearance (hourly rate)	£63.26	2.00	Not The Property Owner	10/07/2010	
EES02a Remove and dispose existing insulation (per squire metre)	£105.00	25.00	Not The Property Owner	10/07/2010	
EES07 200mm thick loft insulation	£267.30	30.00	Not The Property Owner	10/07/2010	
EES06 100mm thick loft insulation	£206.40	30.00	Not The Property Owner	10/07/2010	
EES22 Mastic pointing	£78.00	20.00	Not The Property Owner	10/07/2010	
EES26 Draught stripping to windows	£109.20	12.00	Not The Property Owner	10/07/2010	
EES69 Miscellaneous Charge	£45.50	5.00	Not The Property Owner	10/07/2010	
EES66 Low energy lamp replacement	£22.75	13.00	Not The Property Owner	10/07/2010	
EES67 Smoke detector installation	£9.80	1.00	Not The Property Owner	10/07/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	16/08/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/06/2010	
EES77 HEC to House	£150.00	1.00	Not The Property Owner	30/06/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/06/2010	
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Not The Property Owner	10/01/2010	
EES03a Remove and replace nailed floor board	£0.00	0.00	Not The Property Owner	10/01/2010	
EES07 200mm thick loft insulation	£0.00	0.00	Not The Property Owner	10/01/2010	
EES09 Intumescent bag/fire hood to downlighter	£0.00	0.00	Not The Property Owner	10/01/2010	
EES15 Insulation to 65mm wide cavity wall	£373.00	50.00	Not The Property Owner	10/01/2010	
EES69 Miscellaneous Charge	£36.40	4.00	Not The Property Owner	10/01/2010	
EES66 Low energy lamp replacement	£5.25	1.00	Not The Property Owner	10/01/2010	

EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	08/08/2010	
EES25 Draught stripping to exterior door	£149.70	16.45	Not The Property Owner	08/08/2010	
EES 11 Cold water tank insulation jacket	£64.89	1.00	Not The Property Owner	28/06/2010	
EES12 Cold water tank lid	£35.70	1.00	Not The Property Owner	28/06/2010	
EES47 Pipework lagging 13mm thick to 22mm pipe	£24.27	3.00	Not The Property Owner	28/06/2010	
EES66 Low energy lamp replacement	£55.80	1.00	Not The Property Owner	28/06/2010	
EES69 Miscellaneous Charge	£41.00	1.00	Not The Property Owner	28/06/2010	
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	05/07/2011	
EES66 Low energy lamp replacement	£90.96	8.00	Sole Property Owner	05/07/2011	
EES26 Draught stripping to windows	£46.80	2.00	Sole Property Owner	05/07/2011	
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	05/07/2011	
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	05/07/2011	
EES25 Draught stripping to exterior door	£100.00	10.00	Sole Property Owner	01/06/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	01/06/2011	
EES33 Replacement hot water cylinder (150l)	£980.00	1.00	Sole Property Owner	01/06/2011	
EES40 Hot water cylinder thermostat	£65.00	1.00	Sole Property Owner	01/06/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£40.00	5.00	Sole Property Owner	01/06/2011	
EES77 HEC to House	£150.00	1.00	Sole Property Owner	05/07/2010	
EES48 Pipework lagging 19mm thick to 22mm pipe	£1.09	1.00	Sole Property Owner	05/07/2010	
EES01a Loft Clearance (hourly rate)	£31.63	1.00	Sole Property Owner	05/07/2010	
EES06 100mm thick loft insulation	£254.56	37.00	Sole Property Owner	05/07/2010	
EES25 Draught stripping to exterior door	£91.00	10.00	Sole Property Owner	05/07/2010	
EES77 HEC to House	£150.00	1.00	Not The Property Owner	30/06/2010	
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.54	1.00	Not The Property Owner	30/06/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/06/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	19/05/2010	
EES25 Draught stripping to exterior door	£67.70	7.44	Not The Property Owner	19/05/2010	
EES07 200mm thick loft insulation	£474.50	73.00	Sole Property Owner	13/07/2010	
EES15 Insulation to 65mm wide cavity wall	£473.78	63.17	Sole Property Owner	13/07/2010	
HES22 Minimum per property charge	£50.00	1.00	Sole Property Owner	13/07/2010	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Joint Owner	10/07/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/06/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	08/08/2010	
EES25 Draught stripping to exterior door	£67.70	7.44	Not The Property Owner	08/08/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	05/09/2010	
EES25 Draught stripping to exterior door	£100.10	11.00	Not The Property Owner	05/09/2010	
EES01a Loft Clearance (hourly rate)	£46.80	1.00	Not The Property Owner	28/06/2010	
EES06 100mm thick loft insulation	£52.22	7.00	Not The Property Owner	28/06/2010	
EES07 200mm thick loft insulation	£20.80	2.00	Not The Property Owner	28/06/2010	
EES69 Miscellaneous Charge	£41.00	1.00	Not The Property Owner	28/06/2010	
EES01a Loft Clearance (hourly rate)	£253.04	8.00	Not The Property Owner	10/07/2010	
EES03a Remove and replace nailed floor board	£975.86	82.70	Not The Property Owner	10/07/2010	
EES07 200mm thick loft insulation	£335.02	37.60	Not The Property Owner	10/07/2010	
EES06 100mm thick loft insulation	£568.98	82.70	Not The Property Owner	10/07/2010	
EES09 Intumescent bag/fire hood to downlighter	£85.00	4.00	Not The Property Owner	10/07/2010	
EES10 Cold water tank insulation quilt	£37.42	1.00	Not The Property Owner	10/07/2010	
EES25 Draught stripping to exterior door	£136.50	15.00	Not The Property Owner	10/07/2010	
EES69 Miscellaneous Charge	£66.60	3.00	Not The Property Owner	10/07/2010	
EES38a Thermostatic radiator valve (per valve)	£484.00	11.00	Not The Property Owner	10/07/2010	
EES42 Two channel programmable heating controller	£111.00	1.00	Not The Property Owner	10/07/2010	
EES66 Low energy lamp replacement	£21.00	12.00	Not The Property Owner	10/07/2010	
EES67 Smoke detector installation	£9.80	1.00	Not The Property Owner	10/07/2010	
EES25 Draught stripping to exterior door	£120.00	12.00	Not The Property Owner	27/11/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	27/11/2010	
EES36 Electrical room thermostat	£61.60	1.00	Sole Property Owner	11/11/2011	
EES40 Hot water cylinder thermostat	£60.19	1.00	Sole Property Owner	11/11/2011	
EES42 Two channel programmable heating controller	£139.59	1.00	Sole Property Owner	11/11/2011	
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	11/11/2011	
EES70 Miscellaneous heating review charge	£1,900.12	1,900.12	Sole Property Owner	11/11/2011	
EES49 Pipework lagging 25mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	11/11/2011	
EES06 100mm thick loft insulation	£124.16	16.00	Sole Property Owner	11/11/2011	
EES15 Insulation to 65mm wide cavity wall	£786.45	105.00	Sole Property Owner	11/11/2011	
EES69 Miscellaneous Charge	£112.50	1.00	Sole Property Owner	11/11/2011	
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	11/11/2011	
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	11/11/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£121.35	15.00	Sole Property Owner	11/11/2011	
EES48 Pipework lagging 19mm thick to 22mm pipe	£73.76	8.00	Sole Property Owner	11/11/2011	
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	11/11/2011	
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	11/11/2011	
EES38a Thermostatic radiator valve (per valve)	£496.00	8.00	Sole Property Owner	11/11/2011	
EES34 Replacement hot water cylinder (170l)	£1,200.00	1.00	Sole Property Owner	11/11/2011	
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	11/11/2011	
HES85 Building Control Officer inspection undertaken	£103.85	1.00	Sole Property Owner	11/11/2011	
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Joint Owner	26/06/2012	
EES 83 Powerflush central heating system	£0.00	0.00	Joint Owner	26/06/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/06/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/06/2010	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/06/2010	
EES07 200mm thick loft insulation	£156.00	15.00	Joint Owner	30/06/2010	
EES03a Remove and replace nailed floor board	£182.00	70.00	Joint Owner	30/06/2010	
EES 11 Cold water tank insulation jacket	£129.78	2.00	Joint Owner	30/06/2010	
EES12 Cold water tank lid	£71.40	2.00	Joint Owner	30/06/2010	
EES47 Pipework lagging 13mm thick to 22mm pipe	£48.54	6.00	Joint Owner	30/06/2010	
EES48 Pipework lagging 19mm thick to 22mm pipe	£55.32	6.00	Joint Owner	30/06/2010	

EES66 Low energy lamp replacement	£55.80	1.00	Joint Owner	30/06/2010
EES42 Two channel programmable heating controller	£0.00	0.00	Joint Owner	30/06/2010
EES69 Miscellaneous Charge	£41.00	1.00	Joint Owner	30/06/2010
EES38a Thermostatic radiator valve (per valve)	£330.50	10.00	Joint Owner	30/06/2010
HES120 Standard QA check	£90.00	1.00	Joint Owner	30/06/2010
EES12 Cold water tank lid	£35.70	1.00	Not The Property Owner	28/06/2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Not The Property Owner	28/06/2010
EES66 Low energy lamp replacement	£55.80	1.00	Not The Property Owner	28/06/2010
EES69 Miscellaneous Charge	£41.00	1.00	Not The Property Owner	28/06/2010
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Sole Property Owner	01/11/2009
EES66 Low energy lamp replacement	£0.00	20.00	Sole Property Owner	01/11/2009
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	01/11/2009
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	01/11/2009
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	30/06/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	08/08/2010
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Not The Property Owner	08/08/2010
EES25 Draught stripping to exterior door	£113.20	12.44	Not The Property Owner	08/08/2010
EES77 HEC to House	£150.00	1.00	Not The Property Owner	28/10/2010
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Joint Owner	15/09/2010
EES02a Remove and dispose existing insulation (per squire metre)	£60.00	20.00	Joint Owner	15/09/2010
EES08 300mm thick loft insulation	£810.96	67.58	Joint Owner	15/09/2010
EES13a Cold water tank bye law kit (including associated products)	£280.00	1.00	Joint Owner	15/09/2010
EES69 Miscellaneous Charge	£535.00	1.00	Joint Owner	15/09/2010
EES12 Cold water tank lid	£35.70	1.00	Joint Owner	28/06/2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Joint Owner	28/06/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£46.10	5.00	Joint Owner	28/06/2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£16.18	2.00	Joint Owner	28/06/2010
EES66 Low energy lamp replacement	£55.80	1.00	Joint Owner	28/06/2010
EES69 Miscellaneous Charge	£41.00	1.00	Joint Owner	28/06/2010
EES69 Miscellaneous Charge	£350.00	1.00	Joint Owner	28/06/2010
EES01a Loft Clearance (hourly rate)	£126.52	4.00	Sole Property Owner	21/04/2011
EES03a Remove and replace nailed floor board	£767.00	65.00	Sole Property Owner	21/04/2011
EES07 200mm thick loft insulation	£1,299.08	145.80	Sole Property Owner	21/04/2011
EES06 100mm thick loft insulation	£1,003.10	145.80	Sole Property Owner	21/04/2011
EES09 Intumescent bag/fire hood to downlighter	£148.75	7.00	Sole Property Owner	21/04/2011
EES10 Cold water tank insulation quilt	£37.42	1.00	Sole Property Owner	21/04/2011
EES 11 Cold water tank insulation jacket	£32.03	1.00	Sole Property Owner	21/04/2011
EES21 Scaffold	£901.60	112.00	Sole Property Owner	21/04/2011
EES19 Airbrick	£18.40	2.00	Sole Property Owner	21/04/2011
EES18b Cavity brush (per metre)	£4.20	1.00	Sole Property Owner	21/04/2011
EES15 Insulation to 65mm wide cavity wall	£1,217.47	163.20	Sole Property Owner	21/04/2011
EES34 Replacement hot water cylinder (170l)	£715.00	1.00	Sole Property Owner	21/04/2011
EES38a Thermostatic radiator valve (per valve)	£132.00	3.00	Sole Property Owner	21/04/2011
EES36 Electrical room thermostat	£103.40	1.00	Sole Property Owner	21/04/2011
EES40 Hot water cylinder thermostat	£74.70	1.00	Sole Property Owner	21/04/2011
EES42 Two channel programmable heating controller	£111.00	1.00	Sole Property Owner	21/04/2011
EES66 Low energy lamp replacement	£59.50	34.00	Sole Property Owner	21/04/2011
EES67 Smoke detector installation	£9.80	1.00	Sole Property Owner	21/04/2011
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	21/04/2011
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	21/04/2011
EES03a Remove and replace nailed floor board	£495.60	42.00	Sole Property Owner	21/04/2011
EES07 200mm thick loft insulation	£374.22	42.00	Sole Property Owner	21/04/2011
EES09 Intumescent bag/fire hood to downlighter	£148.75	7.00	Sole Property Owner	21/04/2011
EES40 Hot water cylinder thermostat	£59.27	1.00	Sole Property Owner	19/07/2011
EES70 Miscellaneous heating review charge	£465.00	1.00	Sole Property Owner	19/07/2011
EES01a Loft Clearance (hourly rate)	£175.00	7.00	Sole Property Owner	19/07/2011
EES03a Remove and replace nailed floor board	£37.50	2.50	Sole Property Owner	19/07/2011
EES08 300mm thick loft insulation	£899.91	11.11	Sole Property Owner	19/07/2011
EES34 Replacement hot water cylinder (170l)	£1,200.00	1.00	Sole Property Owner	19/07/2011
EES 11 Cold water tank insulation jacket	£100.00	1.00	Sole Property Owner	19/07/2011
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	19/07/2011
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Not The Property Owner	26/01/2011
EES51b 16-20kW Gas replacement boiler	£1,544.00	1.00	Sole Property Owner	15/07/2011
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	15/07/2011
EES00a Full Energy Survey	£401.68	1.00	Not The Property Owner	30/04/2009
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	12/08/2011
HES111 HER Survey for Flat	£120.00	1.00	Not The Property Owner	12/08/2011
EES01a Loft Clearance (hourly rate)	£300.00	12.00	Joint Owner	22/09/2011
EES03a Remove and replace nailed floor board	£50.00	20.00	Joint Owner	22/09/2011
EES08 300mm thick loft insulation	£365.04	30.42	Joint Owner	22/09/2011
EES25 Draught stripping to exterior door	£170.00	17.00	Joint Owner	22/09/2011
HES120 Standard QA check	£90.00	1.00	Joint Owner	22/09/2011
HES90 Other miscellaneous oil heating works for EES approval	£70.00	1.00	Joint Owner	22/09/2011
EES77 HEC to House	£150.00	1.00	Not The Property Owner	21/07/2010
EES25 Draught stripping to exterior door	£100.10	11.00	Not The Property Owner	21/07/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	05/09/2010
EES25 Draught stripping to exterior door	£145.60	16.00	Sole Property Owner	05/09/2010
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	05/09/2010
EES27 Draught stripping to letterbox	£44.40	2.00	Sole Property Owner	05/09/2010
EES77 HEC to House	£150.00	1.00	Not The Property Owner	08/12/2010
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	09/06/2011
EES03a Remove and replace nailed floor board	£37.50	15.00	Sole Property Owner	09/06/2011
EES08 300mm thick loft insulation	£120.60	15.00	Sole Property Owner	09/06/2011
EES50b 12-15kW Gas replacement boiler	£1,657.05	1.00	Sole Property Owner	09/06/2011

HES01 Loft preparation labour (clearance, disposal of old insulation)	£30.00	3.00	Sole Property Owner	09/06/2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	09/06/2011
EES82 Boiler replacement miscellaneous works	£400.00	1.00	Sole Property Owner	09/06/2011
EES02a Remove and dispose existing insulation (per square metre)	£360.00	120.00	Joint Owner	19/05/2011
EES08 300mm thick loft insulation	£1,300.08	108.34	Joint Owner	19/05/2011
EES13a Cold water tank bye law kit (including associated products)	£280.00	1.00	Joint Owner	19/05/2011
HES120 Standard QA check	£90.00	1.00	Joint Owner	19/05/2011
EES34 Replacement hot water cylinder (170L)	£1,200.00	1.00	Sole Property Owner	20/06/2011
EES69 Miscellaneous Charge	£75.00	1.00	Sole Property Owner	20/06/2011
EES15 Insulation to 65mm wide cavity wall	£844.28	112.57	Sole Property Owner	20/06/2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	21/07/2010
HES111 HER Survey for Flat	£136.00	1.00	Joint Owner	24/04/2013
HES20 Low energy lamp installation	£0.00	8.00	Joint Owner	24/04/2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	26/01/2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	26/01/2011
EES81 Insulation to 50mm cavity	£179.40	26.00	Sole Property Owner	26/01/2011
EES77 HEC to House	£150.00	1.00	Not The Property Owner	21/07/2010
EES06 100mm thick loft insulation	£141.04	20.50	Sole Property Owner	16/08/2011
EES09 Intumescent bag/fire hood to downlighter	£85.00	4.00	Sole Property Owner	16/08/2011
EES10 Cold water tank insulation quilt	£32.02	1.00	Sole Property Owner	16/08/2011
EES15 Insulation to 65mm wide cavity wall	£723.62	97.00	Sole Property Owner	16/08/2011
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	16/08/2011
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	16/08/2011
EES69 Miscellaneous Charge	£22.20	1.00	Sole Property Owner	16/08/2011
EES66 Low energy lamp replacement	£24.50	14.00	Sole Property Owner	16/08/2011
EES08 300mm thick loft insulation	£315.80	20.00	Not The Property Owner	21/04/2011
EES77 HEC to House	£150.00	1.00	Not The Property Owner	21/04/2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	03/11/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	21/07/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	21/07/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£2.18	2.00	Not The Property Owner	21/07/2010
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Not The Property Owner	03/12/2012
EES03a Remove and replace nailed floor board	£0.00	0.00	Not The Property Owner	03/12/2012
EES07 200mm thick loft insulation	£0.00	0.00	Not The Property Owner	03/12/2012
EES09 Intumescent bag/fire hood to downlighter	£0.00	0.00	Not The Property Owner	03/12/2012
EES25 Draught stripping to exterior door	£45.50	5.00	Not The Property Owner	03/12/2012
EES69 Miscellaneous Charge	£22.20	1.00	Not The Property Owner	03/12/2012
EES34 Replacement hot water cylinder (170L)	£715.00	1.00	Not The Property Owner	03/12/2012
EES66 Low energy lamp replacement	£31.50	18.00	Not The Property Owner	03/12/2012
EES25 Draught stripping to exterior door	£300.30	33.00	Not The Property Owner	26/01/2011
EES27 Draught stripping to letterbox	£44.40	2.00	Not The Property Owner	26/01/2011
EES66 Low energy lamp replacement	£31.50	1.00	Not The Property Owner	26/01/2011
EES03b Remove and replace nailed floor board (hourly rate)	£50.00	20.00	Sole Property Owner	26/01/2012
EES08 300mm thick loft insulation	£516.00	43.00	Sole Property Owner	26/01/2012
EES50c Replacement electrical storage heater	£411.00	1.00	Sole Property Owner	26/01/2012
EES50c Replacement electrical storage heater	£950.00	2.00	Sole Property Owner	26/01/2012
EES06 100mm thick loft insulation	£261.44	38.00	Not The Property Owner	09/08/2010
EES25 Draught stripping to exterior door	£45.50	5.00	Not The Property Owner	09/08/2010
EES27 Draught stripping to letterbox	£22.20	1.00	Not The Property Owner	09/08/2010
EES38a Thermostatic radiator valve (per valve)	£352.00	8.00	Not The Property Owner	09/08/2010
EES66 Low energy lamp replacement	£22.75	13.00	Not The Property Owner	09/08/2010
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	21/07/2010
HES31 16-20kW Oil replacement condensing boiler	£1,582.64	1.00	Sole Property Owner	21/06/2011
HES55 2 port zone valve	£57.84	1.00	Sole Property Owner	21/06/2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£32.72	32.72	Sole Property Owner	21/06/2011
HES46 Automatic bypass	£64.20	1.00	Sole Property Owner	21/06/2011
HES63 Stainless steel replacement hot water cylinder (150L)	£1,050.63	1.00	Sole Property Owner	21/06/2011
HES90 Other miscellaneous oil heating works for EES approval	£1,108.86	1.00	Sole Property Owner	21/06/2011
HES99 Building works	£300.00	1.00	Sole Property Owner	21/06/2011
HES90 Other miscellaneous oil heating works for EES approval	£1,032.20	1.00	Sole Property Owner	21/06/2011
HES92 Other miscellaneous electrical heating works for EES approval	£590.00	1.00	Sole Property Owner	21/06/2011
EES07 200mm thick loft insulation	£481.14	54.00	Sole Property Owner	01/07/2011
EES 11 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	01/07/2011
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	01/07/2011
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	01/07/2011
EES26 Draught stripping to windows	£36.40	4.00	Sole Property Owner	01/07/2011
EES27 Draught stripping to letterbox	£44.40	2.00	Sole Property Owner	01/07/2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	01/07/2011
EES50c Replacement electrical storage heater	£886.00	2.00	Sole Property Owner	26/01/2012
EES69 Miscellaneous Charge	£30.00	1.00	Sole Property Owner	26/01/2012
EES19 Airbrick	£18.40	2.00	Sole Property Owner	26/01/2012
EES15 Insulation to 65mm wide cavity wall	£486.77	65.25	Sole Property Owner	26/01/2012
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	26/01/2012
EES69 Miscellaneous Charge	£199.80	9.00	Sole Property Owner	26/01/2012
EES66 Low energy lamp replacement	£19.25	11.00	Sole Property Owner	26/01/2012
EES69 Miscellaneous Charge	£147.25	1.00	Sole Property Owner	26/01/2012
EES07 200mm thick loft insulation	£291.20	28.00	Joint Owner	18/02/2011
EES13a Cold water tank bye law kit (including associated products)	£72.46	1.00	Joint Owner	18/02/2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£110.64	12.00	Joint Owner	18/02/2011
EES66 Low energy lamp replacement	£55.80	1.00	Joint Owner	18/02/2011
EES06 100mm thick loft insulation	£217.28	28.00	Not The Property Owner	12/12/2010
EES13a Cold water tank bye law kit (including associated products)	£0.00	0.00	Not The Property Owner	12/12/2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£24.27	3.00	Not The Property Owner	12/12/2010
EES49 Pipework lagging 25mm thick to 22mm pipe	£36.88	4.00	Not The Property Owner	12/12/2010

EES66 Low energy lamp replacement	£55.80	1.00	Not The Property Owner	12/12/2010	
EES67 Smoke detector installation	£0.00	1.00	Not The Property Owner	12/12/2010	
EES36 Electrical room thermostat	£105.00	1.00	Sole Property Owner	18/10/2012	
EES42 Two channel programmable heating controller	£105.00	1.00	Sole Property Owner	18/10/2012	
EES51a 16-20kW Oil replacement boiler	£2,900.00	1.00	Sole Property Owner	18/10/2012	
EES70 Miscellaneous heating review charge	£1,425.00	1.00	Sole Property Owner	18/10/2012	
EES01a Loft Clearance (hourly rate)	£70.20	3.00	Sole Property Owner	18/10/2012	
EES03a Remove and replace nailed floor board	£10.40	4.00	Sole Property Owner	18/10/2012	
EES06 100mm thick loft insulation	£558.72	72.00	Sole Property Owner	18/10/2012	
EES13a Cold water tank bye law kit (including associated products)	£72.46	1.00	Sole Property Owner	18/10/2012	
EES25 Draught stripping to exterior door	£90.36	12.00	Sole Property Owner	18/10/2012	
EES27 Draught stripping to letterbox	£15.41	1.00	Sole Property Owner	18/10/2012	
EES34 Replacement hot water cylinder (170l)	£871.23	1.00	Sole Property Owner	18/10/2012	
EES38a Thermostatic radiator valve (per valve)	£330.50	10.00	Sole Property Owner	18/10/2012	
EES42 Two channel programmable heating controller	£90.31	1.00	Sole Property Owner	18/10/2012	
EES49 Pipework lagging 25mm thick to 22mm pipe	£55.32	6.00	Sole Property Owner	18/10/2012	
EES49 Pipework lagging 25mm thick to 22mm pipe	£57.08	4.00	Sole Property Owner	18/10/2012	
EES40 Hot water cylinder thermostat	£44.59	1.00	Sole Property Owner	18/10/2012	
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	18/10/2012	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	18/10/2012	
EES00 Property Assessment	£185.00	1.00	Sole Property Owner	18/10/2012	
EES69 Miscellaneous Charge	£1,366.67	1.00	Sole Property Owner	18/10/2012	
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	18/10/2012	
EES25 Draught stripping to exterior door	£80.00	8.00	Not The Property Owner	01/11/2009	
EES66 Low energy lamp replacement	£0.00	11.00	Not The Property Owner	01/11/2009	
HES99 Building works	£51.10	1.00	Not The Property Owner	01/11/2009	
HES99 Building works	£56.30	1.00	Not The Property Owner	01/11/2009	
EES00a Full Energy Survey	£401.68	1.00	Not The Property Owner	01/11/2009	
HES73 Storage heater rated 3kW - 4kW	£375.34	1.00	Sole Property Owner	02/10/2013	
HES74 Comfort heat main switch	£57.20	1.00	Sole Property Owner	02/10/2013	
HES75 Storage heater consumer unit	£49.40	1.00	Sole Property Owner	02/10/2013	
HES76 Storage heater miniature circuit breaker	£19.50	2.00	Sole Property Owner	02/10/2013	
HES77 Main bonding of necessary services	£174.40	16.00	Sole Property Owner	02/10/2013	
HES78 Twin and earth 16mm cabling with clips and trunking	£298.72	16.00	Sole Property Owner	02/10/2013	
HES80 16mm meter tails	£12.48	1.00	Sole Property Owner	02/10/2013	
HES54 Water heating time clock and boost controller	£58.50	1.00	Sole Property Owner	02/10/2013	
HES65 Stainless steel replacement hot water cylinder (210L)	£322.17	1.00	Sole Property Owner	02/10/2013	
HES97 Electrician	£640.00	20.00	Sole Property Owner	02/10/2013	
HES94 Heating engineer	£512.00	16.00	Sole Property Owner	02/10/2013	
HES92 Other miscellaneous electrical heating works for EES approval	£242.00	1.00	Sole Property Owner	02/10/2013	
HES01 Loft preparation labour (clearance, disposal of old insulating material)	£250.00	10.00	Sole Property Owner	02/10/2013	
HES03 200mm thick loft insulation quilt	£665.00	70.00	Sole Property Owner	02/10/2013	
HES20 Low energy lamp installation	£0.00	3.00	Sole Property Owner	02/10/2013	
EES25 Draught stripping to exterior door	£86.50	10.00	Not The Property Owner	01/05/2011	
EES66 Low energy lamp replacement	£55.80	1.00	Not The Property Owner	01/05/2011	
EES67 Smoke detector installation	£0.00	0.00	Not The Property Owner	01/05/2011	
EES25 Draught stripping to exterior door	£60.24	8.00	Not The Property Owner	05/11/2010	
EES49 Pipework lagging 25mm thick to 22mm pipe	£40.45	5.00	Not The Property Owner	05/11/2010	
EES49 Pipework lagging 25mm thick to 22mm pipe	£110.64	12.00	Not The Property Owner	05/11/2010	
EES66 Low energy lamp replacement	£55.80	1.00	Not The Property Owner	05/11/2010	
EES67 Smoke detector installation	£0.00	1.00	Not The Property Owner	05/11/2010	
EES69 Miscellaneous Charge	£50.00	1.00	Not The Property Owner	12/08/2011	
EES77 HEC to House	£150.00	1.00	Not The Property Owner	12/08/2011	
EES50c Replacement electrical storage heater	£0.00	0.00	Sole Property Owner	16/01/2012	
EES01a Loft Clearance (hourly rate)	£70.20	3.00	Sole Property Owner	16/01/2012	
EES03a Remove and replace nailed floor board	£26.00	10.00	Sole Property Owner	16/01/2012	
EES06 100mm thick loft insulation	£186.24	24.00	Sole Property Owner	16/01/2012	
EES13b Cold water tank bye law kit (excluding associated products)	£72.46	1.00	Sole Property Owner	16/01/2012	
EES49 Pipework lagging 25mm thick to 22mm pipe	£64.72	8.00	Sole Property Owner	16/01/2012	
EES49 Pipework lagging 25mm thick to 22mm pipe	£221.28	24.00	Sole Property Owner	16/01/2012	
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	16/01/2012	
EES77 HEC to House	£150.00	1.00	Not The Property Owner	26/01/2011	
EES33 Replacement hot water cylinder (150l)	£532.93	1.00	Sole Property Owner	26/01/2012	
EES44 Water heating time clock and boost	£114.90	1.00	Sole Property Owner	26/01/2012	
EES40 Hot water cylinder thermostat	£44.59	1.00	Sole Property Owner	26/01/2012	
EES50c Replacement electrical storage heater	£822.00	2.00	Sole Property Owner	26/01/2012	
EES50c Replacement electrical storage heater	£475.00	1.00	Sole Property Owner	26/01/2012	
EES01a Loft Clearance (hourly rate)	£46.80	2.00	Sole Property Owner	26/01/2012	
EES06 100mm thick loft insulation	£388.00	50.00	Sole Property Owner	26/01/2012	
EES13a Cold water tank bye law kit (including associated products)	£72.46	1.00	Sole Property Owner	26/01/2012	
EES49 Pipework lagging 25mm thick to 22mm pipe	£92.00	10.00	Sole Property Owner	26/01/2012	
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	26/01/2012	
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Sole Property Owner	12/10/2010	
EES03a Remove and replace nailed floor board	£0.00	0.00	Sole Property Owner	12/10/2010	
EES07 200mm thick loft insulation	£0.00	0.00	Sole Property Owner	12/10/2010	
EES48 Pipework lagging 19mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	12/10/2010	
EES66 Low energy lamp replacement	£0.00	0.00	Sole Property Owner	12/10/2010	
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Sole Property Owner	01/11/2009	
EES03a Remove and replace nailed floor board	£37.50	15.00	Sole Property Owner	01/11/2009	
EES07 200mm thick loft insulation	£783.00	87.00	Sole Property Owner	01/11/2009	
EES13b Cold water tank bye law kit (excluding associated products)	£560.00	2.00	Sole Property Owner	01/11/2009	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	01/11/2009	
EES69 Miscellaneous Charge	£105.00	3.00	Sole Property Owner	01/11/2009	
EES27 Draught stripping to letterbox	£40.00	1.00	Sole Property Owner	01/11/2009	

EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	01/11/2009	
EES01a Loft Clearance (hourly rate)	£200.00	10.00	Joint Owner	22/06/2011	
EES02b Remove and dispose existing insulation (hourly rate)	£40.00	2.00	Joint Owner	22/06/2011	
EES03b Remove and replace nailed floor board (hourly rate)	£40.00	2.00	Joint Owner	22/06/2011	
EES06 100mm thick loft insulation	£346.50	63.00	Joint Owner	22/06/2011	
EES10 Cold water tank insulation quilt	£0.00	0.00	Joint Owner	22/06/2011	
EES 11 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	22/06/2011	
EES12 Cold water tank lid	£50.00	1.00	Joint Owner	22/06/2011	
EES13b Cold water tank bye law kit (excluding associated product)	£25.00	1.00	Joint Owner	22/06/2011	
EES22 Mastic pointing	£30.00	10.00	Joint Owner	22/06/2011	
EES25 Draught stripping to exterior door	£24.00	8.00	Joint Owner	22/06/2011	
EES26 Draught stripping to windows	£24.00	8.00	Joint Owner	22/06/2011	
EES27 Draught stripping to letterbox	£30.00	1.00	Joint Owner	22/06/2011	
EES 30 Hot water cylinder jacket (46x18 inch)	£60.00	1.00	Joint Owner	22/06/2011	
EES36 Electrical room thermostat	£105.00	1.00	Joint Owner	22/06/2011	
EES38a Thermostatic radiator valve (per valve)	£387.00	9.00	Joint Owner	22/06/2011	
EES42 Two channel programmable heating controller	£105.00	1.00	Joint Owner	22/06/2011	
EES44 Water heating time clock and boost	£125.00	1.00	Joint Owner	22/06/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£80.00	10.00	Joint Owner	22/06/2011	
EES50a 12-15kW Oil replacement boiler	£2,620.00	1.00	Joint Owner	22/06/2011	
EES64 Dual flush retrofit device	£100.00	2.00	Joint Owner	22/06/2011	
EES66 Low energy lamp replacement	£40.00	1.00	Joint Owner	22/06/2011	
EES67 Smoke detector installation	£30.00	1.00	Joint Owner	22/06/2011	
EES00 Property Assessment	£185.00	1.00	Joint Owner	22/06/2011	
HES121 Boiler QA Check	£105.00	1.00	Joint Owner	22/06/2011	
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Sole Property Owner	21/04/2011	
EES02a Remove and dispose existing insulation (per square metre)	£72.99	24.33	Sole Property Owner	21/04/2011	
EES07 200mm thick loft insulation	£252.00	28.00	Sole Property Owner	21/04/2011	
EES08 300mm thick loft insulation	£204.00	17.00	Sole Property Owner	21/04/2011	
EES66 Low energy lamp replacement	£0.00	0.00	Sole Property Owner	21/04/2011	
EES67 Smoke detector installation	£0.00	0.00	Sole Property Owner	21/04/2011	
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	21/04/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	22/10/2010	
EES01a Loft Clearance (hourly rate)	£96.00	4.00	Sole Property Owner	21/04/2011	
EES02a Remove and dispose existing insulation (per square metre)	£201.60	48.00	Sole Property Owner	21/04/2011	
EES06 100mm thick loft insulation	£330.24	48.00	Sole Property Owner	21/04/2011	
EES07 200mm thick loft insulation	£427.68	48.00	Sole Property Owner	21/04/2011	
EES09 Intumescent bag/fire hood to downlighter	£195.75	9.00	Sole Property Owner	21/04/2011	
EES 11 Cold water tank insulation jacket	£41.25	1.00	Sole Property Owner	21/04/2011	
EES15 Insulation to 65mm wide cavity wall	£1,538.22	186.00	Sole Property Owner	21/04/2011	
EES18a Cavity brush (per brush)	£80.00	10.00	Sole Property Owner	21/04/2011	
EES66 Low energy lamp replacement	£63.00	1.00	Sole Property Owner	21/04/2011	
EES67 Smoke detector installation	£9.80	1.00	Sole Property Owner	21/04/2011	
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	21/04/2011	
EES50c Replacement electrical storage heater	£701.00	1.00	Sole Property Owner	15/08/2011	
EES02a Remove and dispose existing insulation (per square metre)	£96.00	32.00	Sole Property Owner	15/08/2011	
EES08 300mm thick loft insulation	£384.00	32.00	Sole Property Owner	15/08/2011	
EES35 Replacement hot water cylinder (210l)	£0.00	0.00	Sole Property Owner	15/08/2011	
EES66 Low energy lamp replacement	£0.00	1.00	Sole Property Owner	15/08/2011	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	15/08/2011	
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Sole Property Owner	15/08/2011	
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	15/08/2011	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	15/08/2011	
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	15/08/2011	
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Sole Property Owner	15/08/2011	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	15/08/2011	
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	15/08/2011	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	26/01/2011	
EES66 Low energy lamp replacement	£0.00	16.00	Sole Property Owner	26/01/2011	
EES67 Smoke detector installation	£0.00	3.00	Sole Property Owner	26/01/2011	
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Not The Property Owner	26/01/2011	
EES66 Low energy lamp replacement	£0.00	12.00	Not The Property Owner	26/01/2011	
EES67 Smoke detector installation	£0.00	2.00	Not The Property Owner	26/01/2011	
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Sole Property Owner	31/05/2011	
EES07 200mm thick loft insulation	£225.00	25.00	Sole Property Owner	31/05/2011	
EES02a Remove and dispose existing insulation (per square metre)	£0.00	0.00	Sole Property Owner	31/05/2011	
EES08 300mm thick loft insulation	£0.00	0.00	Sole Property Owner	31/05/2011	
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	31/05/2011	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	31/05/2011	
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Sole Property Owner	31/05/2011	
EES66 Low energy lamp replacement	£0.00	17.00	Sole Property Owner	31/05/2011	
EES67 Smoke detector installation	£0.00	3.00	Sole Property Owner	31/05/2011	
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	31/05/2011	
EES48 Pipework lagging 19mm thick to 22mm pipe	£153.00	17.00	Sole Property Owner	26/01/2011	
EES69 Miscellaneous Charge	£105.00	3.00	Sole Property Owner	26/01/2011	
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Sole Property Owner	26/01/2011	
EES08 300mm thick loft insulation	£1,080.00	90.00	Sole Property Owner	26/01/2011	
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	26/01/2011	
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	26/01/2011	
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	26/01/2011	
EES13b Cold water tank bye law kit (excluding associated product)	£100.00	2.00	Sole Property Owner	26/01/2011	
EES38a Thermostatic radiator valve (per valve)	£425.00	5.00	Sole Property Owner	26/01/2011	
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	26/01/2011	
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	26/01/2011	

EES08 300mm thick loft insulation	£947.40	60.00	Sole Property Owner	26/01/2011
EES15 Insulation to 65mm wide cavity wall	£682.28	82.50	Sole Property Owner	26/01/2011
EES19 Airbrick	£64.40	7.00	Sole Property Owner	26/01/2011
EES66 Low energy lamp replacement	£63.00	1.00	Sole Property Owner	26/01/2011
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	26/01/2011
EES01a Loft Clearance (hourly rate)	£158.13	2.50	Sole Property Owner	01/02/2010
EES03a Remove and replace nailed floor board	£590.00	50.00	Sole Property Owner	01/02/2010
EES02a Remove and dispose existing insulation (per squire metre)	£205.80	98.00	Sole Property Owner	01/02/2010
EES08 300mm thick loft insulation	£1,547.42	98.00	Sole Property Owner	01/02/2010
EES25 Draught stripping to exterior door	£109.20	12.00	Sole Property Owner	01/02/2010
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	01/02/2010
EES69 Miscellaneous Charge	£83.20	2.00	Sole Property Owner	01/02/2010
EES66 Low energy lamp replacement	£61.25	35.00	Sole Property Owner	01/02/2010
EES52b 21-25kW Gas replacement boiler	£2,588.45	1.00	Sole Property Owner	01/02/2010
EES70 Miscellaneous heating review charge	£114.84	1.00	Sole Property Owner	01/02/2010
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	01/02/2010
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Sole Property Owner	01/02/2010
EES07 200mm thick loft insulation	£0.00	0.00	Sole Property Owner	01/02/2010
EES25 Draught stripping to exterior door	£0.00	2.00	Sole Property Owner	01/02/2010
EES10 Cold water tank insulation quilt	£0.00	0.00	Sole Property Owner	01/02/2010
EES 11 Cold water tank insulation jacket	£0.00	0.00	Sole Property Owner	01/02/2010
EES12 Cold water tank lid	£0.00	0.00	Sole Property Owner	01/02/2010
EES13a Cold water tank bye law kit (including associated product)	£0.00	0.00	Sole Property Owner	01/02/2010
EES69 Miscellaneous Charge	£104.65	1.00	Sole Property Owner	01/02/2010
EES69 Miscellaneous Charge	£23.68	1.00	Sole Property Owner	01/02/2010
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	01/02/2010
HES85 Building Control Officer inspection undertaken	£103.85	1.00	Sole Property Owner	01/02/2010
EES 30 Hot water cylinder jacket (46x18 inch)	£47.04	1.00	Sole Property Owner	01/02/2010
EES38a Thermostatic radiator valve (per valve)	£484.12	13.00	Sole Property Owner	01/02/2010
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Sole Property Owner	
EES07 200mm thick loft insulation	£237.60	22.00	Sole Property Owner	
EES13a Cold water tank bye law kit (including associated product)	£0.00	0.00	Sole Property Owner	
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	
EES22 Mastic pointing	£0.00	0.00	Sole Property Owner	
EES25 Draught stripping to exterior door	£0.00	0.00	Sole Property Owner	
EES26 Draught stripping to windows	£0.00	0.00	Sole Property Owner	
EES27 Draught stripping to letterbox	£0.00	0.00	Sole Property Owner	
EES48 Pipework lagging 19mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	
EES66 Low energy lamp replacement	£0.00	0.00	Sole Property Owner	
EES67 Smoke detector installation	£0.00	0.00	Sole Property Owner	
EES01a Loft Clearance (hourly rate)	£48.00	2.00	Joint Owner	21/04/2011
EES06 100mm thick loft insulation	£295.84	43.00	Joint Owner	21/04/2011
EES07 200mm thick loft insulation	£383.13	43.00	Joint Owner	21/04/2011
EES15 Insulation to 65mm wide cavity wall	£818.73	99.00	Joint Owner	21/04/2011
EES26 Draught stripping to windows	£36.40	4.00	Joint Owner	21/04/2011
EES66 Low energy lamp replacement	£63.00	1.00	Joint Owner	21/04/2011
HES120 Standard QA check	£90.00	1.00	Joint Owner	21/04/2011
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Joint Owner	21/04/2011
EES02a Remove and dispose existing insulation (per squire metre)	£112.98	37.66	Joint Owner	21/04/2011
EES03a Remove and replace nailed floor board	£12.00	4.00	Joint Owner	21/04/2011
EES08 300mm thick loft insulation	£432.00	36.00	Joint Owner	21/04/2011
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	21/04/2011
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	21/04/2011
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	21/04/2011
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Joint Owner	21/04/2011
EES44 Water heating time clock and boost	£0.00	0.00	Joint Owner	21/04/2011
EES66 Low energy lamp replacement	£0.00	8.00	Joint Owner	21/04/2011
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	21/04/2011
EES70 Miscellaneous heating review charge	£15.00	1.00	Joint Owner	21/04/2011
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Joint Owner	22/11/2011
EES03a Remove and replace nailed floor board	£0.00	0.00	Joint Owner	22/11/2011
EES07 200mm thick loft insulation	£486.00	45.00	Joint Owner	22/11/2011
EES13a Cold water tank bye law kit (including associated product)	£0.00	0.00	Joint Owner	22/11/2011
EES34 Replacement hot water cylinder (170l)	£0.00	0.00	Joint Owner	22/11/2011
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Joint Owner	22/11/2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£0.00	0.00	Joint Owner	22/11/2011
EES53a 26-35kW Oil replacement boiler	£0.00	0.00	Joint Owner	22/11/2011
EES66 Low energy lamp replacement	£32.00	1.00	Joint Owner	22/11/2011
EES67 Smoke detector installation	£0.00	0.00	Joint Owner	22/11/2011
EES01a Loft Clearance (hourly rate)	£400.00	20.00	Sole Property Owner	09/06/2011
EES02b Remove and dispose existing insulation (hourly rate)	£20.00	1.00	Sole Property Owner	09/06/2011
EES06 100mm thick loft insulation	£396.00	72.00	Sole Property Owner	09/06/2011
EES25 Draught stripping to exterior door	£30.00	10.00	Sole Property Owner	09/06/2011
EES58 Low flow showerhead	£70.00	1.00	Sole Property Owner	09/06/2011
EES64 Dual flush retrofit device	£100.00	2.00	Sole Property Owner	09/06/2011
EES66 Low energy lamp replacement	£40.00	1.00	Sole Property Owner	09/06/2011
EES67 Smoke detector installation	£30.00	1.00	Sole Property Owner	09/06/2011
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	09/06/2011
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Sole Property Owner	02/07/2012
EES02a Remove and dispose existing insulation (per squire metre)	£0.00	0.00	Sole Property Owner	02/07/2012
EES08 300mm thick loft insulation	£0.00	0.00	Sole Property Owner	02/07/2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	02/07/2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	02/07/2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	02/07/2012

EES13a Cold water tank bye law kit (including associated product	£100.00	2.00	Sole Property Owner	02/07/2012	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	02/07/2012	
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	02/07/2012	
EES38a Thermostatic radiator valve (per valve)	£765.00	9.00	Sole Property Owner	02/07/2012	
EES42 Two channel programmable heating controller	£0.00	0.00	Sole Property Owner	02/07/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£182.00	26.00	Sole Property Owner	02/07/2012	
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	02/07/2012	
EES66 Low energy lamp replacement	£0.00	30.00	Sole Property Owner	02/07/2012	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	02/07/2012	
EES70 Miscellaneous heating review charge	£540.00	1.00	Sole Property Owner	02/07/2012	
HES118 Ecological Survey	£305.00	1.00	Sole Property Owner	02/07/2012	
EES25 Draught stripping to exterior door	£30.00	10.00	Sole Property Owner	21/04/2011	
EES26 Draught stripping to windows	£21.00	7.00	Sole Property Owner	21/04/2011	
EES27 Draught stripping to letterbox	£30.00	1.00	Sole Property Owner	21/04/2011	
EES33 Replacement hot water cylinder (150l)	£980.00	1.00	Sole Property Owner	21/04/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£160.00	20.00	Sole Property Owner	21/04/2011	
EES66 Low energy lamp replacement	£40.00	1.00	Sole Property Owner	21/04/2011	
EES67 Smoke detector installation	£30.00	1.00	Sole Property Owner	21/04/2011	
EES02a Remove and dispose existing insulation (per square metre	£165.00	55.00	Joint Owner	19/04/2013	
EES08 300mm thick loft insulation	£660.00	55.00	Joint Owner	19/04/2013	
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	19/04/2013	
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	19/04/2013	
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	19/04/2013	
EES13a Cold water tank bye law kit (including associated product	£100.00	2.00	Joint Owner	19/04/2013	
EES26 Draught stripping to windows	£0.00	0.00	Joint Owner	19/04/2013	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Joint Owner	19/04/2013	
EES66 Low energy lamp replacement	£0.00	10.00	Joint Owner	19/04/2013	
EES67 Smoke detector installation	£0.00	3.00	Joint Owner	19/04/2013	
EES47 Pipework lagging 13mm thick to 22mm pipe	£28.00	4.00	Joint Owner	19/04/2013	
HES108 Electric flow boiler 12-15kW	£980.70	1.00	Joint Owner	19/04/2013	
HES44 Pipework / feed modifications	£300.00	1.00	Joint Owner	19/04/2013	
HES46 Automatic bypass	£31.85	1.00	Joint Owner	19/04/2013	
HES48 Power / system flush and treatment	£102.70	1.00	Joint Owner	19/04/2013	
HES78 Twin and earth 16mm cabling with clips and trunking	£298.72	16.00	Joint Owner	19/04/2013	
HES79 Heating point twin and earth mini trunk DP switch	£152.84	1.00	Joint Owner	19/04/2013	
HES80 16mm meter tails	£12.48	1.00	Joint Owner	19/04/2013	
HES81 2.5mm cabling	£7.30	10.00	Joint Owner	19/04/2013	
HES115 Supply MCB	£5.49	1.00	Joint Owner	19/04/2013	
HES116 Supply of suitably rated isolator	£27.05	1.00	Joint Owner	19/04/2013	
HES50 Electrical room thermostat	£20.97	1.00	Joint Owner	19/04/2013	
HES52 Hot water cylinder thermostat	£24.84	1.00	Joint Owner	19/04/2013	
HES53 Two channel heating programmer control	£71.83	1.00	Joint Owner	19/04/2013	
HES54 Water heating time clock and boost controller	£58.50	1.00	Joint Owner	19/04/2013	
HES55 2 port zone valve	£88.40	1.00	Joint Owner	19/04/2013	
HES94 Heating engineer	£768.00	24.00	Joint Owner	19/04/2013	
HES97 Electrician	£768.00	24.00	Joint Owner	19/04/2013	
HES99 Building works	£240.00	8.00	Joint Owner	19/04/2013	
HES51 Thermostatic radiator valve	£0.00	0.00	Joint Owner	19/04/2013	
EES00a Full Energy Survey	£401.68	1.00	Not The Property Owner	22/07/2009	
EES47 Pipework lagging 13mm thick to 22mm pipe	£84.00	12.00	Joint Owner	02/06/2011	
EES49 Pipework lagging 25mm thick to 22mm pipe	£154.00	14.00	Joint Owner	02/06/2011	
EES69 Miscellaneous Charge	£281.99	1.00	Joint Owner	02/06/2011	
EES52b 21-25kW Gas replacement boiler	£3,462.00	1.00	Joint Owner	02/06/2011	
EES70 Miscellaneous heating review charge	£325.00	1.00	Joint Owner	02/06/2011	
EES70 Miscellaneous heating review charge	£1,084.93	1.00	Joint Owner	02/06/2011	
EES06 100mm thick loft insulation	£327.00	50.00	Joint Owner	02/06/2011	
EES07 200mm thick loft insulation	£855.00	95.00	Joint Owner	02/06/2011	
EES01a Loft Clearance (hourly rate)	£450.00	18.00	Joint Owner	02/06/2011	
EES03a Remove and replace nailed floor board	£0.00	0.00	Joint Owner	02/06/2011	
EES08 300mm thick loft insulation	£0.00	0.00	Joint Owner	02/06/2011	
EES25 Draught stripping to exterior door	£60.00	6.00	Joint Owner	02/06/2011	
EES 30 Hot water cylinder jacket (46x18 inch)	£0.00	0.00	Joint Owner	02/06/2011	
EES38a Thermostatic radiator valve (per valve)	£595.00	7.00	Joint Owner	02/06/2011	
EES42 Two channel programmable heating controller	£0.00	0.00	Joint Owner	02/06/2011	
EES66 Low energy lamp replacement	£0.00	0.00	Joint Owner	02/06/2011	
EES67 Smoke detector installation	£0.00	0.00	Joint Owner	02/06/2011	
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	02/06/2011	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	02/06/2011	
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	02/06/2011	
EES13b Cold water tank bye law kit (excluding associated product	£50.00	1.00	Joint Owner	02/06/2011	
EES44 Water heating time clock and boost	£130.00	1.00	Joint Owner	02/06/2011	
HES120 Standard QA check	£75.00	1.00	Joint Owner	02/06/2011	
HES121 Boiler QA Check	£90.00	1.00	Joint Owner	02/06/2011	
EES25 Draught stripping to exterior door	£0.00	0.00	Not The Property Owner	09/11/2010	
EES26 Draught stripping to windows	£0.00	0.00	Not The Property Owner	09/11/2010	
EES27 Draught stripping to letterbox	£0.00	0.00	Not The Property Owner	09/11/2010	
EES66 Low energy lamp replacement	£0.00	0.00	Not The Property Owner	09/11/2010	
EES07 200mm thick loft insulation	£639.00	71.00	Sole Property Owner	21/04/2011	
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	21/04/2011	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	21/04/2011	
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	21/04/2011	
EES13b Cold water tank bye law kit (excluding associated product	£50.00	1.00	Sole Property Owner	21/04/2011	
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Sole Property Owner	21/04/2011	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	21/04/2011	

EES66 Low energy lamp replacement	£0.00	20.00	Sole Property Owner	21/04/2011	
EES67 Smoke detector installation	£0.00	3.00	Sole Property Owner	21/04/2011	
EES69 Miscellaneous Charge	£75.00	3.00	Sole Property Owner	21/04/2011	
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	21/04/2011	
EES16 Insulation to 75mm wide cavity wall	£230.72	26.07	Sole Property Owner	26/01/2011	
EES21 Scaffold	£615.00	60.00	Sole Property Owner	26/01/2011	
EES66 Low energy lamp replacement	£63.00	1.00	Sole Property Owner	26/01/2011	
EES67 Smoke detector installation	£9.80	1.00	Sole Property Owner	26/01/2011	
EES16 Insulation to 75mm wide cavity wall	£725.08	81.93	Sole Property Owner	26/01/2011	
EES01a Loft Clearance (hourly rate)	£240.00	12.00	Sole Property Owner	21/04/2011	
EES02b Remove and dispose existing insulation (hourly rate)	£140.00	7.00	Sole Property Owner	21/04/2011	
EES03b Remove and replace nailed floor board (hourly rate)	£80.00	4.00	Sole Property Owner	21/04/2011	
EES06 100mm thick loft insulation	£346.50	63.00	Sole Property Owner	21/04/2011	
EES64 Dual flush retrofit device	£50.00	1.00	Sole Property Owner	21/04/2011	
EES66 Low energy lamp replacement	£40.00	1.00	Sole Property Owner	21/04/2011	
EES67 Smoke detector installation	£30.00	1.00	Sole Property Owner	21/04/2011	
HES100 Asbestos survey & sample	£166.00	1.00	Sole Property Owner	21/04/2011	
HES73 Storage heater rated 3kW - 4kW	£416.82	1.00	Sole Property Owner	21/04/2011	
HES97 Electrician	£200.00	8.00	Sole Property Owner	21/04/2011	
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	21/04/2011	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Joint Owner	12/08/2011	
EES36 Electrical room thermostat	£135.00	1.00	Joint Owner	12/08/2011	
EES38a Thermostatic radiator valve (per valve)	£595.00	7.00	Joint Owner	12/08/2011	
EES40 Hot water cylinder thermostat	£85.00	1.00	Joint Owner	12/08/2011	
EES50a 12-15kW Oil replacement boiler	£0.00	0.00	Joint Owner	12/08/2011	
EES69 Miscellaneous Charge	£245.00	1.00	Joint Owner	12/08/2011	
EES50c Replacement electrical storage heater	£2,220.00	1.00	Joint Owner	12/08/2011	
EES69 Miscellaneous Charge	£417.77	1.00	Joint Owner	12/08/2011	
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Joint Owner	12/08/2011	
EES02a Remove and dispose existing insulation (per square metre)	£144.00	48.00	Joint Owner	12/08/2011	
EES03a Remove and replace nailed floor board	£12.00	4.00	Joint Owner	12/08/2011	
EES08 300mm thick loft insulation	£576.00	48.00	Joint Owner	12/08/2011	
EES10 Cold water tank insulation quilt	£0.00	0.00	Joint Owner	12/08/2011	
EES 11 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	12/08/2011	
EES66 Low energy lamp replacement	£0.00	1.00	Joint Owner	12/08/2011	
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	12/08/2011	
EES12 Cold water tank lid	£0.00	0.00	Joint Owner	12/08/2011	
EES13b Cold water tank bye law kit (excluding associated product)	£0.00	0.00	Joint Owner	12/08/2011	
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	12/08/2011	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	12/08/2011	
EES12 Cold water tank lid	£0.00	0.00	Joint Owner	12/08/2011	
EES13b Cold water tank bye law kit (excluding associated product)	£0.00	0.00	Joint Owner	12/08/2011	
HES120 Standard QA check	£75.00	1.00	Joint Owner	12/08/2011	
HES121 Boiler QA Check	£90.00	1.00	Joint Owner	12/08/2011	
EES01a Loft Clearance (hourly rate)	£161.48	11.00	Sole Property Owner	07/11/2012	
EES02b Remove and dispose existing insulation (hourly rate)	£80.00	4.00	Sole Property Owner	07/11/2012	
EES03b Remove and replace nailed floor board (hourly rate)	£100.00	5.00	Sole Property Owner	07/11/2012	
EES06 100mm thick loft insulation	£440.00	80.00	Sole Property Owner	07/11/2012	
EES09 Intumescent bag/fire hood to downlighter	£40.00	4.00	Sole Property Owner	07/11/2012	
EES10 Cold water tank insulation quilt	£5.00	1.00	Sole Property Owner	07/11/2012	
EES 11 Cold water tank insulation jacket	£50.00	1.00	Sole Property Owner	07/11/2012	
EES13b Cold water tank bye law kit (excluding associated product)	£25.00	1.00	Sole Property Owner	07/11/2012	
EES25 Draught stripping to exterior door	£72.00	24.00	Sole Property Owner	07/11/2012	
EES26 Draught stripping to windows	£15.00	5.00	Sole Property Owner	07/11/2012	
EES29 Hot water cylinder jacket (30x18 inch)	£45.00	1.00	Sole Property Owner	07/11/2012	
EES38a Thermostatic radiator valve (per valve)	£473.00	11.00	Sole Property Owner	07/11/2012	
EES42 Two channel programmable heating controller	£105.00	1.00	Sole Property Owner	07/11/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£160.00	20.00	Sole Property Owner	07/11/2012	
EES50a 12-15kW Oil replacement boiler	£2,620.00	1.00	Sole Property Owner	07/11/2012	
EES66 Low energy lamp replacement	£40.00	1.00	Sole Property Owner	07/11/2012	
EES67 Smoke detector installation	£30.00	1.00	Sole Property Owner	07/11/2012	
EES15 Insulation to 65mm wide cavity wall	£525.00	70.00	Sole Property Owner	07/11/2012	
EES00 Property Assessment	£185.00	1.00	Sole Property Owner	07/11/2012	
EES69 Miscellaneous Charge	£2,373.43	1.00	Sole Property Owner	07/11/2012	
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	07/11/2012	
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Sole Property Owner	22/11/2011	
EES07 200mm thick loft insulation	£0.00	0.00	Sole Property Owner	22/11/2011	
EES13a Cold water tank bye law kit (including associated product)	£0.00	0.00	Sole Property Owner	22/11/2011	
EES25 Draught stripping to exterior door	£0.00	0.00	Sole Property Owner	22/11/2011	
EES40 Hot water cylinder thermostat	£0.00	0.00	Sole Property Owner	22/11/2011	
EES48 Pipework lagging 19mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	22/11/2011	
EES64 Dual flush retrofit device	£0.00	0.00	Sole Property Owner	22/11/2011	
EES66 Low energy lamp replacement	£0.00	0.00	Sole Property Owner	22/11/2011	
EES67 Smoke detector installation	£0.00	0.00	Sole Property Owner	22/11/2011	
HES70 Storage heater rated < 1kW	£0.00	0.00	Joint Owner	02/08/2012	
EES02a Remove and dispose existing insulation (per square metre)	£30.00	8.00	Joint Owner	02/08/2012	
EES07 200mm thick loft insulation	£86.40	8.00	Joint Owner	02/08/2012	
EES13a Cold water tank bye law kit (including associated product)	£428.00	1.00	Joint Owner	02/08/2012	
EES48 Pipework lagging 19mm thick to 22mm pipe	£189.75	15.00	Joint Owner	02/08/2012	
EES66 Low energy lamp replacement	£32.00	1.00	Joint Owner	02/08/2012	
HES71 Storage heater rated 1kW - 2kW	£489.06	2.00	Joint Owner	02/08/2012	
HES75 Storage heater consumer unit	£49.40	1.00	Joint Owner	02/08/2012	
HES76 Storage heater miniature circuit breaker	£29.25	3.00	Joint Owner	02/08/2012	
HES77 Main bonding of necessary services	£10.90	1.00	Joint Owner	02/08/2012	

HES80 16mm meter tails	£12.48	1.00	Joint Owner	02/08/2012
HES97 Electrician	£448.00	14.00	Joint Owner	02/08/2012
HES92 Other miscellaneous electrical heating works for EES appr	£57.68	1.00	Joint Owner	02/08/2012
HES120 Standard QA check	£90.00	1.00	Joint Owner	02/08/2012
EES66 Low energy lamp replacement	£63.00	1.00	Not The Property Owner	26/01/2011
EES15 Insulation to 65mm wide cavity wall	£179.76	24.00		17/09/2009
EES47 Pipework lagging 13mm thick to 22mm pipe	£105.17	13.00		17/09/2009
EES48 Pipework lagging 19mm thick to 22mm pipe	£202.84	22.00		17/09/2009
EES66 Low energy lamp replacement	£102.33	9.00		17/09/2009
EES69 Miscellaneous Charge	£112.50	1.00		17/09/2009
EES69 Miscellaneous Charge	£41.00	1.00		17/09/2009
EES00a Full Energy Survey	£246.55	1.00		17/09/2009
EES01a Loft Clearance (hourly rate)	£93.60	2.00	Sole Property Owner	01/04/2010
EES06 100mm thick loft insulation	£365.54	49.00	Sole Property Owner	01/04/2010
EES07 200mm thick loft insulation	£509.60	49.00	Sole Property Owner	01/04/2010
EES03a Remove and replace nailed floor board	£78.00	30.00	Sole Property Owner	01/04/2010
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	01/04/2010
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	01/04/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£110.64	12.00	Sole Property Owner	01/04/2010
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	01/04/2010
EES33 Replacement hot water cylinder (150l)	£532.93	1.00	Sole Property Owner	01/04/2010
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	01/04/2010
EES01a Loft Clearance (hourly rate)	£280.00	14.00	Sole Property Owner	21/04/2011
EES02b Remove and dispose existing insulation (hourly rate)	£40.00	2.00	Sole Property Owner	21/04/2011
EES06 100mm thick loft insulation	£220.00	40.00	Sole Property Owner	21/04/2011
EES09 Intumescent bag/fire hood to downlighter	£40.00	4.00	Sole Property Owner	21/04/2011
EES38a Thermostatic radiator valve (per valve)	£301.00	7.00	Sole Property Owner	21/04/2011
EES66 Low energy lamp replacement	£40.00	1.00	Sole Property Owner	21/04/2011
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	21/04/2011
EES01a Loft Clearance (hourly rate)	£96.00	4.00	Sole Property Owner	28/08/2012
EES06 100mm thick loft insulation	£344.00	50.00	Sole Property Owner	28/08/2012
EES07 200mm thick loft insulation	£445.50	50.00	Sole Property Owner	28/08/2012
EES09 Intumescent bag/fire hood to downlighter	£65.25	3.00	Sole Property Owner	28/08/2012
EES 11 Cold water tank insulation jacket	£41.25	1.00	Sole Property Owner	28/08/2012
EES15 Insulation to 65mm wide cavity wall	£504.47	61.00	Sole Property Owner	28/08/2012
EES21 Scaffold	£1,824.50	178.00	Sole Property Owner	28/08/2012
EES35 Replacement hot water cylinder (210l)	£0.00	0.00	Sole Property Owner	28/08/2012
EES36 Electrical room thermostat	£0.00	0.00	Sole Property Owner	28/08/2012
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Sole Property Owner	28/08/2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£24.54	3.00	Sole Property Owner	28/08/2012
EES51a 16-20kW Oil replacement boiler	£2,629.00	1.00	Sole Property Owner	28/08/2012
EES66 Low energy lamp replacement	£63.00	1.00	Sole Property Owner	28/08/2012
HES120 Standard QA check	£75.00	1.00	Sole Property Owner	28/08/2012
HES121 Boiler QA Check	£90.00	1.00	Sole Property Owner	28/08/2012
EES50c Replacement electrical storage heater	£926.00	1.00	Sole Property Owner	14/03/2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	14/03/2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£2.18	2.00	Sole Property Owner	14/03/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£1.90	2.00	Sole Property Owner	14/03/2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	21/04/2011
EES01a Loft Clearance (hourly rate)	£250.00	10.00	Joint Owner	21/04/2011
EES02a Remove and dispose existing insulation (per squire metre)	£35.01	11.67	Joint Owner	21/04/2011
EES03a Remove and replace nailed floor board	£0.00	0.00	Joint Owner	21/04/2011
EES06 100mm thick loft insulation	£130.80	20.00	Joint Owner	21/04/2011
EES07 200mm thick loft insulation	£315.00	35.00	Joint Owner	21/04/2011
EES10 Cold water tank insulation quilt	£150.00	3.00	Joint Owner	21/04/2011
EES 11 Cold water tank insulation jacket	£225.00	3.00	Joint Owner	21/04/2011
EES12 Cold water tank lid	£225.00	3.00	Joint Owner	21/04/2011
EES13b Cold water tank bye law kit (excluding associated product	£150.00	3.00	Joint Owner	21/04/2011
EES 30 Hot water cylinder jacket (46x18 inch)	£0.00	1.00	Joint Owner	21/04/2011
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Not The Property Owner	27/10/2010
EES02b Remove and dispose existing insulation (hourly rate)	£0.00	0.00	Not The Property Owner	27/10/2010
EES03b Remove and replace nailed floor board (hourly rate)	£0.00	0.00	Not The Property Owner	27/10/2010
EES07 200mm thick loft insulation	£0.00	0.00	Not The Property Owner	27/10/2010
EES10 Cold water tank insulation quilt	£0.00	0.00	Not The Property Owner	27/10/2010
EES 11 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	27/10/2010
EES12 Cold water tank lid	£0.00	0.00	Not The Property Owner	27/10/2010
EES13b Cold water tank bye law kit (excluding associated product	£0.00	0.00	Not The Property Owner	27/10/2010
EES26 Draught stripping to windows	£0.00	0.00	Not The Property Owner	27/10/2010
EES25 Draught stripping to exterior door	£0.00	0.00	Not The Property Owner	27/10/2010
EES27 Draught stripping to letterbox	£0.00	0.00	Not The Property Owner	27/10/2010
EES 30 Hot water cylinder jacket (46x18 inch)	£0.00	0.00	Not The Property Owner	27/10/2010
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Not The Property Owner	27/10/2010
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Not The Property Owner	27/10/2010
EES64 Dual flush retrofit device	£0.00	0.00	Not The Property Owner	27/10/2010
EES66 Low energy lamp replacement	£0.00	0.00	Not The Property Owner	27/10/2010
EES67 Smoke detector installation	£0.00	0.00	Not The Property Owner	27/10/2010
EES76 HEC to Bungalow	£150.00	1.00	Not The Property Owner	22/10/2010
EES01a Loft Clearance (hourly rate)	£192.00	8.00	Sole Property Owner	01/08/2012
EES03a Remove and replace nailed floor board	£283.20	24.00	Sole Property Owner	01/08/2012
EES06 100mm thick loft insulation	£288.96	42.00	Sole Property Owner	01/08/2012
EES07 200mm thick loft insulation	£374.22	42.00	Sole Property Owner	01/08/2012
EES09 Intumescent bag/fire hood to downlighter	£174.00	8.00	Sole Property Owner	01/08/2012
EES36 Electrical room thermostat	£103.40	1.00	Sole Property Owner	01/08/2012
EES38a Thermostatic radiator valve (per valve)	£352.00	8.00	Sole Property Owner	01/08/2012

EES50a 12-15kW Oil replacement boiler	£2,629.00	1.00	Sole Property Owner	01/08/2012	
EES66 Low energy lamp replacement	£63.00	1.00	Sole Property Owner	01/08/2012	
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	01/08/2012	
EES01a Loft Clearance (hourly rate)	£480.00	24.00	Not The Property Owner	09/06/2011	
EES02b Remove and dispose existing insulation (hourly rate)	£20.00	1.00	Not The Property Owner	09/06/2011	
EES06 100mm thick loft insulation	£550.00	100.00	Not The Property Owner	09/06/2011	
EES10 Cold water tank insulation quilt	£0.00	0.00	Not The Property Owner	09/06/2011	
EES 11 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	09/06/2011	
EES12 Cold water tank lid	£50.00	1.00	Not The Property Owner	09/06/2011	
EES25 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	09/06/2011	
EES31 Hot water cylinder jacket (58x20 inch)	£75.00	1.00	Not The Property Owner	09/06/2011	
EES35 Replacement hot water cylinder (210l)	£1,250.00	1.00	Not The Property Owner	09/06/2011	
EES40 Hot water cylinder thermostat	£65.00	1.00	Not The Property Owner	09/06/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£104.00	13.00	Not The Property Owner	09/06/2011	
EES64 Dual flush retrofit device	£150.00	3.00	Not The Property Owner	09/06/2011	
EES13b Cold water tank bye law kit (excluding associated product)	£25.00	1.00	Not The Property Owner	09/06/2011	
EES66 Low energy lamp replacement	£40.00	1.00	Not The Property Owner	09/06/2011	
EES67 Smoke detector installation	£30.00	1.00	Not The Property Owner	09/06/2011	
EES15 Insulation to 65mm wide cavity wall	£2,325.00	310.00	Not The Property Owner	09/06/2011	
HES120 Standard QA check	£90.00	1.00	Not The Property Owner	09/06/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	26/01/2011	
EES64 Dual flush retrofit device	£50.00	1.00	Sole Property Owner	21/04/2011	
EES68 Minimum charge for lamps and detectors	£80.00	1.00	Sole Property Owner	21/04/2011	
EES01a Loft Clearance (hourly rate)	£480.00	24.00	Not The Property Owner	10/06/2011	
EES02b Remove and dispose existing insulation (hourly rate)	£40.00	2.00	Not The Property Owner	10/06/2011	
EES03b Remove and replace nailed floor board (hourly rate)	£40.00	2.00	Not The Property Owner	10/06/2011	
EES06 100mm thick loft insulation	£247.50	45.00	Not The Property Owner	10/06/2011	
EES35 Replacement hot water cylinder (210l)	£1,250.00	1.00	Not The Property Owner	10/06/2011	
EES36 Electrical room thermostat	£105.00	1.00	Not The Property Owner	10/06/2011	
EES42 Two channel programmable heating controller	£105.00	1.00	Not The Property Owner	10/06/2011	
EES44 Water heating time clock and boost	£125.00	1.00	Not The Property Owner	10/06/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	25.00	Not The Property Owner	10/06/2011	
EES64 Dual flush retrofit device	£50.00	1.00	Not The Property Owner	10/06/2011	
EES66 Low energy lamp replacement	£40.00	1.00	Not The Property Owner	10/06/2011	
HES120 Standard QA check	£90.00	1.00	Not The Property Owner	10/06/2011	
EES69 Miscellaneous Charge	£529.00	1.00	Not The Property Owner	10/06/2011	
EES77 HEC to House	£150.00	1.00	Not The Property Owner	26/01/2011	
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	26/01/2011	
EES 30 Hot water cylinder jacket (46x18 inch)	£100.00	1.00	Joint Owner	21/04/2011	
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Joint Owner	21/04/2011	
EES66 Low energy lamp replacement	£0.00	1.00	Joint Owner	21/04/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	26/01/2011	
EES17 Insulation to 90mm wide cavity wall	£1,309.79	113.50	Not The Property Owner	21/04/2011	
EES06 100mm thick loft insulation	£178.88	26.00	Not The Property Owner	21/04/2011	
EES07 200mm thick loft insulation	£231.66	26.00	Not The Property Owner	21/04/2011	
EES19 Airbrick	£82.80	9.00	Not The Property Owner	21/04/2011	
EES25 Draught stripping to exterior door	£36.40	4.00	Not The Property Owner	21/04/2011	
EES27 Draught stripping to letterbox	£44.40	2.00	Not The Property Owner	21/04/2011	
HES120 Standard QA check	£90.00	1.00	Not The Property Owner	21/04/2011	
EES08 300mm thick loft insulation	£650.04	54.17	Sole Property Owner	26/01/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	26/01/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	26/01/2011	
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	26/01/2011	
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Not The Property Owner	07/03/2011	
EES03a Remove and replace nailed floor board	£0.00	0.00	Not The Property Owner	07/03/2011	
EES07 200mm thick loft insulation	£0.00	0.00	Not The Property Owner	07/03/2011	
EES33 Replacement hot water cylinder (150l)	£0.00	0.00	Not The Property Owner	07/03/2011	
EES40 Hot water cylinder thermostat	£0.00	0.00	Not The Property Owner	07/03/2011	
EES77 HEC to House	£150.00	1.00	Not The Property Owner	26/01/2011	
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	26/01/2011	
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	01/11/2009	
EES66 Low energy lamp replacement	£0.00	18.00	Not The Property Owner	01/11/2009	
EES00a Full Energy Survey	£401.68	1.00	Not The Property Owner	01/11/2009	
EES07 200mm thick loft insulation	£132.21	14.69	Not The Property Owner	17/03/2014	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Not The Property Owner	17/03/2014	
EES50c Replacement electrical storage heater	£0.00	0.00	Not The Property Owner	17/03/2014	
HES20 Low energy lamp installation	£0.00	3.00	Not The Property Owner	17/03/2014	
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner	17/03/2014	
HES22 Minimum per property charge	£0.00	0.00	Not The Property Owner	17/03/2014	
HES102 QA Survey for House/Bungalow/Flat	£0.00	1.00	Not The Property Owner	17/03/2014	
HES53 Two channel heating programmer control	£0.00	0.00	Not The Property Owner	17/03/2014	
HES95 Senior heating engineer	£0.00	0.00	Not The Property Owner	17/03/2014	
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£211.20	22.00	Not The Property Owner	17/03/2014	
HES111 HER Survey for Flat	£120.00	1.00	Sole Property Owner	26/01/2011	
EES44 Water heating time clock and boost	£0.00	0.00	Joint Owner	09/06/2011	
EES52b 21-25kW Gas replacement boiler	£2,160.00	1.00	Joint Owner	09/06/2011	
EES69 Miscellaneous Charge	£150.00	1.00	Joint Owner	09/06/2011	
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Joint Owner	09/06/2011	
EES08 300mm thick loft insulation	£180.00	15.00	Joint Owner	09/06/2011	
EES34 Replacement hot water cylinder (170l)	£1,240.00	1.00	Joint Owner	09/06/2011	
EES38a Thermostatic radiator valve (per valve)	£1,190.00	14.00	Joint Owner	09/06/2011	
EES36 Electrical room thermostat	£135.00	1.00	Joint Owner	09/06/2011	
EES42 Two channel programmable heating controller	£145.00	1.00	Joint Owner	09/06/2011	
EES69 Miscellaneous Charge	£120.00	1.00	Joint Owner	09/06/2011	

EES69 Miscellaneous Charge	£40.00	1.00	Joint Owner	09/06/2011	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	09/06/2011	
EES12 Cold water tank lid	£50.00	1.00	Joint Owner	09/06/2011	
HES121 Boiler QA Check	£105.00	1.00	Joint Owner	09/06/2011	
EES01a Loft Clearance (hourly rate)	£192.00	8.00	Sole Property Owner	26/01/2011	
EES07 200mm thick loft insulation	£338.58	38.00	Sole Property Owner	26/01/2011	
EES 11 Cold water tank insulation jacket	£41.25	1.00	Sole Property Owner	26/01/2011	
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	26/01/2011	
EES66 Low energy lamp replacement	£63.00	1.00	Sole Property Owner	26/01/2011	
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Not The Property Owner	21/04/2011	
EES08 300mm thick loft insulation	£360.00	30.00	Not The Property Owner	21/04/2011	
EES10 Cold water tank insulation quilt	£0.00	0.00	Not The Property Owner	21/04/2011	
EES 11 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	21/04/2011	
EES12 Cold water tank lid	£75.00	1.00	Not The Property Owner	21/04/2011	
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Not The Property Owner	21/04/2011	
EES25 Draught stripping to exterior door	£0.00	0.00	Not The Property Owner	21/04/2011	
EES34 Replacement hot water cylinder (170l)	£1,240.00	1.00	Not The Property Owner	21/04/2011	
EES66 Low energy lamp replacement	£0.00	20.00	Not The Property Owner	21/04/2011	
EES67 Smoke detector installation	£0.00	2.00	Not The Property Owner	21/04/2011	
EES76 HEC to Bungalow	£150.00	1.00	Sole Property Owner	26/01/2011	
EES77 HEC to House	£150.00	1.00	Not The Property Owner	26/01/2011	
EES25 Draught stripping to exterior door	£100.00	10.00	Not The Property Owner	26/01/2011	
EES76 HEC to Bungalow	£150.00	1.00	Not The Property Owner	26/01/2011	
EES69 Miscellaneous Charge	£0.00	0.00	Not The Property Owner	26/01/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	26/01/2011	
EES77 HEC to House	£150.00	1.00	Not The Property Owner	26/01/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	23/11/2010	
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Not The Property Owner	21/04/2011	
EES03a Remove and replace nailed floor board	£66.00	22.00	Not The Property Owner	21/04/2011	
EES08 300mm thick loft insulation	£264.00	22.00	Not The Property Owner	21/04/2011	
EES10 Cold water tank insulation quilt	£100.00	2.00	Not The Property Owner	21/04/2011	
EES 11 Cold water tank insulation jacket	£150.00	2.00	Not The Property Owner	21/04/2011	
EES12 Cold water tank lid	£150.00	2.00	Not The Property Owner	21/04/2011	
EES13b Cold water tank bye law kit (excluding associated product)	£100.00	2.00	Not The Property Owner	21/04/2011	
EES25 Draught stripping to exterior door	£120.00	12.00	Not The Property Owner	21/04/2011	
EES25 Draught stripping to exterior door	£0.00	0.00	Joint Owner	24/05/2011	
EES26 Draught stripping to windows	£0.00	0.00	Joint Owner	24/05/2011	
EES27 Draught stripping to letterbox	£0.00	0.00	Joint Owner	24/05/2011	
HES111 HER Survey for Flat	£120.00	1.00	Joint Owner	24/05/2011	
HES111 HER Survey for Flat	£120.00	1.00	Not The Property Owner	15/04/2011	
HES71 Storage heater rated 1kW - 2kW	£244.53	1.00	Joint Owner	09/08/2012	
HES72 Storage heater rated 2kW - 3kW	£616.98	2.00	Joint Owner	09/08/2012	
HES73 Storage heater rated 3kW - 4kW	£375.34	1.00	Joint Owner	09/08/2012	
HES97 Electrician	£368.00	11.50	Joint Owner	09/08/2012	
EES02a Remove and dispose existing insulation (per square metre)	£75.60	18.00	Joint Owner	09/08/2012	
EES07 200mm thick loft insulation	£160.38	18.00	Joint Owner	09/08/2012	
EES 11 Cold water tank insulation jacket	£82.50	2.00	Joint Owner	09/08/2012	
EES15 Insulation to 65mm wide cavity wall	£905.56	109.50	Joint Owner	09/08/2012	
EES19 Airbrick	£18.40	2.00	Joint Owner	09/08/2012	
HES120 Standard QA check	£90.00	1.00	Joint Owner	09/08/2012	
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Not The Property Owner	01/03/2013	
EES08 300mm thick loft insulation	£0.00	0.00	Not The Property Owner	01/03/2013	
EES 11 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	01/03/2013	
EES26 Draught stripping to windows	£0.00	0.00	Not The Property Owner	01/03/2013	
EES27 Draught stripping to letterbox	£0.00	0.00	Not The Property Owner	01/03/2013	
HES01 Loft preparation labour (clearance, disposal of old insulation)	£150.00	6.00	Not The Property Owner	01/03/2013	
HES04 300mm thick loft insulation quilt	£500.00	40.00	Not The Property Owner	01/03/2013	
HES06 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	01/03/2013	
HES07 Cold water tank bye-law kit (including insulation & lid)	£0.00	0.00	Not The Property Owner	01/03/2013	
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£2,572.80	268.00	Not The Property Owner	01/03/2013	
HES20 Low energy lamp installation	£0.00	5.00	Not The Property Owner	01/03/2013	
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner	01/03/2013	
HES111 HER Survey for Flat	£120.00	1.00	Not The Property Owner	01/03/2013	
EES07 200mm thick loft insulation	£338.58	38.00	Not The Property Owner	01/12/2011	
EES 11 Cold water tank insulation jacket	£41.25	1.00	Not The Property Owner	01/12/2011	
EES19 Airbrick	£0.00	0.00	Not The Property Owner	01/12/2011	
EES25 Draught stripping to exterior door	£81.90	9.00	Not The Property Owner	01/12/2011	
EES26 Draught stripping to windows	£27.30	3.00	Not The Property Owner	01/12/2011	
EES27 Draught stripping to letterbox	£66.60	3.00	Not The Property Owner	01/12/2011	
EES66 Low energy lamp replacement	£63.00	1.00	Not The Property Owner	01/12/2011	
HES120 Standard QA check	£90.00	1.00	Not The Property Owner	01/12/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£26.00	2.00	Sole Property Owner	12/03/2010	
EES66 Low energy lamp replacement	£62.40	13.00	Sole Property Owner	12/03/2010	
EES67 Smoke detector installation	£22.50	3.00	Sole Property Owner	12/03/2010	
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	12/03/2010	
EES01a Loft Clearance (hourly rate)	£96.00	4.00	Not The Property Owner	26/01/2011	
EES03a Remove and replace nailed floor board	£389.40	33.00	Not The Property Owner	26/01/2011	
EES07 200mm thick loft insulation	£294.03	33.00	Not The Property Owner	26/01/2011	
EES25 Draught stripping to exterior door	£31.85	3.50	Not The Property Owner	26/01/2011	
EES27 Draught stripping to letterbox	£44.40	2.00	Not The Property Owner	26/01/2011	
EES38a Thermostatic radiator valve (per valve)	£800.03	11.00	Not The Property Owner	26/01/2011	
EES66 Low energy lamp replacement	£63.00	1.00	Not The Property Owner	26/01/2011	
EES67 Smoke detector installation	£0.00	0.00	Not The Property Owner	26/01/2011	
EES03a Remove and replace nailed floor board	£379.96	64.40	Not The Property Owner	01/12/2011	

EES06 100mm thick loft insulation	£454.08	66.00	Not The Property Owner	01/12/2011
EES 11 Cold water tank insulation jacket	£41.25	1.00	Not The Property Owner	01/12/2011
EES17 Insulation to 90mm wide cavity wall	£818.30	83.50	Not The Property Owner	01/12/2011
EES21 Scaffold	£328.00	32.00	Not The Property Owner	01/12/2011
EES25 Draught stripping to exterior door	£45.50	5.00	Not The Property Owner	01/12/2011
EES27 Draught stripping to letterbox	£0.00	0.00	Not The Property Owner	01/12/2011
HES120 Standard QA check	£90.00	1.00	Not The Property Owner	01/12/2011
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Not The Property Owner	07/03/2011
EES02a Remove and dispose existing insulation (per squire metre	£0.00	0.00	Not The Property Owner	07/03/2011
EES03a Remove and replace nailed floor board	£0.00	0.00	Not The Property Owner	07/03/2011
EES07 200mm thick loft insulation	£0.00	0.00	Not The Property Owner	07/03/2011
EES08 300mm thick loft insulation	£0.00	0.00	Not The Property Owner	07/03/2011
EES10 Cold water tank insulation quilt	£0.00	0.00	Not The Property Owner	07/03/2011
EES 11 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	07/03/2011
EES25 Draught stripping to exterior door	£0.00	0.00	Not The Property Owner	07/03/2011
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Not The Property Owner	07/03/2011
EES40 Hot water cylinder thermostat	£0.00	0.00	Not The Property Owner	07/03/2011
EES66 Low energy lamp replacement	£0.00	0.00	Not The Property Owner	07/03/2011
EES67 Smoke detector installation	£0.00	0.00	Not The Property Owner	07/03/2011
EES25 Draught stripping to exterior door	£60.00	6.00	Sole Property Owner	21/04/2011
HES111 HER Survey for Flat	£120.00	1.00	Sole Property Owner	21/04/2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£1.09	1.00	Sole Property Owner	21/04/2011
EES01a Loft Clearance (hourly rate)	£96.00	4.00	Joint Owner	01/08/2012
EES02a Remove and dispose existing insulation (per squire metre	£436.80	104.00	Joint Owner	01/08/2012
EES07 200mm thick loft insulation	£926.64	104.00	Joint Owner	01/08/2012
EES09 Intumescent bag/fire hood to downlighter	£152.25	7.00	Joint Owner	01/08/2012
EES 11 Cold water tank insulation jacket	£82.50	2.00	Joint Owner	01/08/2012
EES15 Insulation to 65mm wide cavity wall	£963.45	116.50	Joint Owner	01/08/2012
EES25 Draught stripping to exterior door	£45.50	5.00	Joint Owner	01/08/2012
EES26 Draught stripping to windows	£81.90	9.00	Joint Owner	01/08/2012
EES27 Draught stripping to letterbox	£66.60	3.00	Joint Owner	01/08/2012
EES38a Thermostatic radiator valve (per valve)	£308.00	7.00	Joint Owner	01/08/2012
EES52a 21-25kW Oil replacement boiler	£2,909.50	1.00	Joint Owner	01/08/2012
EES67 Smoke detector installation	£19.60	2.00	Joint Owner	01/08/2012
HES121 Boiler QA Check	£105.00	1.00	Joint Owner	01/08/2012
EES01a Loft Clearance (hourly rate)	£96.00	4.00	Sole Property Owner	01/08/2012
EES02a Remove and dispose existing insulation (per squire metre	£264.60	63.00	Sole Property Owner	01/08/2012
EES07 200mm thick loft insulation	£561.33	63.00	Sole Property Owner	01/08/2012
EES 11 Cold water tank insulation jacket	£41.25	1.00	Sole Property Owner	01/08/2012
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Sole Property Owner	01/08/2012
EES51b 16-20kW Gas replacement boiler	£1,760.00	1.00	Sole Property Owner	01/08/2012
EES66 Low energy lamp replacement	£63.00	1.00	Sole Property Owner	01/08/2012
EES67 Smoke detector installation	£19.60	2.00	Sole Property Owner	01/08/2012
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	01/08/2012
EES25 Draught stripping to exterior door	£120.00	12.00	Not The Property Owner	21/04/2011
HES112 HER Survey for House	£150.00	1.00	Not The Property Owner	21/04/2011
EES01a Loft Clearance (hourly rate)	£300.00	12.00	Joint Owner	02/08/2012
EES03a Remove and replace nailed floor board	£90.00	30.00	Joint Owner	02/08/2012
EES08 300mm thick loft insulation	£480.00	40.00	Joint Owner	02/08/2012
HES120 Standard QA check	£90.00	1.00	Joint Owner	02/08/2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Not The Property Owner	21/04/2011
EES02a Remove and dispose existing insulation (per squire metre	£90.00	30.00	Not The Property Owner	21/04/2011
EES08 300mm thick loft insulation	£300.00	25.00	Not The Property Owner	21/04/2011
EES22 Mastic pointing	£8.00	4.00	Not The Property Owner	21/04/2011
HES120 Standard QA check	£90.00	1.00	Not The Property Owner	21/04/2011
EES25 Draught stripping to exterior door	£0.00	0.00	Not The Property Owner	01/03/2012
HES111 HER Survey for Flat	£120.00	1.00	Not The Property Owner	01/03/2012
EES01a Loft Clearance (hourly rate)	£96.00	4.00	Not The Property Owner	01/12/2011
EES03a Remove and replace nailed floor board	£212.40	18.00	Not The Property Owner	01/12/2011
EES06 100mm thick loft insulation	£247.68	36.00	Not The Property Owner	01/12/2011
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Not The Property Owner	01/12/2011
EES21 Scaffold	£0.00	0.00	Not The Property Owner	01/12/2011
EES07 200mm thick loft insulation	£320.76	36.00	Not The Property Owner	01/12/2011
EES67 Smoke detector installation	£19.60	2.00	Not The Property Owner	01/12/2011
EES69 Miscellaneous Charge	£100.00	1.00	Not The Property Owner	01/12/2011
HES120 Standard QA check	£90.00	1.00	Not The Property Owner	01/12/2011
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	21/04/2011
EES07 200mm thick loft insulation	£540.00	60.00	Sole Property Owner	21/04/2011
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	21/04/2011
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	21/04/2011
HES111 HER Survey for Flat	£120.00	1.00	Sole Property Owner	21/04/2011
HES112 HER Survey for House	£150.00	1.00	Not The Property Owner	26/01/2011
EES25 Draught stripping to exterior door	£50.00	5.00	Not The Property Owner	21/04/2011
HES111 HER Survey for Flat	£120.00	1.00	Not The Property Owner	21/04/2011
HES111 HER Survey for Flat	£120.00	1.00	Not The Property Owner	26/01/2011
EES34 Replacement hot water cylinder (170l)	£1,240.00	1.00	Joint Owner	21/04/2011
EES69 Miscellaneous Charge	£50.00	1.00	Joint Owner	21/04/2011
EES15 Insulation to 65mm wide cavity wall	£452.02	52.56	Joint Owner	21/04/2011
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Joint Owner	21/04/2011
EES02a Remove and dispose existing insulation (per squire metre	£135.00	45.00	Joint Owner	21/04/2011
EES08 300mm thick loft insulation	£540.00	45.00	Joint Owner	21/04/2011
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	21/04/2011
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	21/04/2011
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	21/04/2011

EES13b Cold water tank bye law kit (excluding associated product	£50.00	1.00	Joint Owner	21/04/2011	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Joint Owner	21/04/2011	
EES40 Hot water cylinder thermostat	£0.00	0.00	Joint Owner	21/04/2011	
EES44 Water heating time clock and boost	£0.00	0.00	Joint Owner	21/04/2011	
EES66 Low energy lamp replacement	£0.00	12.00	Joint Owner	21/04/2011	
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	21/04/2011	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Not The Property Owner	26/01/2011	
EES67 Smoke detector installation	£0.00	2.00	Not The Property Owner	09/06/2011	
EES70 Miscellaneous heating review charge	£229.20	1.00	Not The Property Owner	09/06/2011	
EES01a Loft Clearance (hourly rate)	£225.00	9.00	Not The Property Owner	09/06/2011	
EES02a Remove and dispose existing insulation (per square metre)	£108.00	36.00	Not The Property Owner	09/06/2011	
EES08 300mm thick loft insulation	£432.00	36.00	Not The Property Owner	09/06/2011	
EES34 Replacement hot water cylinder (170l)	£1,240.00	1.00	Not The Property Owner	09/06/2011	
EES42 Two channel programmable heating controller	£0.00	0.00	Not The Property Owner	09/06/2011	
EES66 Low energy lamp replacement	£0.00	1.00	Not The Property Owner	09/06/2011	
HES120 Standard QA check	£90.00	1.00	Not The Property Owner	09/06/2011	
EES38a Thermostatic radiator valve (per valve)	£510.00	6.00	Sole Property Owner	21/04/2011	
EES51b 16-20kW Gas replacement boiler	£2,160.00	1.00	Sole Property Owner	21/04/2011	
EES69 Miscellaneous Charge	£510.00	1.00	Sole Property Owner	21/04/2011	
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	21/04/2011	
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	21/04/2011	
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Sole Property Owner	21/04/2011	
EES02a Remove and dispose existing insulation (per square metre)	£150.00	50.00	Sole Property Owner	21/04/2011	
EES08 300mm thick loft insulation	£600.00	50.00	Sole Property Owner	21/04/2011	
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	21/04/2011	
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	21/04/2011	
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	21/04/2011	
EES13b Cold water tank bye law kit (excluding associated product	£50.00	1.00	Sole Property Owner	21/04/2011	
EES66 Low energy lamp replacement	£0.00	1.00	Sole Property Owner	21/04/2011	
HES120 Standard QA check	£75.00	1.00	Sole Property Owner	21/04/2011	
HES121 Boiler QA Check	£90.00	1.00	Sole Property Owner	21/04/2011	
EES01a Loft Clearance (hourly rate)	£253.00	4.00	Sole Property Owner	30/03/2010	
EES03a Remove and replace nailed floor board	£472.00	40.00	Sole Property Owner	30/03/2010	
EES69 Miscellaneous Charge	£8.26	1.00	Sole Property Owner	30/03/2010	
EES07 200mm thick loft insulation	£356.40	40.00	Sole Property Owner	30/03/2010	
EES69 Miscellaneous Charge	£6.24	1.00	Sole Property Owner	30/03/2010	
EES10 Cold water tank insulation quilt	£32.03	1.00	Sole Property Owner	30/03/2010	
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	30/03/2010	
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	30/03/2010	
EES69 Miscellaneous Charge	£58.60	1.00	Sole Property Owner	30/03/2010	
EES36 Electrical room thermostat	£103.40	1.00	Sole Property Owner	30/03/2010	
EES66 Low energy lamp replacement	£29.75	17.00	Sole Property Owner	30/03/2010	
EES67 Smoke detector installation	£3.50	2.00	Sole Property Owner	30/03/2010	
EES06 100mm thick loft insulation	£275.20	40.00	Sole Property Owner	30/03/2010	
EES69 Miscellaneous Charge	£4.82	1.00	Sole Property Owner	30/03/2010	
EES69 Miscellaneous Charge	£0.00	0.00	Not The Property Owner	07/02/2011	
HES111 HER Survey for Flat	£120.00	1.00	Not The Property Owner	07/02/2011	
HES22 Minimum per property charge	£50.00	1.00	Not The Property Owner	07/02/2011	
EES33 Replacement hot water cylinder (150l)	£0.00	0.00	Not The Property Owner	07/03/2011	
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Not The Property Owner	07/03/2011	
EES40 Hot water cylinder thermostat	£0.00	0.00	Not The Property Owner	07/03/2011	
EES66 Low energy lamp replacement	£0.00	0.00	Not The Property Owner	07/03/2011	
EES67 Smoke detector installation	£0.00	2.00	Not The Property Owner	14/02/2012	
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Not The Property Owner	14/02/2012	
EES02a Remove and dispose existing insulation (per square metre)	£81.00	27.00	Not The Property Owner	14/02/2012	
EES08 300mm thick loft insulation	£324.00	27.00	Not The Property Owner	14/02/2012	
EES10 Cold water tank insulation quilt	£0.00	0.00	Not The Property Owner	14/02/2012	
EES 11 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	14/02/2012	
EES12 Cold water tank lid	£0.00	0.00	Not The Property Owner	14/02/2012	
EES13b Cold water tank bye law kit (excluding associated product	£0.00	0.00	Not The Property Owner	14/02/2012	
EES33 Replacement hot water cylinder (150l)	£0.00	0.00	Not The Property Owner	14/02/2012	
EES66 Low energy lamp replacement	£0.00	4.00	Not The Property Owner	14/02/2012	
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	21/04/2011	
HES111 HER Survey for Flat	£120.00	1.00	Not The Property Owner	21/04/2011	
EES68 Minimum charge for lamps and detectors	£100.00	1.00	Not The Property Owner	26/01/2011	
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	27/09/2012	
HES52 Hot water cylinder thermostat	£33.21	1.00	Sole Property Owner	27/09/2012	
HES53 Two channel heating programmer control	£85.11	1.00	Sole Property Owner	27/09/2012	
HES55 2 port zone valve	£138.56	2.00	Sole Property Owner	27/09/2012	
HES64 Stainless steel replacement hot water cylinder (170L)	£435.60	1.00	Sole Property Owner	27/09/2012	
HES67 22mm thick pipework lagging	£69.80	20.00	Sole Property Owner	27/09/2012	
HES68 28mm thick pipework lagging	£37.60	10.00	Sole Property Owner	27/09/2012	
HES94 Heating engineer	£1,216.00	32.00	Sole Property Owner	27/09/2012	
HES97 Electrician	£150.00	6.00	Sole Property Owner	27/09/2012	
HES33 26-35kW Oil replacement condensing boiler	£1,817.37	1.00	Sole Property Owner	27/09/2012	
HES41 Condensate pipework (and pump if required)	£150.00	1.00	Sole Property Owner	27/09/2012	
HES42 Purpose built lime soakaway (condensate sump)	£36.23	1.00	Sole Property Owner	27/09/2012	
HES44 Pipework / feed modifications	£200.00	1.00	Sole Property Owner	27/09/2012	
HES46 Automatic bypass	£46.32	1.00	Sole Property Owner	27/09/2012	
HES48 Power / system flush and treatment	£38.00	1.00	Sole Property Owner	27/09/2012	
HES49 Carbon Monoxide alarm	£85.35	1.00	Sole Property Owner	27/09/2012	
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	27/09/2012	
HES88 Commissioning and issue of CD11 and flue gas analysis	£38.00	1.00	Sole Property Owner	27/09/2012	
HES40 Flue specification and location	£461.00	1.00	Sole Property Owner	27/09/2012	

EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	27/09/2012	
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	27/09/2012	
EES48 Pipework lagging 19mm thick to 22mm pipe	£2.18	2.00	Sole Property Owner	27/09/2012	
EES01a Loft Clearance (hourly rate)	£96.00	4.00	Sole Property Owner	16/02/2011	
EES06 100mm thick loft insulation	£791.20	115.00	Sole Property Owner	16/02/2011	
EES07 200mm thick loft insulation	£1,024.65	115.00	Sole Property Owner	16/02/2011	
EES09 Intumescent bag/fire hood to downlighter	£87.00	4.00	Sole Property Owner	16/02/2011	
EES 11 Cold water tank insulation jacket	£41.25	1.00	Sole Property Owner	16/02/2011	
EES15 Insulation to 65mm wide cavity wall	£1,070.00	125.00	Sole Property Owner	16/02/2011	
EES25 Draught stripping to exterior door	£36.40	4.00	Sole Property Owner	16/02/2011	
EES26 Draught stripping to windows	£109.20	12.00	Sole Property Owner	16/02/2011	
EES27 Draught stripping to letterbox	£88.80	4.00	Sole Property Owner	16/02/2011	
EES66 Low energy lamp replacement	£63.00	1.00	Sole Property Owner	16/02/2011	
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	16/02/2011	
EES25 Draught stripping to exterior door	£0.00	0.00	Not The Property Owner	09/01/2012	
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	09/01/2012	
EES27 Draught stripping to letterbox	£40.00	1.00	Not The Property Owner	09/01/2012	
HES111 HER Survey for Flat	£120.00	1.00	Not The Property Owner	09/01/2012	
EES66 Low energy lamp replacement	£0.00	5.00	Sole Property Owner	11/08/2011	
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	11/08/2011	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	11/08/2011	
EES07 200mm thick loft insulation	£374.40	36.00	Sole Property Owner	01/04/2010	
EES 11 Cold water tank insulation jacket	£64.89	1.00	Sole Property Owner	01/04/2010	
EES12 Cold water tank lid	£35.70	1.00	Sole Property Owner	01/04/2010	
EES47 Pipework lagging 13mm thick to 22mm pipe	£32.36	4.00	Sole Property Owner	01/04/2010	
EES66 Low energy lamp replacement	£55.80	1.00	Sole Property Owner	01/04/2010	
EES69 Miscellaneous Charge	£41.00	1.00	Sole Property Owner	01/04/2010	
EES06 100mm thick loft insulation	£0.00	0.00	Not The Property Owner	19/07/2011	
EES07 200mm thick loft insulation	£0.00	0.00	Not The Property Owner	19/07/2011	
EES 11 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	19/07/2011	
EES26 Draught stripping to windows	£0.00	0.00	Not The Property Owner	19/07/2011	
EES66 Low energy lamp replacement	£0.00	0.00	Not The Property Owner	19/07/2011	
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Not The Property Owner	01/03/2013	
EES07 200mm thick loft insulation	£0.00	0.00	Not The Property Owner	01/03/2013	
EES 11 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	01/03/2013	
EES25 Draught stripping to exterior door	£0.00	0.00	Not The Property Owner	01/03/2013	
EES26 Draught stripping to windows	£0.00	0.00	Not The Property Owner	01/03/2013	
EES27 Draught stripping to letterbox	£0.00	0.00	Not The Property Owner	01/03/2013	
EES66 Low energy lamp replacement	£0.00	0.00	Not The Property Owner	01/03/2013	
HES01 Loft preparation labour (clearance, disposal of old insulatio	£50.00	2.00	Not The Property Owner	01/03/2013	
HES03 200mm thick loft insulation quilt	£494.00	52.00	Not The Property Owner	01/03/2013	
HES11 CIGA approved cavity wall insulation to 75mm wide cavity	£0.00	0.00	Not The Property Owner	01/03/2013	
HES20 Low energy lamp installation	£0.00	10.00	Not The Property Owner	01/03/2013	
HES21 Smoke detector installation	£0.00	1.00	Not The Property Owner	01/03/2013	
HES15 Draught stripping to exterior door	£18.00	6.00	Not The Property Owner	01/03/2013	
HES19 Draught proofing labour	£50.00	2.00	Not The Property Owner	01/03/2013	
HES66 15mm thick pipework lagging	£42.12	13.00	Not The Property Owner	01/03/2013	
HES67 22mm thick pipework lagging	£46.42	11.00	Not The Property Owner	01/03/2013	
HES94 Heating engineer	£165.60	4.50	Not The Property Owner	01/03/2013	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	21/04/2011	
EES66 Low energy lamp replacement	£0.00	2.00	Not The Property Owner	21/04/2011	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	11/08/2011	
EES66 Low energy lamp replacement	£0.00	15.00	Sole Property Owner	11/08/2011	
EES67 Smoke detector installation	£0.00	3.00	Sole Property Owner	11/08/2011	
EES16 Insulation to 75mm wide cavity wall	£0.00	0.00	Sole Property Owner	11/08/2011	
HES112 HER Survey for House	£150.00	1.00	Not The Property Owner	26/01/2011	
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Sole Property Owner	12/08/2011	
EES02a Remove and dispose existing insulation (per squire metre	£165.00	55.00	Sole Property Owner	12/08/2011	
EES03a Remove and replace nailed floor board	£135.00	45.00	Sole Property Owner	12/08/2011	
EES08 300mm thick loft insulation	£660.00	55.00	Sole Property Owner	12/08/2011	
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	12/08/2011	
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	12/08/2011	
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	12/08/2011	
EES13b Cold water tank bye law kit (excluding associated product	£100.00	2.00	Sole Property Owner	12/08/2011	
EES38a Thermostatic radiator valve (per valve)	£680.00	8.00	Sole Property Owner	12/08/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£259.00	37.00	Sole Property Owner	12/08/2011	
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	12/08/2011	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	12/08/2011	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	12/08/2011	
EES52b 21-25kW Gas replacement boiler	£3,612.00	1.00	Sole Property Owner	12/08/2011	
HES121 Boiler QA Check	£90.00	1.00	Sole Property Owner	12/08/2011	
HES120 Standard QA check	£75.00	1.00	Sole Property Owner	12/08/2011	
EES02a Remove and dispose existing insulation (per squire metre	£210.00	50.00	Not The Property Owner	26/06/2012	
EES 11 Cold water tank insulation jacket	£41.25	1.00	Not The Property Owner	26/06/2012	
EES26 Draught stripping to windows	£27.30	3.00	Not The Property Owner	26/06/2012	
EES06 100mm thick loft insulation	£688.00	100.00	Not The Property Owner	26/06/2012	
EES07 200mm thick loft insulation	£891.00	100.00	Not The Property Owner	26/06/2012	
EES26 Draught stripping to windows	£72.80	8.00	Not The Property Owner	26/06/2012	
EES27 Draught stripping to letterbox	£44.40	2.00	Not The Property Owner	26/06/2012	
HES120 Standard QA check	£90.00	1.00	Not The Property Owner	26/06/2012	
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	09/06/2011	
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	09/06/2011	
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	09/06/2011	
EES13b Cold water tank bye law kit (excluding associated product	£50.00	1.00	Joint Owner	09/06/2011	

EES47 Pipework lagging 13mm thick to 22mm pipe	£70.00	10.00	Joint Owner	09/06/2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£44.00	4.00	Joint Owner	09/06/2011
EES66 Low energy lamp replacement	£0.00	4.00	Joint Owner	09/06/2011
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	09/06/2011
EES01a Loft Clearance (hourly rate)	£400.00	16.00	Joint Owner	09/06/2011
EES02a Remove and dispose existing insulation (per square metre)	£225.00	75.00	Joint Owner	09/06/2011
EES03a Remove and replace nailed floor board	£75.00	25.00	Joint Owner	09/06/2011
EES06 100mm thick loft insulation	£261.60	40.00	Joint Owner	09/06/2011
EES07 200mm thick loft insulation	£675.00	75.00	Joint Owner	09/06/2011
EES66 Low energy lamp replacement	£0.00	1.00	Joint Owner	09/06/2011
HES120 Standard QA check	£90.00	1.00	Joint Owner	09/06/2011
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	03/02/2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	03/02/2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	03/02/2012
EES01a Loft Clearance (hourly rate)	£288.00	12.00	Not The Property Owner	02/08/2012
EES02a Remove and dispose existing insulation (per square metre)	£201.60	48.00	Not The Property Owner	02/08/2012
EES07 200mm thick loft insulation	£427.68	48.00	Not The Property Owner	02/08/2012
EES 11 Cold water tank insulation jacket	£41.25	1.00	Not The Property Owner	02/08/2012
EES25 Draught stripping to exterior door	£45.50	5.00	Not The Property Owner	02/08/2012
EES26 Draught stripping to windows	£0.00	0.00	Not The Property Owner	02/08/2012
EES27 Draught stripping to letterbox	£22.20	1.00	Not The Property Owner	02/08/2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£81.80	10.00	Not The Property Owner	02/08/2012
EES66 Low energy lamp replacement	£63.00	1.00	Not The Property Owner	02/08/2012
EES25 Draught stripping to exterior door	£50.00	5.00	Not The Property Owner	12/03/2010
EES31 Hot water cylinder jacket (58x20 inch)	£100.00	1.00	Not The Property Owner	12/03/2010
EES00a Full Energy Survey	£401.68	1.00	Not The Property Owner	12/03/2010
HES50 Electrical room thermostat	£0.00	0.00	Joint Owner	23/11/2012
HES51 Thermostatic radiator valve	£136.80	6.00	Joint Owner	23/11/2012
HES93 Junior heating engineer	£0.00	0.00	Joint Owner	23/11/2012
HES94 Heating engineer	£0.00	0.00	Joint Owner	23/11/2012
HES97 Electrician	£0.00	0.00	Joint Owner	23/11/2012
EES69 Miscellaneous Charge	£40.00	1.00	Joint Owner	23/11/2012
HES95 Senior heating engineer	£390.00	10.00	Joint Owner	23/11/2012
EES01a Loft Clearance (hourly rate)	£192.00	8.00	Joint Owner	23/11/2012
EES02a Remove and dispose existing insulation (per square metre)	£239.40	57.00	Joint Owner	23/11/2012
EES03a Remove and replace nailed floor board	£259.60	22.00	Joint Owner	23/11/2012
EES07 200mm thick loft insulation	£507.87	57.00	Joint Owner	23/11/2012
EES 11 Cold water tank insulation jacket	£41.25	1.00	Joint Owner	23/11/2012
EES26 Draught stripping to windows	£54.60	6.00	Joint Owner	23/11/2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£40.90	5.00	Joint Owner	23/11/2012
EES66 Low energy lamp replacement	£63.00	1.00	Joint Owner	23/11/2012
HES120 Standard QA check	£90.00	1.00	Joint Owner	23/11/2012
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Joint Owner	21/04/2011
EES02a Remove and dispose existing insulation (per square metre)	£96.00	32.00	Joint Owner	21/04/2011
EES03a Remove and replace nailed floor board	£96.00	32.00	Joint Owner	21/04/2011
EES08 300mm thick loft insulation	£300.00	25.00	Joint Owner	21/04/2011
EES38a Thermostatic radiator valve (per valve)	£595.00	7.00	Joint Owner	21/04/2011
EES66 Low energy lamp replacement	£0.00	1.00	Joint Owner	21/04/2011
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	21/04/2011
EES06 100mm thick loft insulation	£45.78	7.00	Joint Owner	21/04/2011
EES77 HEC to House	£150.00	1.00	Not The Property Owner	21/04/2011
EES66 Low energy lamp replacement	£0.00	9.00	Not The Property Owner	21/04/2011
EES17 Insulation to 90mm wide cavity wall	£854.88	78.00	Not The Property Owner	02/08/2012
EES18a Cavity brush (per brush)	£88.00	11.00	Not The Property Owner	02/08/2012
EES26 Draught stripping to windows	£0.00	0.00	Not The Property Owner	02/08/2012
EES66 Low energy lamp replacement	£63.00	1.00	Not The Property Owner	02/08/2012
EES01a Loft Clearance (hourly rate)	£96.00	4.00	Not The Property Owner	02/08/2012
EES07 200mm thick loft insulation	£267.30	30.00	Not The Property Owner	02/08/2012
EES 11 Cold water tank insulation jacket	£41.25	1.00	Not The Property Owner	02/08/2012
EES25 Draught stripping to exterior door	£45.50	5.00	Not The Property Owner	02/08/2012
EES26 Draught stripping to windows	£0.00	0.00	Not The Property Owner	02/08/2012
EES27 Draught stripping to letterbox	£44.40	2.00	Not The Property Owner	02/08/2012
EES66 Low energy lamp replacement	£63.00	1.00	Not The Property Owner	02/08/2012
EES26 Draught stripping to windows	£364.00	40.00	Sole Property Owner	02/08/2012
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	02/08/2012
EES66 Low energy lamp replacement	£63.00	1.00	Sole Property Owner	02/08/2012
EES01a Loft Clearance (hourly rate)	£120.00	5.00	Sole Property Owner	02/08/2012
EES07 200mm thick loft insulation	£490.05	55.00	Sole Property Owner	02/08/2012
EES08 300mm thick loft insulation	£536.86	34.00	Sole Property Owner	02/08/2012
EES 11 Cold water tank insulation jacket	£41.25	1.00	Sole Property Owner	02/08/2012
EES26 Draught stripping to windows	£364.00	40.00	Sole Property Owner	02/08/2012
EES27 Draught stripping to letterbox	£44.40	2.00	Sole Property Owner	02/08/2012
EES66 Low energy lamp replacement	£63.00	1.00	Sole Property Owner	02/08/2012
EES67 Smoke detector installation	£0.00	0.00	Sole Property Owner	02/08/2012
EES36 Electrical room thermostat	£61.60	1.00	Sole Property Owner	02/08/2012
EES38a Thermostatic radiator valve (per valve)	£827.97	13.00	Sole Property Owner	02/08/2012
EES42 Two channel programmable heating controller	£139.59	1.00	Sole Property Owner	02/08/2012
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	02/08/2012
EES21 Scaffold	£900.00	900.00	Sole Property Owner	02/08/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	02/08/2012
EES70 Miscellaneous heating review charge	£2,349.68	1.00	Sole Property Owner	02/08/2012
HES49 Carbon Monoxide alarm	£80.00	2.00	Sole Property Owner	02/08/2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	02/08/2012
EES01a Loft Clearance (hourly rate)	£126.52	4.00	Sole Property Owner	01/02/2010

EES03a Remove and replace nailed floor board	£236.00	20.00	Sole Property Owner	01/02/2010
EES07 200mm thick loft insulation	£1,376.00	100.00	Sole Property Owner	01/02/2010
EES10 Cold water tank insulation quilt	£34.62	1.00	Sole Property Owner	01/02/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£133.60	10.00	Sole Property Owner	01/02/2010
EES66 Low energy lamp replacement	£17.50	10.00	Sole Property Owner	01/02/2010
EES67 Smoke detector installation	£19.60	2.00	Sole Property Owner	01/02/2010
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	01/02/2010
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	01/02/2010
EES 30 Hot water cylinder jacket (46x18 inch)	£47.04	1.00	Sole Property Owner	01/02/2010
EES69 Miscellaneous Charge	£180.72	1.00	Sole Property Owner	01/02/2010
EES50a 12-15kW Oil replacement boiler	£1,722.00	1.00	Sole Property Owner	01/02/2010
EES48 Pipework lagging 19mm thick to 22mm pipe	£265.00	26.50	Sole Property Owner	01/02/2010
EES38a Thermostatic radiator valve (per valve)	£509.53	7.00	Sole Property Owner	01/02/2010
EES82 Boiler replacement miscellaneous works	£1,352.00	1.00	Sole Property Owner	01/02/2010
HES53 Two channel heating programmer control	£76.30	1.00	Sole Property Owner	01/02/2010
HES50 Electrical room thermostat	£76.30	1.00	Sole Property Owner	01/02/2010
EES38a Thermostatic radiator valve (per valve)	£445.83	7.00	Sole Property Owner	01/02/2010
EES34 Replacement hot water cylinder (170l)	£750.00	1.00	Sole Property Owner	01/02/2010
EES82 Boiler replacement miscellaneous works	£228.12	1.00	Sole Property Owner	01/02/2010
EES01a Loft Clearance (hourly rate)	£375.00	15.00	Joint Owner	02/08/2012
EES03a Remove and replace nailed floor board	£300.00	100.00	Joint Owner	02/08/2012
EES07 200mm thick loft insulation	£0.00	0.00	Joint Owner	02/08/2012
EES10 Cold water tank insulation quilt	£200.00	4.00	Joint Owner	02/08/2012
EES 11 Cold water tank insulation jacket	£300.00	4.00	Joint Owner	02/08/2012
EES12 Cold water tank lid	£300.00	4.00	Joint Owner	02/08/2012
EES13a Cold water tank bye law kit (including associated product)	£200.00	4.00	Joint Owner	02/08/2012
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Joint Owner	02/08/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£308.00	44.00	Joint Owner	02/08/2012
EES66 Low energy lamp replacement	£0.00	25.00	Joint Owner	02/08/2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	02/08/2012
EES08 300mm thick loft insulation	£1,920.00	160.00	Joint Owner	02/08/2012
HES66 15mm thick pipework lagging	£19.44	6.00	Joint Owner	02/08/2012
HES67 22mm thick pipework lagging	£25.32	6.00	Joint Owner	02/08/2012
HES94 Heating engineer	£147.20	4.00	Joint Owner	02/08/2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Not The Property Owner	11/08/2011
EES02a Remove and dispose existing insulation (per square metre)	£60.00	20.00	Not The Property Owner	11/08/2011
EES03a Remove and replace nailed floor board	£24.00	8.00	Not The Property Owner	11/08/2011
EES08 300mm thick loft insulation	£0.00	0.00	Not The Property Owner	11/08/2011
EES66 Low energy lamp replacement	£0.00	1.00	Not The Property Owner	11/08/2011
EES67 Smoke detector installation	£0.00	3.00	Not The Property Owner	11/08/2011
EES06 100mm thick loft insulation	£130.80	20.00	Not The Property Owner	11/08/2011
EES07 200mm thick loft insulation	£315.00	35.00	Not The Property Owner	11/08/2011
EES16 Insulation to 75mm wide cavity wall	£1,027.50	137.00	Not The Property Owner	11/08/2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£14.00	2.00	Not The Property Owner	11/08/2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£22.00	2.00	Not The Property Owner	11/08/2011
EES10 Cold water tank insulation quilt	£50.00	1.00	Not The Property Owner	11/08/2011
EES 11 Cold water tank insulation jacket	£75.00	1.00	Not The Property Owner	11/08/2011
EES12 Cold water tank lid	£75.00	1.00	Not The Property Owner	11/08/2011
EES13b Cold water tank bye law kit (excluding associated product)	£50.00	1.00	Not The Property Owner	11/08/2011
HES21 Smoke detector installation	£0.00	2.00	Not The Property Owner	11/08/2011
HES22 Minimum per property charge	£50.00	1.00	Not The Property Owner	11/08/2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	13/09/2011
EES66 Low energy lamp replacement	£0.00	11.00	Not The Property Owner	13/09/2011
EES67 Smoke detector installation	£0.00	1.00	Not The Property Owner	13/09/2011
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Not The Property Owner	13/09/2011
EES02a Remove and dispose existing insulation (per square metre)	£90.00	30.00	Not The Property Owner	13/09/2011
EES08 300mm thick loft insulation	£720.00	60.00	Not The Property Owner	13/09/2011
EES10 Cold water tank insulation quilt	£50.00	1.00	Not The Property Owner	13/09/2011
EES 11 Cold water tank insulation jacket	£75.00	1.00	Not The Property Owner	13/09/2011
EES12 Cold water tank lid	£75.00	1.00	Not The Property Owner	13/09/2011
EES13a Cold water tank bye law kit (including associated product)	£50.00	1.00	Not The Property Owner	13/09/2011
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	13/09/2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£448.00	64.00	Not The Property Owner	13/09/2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	21/04/2011
EES69 Miscellaneous Charge	£60.00	1.00	Sole Property Owner	21/04/2011
EES29 Hot water cylinder jacket (30x18 inch)	£90.00	1.00	Sole Property Owner	02/08/2011
EES66 Low energy lamp replacement	£0.00	15.00	Sole Property Owner	02/08/2011
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	02/08/2011
EES50c Replacement electrical storage heater	£1,824.48	4.00	Sole Property Owner	02/08/2011
HES120 Standard QA check	£75.00	1.00	Sole Property Owner	02/08/2011
HES121 Boiler QA Check	£90.00	1.00	Sole Property Owner	02/08/2011
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Sole Property Owner	08/02/2012
EES82 Boiler replacement miscellaneous works	£470.00	1.00	Sole Property Owner	08/02/2012
EES07 200mm thick loft insulation	£378.00	42.00	Sole Property Owner	08/02/2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	08/02/2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	08/02/2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	08/02/2012
EES13a Cold water tank bye law kit (including associated product)	£100.00	2.00	Sole Property Owner	08/02/2012
EES35 Replacement hot water cylinder (210l)	£1,450.00	1.00	Sole Property Owner	08/02/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£322.00	46.00	Sole Property Owner	08/02/2012
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	08/02/2012
EES66 Low energy lamp replacement	£0.00	8.00	Sole Property Owner	08/02/2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	08/02/2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	08/02/2012

EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	08/02/2012	
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	08/02/2012	
EES54a 36-45kW Oil replacement boiler	£4,137.00	1.00	Sole Property Owner	08/02/2012	
EES70 Miscellaneous heating review charge	£2,336.80	1.00	Sole Property Owner	08/02/2012	
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	08/02/2012	
EES77 HEC to House	£150.00	1.00	Not The Property Owner	12/08/2011	
EES66 Low energy lamp replacement	£0.00	3.00	Not The Property Owner	12/08/2011	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Not The Property Owner	12/08/2011	
EES16 Insulation to 75mm wide cavity wall	£999.60	105.00	Sole Property Owner	08/02/2012	
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	08/02/2012	
EES02a Remove and dispose existing insulation (per square metre)	£210.00	70.00	Sole Property Owner	08/02/2012	
EES03a Remove and replace nailed floor board	£0.00	0.00	Sole Property Owner	08/02/2012	
EES08 300mm thick loft insulation	£960.00	80.00	Sole Property Owner	08/02/2012	
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	08/02/2012	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	08/02/2012	
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	08/02/2012	
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Sole Property Owner	08/02/2012	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	08/02/2012	
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Sole Property Owner	08/02/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£56.00	8.00	Sole Property Owner	08/02/2012	
EES55a 46-55kW Oil replacement boiler	£5,100.00	1.00	Sole Property Owner	08/02/2012	
EES17 Insulation to 90mm wide cavity wall	£0.00	0.00	Sole Property Owner	08/02/2012	
EES66 Low energy lamp replacement	£0.00	25.00	Sole Property Owner	08/02/2012	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	08/02/2012	
EES49 Pipework lagging 25mm thick to 22mm pipe	£110.00	10.00	Sole Property Owner	08/02/2012	
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	08/02/2012	
EES77 HEC to House	£150.00	1.00	Not The Property Owner	21/04/2011	
EES66 Low energy lamp replacement	£0.00	23.00	Not The Property Owner	21/04/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	21/04/2011	
EES66 Low energy lamp replacement	£0.00	10.00	Not The Property Owner	21/04/2011	
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Sole Property Owner	01/11/2009	
EES15 Insulation to 65mm wide cavity wall	£612.30	81.64	Sole Property Owner	01/11/2009	
EES07 200mm thick loft insulation	£476.00	68.00	Sole Property Owner	01/11/2009	
EES66 Low energy lamp replacement	£0.00	27.00	Sole Property Owner	01/11/2009	
EES00a Full Energy Survey	£246.55	1.00	Sole Property Owner	01/11/2009	
EES77 HEC to House	£150.00	1.00	Not The Property Owner	21/04/2011	
EES66 Low energy lamp replacement	£0.00	9.00	Not The Property Owner	21/04/2011	
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Sole Property Owner	09/07/2011	
EES02a Remove and dispose existing insulation (per square metre)	£135.00	45.00	Sole Property Owner	09/07/2011	
EES03a Remove and replace nailed floor board	£24.00	8.00	Sole Property Owner	09/07/2011	
EES08 300mm thick loft insulation	£540.00	45.00	Sole Property Owner	09/07/2011	
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	09/07/2011	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	09/07/2011	
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	09/07/2011	
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Sole Property Owner	09/07/2011	
EES38a Thermostatic radiator valve (per valve)	£935.00	11.00	Sole Property Owner	09/07/2011	
EES66 Low energy lamp replacement	£0.00	15.00	Sole Property Owner	09/07/2011	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	09/07/2011	
EES53a 26-35kW Oil replacement boiler	£4,070.00	1.00	Sole Property Owner	09/07/2011	
EES69 Miscellaneous Charge	£814.00	1.00	Sole Property Owner	09/07/2011	
EES15 Insulation to 65mm wide cavity wall	£440.40	1.00	Sole Property Owner	09/07/2011	
HES101 Asbestos removal & disposal	£580.00	1.00	Sole Property Owner	09/07/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£182.00	26.00	Sole Property Owner	09/07/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£210.00	30.00	Sole Property Owner	09/07/2011	
HES120 Standard QA check	£75.00	1.00	Sole Property Owner	09/07/2011	
HES121 Boiler QA Check	£90.00	1.00	Sole Property Owner	09/07/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	12/08/2011	
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	12/08/2011	
EES67 Smoke detector installation	£0.00	1.00	Not The Property Owner	12/08/2011	
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	12/08/2011	
EES77 HEC to House	£150.00	1.00	Joint Owner	09/01/2012	
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	09/01/2012	
EES15 Insulation to 65mm wide cavity wall	£1,404.00	1.00	Joint Owner	09/01/2012	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	17/01/2013	
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	17/01/2013	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	17/01/2013	
EES36 Electrical room thermostat	£135.00	1.00	Joint Owner	24/09/2011	
EES38a Thermostatic radiator valve (per valve)	£765.00	9.00	Joint Owner	24/09/2011	
EES66 Low energy lamp replacement	£0.00	5.00	Joint Owner	24/09/2011	
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	24/09/2011	
EES53b 26-35kW Gas replacement boiler	£1,920.00	1.00	Joint Owner	24/09/2011	
EES69 Miscellaneous Charge	£384.00	1.00	Joint Owner	24/09/2011	
EES16 Insulation to 75mm wide cavity wall	£1,318.80	1.00	Joint Owner	24/09/2011	
HES121 Boiler QA Check	£105.00	1.00	Joint Owner	24/09/2011	
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	27/07/2011	
EES02a Remove and dispose existing insulation (per square metre)	£135.00	45.00	Sole Property Owner	27/07/2011	
EES08 300mm thick loft insulation	£540.00	45.00	Sole Property Owner	27/07/2011	
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	27/07/2011	
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	27/07/2011	
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	27/07/2011	
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	27/07/2011	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	27/07/2011	
EES38a Thermostatic radiator valve (per valve)	£680.00	8.00	Sole Property Owner	27/07/2011	
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	27/07/2011	

EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	27/07/2011
EES53a 26-35kW Oil replacement boiler	£3,754.00	1.00	Sole Property Owner	27/07/2011
EES70 Miscellaneous heating review charge	£750.80	1.00	Sole Property Owner	27/07/2011
EES16 Insulation to 75mm wide cavity wall	£1,079.00	1.00	Sole Property Owner	27/07/2011
EES69 Miscellaneous Charge	£215.80	1.00	Sole Property Owner	27/07/2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£224.00	32.00	Sole Property Owner	27/07/2011
EES70 Miscellaneous heating review charge	£196.00	1.00	Sole Property Owner	27/07/2011
HES120 Standard QA check	£75.00	1.00	Sole Property Owner	27/07/2011
HES121 Boiler QA Check	£90.00	1.00	Sole Property Owner	27/07/2011
EES01a Loft Clearance (hourly rate)	£175.00	7.00	Sole Property Owner	23/07/2011
EES02a Remove and dispose existing insulation (per squire metre)	£0.00	0.00	Sole Property Owner	23/07/2011
EES03a Remove and replace nailed floor board	£240.00	80.00	Sole Property Owner	23/07/2011
EES08 300mm thick loft insulation	£0.00	0.00	Sole Property Owner	23/07/2011
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	23/07/2011
EES38a Thermostatic radiator valve (per valve)	£595.00	7.00	Sole Property Owner	23/07/2011
EES66 Low energy lamp replacement	£0.00	9.00	Sole Property Owner	23/07/2011
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	23/07/2011
EES68 Minimum charge for lamps and detectors	£0.00	0.00	Sole Property Owner	23/07/2011
EES53b 26-35kW Gas replacement boiler	£2,320.00	1.00	Sole Property Owner	23/07/2011
EES70 Miscellaneous heating review charge	£464.00	1.00	Sole Property Owner	23/07/2011
EES07 200mm thick loft insulation	£270.00	30.00	Sole Property Owner	23/07/2011
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	23/07/2011
HES21 Smoke detector installation	£50.00	1.00	Sole Property Owner	23/07/2011
EES66 Low energy lamp replacement	£0.00	1.00	Not The Property Owner	01/03/2010
EES00a Full Energy Survey	£401.68	1.00	Not The Property Owner	01/03/2010
EES03a Remove and replace nailed floor board	£135.00	45.00	Not The Property Owner	02/08/2012
EES08 300mm thick loft insulation	£540.00	45.00	Not The Property Owner	02/08/2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Not The Property Owner	02/08/2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Not The Property Owner	02/08/2012
EES12 Cold water tank lid	£150.00	2.00	Not The Property Owner	02/08/2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Not The Property Owner	02/08/2012
EES66 Low energy lamp replacement	£0.00	5.00	Not The Property Owner	02/08/2012
EES67 Smoke detector installation	£0.00	2.00	Not The Property Owner	02/08/2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	02/08/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£70.00	10.00	Not The Property Owner	02/08/2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	02/08/2012
EES50c Replacement electrical storage heater	£1,361.25	3.00	Joint Owner	26/01/2012
EES70 Miscellaneous heating review charge	£604.28	1.00	Joint Owner	26/01/2012
EES70 Miscellaneous heating review charge	£741.30	1.00	Joint Owner	26/01/2012
EES66 Low energy lamp replacement	£0.00	18.00	Joint Owner	26/01/2012
EES67 Smoke detector installation	£0.00	3.00	Joint Owner	26/01/2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Joint Owner	26/01/2012
EES29 Hot water cylinder jacket (30x18 inch)	£0.00	0.00	Joint Owner	06/01/2012
EES36 Electrical room thermostat	£135.00	1.00	Joint Owner	06/01/2012
EES66 Low energy lamp replacement	£0.00	19.00	Joint Owner	06/01/2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	06/01/2012
EES15 Insulation to 65mm wide cavity wall	£1,310.40	1.00	Joint Owner	06/01/2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	06/01/2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	06/01/2012
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	06/01/2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Joint Owner	06/01/2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Joint Owner	06/01/2012
EES38a Thermostatic radiator valve (per valve)	£680.00	8.00	Joint Owner	06/01/2012
EES49 Pipework lagging 25mm thick to 22mm pipe	£88.00	8.00	Joint Owner	06/01/2012
EES70 Miscellaneous heating review charge	£133.12	1.00	Joint Owner	06/01/2012
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Joint Owner	06/01/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	20.00	Joint Owner	06/01/2012
EES70 Miscellaneous heating review charge	£1,527.68	1,527.68	Joint Owner	06/01/2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	06/01/2012
EES66 Low energy lamp replacement	£0.00	15.00	Joint Owner	11/08/2011
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Joint Owner	11/08/2011
EES06 100mm thick loft insulation	£294.30	45.00	Sole Property Owner	06/01/2012
EES66 Low energy lamp replacement	£0.00	15.00	Sole Property Owner	06/01/2012
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	06/01/2012
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	06/01/2012
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	06/01/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	06/01/2012
EES70 Miscellaneous heating review charge	£1,996.30	1,996.30	Sole Property Owner	06/01/2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	06/01/2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Joint Owner	06/01/2012
EES02a Remove and dispose existing insulation (per squire metre)	£144.00	48.00	Joint Owner	06/01/2012
EES03a Remove and replace nailed floor board	£24.00	8.00	Joint Owner	06/01/2012
EES08 300mm thick loft insulation	£480.00	40.00	Joint Owner	06/01/2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	06/01/2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	06/01/2012
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	06/01/2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Joint Owner	06/01/2012
EES29 Hot water cylinder jacket (30x18 inch)	£90.00	1.00	Joint Owner	06/01/2012
EES36 Electrical room thermostat	£135.00	1.00	Joint Owner	06/01/2012
EES38a Thermostatic radiator valve (per valve)	£595.00	7.00	Joint Owner	06/01/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£126.00	18.00	Joint Owner	06/01/2012
EES66 Low energy lamp replacement	£0.00	10.00	Joint Owner	06/01/2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	06/01/2012
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Joint Owner	06/01/2012

EES06 100mm thick loft insulation	£52.32	8.00	Joint Owner	06/01/2012
EES49 Pipework lagging 25mm thick to 22mm pipe	£132.00	12.00	Joint Owner	06/01/2012
HES120 Standard QA check	£90.00	1.00	Joint Owner	06/01/2012
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Sole Property Owner	11/11/2011
EES02a Remove and dispose existing insulation (per square metre)	£270.00	90.00	Sole Property Owner	11/11/2011
EES03a Remove and replace nailed floor board	£0.00	0.00	Sole Property Owner	11/11/2011
EES08 300mm thick loft insulation	£1,080.00	90.00	Sole Property Owner	11/11/2011
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	11/11/2011
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	11/11/2011
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	11/11/2011
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	11/11/2011
EES38a Thermostatic radiator valve (per valve)	£765.00	9.00	Sole Property Owner	11/11/2011
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	11/11/2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£210.00	30.00	Sole Property Owner	11/11/2011
EES66 Low energy lamp replacement	£0.00	22.00	Sole Property Owner	11/11/2011
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	11/11/2011
EES15 Insulation to 65mm wide cavity wall	£1,052.40	1.00	Sole Property Owner	11/11/2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£72.00	8.00	Sole Property Owner	11/11/2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£110.00	10.00	Sole Property Owner	11/11/2011
EES70 Miscellaneous heating review charge	£45.00	1.00	Sole Property Owner	11/11/2011
EES51a 16-20kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	11/11/2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	11/11/2011
EES21 Scaffold	£500.00	50.00	Sole Property Owner	11/11/2011
EES70 Miscellaneous heating review charge	£2,521.09	2,521.09	Sole Property Owner	11/11/2011
EES70 Miscellaneous heating review charge	£218.40	1.00	Sole Property Owner	11/11/2011
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	11/11/2011
EES66 Low energy lamp replacement	£0.00	25.00	Sole Property Owner	06/01/2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	06/01/2012
EES15 Insulation to 65mm wide cavity wall	£108.00	108.00	Sole Property Owner	06/01/2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	06/01/2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	09/11/2011
EES02a Remove and dispose existing insulation (per square metre)	£132.00	44.00	Sole Property Owner	09/11/2011
EES08 300mm thick loft insulation	£528.00	44.00	Sole Property Owner	09/11/2011
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	09/11/2011
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	09/11/2011
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	09/11/2011
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	09/11/2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£14.00	2.00	Sole Property Owner	09/11/2011
EES66 Low energy lamp replacement	£0.00	30.00	Sole Property Owner	09/11/2011
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	09/11/2011
EES15 Insulation to 65mm wide cavity wall	£922.80	1.00	Sole Property Owner	09/11/2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£44.00	4.00	Sole Property Owner	09/11/2011
EES36 Electrical room thermostat	£61.60	1.00	Sole Property Owner	09/11/2011
EES42 Two channel programmable heating controller	£139.50	1.00	Sole Property Owner	09/11/2011
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	09/11/2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	09/11/2011
EES21 Scaffold	£800.00	80.00	Sole Property Owner	09/11/2011
EES70 Miscellaneous heating review charge	£2,461.66	2,461.66	Sole Property Owner	09/11/2011
EES38a Thermostatic radiator valve (per valve)	£254.76	4.00	Sole Property Owner	09/11/2011
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	09/11/2011
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	21/11/2011
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	21/11/2011
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Not The Property Owner	01/03/2012
EES03a Remove and replace nailed floor board	£0.00	0.00	Not The Property Owner	01/03/2012
EES08 300mm thick loft insulation	£0.00	0.00	Not The Property Owner	01/03/2012
EES66 Low energy lamp replacement	£0.00	0.00	Not The Property Owner	01/03/2012
EES67 Smoke detector installation	£0.00	0.00	Not The Property Owner	01/03/2012
EES77 HEC to House	£150.00	1.00	Not The Property Owner	06/01/2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012
HES119 Missed appointment charge	£60.00	1.00	Not The Property Owner	06/01/2012
EES01a Loft Clearance (hourly rate)	£25.00	1.00	Joint Owner	16/11/2011
EES02a Remove and dispose existing insulation (per square metre)	£15.00	5.00	Joint Owner	16/11/2011
EES03a Remove and replace nailed floor board	£6.00	2.00	Joint Owner	16/11/2011
EES08 300mm thick loft insulation	£420.00	35.00	Joint Owner	16/11/2011
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	16/11/2011
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	16/11/2011
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	16/11/2011
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Joint Owner	16/11/2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Joint Owner	16/11/2011
EES66 Low energy lamp replacement	£0.00	15.00	Joint Owner	16/11/2011
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	16/11/2011
EES15 Insulation to 65mm wide cavity wall	£614.40	1.00	Joint Owner	16/11/2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£18.00	2.00	Joint Owner	16/11/2011
EES49 Pipework lagging 25mm thick to 22mm pipe	£44.00	4.00	Joint Owner	16/11/2011
HES120 Standard QA check	£90.00	1.00	Joint Owner	16/11/2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	06/01/2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	11/08/2011
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	11/08/2011
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Sole Property Owner	16/11/2011
EES03a Remove and replace nailed floor board	£0.00	0.00	Sole Property Owner	16/11/2011
EES07 200mm thick loft insulation	£720.00	80.00	Sole Property Owner	16/11/2011
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	16/11/2011
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	16/11/2011

EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	16/11/2011	
EES13a Cold water tank bye law kit (including associated product	£100.00	2.00	Sole Property Owner	16/11/2011	
EES66 Low energy lamp replacement	£0.00	25.00	Sole Property Owner	16/11/2011	
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	16/11/2011	
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Joint Owner	16/11/2011	
EES02a Remove and dispose existing insulation (per squire metre	£108.00	36.00	Joint Owner	16/11/2011	
EES03a Remove and replace nailed floor board	£30.00	10.00	Joint Owner	16/11/2011	
EES08 300mm thick loft insulation	£432.00	36.00	Joint Owner	16/11/2011	
EES66 Low energy lamp replacement	£0.00	15.00	Joint Owner	16/11/2011	
EES15 Insulation to 65mm wide cavity wall	£1,321.20	1.00	Joint Owner	16/11/2011	
HES120 Standard QA check	£90.00	1.00	Joint Owner	16/11/2011	
HES100 Asbestos survey & sample	£55.00	1.00	Sole Property Owner	31/07/2013	
HES101 Asbestos removal & disposal	£500.00	1.00	Sole Property Owner	31/07/2013	
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Sole Property Owner	31/07/2013	
EES07 200mm thick loft insulation	£0.00	0.00	Sole Property Owner	31/07/2013	
EES66 Low energy lamp replacement	£0.00	55.00	Sole Property Owner	31/07/2013	
EES67 Smoke detector installation	£0.00	3.00	Sole Property Owner	31/07/2013	
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	31/07/2013	
HES101 Asbestos removal & disposal	£1,690.00	1.00	Sole Property Owner	31/07/2013	
HES23 Scaffold / cherry picker	£250.00	1.00	Sole Property Owner	31/07/2013	
EES08 300mm thick loft insulation	£1,680.00	140.00	Sole Property Owner	31/07/2013	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	31/07/2013	
HES34 36-45kW Oil replacement condensing boiler	£1,836.00	1.00	Sole Property Owner	31/07/2013	
HES40 Flue specification and location	£1,548.00	1.00	Sole Property Owner	31/07/2013	
HES41 Condensate pipework (and pump if required)	£382.00	1.00	Sole Property Owner	31/07/2013	
HES43 Central heating pump	£312.00	1.00	Sole Property Owner	31/07/2013	
HES44 Pipework / feed modifications	£535.92	535.92	Sole Property Owner	31/07/2013	
HES45 Fire valve	£36.90	1.00	Sole Property Owner	31/07/2013	
HES46 Automatic bypass	£27.50	1.00	Sole Property Owner	31/07/2013	
HES48 Power / system flush and treatment	£43.80	1.00	Sole Property Owner	31/07/2013	
HES50 Electrical room thermostat	£458.00	1.00	Sole Property Owner	31/07/2013	
HES53 Two channel heating programmer control	£33.80	1.00	Sole Property Owner	31/07/2013	
HES55 2 port zone valve	£147.00	3.00	Sole Property Owner	31/07/2013	
HES66 15mm thick pipework lagging	£14.49	9.00	Sole Property Owner	31/07/2013	
HES67 22mm thick pipework lagging	£23.76	12.00	Sole Property Owner	31/07/2013	
HES68 28mm thick pipework lagging	£28.92	12.00	Sole Property Owner	31/07/2013	
HES95 Senior heating engineer	£2,625.00	75.00	Sole Property Owner	31/07/2013	
HES98 Senior electrician	£350.00	10.00	Sole Property Owner	31/07/2013	
HES99 Building works	£176.00	8.00	Sole Property Owner	31/07/2013	
HES87 Commissioning and issue of CD10 and Building Control no	£0.00	1.00	Sole Property Owner	31/07/2013	
HES90 Other miscellaneous oil heating works for EES approval	£0.00	0.00	Sole Property Owner	31/07/2013	
HES122 Consultancy Fees	£1,042.50	1.00	Sole Property Owner	31/07/2013	
HES120 Standard QA check	£0.00	1.00	Sole Property Owner	31/07/2013	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	12/08/2011	
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	12/08/2011	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	12/08/2011	
EES25 Draught stripping to exterior door	£60.00	6.00	Sole Property Owner	12/08/2011	
EES07 200mm thick loft insulation	£0.00	0.00	Not The Property Owner	03/09/2012	
EES10 Cold water tank insulation quilt	£0.00	0.00	Not The Property Owner	03/09/2012	
EES 11 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	03/09/2012	
EES12 Cold water tank lid	£0.00	0.00	Not The Property Owner	03/09/2012	
EES13a Cold water tank bye law kit (including associated product	£0.00	0.00	Not The Property Owner	03/09/2012	
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Not The Property Owner	03/09/2012	
EES66 Low energy lamp replacement	£0.00	0.00	Not The Property Owner	03/09/2012	
EES67 Smoke detector installation	£0.00	0.00	Not The Property Owner	03/09/2012	
EES03a Remove and replace nailed floor board	£295.00	25.00	Sole Property Owner	01/02/2010	
EES07 200mm thick loft insulation	£222.75	25.00	Sole Property Owner	01/02/2010	
EES10 Cold water tank insulation quilt	£34.62	1.00	Sole Property Owner	01/02/2010	
EES25 Draught stripping to exterior door	£14.10	5.00	Sole Property Owner	01/02/2010	
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	01/02/2010	
EES66 Low energy lamp replacement	£31.50	18.00	Sole Property Owner	01/02/2010	
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	01/02/2010	
EES33 Replacement hot water cylinder (150l)	£928.21	1.00	Sole Property Owner	01/02/2010	
EES44 Water heating time clock and boost	£107.39	1.00	Sole Property Owner	01/02/2010	
EES40 Hot water cylinder thermostat	£46.51	1.00	Sole Property Owner	01/02/2010	
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Joint Owner	09/02/2012	
EES02a Remove and dispose existing insulation (per squire metre	£195.00	65.00	Joint Owner	09/02/2012	
EES03a Remove and replace nailed floor board	£9.00	3.00	Joint Owner	09/02/2012	
EES08 300mm thick loft insulation	£780.00	65.00	Joint Owner	09/02/2012	
EES10 Cold water tank insulation quilt	£0.00	0.00	Joint Owner	09/02/2012	
EES 11 Cold water tank insulation jacket	£0.00	0.00	Joint Owner	09/02/2012	
EES12 Cold water tank lid	£0.00	0.00	Joint Owner	09/02/2012	
EES13a Cold water tank bye law kit (including associated product	£0.00	0.00	Joint Owner	09/02/2012	
EES33 Replacement hot water cylinder (150l)	£0.00	0.00	Joint Owner	09/02/2012	
EES36 Electrical room thermostat	£135.00	1.00	Joint Owner	09/02/2012	
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Joint Owner	09/02/2012	
EES40 Hot water cylinder thermostat	£0.00	0.00	Joint Owner	09/02/2012	
EES42 Two channel programmable heating controller	£145.00	1.00	Joint Owner	09/02/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Joint Owner	09/02/2012	
EES66 Low energy lamp replacement	£0.00	15.00	Joint Owner	09/02/2012	
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	09/02/2012	
EES52a 21-25kW Oil replacement boiler	£3,633.00	1.00	Joint Owner	09/02/2012	
EES40 Hot water cylinder thermostat	£85.00	1.00	Joint Owner	09/02/2012	
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Joint Owner	09/02/2012	

EES35 Replacement hot water cylinder (210l)	£1,450.00	1.00	Joint Owner	09/02/2012	
EES70 Miscellaneous heating review charge	£2,022.00	1.00	Joint Owner	09/02/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£266.00	38.00	Joint Owner	09/02/2012	
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	09/02/2012	
EES01a Loft Clearance (hourly rate)	£175.00	7.00	Sole Property Owner	28/10/2011	
EES02a Remove and dispose existing insulation (per square metre)	£105.00	35.00	Sole Property Owner	28/10/2011	
EES03a Remove and replace nailed floor board	£0.00	0.00	Sole Property Owner	28/10/2011	
EES08 300mm thick loft insulation	£420.00	35.00	Sole Property Owner	28/10/2011	
EES29 Hot water cylinder jacket (30x18 inch)	£90.00	1.00	Sole Property Owner	28/10/2011	
EES38a Thermostatic radiator valve (per valve)	£1,105.00	13.00	Sole Property Owner	28/10/2011	
EES66 Low energy lamp replacement	£0.00	24.00	Sole Property Owner	28/10/2011	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	28/10/2011	
EES70 Miscellaneous heating review charge	£183.72	1.00	Sole Property Owner	28/10/2011	
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	28/10/2011	
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	28/10/2011	
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	28/10/2011	
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	28/10/2011	
EES48 Pipework lagging 19mm thick to 22mm pipe	£198.00	22.00	Sole Property Owner	28/10/2011	
EES38a Thermostatic radiator valve (per valve)	£63.69	1.00	Sole Property Owner	28/10/2011	
EES40 Hot water cylinder thermostat	£60.19	1.00	Sole Property Owner	28/10/2011	
EES42 Two channel programmable heating controller	£139.50	1.00	Sole Property Owner	28/10/2011	
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	28/10/2011	
EES21 Scaffold	£500.00	50.00	Sole Property Owner	28/10/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	28/10/2011	
EES70 Miscellaneous heating review charge	£2,067.66	2,067.66	Sole Property Owner	28/10/2011	
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	28/10/2011	
EES70 Miscellaneous heating review charge	£102.00	1.00	Sole Property Owner	28/10/2011	
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	16/11/2011	
EES02a Remove and dispose existing insulation (per square metre)	£135.00	45.00	Sole Property Owner	16/11/2011	
EES03a Remove and replace nailed floor board	£21.00	7.00	Sole Property Owner	16/11/2011	
EES08 300mm thick loft insulation	£540.00	45.00	Sole Property Owner	16/11/2011	
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	16/11/2011	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	16/11/2011	
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	16/11/2011	
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Sole Property Owner	16/11/2011	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	16/11/2011	
EES38a Thermostatic radiator valve (per valve)	£340.00	4.00	Sole Property Owner	16/11/2011	
EES40 Hot water cylinder thermostat	£85.00	1.00	Sole Property Owner	16/11/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£70.00	10.00	Sole Property Owner	16/11/2011	
EES66 Low energy lamp replacement	£0.00	15.00	Sole Property Owner	16/11/2011	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	16/11/2011	
EES15 Insulation to 65mm wide cavity wall	£606.00	1.00	Sole Property Owner	16/11/2011	
EES53a 26-35kW Oil replacement boiler	£2,822.00	1.00	Sole Property Owner	16/11/2011	
EES70 Miscellaneous heating review charge	£606.00	1.00	Sole Property Owner	16/11/2011	
HES85 Building Control Officer inspection undertaken	£103.85	1.00	Sole Property Owner	16/11/2011	
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Not The Property Owner	09/01/2012	
EES07 200mm thick loft insulation	£360.00	40.00	Not The Property Owner	09/01/2012	
EES10 Cold water tank insulation quilt	£50.00	1.00	Not The Property Owner	09/01/2012	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Not The Property Owner	09/01/2012	
EES12 Cold water tank lid	£75.00	1.00	Not The Property Owner	09/01/2012	
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Not The Property Owner	09/01/2012	
EES38a Thermostatic radiator valve (per valve)	£595.00	7.00	Not The Property Owner	09/01/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£28.00	4.00	Not The Property Owner	09/01/2012	
EES66 Low energy lamp replacement	£0.00	13.00	Not The Property Owner	09/01/2012	
EES67 Smoke detector installation	£0.00	2.00	Not The Property Owner	09/01/2012	
HES120 Standard QA check	£90.00	1.00	Not The Property Owner	09/01/2012	
EES66 Low energy lamp replacement	£0.00	15.00	Joint Owner	07/02/2012	
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	07/02/2012	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Joint Owner	07/02/2012	
EES42 Two channel programmable heating controller	£139.50	1.00	Joint Owner	07/02/2012	
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Joint Owner	07/02/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	20.00	Joint Owner	07/02/2012	
EES70 Miscellaneous heating review charge	£1,065.56	1,065.56	Joint Owner	07/02/2012	
EES70 Miscellaneous heating review charge	£316.21	1.00	Joint Owner	07/02/2012	
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	07/02/2012	
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Sole Property Owner	27/09/2012	
EES07 200mm thick loft insulation	£180.00	20.00	Sole Property Owner	27/09/2012	
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	27/09/2012	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	27/09/2012	
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	27/09/2012	
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Sole Property Owner	27/09/2012	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	27/09/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	27/09/2012	
EES66 Low energy lamp replacement	£0.00	12.00	Sole Property Owner	27/09/2012	
EES67 Smoke detector installation	£0.00	0.00	Sole Property Owner	27/09/2012	
HES120 Standard QA check	£102.00	1.00	Sole Property Owner	27/09/2012	
HES67 22mm thick pipework lagging	£8.44	2.00	Sole Property Owner	27/09/2012	
HES94 Heating engineer	£36.80	1.00	Sole Property Owner	27/09/2012	
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Not The Property Owner	01/09/2011	
EES07 200mm thick loft insulation	£0.00	0.00	Not The Property Owner	01/09/2011	
EES10 Cold water tank insulation quilt	£0.00	0.00	Not The Property Owner	01/09/2011	
EES 11 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	01/09/2011	
EES12 Cold water tank lid	£0.00	0.00	Not The Property Owner	01/09/2011	
EES13a Cold water tank bye law kit (including associated products)	£0.00	0.00	Not The Property Owner	01/09/2011	

EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Not The Property Owner	01/09/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	01/09/2011	
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Sole Property Owner	06/01/2012	
EES02a Remove and dispose existing insulation (per squire metre)	£150.00	50.00	Sole Property Owner	06/01/2012	
EES08 300mm thick loft insulation	£600.00	50.00	Sole Property Owner	06/01/2012	
EES10 Cold water tank insulation quilt	£0.00	2.00	Sole Property Owner	06/01/2012	
EES 11 Cold water tank insulation jacket	£0.00	2.00	Sole Property Owner	06/01/2012	
EES12 Cold water tank lid	£0.00	2.00	Sole Property Owner	06/01/2012	
EES13a Cold water tank bye law kit (including associated product)	£0.00	2.00	Sole Property Owner	06/01/2012	
EES29 Hot water cylinder jacket (30x18 inch)	£0.00	0.00	Sole Property Owner	06/01/2012	
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Sole Property Owner	06/01/2012	
EES66 Low energy lamp replacement	£0.00	15.00	Sole Property Owner	06/01/2012	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	06/01/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£210.00	30.00	Sole Property Owner	06/01/2012	
EES42 Two channel programmable heating controller	£0.00	1.00	Sole Property Owner	06/01/2012	
EES38a Thermostatic radiator valve (per valve)	£0.00	5.00	Sole Property Owner	06/01/2012	
EES53a 26-35kW Oil replacement boiler	£4,920.00	1.00	Sole Property Owner	06/01/2012	
EES70 Miscellaneous heating review charge	£480.00	480.00	Sole Property Owner	06/01/2012	
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	06/01/2012	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	16/11/2011	
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	16/11/2011	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	16/11/2011	
EES15 Insulation to 65mm wide cavity wall	£144.00	1.00	Sole Property Owner	16/11/2011	
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	16/11/2011	
EES01a Loft Clearance (hourly rate)	£200.00	8.00	Joint Owner	06/01/2012	
EES02a Remove and dispose existing insulation (per squire metre)	£165.00	55.00	Joint Owner	06/01/2012	
EES03a Remove and replace nailed floor board	£15.00	5.00	Joint Owner	06/01/2012	
EES08 300mm thick loft insulation	£660.00	55.00	Joint Owner	06/01/2012	
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	06/01/2012	
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	06/01/2012	
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	06/01/2012	
EES13a Cold water tank bye law kit (including associated product)	£100.00	2.00	Joint Owner	06/01/2012	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Joint Owner	06/01/2012	
EES38a Thermostatic radiator valve (per valve)	£510.00	6.00	Joint Owner	06/01/2012	
EES40 Hot water cylinder thermostat	£0.00	0.00	Joint Owner	06/01/2012	
EES66 Low energy lamp replacement	£0.00	15.00	Joint Owner	06/01/2012	
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	06/01/2012	
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Joint Owner	06/01/2012	
EES48 Pipework lagging 19mm thick to 22mm pipe	£135.00	15.00	Joint Owner	06/01/2012	
EES49 Pipework lagging 25mm thick to 22mm pipe	£242.00	22.00	Joint Owner	06/01/2012	
EES51b 16-20kW Gas replacement boiler	£2,064.61	1.00	Joint Owner	06/01/2012	
EES70 Miscellaneous heating review charge	£250.00	1.00	Joint Owner	06/01/2012	
HES85 Building Control Officer inspection undertaken	£103.85	1.00	Joint Owner	06/01/2012	
EES25 Draught stripping to exterior door	£87.52	2.00	Sole Property Owner	12/03/2010	
EES38a Thermostatic radiator valve (per valve)	£380.97	9.00	Sole Property Owner	12/03/2010	
EES66 Low energy lamp replacement	£52.80	11.00	Sole Property Owner	12/03/2010	
HES111 HER Survey for Flat	£0.00		Sole Property Owner	12/03/2010	
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	12/03/2010	
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Joint Owner	21/11/2011	
EES02a Remove and dispose existing insulation (per squire metre)	£120.00	40.00	Joint Owner	21/11/2011	
EES03a Remove and replace nailed floor board	£30.00	10.00	Joint Owner	21/11/2011	
EES08 300mm thick loft insulation	£480.00	40.00	Joint Owner	21/11/2011	
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	21/11/2011	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	21/11/2011	
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	21/11/2011	
EES13a Cold water tank bye law kit (including associated product)	£50.00	1.00	Joint Owner	21/11/2011	
EES66 Low energy lamp replacement	£0.00	16.00	Joint Owner	21/11/2011	
EES67 Smoke detector installation	£0.00	1.00	Joint Owner	21/11/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£42.00	6.00	Joint Owner	21/11/2011	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Joint Owner	11/10/2011	
EES66 Low energy lamp replacement	£0.00	10.00	Joint Owner	11/10/2011	
EES67 Smoke detector installation	£0.00	1.00	Joint Owner	11/10/2011	
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	11/08/2011	
EES66 Low energy lamp replacement	£0.00	8.00	Sole Property Owner	11/08/2011	
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	11/08/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	06/01/2012	
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012	
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Not The Property Owner	31/07/2011	
EES02a Remove and dispose existing insulation (per squire metre)	£0.00	0.00	Not The Property Owner	31/07/2011	
EES03a Remove and replace nailed floor board	£0.00	0.00	Not The Property Owner	31/07/2011	
EES08 300mm thick loft insulation	£0.00	0.00	Not The Property Owner	31/07/2011	
EES10 Cold water tank insulation quilt	£0.00	0.00	Not The Property Owner	31/07/2011	
EES 11 Cold water tank insulation jacket	£0.00	0.00	Not The Property Owner	31/07/2011	
EES12 Cold water tank lid	£0.00	0.00	Not The Property Owner	31/07/2011	
EES13a Cold water tank bye law kit (including associated product)	£0.00	0.00	Not The Property Owner	31/07/2011	
EES40 Hot water cylinder thermostat	£0.00	0.00	Not The Property Owner	31/07/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Not The Property Owner	31/07/2011	
EES66 Low energy lamp replacement	£0.00	0.00	Not The Property Owner	31/07/2011	
EES67 Smoke detector installation	£0.00	0.00	Not The Property Owner	31/07/2011	
EES25 Draught stripping to exterior door	£60.00	6.00	Not The Property Owner	02/08/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	02/08/2012	
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	02/08/2012	
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Joint Owner	16/11/2011	
EES66 Low energy lamp replacement	£0.00	26.00	Joint Owner	16/11/2011	

EES67 Smoke detector installation	£0.00	2.00	Joint Owner	16/11/2011	
EES16 Insulation to 75mm wide cavity wall	£1,055.95	1.00	Joint Owner	16/11/2011	
HES120 Standard QA check	£90.00	1.00	Joint Owner	16/11/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	06/01/2012	
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012	
EES25 Draught stripping to exterior door	£60.00	6.00	Sole Property Owner	02/08/2012	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	02/08/2012	
EES66 Low energy lamp replacement	£0.00	5.00	Sole Property Owner	02/08/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	02/08/2012	
EES69 Miscellaneous Charge	£204.08	1.00	Sole Property Owner	02/08/2012	
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	02/08/2012	
EES69 Miscellaneous Charge	£60.00	1.00	Sole Property Owner	02/08/2012	
HES90 Other miscellaneous oil heating works for EES approval	£399.38	1.00	Sole Property Owner	29/02/2012	
EES01a Loft Clearance (hourly rate)	£250.00	10.00	Sole Property Owner	29/02/2012	
EES02a Remove and dispose existing insulation (per square metre)	£144.00	48.00	Sole Property Owner	29/02/2012	
EES03a Remove and replace nailed floor board	£30.00	10.00	Sole Property Owner	29/02/2012	
EES08 300mm thick loft insulation	£576.00	48.00	Sole Property Owner	29/02/2012	
EES38a Thermostatic radiator valve (per valve)	£765.00	9.00	Sole Property Owner	29/02/2012	
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	29/02/2012	
EES66 Low energy lamp replacement	£0.00	16.00	Sole Property Owner	29/02/2012	
EES67 Smoke detector installation	£0.00	3.00	Sole Property Owner	29/02/2012	
EES38a Thermostatic radiator valve (per valve)	£63.69	1.00	Sole Property Owner	29/02/2012	
EES40 Hot water cylinder thermostat	£60.19	1.00	Sole Property Owner	29/02/2012	
EES42 Two channel programmable heating controller	£139.59	1.00	Sole Property Owner	29/02/2012	
EES53a 26-35kW Oil replacement boiler	£2,884.00	1.00	Sole Property Owner	29/02/2012	
EES48 Pipework lagging 19mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	29/02/2012	
EES70 Miscellaneous heating review charge	£1,960.80	1.00	Sole Property Owner	29/02/2012	
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	29/02/2012	
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	01/11/2009	
EES03a Remove and replace nailed floor board	£45.00	18.00	Sole Property Owner	01/11/2009	
EES08 300mm thick loft insulation	£216.00	18.00	Sole Property Owner	01/11/2009	
EES25 Draught stripping to exterior door	£60.00	6.00	Sole Property Owner	01/11/2009	
EES27 Draught stripping to letterbox	£40.00	1.00	Sole Property Owner	01/11/2009	
EES00a Full Energy Survey	£401.68	1.00	Sole Property Owner	01/11/2009	
EES68 Minimum charge for lamps and detectors	£0.00	1.00	Joint Owner	21/11/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	21/11/2011	
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	21/11/2011	
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Joint Owner	21/11/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	06/01/2012	
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012	
EES36 Electrical room thermostat	£61.60	1.00	Sole Property Owner	19/03/2012	
EES38a Thermostatic radiator valve (per valve)	£63.69	1.00	Sole Property Owner	19/03/2012	
EES40 Hot water cylinder thermostat	£60.19	1.00	Sole Property Owner	19/03/2012	
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	19/03/2012	
EES48 Pipework lagging 19mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	19/03/2012	
EES82 Boiler replacement miscellaneous works	£2,418.05	1.00	Sole Property Owner	19/03/2012	
EES01a Loft Clearance (hourly rate)	£400.00	16.00	Sole Property Owner	19/03/2012	
EES02a Remove and dispose existing insulation (per square metre)	£330.00	110.00	Sole Property Owner	19/03/2012	
EES08 300mm thick loft insulation	£1,320.00	110.00	Sole Property Owner	19/03/2012	
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	19/03/2012	
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	19/03/2012	
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	19/03/2012	
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	19/03/2012	
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	19/03/2012	
EES38a Thermostatic radiator valve (per valve)	£510.00	6.00	Sole Property Owner	19/03/2012	
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	19/03/2012	
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	19/03/2012	
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	19/03/2012	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	19/03/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£182.00	26.00	Sole Property Owner	19/03/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	19/03/2012	
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	19/03/2012	
EES29 Hot water cylinder jacket (30x18 inch)	£90.00	1.00	Sole Property Owner	11/08/2011	
EES66 Low energy lamp replacement	£0.00	12.00	Sole Property Owner	11/08/2011	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	11/08/2011	
EES36 Electrical room thermostat	£61.60	1.00	Sole Property Owner	02/08/2012	
EES38a Thermostatic radiator valve (per valve)	£63.69	1.00	Sole Property Owner	02/08/2012	
EES40 Hot water cylinder thermostat	£60.19	1.00	Sole Property Owner	02/08/2012	
EES42 Two channel programmable heating controller	£139.59	1.00	Sole Property Owner	02/08/2012	
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Sole Property Owner	02/08/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£200.00	20.00	Sole Property Owner	02/08/2012	
EES70 Miscellaneous heating review charge	£1,935.30	1.00	Sole Property Owner	02/08/2012	
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Sole Property Owner	02/08/2012	
EES02a Remove and dispose existing insulation (per square metre)	£165.00	55.00	Sole Property Owner	02/08/2012	
EES03a Remove and replace nailed floor board	£30.00	10.00	Sole Property Owner	02/08/2012	
EES08 300mm thick loft insulation	£660.00	55.00	Sole Property Owner	02/08/2012	
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	02/08/2012	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	02/08/2012	
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	02/08/2012	
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Sole Property Owner	02/08/2012	
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Sole Property Owner	02/08/2012	
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	02/08/2012	
EES67 Smoke detector installation	£0.00	1.00	Sole Property Owner	02/08/2012	
EES15 Insulation to 65mm wide cavity wall	£1,453.20	1,453.20	Sole Property Owner	02/08/2012	

HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	02/08/2012
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Joint Owner	02/08/2012
EES03a Remove and replace nailed floor board	£90.00	30.00	Joint Owner	02/08/2012
EES08 300mm thick loft insulation	£1,260.00	105.00	Joint Owner	02/08/2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	02/08/2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	02/08/2012
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	02/08/2012
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Joint Owner	02/08/2012
EES15 Insulation to 65mm wide cavity wall	£1,241.52	1,241.52	Joint Owner	02/08/2012
EES66 Low energy lamp replacement	£0.00	15.00	Joint Owner	02/08/2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	02/08/2012
HES73 Storage heater rated 3kW - 4kW	£1,126.02	3.00	Joint Owner	02/08/2012
HES97 Electrician	£288.00	9.00	Joint Owner	02/08/2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Joint Owner	02/08/2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£36.00	4.00	Joint Owner	02/08/2012
EES49 Pipework lagging 25mm thick to 22mm pipe	£44.00	4.00	Joint Owner	02/08/2012
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Not The Property Owner	09/01/2012
EES02a Remove and dispose existing insulation (per square metre)	£0.00	0.00	Not The Property Owner	09/01/2012
EES03a Remove and replace nailed floor board	£0.00	0.00	Not The Property Owner	09/01/2012
EES08 300mm thick loft insulation	£180.00	15.00	Not The Property Owner	09/01/2012
EES66 Low energy lamp replacement	£0.00	12.00	Not The Property Owner	09/01/2012
EES67 Smoke detector installation	£0.00	2.00	Not The Property Owner	09/01/2012
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Not The Property Owner	09/01/2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Sole Property Owner	16/11/2011
EES02a Remove and dispose existing insulation (per square metre)	£135.00	45.00	Sole Property Owner	16/11/2011
EES03a Remove and replace nailed floor board	£60.00	20.00	Sole Property Owner	16/11/2011
EES08 300mm thick loft insulation	£0.00	0.00	Sole Property Owner	16/11/2011
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	16/11/2011
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	16/11/2011
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	16/11/2011
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	16/11/2011
EES66 Low energy lamp replacement	£0.00	13.00	Sole Property Owner	16/11/2011
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	16/11/2011
EES06 100mm thick loft insulation	£294.30	45.00	Sole Property Owner	16/11/2011
EES07 200mm thick loft insulation	£315.00	35.00	Sole Property Owner	16/11/2011
EES69 Miscellaneous Charge	£409.95	1.00	Sole Property Owner	16/11/2011
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	16/11/2011
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Sole Property Owner	16/11/2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£14.00	2.00	Sole Property Owner	16/11/2011
EES48 Pipework lagging 19mm thick to 22mm pipe	£36.00	4.00	Sole Property Owner	16/11/2011
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	16/11/2011
EES08 300mm thick loft insulation	£720.00	60.00	Sole Property Owner	23/01/2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	23/01/2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	23/01/2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	23/01/2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	23/01/2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	23/01/2012
EES66 Low energy lamp replacement	£0.00	5.00	Sole Property Owner	23/01/2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	23/01/2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Sole Property Owner	23/01/2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£252.00	28.00	Sole Property Owner	23/01/2012
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	23/01/2012
EES00a Full Energy Survey	£401.68	1.00	Not The Property Owner	18/07/2009
EES66 Low energy lamp replacement	£0.00	15.00	Sole Property Owner	23/01/2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	23/01/2012
EES15 Insulation to 65mm wide cavity wall	£1,220.40	1.00	Sole Property Owner	23/01/2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	23/01/2012
EES48 Pipework lagging 19mm thick to 22mm pipe	£36.00	4.00	Sole Property Owner	23/01/2012
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	23/01/2012
EES33 Replacement hot water cylinder (150l)	£0.00	0.00	Joint Owner	06/01/2012
EES38a Thermostatic radiator valve (per valve)	£595.00	7.00	Joint Owner	06/01/2012
EES66 Low energy lamp replacement	£0.00	10.00	Joint Owner	06/01/2012
EES67 Smoke detector installation	£0.00	3.00	Joint Owner	06/01/2012
EES17 Insulation to 90mm wide cavity wall	£1,052.00	1,052.00	Joint Owner	06/01/2012
EES69 Miscellaneous Charge	£1,275.78	1.00	Joint Owner	06/01/2012
EES70 Miscellaneous heating review charge	£122.00	122.00	Joint Owner	06/01/2012
HES36 12-15kW Gas replacement condensing boiler	£616.00	1.00	Sole Property Owner	16/10/2013
HES41 Condensate pipework (and pump if required)	£0.00	0.00	Sole Property Owner	16/10/2013
HES43 Central heating pump	£71.67	1.00	Sole Property Owner	16/10/2013
HES44 Pipework / feed modifications	£0.00	0.00	Sole Property Owner	16/10/2013
HES46 Automatic bypass	£43.30	1.00	Sole Property Owner	16/10/2013
HES48 Power / system flush and treatment	£250.00	1.00	Sole Property Owner	16/10/2013
HES50 Electrical room thermostat	£15.75	1.00	Sole Property Owner	16/10/2013
HES52 Hot water cylinder thermostat	£4.62	1.00	Sole Property Owner	16/10/2013
HES53 Two channel heating programmer control	£0.00	0.00	Sole Property Owner	16/10/2013
HES55 2 port zone valve	£34.36	2.00	Sole Property Owner	16/10/2013
HES66 15mm thick pipework lagging	£6.69	3.00	Sole Property Owner	16/10/2013
HES67 22mm thick pipework lagging	£8.76	3.00	Sole Property Owner	16/10/2013
HES94 Heating engineer	£945.00	20.00	Sole Property Owner	16/10/2013
HES97 Electrician	£236.25	5.00	Sole Property Owner	16/10/2013
HES88 Commissioning and issue of CD11 and flue gas analysis	£47.25	1.00	Sole Property Owner	16/10/2013
HES23 Scaffold / cherry picker	£220.00	220.00	Sole Property Owner	16/10/2013
HES91 Other miscellaneous gas heating works for EES approval	£96.00	96.00	Sole Property Owner	16/10/2013
EES38a Thermostatic radiator valve (per valve)	£680.00	8.00	Sole Property Owner	16/10/2013

EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	16/10/2013	
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	16/10/2013	
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	16/10/2013	
HES40 Flue specification and location	£331.00	1.00	Sole Property Owner	16/10/2013	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	06/01/2012	
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012	
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Joint Owner	09/01/2012	
EES02a Remove and dispose existing insulation (per squire metre)	£198.00	66.00	Joint Owner	09/01/2012	
EES08 300mm thick loft insulation	£792.00	66.00	Joint Owner	09/01/2012	
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	09/01/2012	
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	09/01/2012	
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	09/01/2012	
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Joint Owner	09/01/2012	
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Joint Owner	09/01/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£294.00	42.00	Joint Owner	09/01/2012	
EES66 Low energy lamp replacement	£0.00	20.00	Joint Owner	09/01/2012	
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	09/01/2012	
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Joint Owner	09/01/2012	
EES40 Hot water cylinder thermostat	£60.19	1.00	Joint Owner	09/01/2012	
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Joint Owner	09/01/2012	
EES48 Pipework lagging 19mm thick to 22mm pipe	£200.00	20.00	Joint Owner	09/01/2012	
EES70 Miscellaneous heating review charge	£1,960.80	1.00	Joint Owner	09/01/2012	
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	09/01/2012	
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Sole Property Owner	03/02/2012	
EES03a Remove and replace nailed floor board	£30.00	10.00	Sole Property Owner	03/02/2012	
EES08 300mm thick loft insulation	£504.00	42.00	Sole Property Owner	03/02/2012	
EES10 Cold water tank insulation quilt	£50.00	1.00	Sole Property Owner	03/02/2012	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	03/02/2012	
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	03/02/2012	
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Sole Property Owner	03/02/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£112.00	16.00	Sole Property Owner	03/02/2012	
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	03/02/2012	
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	03/02/2012	
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	03/02/2012	
EES33 Replacement hot water cylinder (150l)	£0.00	0.00	Joint Owner	02/08/2012	
EES36 Electrical room thermostat	£135.00	1.00	Joint Owner	02/08/2012	
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Joint Owner	02/08/2012	
EES40 Hot water cylinder thermostat	£0.00	0.00	Joint Owner	02/08/2012	
EES66 Low energy lamp replacement	£0.00	40.00	Joint Owner	02/08/2012	
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	02/08/2012	
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Joint Owner	02/08/2012	
EES69 Miscellaneous Charge	£0.00	0.00	Joint Owner	02/08/2012	
EES34 Replacement hot water cylinder (170l)	£1,240.00	1.00	Joint Owner	02/08/2012	
EES44 Water heating time clock and boost	£130.00	1.00	Joint Owner	02/08/2012	
HES120 Standard QA check	£90.00	1.00	Joint Owner	02/08/2012	
EES75 HEC to Flat or Bedsit	£0.00	0.00	Sole Property Owner	24/06/2011	
EES52a 21-25kW Oil replacement boiler	£3,633.00	1.00	Sole Property Owner	24/11/2011	
EES70 Miscellaneous heating review charge	£1,779.00	1.00	Sole Property Owner	24/11/2011	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	24/11/2011	
EES38a Thermostatic radiator valve (per valve)	£340.00	4.00	Sole Property Owner	24/11/2011	
EES66 Low energy lamp replacement	£0.00	20.00	Sole Property Owner	24/11/2011	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	24/11/2011	
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Sole Property Owner	24/11/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£210.00	30.00	Sole Property Owner	24/11/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£56.00	8.00	Sole Property Owner	24/11/2011	
EES69 Miscellaneous Charge	£463.00	1.00	Sole Property Owner	24/11/2011	
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Sole Property Owner	24/11/2011	
EES53a 26-35kW Oil replacement boiler	£4,922.24	1.00	Sole Property Owner	17/08/2011	
EES33 Replacement hot water cylinder (150l)	£893.80	1.00	Sole Property Owner	17/08/2011	
EES36 Electrical room thermostat	£61.60	1.00	Sole Property Owner	17/08/2011	
EES38a Thermostatic radiator valve (per valve)	£573.21	9.00	Sole Property Owner	17/08/2011	
EES40 Hot water cylinder thermostat	£60.19	1.00	Sole Property Owner	17/08/2011	
EES42 Two channel programmable heating controller	£139.50	1.00	Sole Property Owner	17/08/2011	
EES08 300mm thick loft insulation	£0.00	0.00	Sole Property Owner	17/08/2011	
EES10 Cold water tank insulation quilt	£34.62	1.00	Sole Property Owner	17/08/2011	
EES02a Remove and dispose existing insulation (per squire metre)	£0.00	0.00	Sole Property Owner	17/08/2011	
EES25 Draught stripping to exterior door	£45.50	5.00	Sole Property Owner	17/08/2011	
EES26 Draught stripping to windows	£136.50	15.00	Sole Property Owner	17/08/2011	
EES27 Draught stripping to letterbox	£22.20	1.00	Sole Property Owner	17/08/2011	
EES48 Pipework lagging 19mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	17/08/2011	
EES66 Low energy lamp replacement	£0.00	0.00	Sole Property Owner	17/08/2011	
EES67 Smoke detector installation	£0.00	0.00	Sole Property Owner	17/08/2011	
EES69 Miscellaneous Charge	£1,017.90	65.00	Sole Property Owner	17/08/2011	
EES00a Full Energy Survey	£401.70	1.00	Sole Property Owner	17/08/2011	
HES121 Boiler QA Check	£105.00	1.00	Sole Property Owner	17/08/2011	
HES120 Standard QA check	£102.00	1.00	Joint Owner	16/11/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	16/11/2012	
HES72 Storage heater rated 2kW - 3kW	£616.98	2.00	Joint Owner	16/11/2012	
HES73 Storage heater rated 3kW - 4kW	£375.34	1.00	Joint Owner	16/11/2012	
HES74 Comfort heat main switch	£57.20	1.00	Joint Owner	16/11/2012	
HES75 Storage heater consumer unit	£49.40	1.00	Joint Owner	16/11/2012	
HES76 Storage heater miniature circuit breaker	£39.00	4.00	Joint Owner	16/11/2012	
HES77 Main bonding of necessary services	£54.50	5.00	Joint Owner	16/11/2012	
HES78 Twin and earth 16mm cabling with clips and trunking	£317.39	17.00	Joint Owner	16/11/2012	

HES80 16mm meter tails	£12.48	1.00	Joint Owner	16/11/2012
HES83 Trunking	£57.84	6.00	Joint Owner	16/11/2012
HES97 Electrician	£544.00	17.00	Joint Owner	16/11/2012
HES92 Other miscellaneous electrical heating works for EES app	£57.68	1.00	Joint Owner	16/11/2012
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	16/11/2012
EES01a Loft Clearance (hourly rate)	£0.00	0.00	Joint Owner	06/01/2012
EES38a Thermostatic radiator valve (per valve)	£680.00	8.00	Joint Owner	06/01/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£126.00	18.00	Joint Owner	06/01/2012
EES66 Low energy lamp replacement	£0.00	10.00	Joint Owner	06/01/2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	06/01/2012
EES38a Thermostatic radiator valve (per valve)	£765.00	9.00	Joint Owner	06/01/2012
EES66 Low energy lamp replacement	£0.00	15.00	Joint Owner	06/01/2012
EES67 Smoke detector installation	£0.00	3.00	Joint Owner	06/01/2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Sole Property Owner	16/11/2011
EES02a Remove and dispose existing insulation (per squire metre)	£108.00	36.00	Sole Property Owner	16/11/2011
EES03a Remove and replace nailed floor board	£30.00	10.00	Sole Property Owner	16/11/2011
EES08 300mm thick loft insulation	£432.00	36.00	Sole Property Owner	16/11/2011
EES10 Cold water tank insulation quilt	£0.00	0.00	Sole Property Owner	16/11/2011
EES 11 Cold water tank insulation jacket	£75.00	1.00	Sole Property Owner	16/11/2011
EES12 Cold water tank lid	£75.00	1.00	Sole Property Owner	16/11/2011
EES13a Cold water tank bye law kit (including associated product	£50.00	1.00	Sole Property Owner	16/11/2011
EES66 Low energy lamp replacement	£0.00	25.00	Sole Property Owner	16/11/2011
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	16/11/2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£49.00	7.00	Sole Property Owner	16/11/2011
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	16/11/2011
EES40 Hot water cylinder thermostat	£0.00	0.00	Joint Owner	20/02/2013
EES42 Two channel programmable heating controller	£0.00	1.00	Joint Owner	20/02/2013
EES48 Pipework lagging 19mm thick to 22mm pipe	£0.00	1.00	Joint Owner	20/02/2013
EES50b 12-15kW Gas replacement boiler	£971.00	1.00	Joint Owner	20/02/2013
EES70 Miscellaneous heating review charge	£1,743.47	1.00	Joint Owner	20/02/2013
EES29 Hot water cylinder jacket (30x18 inch)	£90.00	1.00	Joint Owner	20/02/2013
EES36 Electrical room thermostat	£135.00	1.00	Joint Owner	20/02/2013
EES38a Thermostatic radiator valve (per valve)	£1,020.00	12.00	Joint Owner	20/02/2013
EES66 Low energy lamp replacement	£0.00	13.00	Joint Owner	20/02/2013
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	20/02/2013
EES15 Insulation to 65mm wide cavity wall	£577.00	577.00	Joint Owner	20/02/2013
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	20/02/2013
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	09/01/2012
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	09/01/2012
EES68 Minimum charge for lamps and detectors	£50.00	1.00	Sole Property Owner	09/01/2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Joint Owner	16/11/2011
EES02a Remove and dispose existing insulation (per squire metre)	£270.00	90.00	Joint Owner	16/11/2011
EES03a Remove and replace nailed floor board	£60.00	20.00	Joint Owner	16/11/2011
EES08 300mm thick loft insulation	£1,080.00	90.00	Joint Owner	16/11/2011
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	16/11/2011
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	16/11/2011
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	16/11/2011
EES13a Cold water tank bye law kit (including associated product	£50.00	1.00	Joint Owner	16/11/2011
EES47 Pipework lagging 13mm thick to 22mm pipe	£70.00	10.00	Joint Owner	16/11/2011
EES66 Low energy lamp replacement	£0.00	7.00	Joint Owner	16/11/2011
EES67 Smoke detector installation	£0.00	1.00	Joint Owner	16/11/2011
HES120 Standard QA check	£90.00	1.00	Joint Owner	16/11/2011
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Joint Owner	06/01/2012
EES66 Low energy lamp replacement	£0.00	35.00	Joint Owner	06/01/2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	06/01/2012
EES15 Insulation to 65mm wide cavity wall	£464.40	464.40	Joint Owner	06/01/2012
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Sole Property Owner	08/02/2012
EES03a Remove and replace nailed floor board	£30.00	10.00	Sole Property Owner	08/02/2012
EES07 200mm thick loft insulation	£225.00	25.00	Sole Property Owner	08/02/2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	08/02/2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	08/02/2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	08/02/2012
EES13a Cold water tank bye law kit (including associated product	£100.00	2.00	Sole Property Owner	08/02/2012
EES33 Replacement hot water cylinder (150l)	£0.00	0.00	Sole Property Owner	08/02/2012
EES40 Hot water cylinder thermostat	£0.00	0.00	Sole Property Owner	08/02/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Sole Property Owner	08/02/2012
EES66 Low energy lamp replacement	£0.00	10.00	Sole Property Owner	08/02/2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	08/02/2012
EES69 Miscellaneous Charge	£136.80	1.00	Sole Property Owner	08/02/2012
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	08/02/2012
EES01a Loft Clearance (hourly rate)	£100.00	4.00	Not The Property Owner	17/03/2014
EES02a Remove and dispose existing insulation (per squire metre)	£270.00	90.00	Not The Property Owner	17/03/2014
EES08 300mm thick loft insulation	£1,080.00	90.00	Not The Property Owner	17/03/2014
EES10 Cold water tank insulation quilt	£50.00	1.00	Not The Property Owner	17/03/2014
EES 11 Cold water tank insulation jacket	£75.00	1.00	Not The Property Owner	17/03/2014
EES12 Cold water tank lid	£75.00	1.00	Not The Property Owner	17/03/2014
EES13a Cold water tank bye law kit (including associated product	£50.00	1.00	Not The Property Owner	17/03/2014
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Not The Property Owner	17/03/2014
EES66 Low energy lamp replacement	£0.00	15.00	Not The Property Owner	17/03/2014
EES67 Smoke detector installation	£0.00	1.00	Not The Property Owner	17/03/2014
HES120 Standard QA check	£102.00	1.00	Not The Property Owner	17/03/2014
EES25 Draught stripping to exterior door	£43.75	5.00	Not The Property Owner	01/11/2009
EES66 Low energy lamp replacement	£64.00	1.00	Not The Property Owner	01/11/2009
EES49 Pipework lagging 25mm thick to 22mm pipe	£12.99	3.00	Not The Property Owner	01/11/2009

EES51b 16-20kW Gas replacement boiler	£1,994.00	1.00	Joint Owner	06/02/2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Joint Owner	06/02/2012
EES02a Remove and dispose existing insulation (per squire metre)	£135.00	45.00	Joint Owner	06/02/2012
EES08 300mm thick loft insulation	£540.00	45.00	Joint Owner	06/02/2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	06/02/2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	06/02/2012
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	06/02/2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Joint Owner	06/02/2012
EES38a Thermostatic radiator valve (per valve)	£255.00	3.00	Joint Owner	06/02/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£112.00	16.00	Joint Owner	06/02/2012
EES66 Low energy lamp replacement	£0.00	10.00	Joint Owner	06/02/2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	06/02/2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	06/02/2012
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	11/08/2011
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	11/08/2011
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	15/02/2012
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	15/02/2012
EES25 Draught stripping to exterior door	£50.00	5.00	Not The Property Owner	14/02/2012
EES27 Draught stripping to letterbox	£40.00	1.00	Not The Property Owner	14/02/2012
EES38a Thermostatic radiator valve (per valve)	£1,190.00	14.00	Not The Property Owner	14/02/2012
EES66 Low energy lamp replacement	£0.00	11.00	Not The Property Owner	14/02/2012
EES67 Smoke detector installation	£0.00	2.00	Not The Property Owner	14/02/2012
EES15 Insulation to 65mm wide cavity wall	£333.60	333.60	Joint Owner	03/04/2012
EES52a 21-25kW Oil replacement boiler	£3,633.00	1.00	Joint Owner	03/04/2012
EES34 Replacement hot water cylinder (170l)	£1,240.00	1.00	Joint Owner	03/04/2012
EES36 Electrical room thermostat	£135.00	1.00	Joint Owner	03/04/2012
EES40 Hot water cylinder thermostat	£85.00	1.00	Joint Owner	03/04/2012
EES42 Two channel programmable heating controller	£145.00	1.00	Joint Owner	03/04/2012
EES70 Miscellaneous heating review charge	£2,610.00	1.00	Joint Owner	03/04/2012
EES01a Loft Clearance (hourly rate)	£125.00	5.00	Joint Owner	03/04/2012
EES07 200mm thick loft insulation	£441.00	49.00	Joint Owner	03/04/2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	03/04/2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	03/04/2012
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	03/04/2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Joint Owner	03/04/2012
EES33 Replacement hot water cylinder (150l)	£0.00	0.00	Joint Owner	03/04/2012
EES38a Thermostatic radiator valve (per valve)	£850.00	10.00	Joint Owner	03/04/2012
EES40 Hot water cylinder thermostat	£0.00	0.00	Joint Owner	03/04/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£112.00	16.00	Joint Owner	03/04/2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	03/04/2012
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	03/04/2012
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	06/01/2012
EES02a Remove and dispose existing insulation (per squire metre)	£129.00	43.00	Sole Property Owner	06/01/2012
EES08 300mm thick loft insulation	£516.00	43.00	Sole Property Owner	06/01/2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	06/01/2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	06/01/2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	06/01/2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	06/01/2012
EES38a Thermostatic radiator valve (per valve)	£595.00	7.00	Sole Property Owner	06/01/2012
EES42 Two channel programmable heating controller	£145.00	1.00	Sole Property Owner	06/01/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£70.00	10.00	Sole Property Owner	06/01/2012
EES66 Low energy lamp replacement	£0.00	12.00	Sole Property Owner	06/01/2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	06/01/2012
EES15 Insulation to 65mm wide cavity wall	£1,220.40	1,220.40	Sole Property Owner	06/01/2012
EES36 Electrical room thermostat	£135.00	1.00	Sole Property Owner	06/01/2012
EES70 Miscellaneous heating review charge	£110.00	1.00	Sole Property Owner	06/01/2012
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	06/01/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£98.00	14.00	Joint Owner	06/01/2012
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Joint Owner	06/01/2012
EES06 100mm thick loft insulation	£98.10	15.00	Joint Owner	06/01/2012
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	06/01/2012
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	06/01/2012
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	06/01/2012
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Joint Owner	06/01/2012
EES66 Low energy lamp replacement	£0.00	10.00	Joint Owner	06/01/2012
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	06/01/2012
EES77 HEC to House	£150.00	1.00	Joint Owner	11/08/2011
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	11/08/2011
EES01a Loft Clearance (hourly rate)	£50.00	2.00	Sole Property Owner	03/02/2012
EES02a Remove and dispose existing insulation (per squire metre)	£144.00	48.00	Sole Property Owner	03/02/2012
EES03a Remove and replace nailed floor board	£15.00	5.00	Sole Property Owner	03/02/2012
EES08 300mm thick loft insulation	£576.00	48.00	Sole Property Owner	03/02/2012
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	03/02/2012
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	03/02/2012
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	03/02/2012
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	03/02/2012
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Sole Property Owner	03/02/2012
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Sole Property Owner	03/02/2012
EES42 Two channel programmable heating controller	£0.00	0.00	Sole Property Owner	03/02/2012
EES47 Pipework lagging 13mm thick to 22mm pipe	£196.00	28.00	Sole Property Owner	03/02/2012
EES66 Low energy lamp replacement	£0.00	18.00	Sole Property Owner	03/02/2012
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	03/02/2012
EES15 Insulation to 65mm wide cavity wall	£1,869.60	1,869.60	Sole Property Owner	03/02/2012
EES70 Miscellaneous heating review charge	£324.00	1.00	Sole Property Owner	03/02/2012

HES120 Standard QA check	£90.00	1.00	Sole Property Owner	03/02/2012	
EES01a Loft Clearance (hourly rate)	£250.00	10.00	Joint Owner	16/11/2011	
EES03a Remove and replace nailed floor board	£60.00	20.00	Joint Owner	16/11/2011	
EES08 300mm thick loft insulation	£900.00	75.00	Joint Owner	16/11/2011	
EES10 Cold water tank insulation quilt	£100.00	2.00	Joint Owner	16/11/2011	
EES 11 Cold water tank insulation jacket	£150.00	2.00	Joint Owner	16/11/2011	
EES12 Cold water tank lid	£150.00	2.00	Joint Owner	16/11/2011	
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Joint Owner	16/11/2011	
EES33 Replacement hot water cylinder (150l)	£0.00	0.00	Joint Owner	16/11/2011	
EES47 Pipework lagging 13mm thick to 22mm pipe	£70.00	10.00	Joint Owner	16/11/2011	
EES66 Low energy lamp replacement	£0.00	15.00	Joint Owner	16/11/2011	
EES67 Smoke detector installation	£0.00	1.00	Joint Owner	16/11/2011	
EES15 Insulation to 65mm wide cavity wall	£0.00	0.00	Joint Owner	16/11/2011	
EES69 Miscellaneous Charge	£0.00	0.00	Joint Owner	16/11/2011	
HES44 Pipework / feed modifications	£149.50	1.00	Joint Owner	16/11/2011	
HES63 Stainless steel replacement hot water cylinder (150L)	£243.60	1.00	Joint Owner	16/11/2011	
HES94 Heating engineer	£368.00	10.00	Joint Owner	16/11/2011	
HES95 Senior heating engineer	£39.68	1.00	Joint Owner	16/11/2011	
HES90 Other miscellaneous oil heating works for EES approval	£31.05	1.00	Joint Owner	16/11/2011	
HES120 Standard QA check	£90.00	1.00	Joint Owner	16/11/2011	
EES00a Full Energy Survey	£401.67	1.00	Not The Property Owner	29/10/2009	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Joint Owner	31/07/2013	
EES66 Low energy lamp replacement	£15.00	1.00	Joint Owner	31/07/2013	
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	31/07/2013	
EES25 Draught stripping to exterior door	£110.00	11.00	Joint Owner	31/07/2013	
HES97 Electrician	£450.00	18.00	Joint Owner	31/07/2013	
HES72 Storage heater rated 2kW - 3kW	£342.23	1.00	Joint Owner	31/07/2013	
HES73 Storage heater rated 3kW - 4kW	£833.64	2.00	Joint Owner	31/07/2013	
HES76 Storage heater miniature circuit breaker	£16.02	3.00	Joint Owner	31/07/2013	
HES79 Heating point twin and earth mini trunk DP switch	£19.68	3.00	Joint Owner	31/07/2013	
EES01a Loft Clearance (hourly rate)	£75.00	3.00	Sole Property Owner	08/02/2012	
EES02a Remove and dispose existing insulation (per square metre)	£225.00	75.00	Sole Property Owner	08/02/2012	
EES08 300mm thick loft insulation	£900.00	75.00	Sole Property Owner	08/02/2012	
EES10 Cold water tank insulation quilt	£100.00	2.00	Sole Property Owner	08/02/2012	
EES 11 Cold water tank insulation jacket	£150.00	2.00	Sole Property Owner	08/02/2012	
EES12 Cold water tank lid	£150.00	2.00	Sole Property Owner	08/02/2012	
EES13a Cold water tank bye law kit (including associated products)	£100.00	2.00	Sole Property Owner	08/02/2012	
EES38a Thermostatic radiator valve (per valve)	£1,105.00	13.00	Sole Property Owner	08/02/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£238.00	34.00	Sole Property Owner	08/02/2012	
EES66 Low energy lamp replacement	£0.00	22.00	Sole Property Owner	08/02/2012	
EES67 Smoke detector installation	£0.00	2.00	Sole Property Owner	08/02/2012	
EES15 Insulation to 65mm wide cavity wall	£2,354.40	2,354.40	Sole Property Owner	08/02/2012	
HES120 Standard QA check	£90.00	1.00	Sole Property Owner	08/02/2012	
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Joint Owner	06/01/2012	
EES02a Remove and dispose existing insulation (per square metre)	£135.00	45.00	Joint Owner	06/01/2012	
EES03a Remove and replace nailed floor board	£135.00	45.00	Joint Owner	06/01/2012	
EES08 300mm thick loft insulation	£540.00	45.00	Joint Owner	06/01/2012	
EES10 Cold water tank insulation quilt	£50.00	1.00	Joint Owner	06/01/2012	
EES 11 Cold water tank insulation jacket	£75.00	1.00	Joint Owner	06/01/2012	
EES12 Cold water tank lid	£75.00	1.00	Joint Owner	06/01/2012	
EES13a Cold water tank bye law kit (including associated products)	£50.00	1.00	Joint Owner	06/01/2012	
EES38a Thermostatic radiator valve (per valve)	£510.00	6.00	Joint Owner	06/01/2012	
EES47 Pipework lagging 13mm thick to 22mm pipe	£0.00	0.00	Joint Owner	06/01/2012	
EES66 Low energy lamp replacement	£0.00	22.00	Joint Owner	06/01/2012	
EES67 Smoke detector installation	£0.00	2.00	Joint Owner	06/01/2012	
EES15 Insulation to 65mm wide cavity wall	£994.80	994.80	Joint Owner	06/01/2012	
EES33 Replacement hot water cylinder (150l)	£1,200.00	1.00	Joint Owner	06/01/2012	
HES21 Smoke detector installation	£0.00	1.00	Joint Owner	06/01/2012	
HES22 Minimum per property charge	£50.00	1.00	Joint Owner	06/01/2012	
HES120 Standard QA check	£90.00	1.00	Joint Owner	06/01/2012	
EES75 HEC to Flat or Bedsit	£0.00	0.00	Joint Owner	09/09/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	11/08/2011	
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	11/08/2011	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	06/01/2012	
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	06/01/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Not The Property Owner	11/08/2011	
EES66 Low energy lamp replacement	£15.00	1.00	Not The Property Owner	11/08/2011	
EES27 Draught stripping to letterbox	£40.00	1.00	Not The Property Owner	08/02/2012	
EES01a Loft Clearance (hourly rate)	£150.00	6.00	Not The Property Owner	08/02/2012	
EES03a Remove and replace nailed floor board	£30.00	10.00	Not The Property Owner	08/02/2012	
EES08 300mm thick loft insulation	£120.00	10.00	Not The Property Owner	08/02/2012	
EES25 Draught stripping to exterior door	£50.00	5.00	Not The Property Owner	08/02/2012	
EES66 Low energy lamp replacement	£0.00	5.00	Not The Property Owner	08/02/2012	
EES67 Smoke detector installation	£0.00	1.00	Not The Property Owner	08/02/2012	
HES120 Standard QA check	£90.00	1.00	Not The Property Owner	08/02/2012	
EES75 HEC to Flat or Bedsit	£120.00	1.00	Sole Property Owner	12/08/2011	
EES66 Low energy lamp replacement	£15.00	1.00	Sole Property Owner	12/08/2011	
EES25 Draught stripping to exterior door	£60.00	6.00	Sole Property Owner	12/08/2011	
EES40 Hot water cylinder thermostat	£60.19	1.00	Joint Owner	02/02/2012	
EES42 Two channel programmable heating controller	£139.59	1.00	Joint Owner	02/02/2012	
EES53a 26-35kW Oil replacement boiler	£2,684.00	1.00	Joint Owner	02/02/2012	
EES49 Pipework lagging 25mm thick to 22mm pipe	£200.00	20.00	Joint Owner	02/02/2012	
EES70 Miscellaneous heating review charge	£2,571.58	2,571.58	Joint Owner	02/02/2012	
EES70 Miscellaneous heating review charge	£157.82	1.00	Joint Owner	02/02/2012	

EES01a Loft Clearance (hourly rate)	£100.00	4.00	Joint Owner	02/02/2012	
EES07 200mm thick loft insulation	£495.00	55.00	Joint Owner	02/02/2012	
EES38a Thermostatic radiator valve (per valve)	£0.00	0.00	Joint Owner	02/02/2012	
EES66 Low energy lamp replacement	£0.00	7.00	Joint Owner	02/02/2012	
EES67 Smoke detector installation	£0.00	1.00	Joint Owner	02/02/2012	
HES85 Building Control Officer inspection undertaken	£90.00	1.00	Joint Owner	02/02/2012	
EES77 HEC to House	£150.00	1.00	Not The Property Owner	26/01/2011	